

ASS. REC. BY:

Kenneth

REF: MSG/20001838/KHV

ASSIGNMENT

From:

Estimated Cost:

Date:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

12/6 @ 2132.16 Confirm (Red 608.88, 22%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

16/6/20-Typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Report Format: Merimen

ump Sum / I.B.I: (\$) \$2132.16

Add Fee:

☐

: Site Insp (\$

☐


: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$



Veh No:

SMF 348L

Yr Regn:

10, 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Eletra Sc 1591

Colour:

M. Red

A/C: Insured / Std / NI / NA

Sp. Reading

28238

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM110841CMJ4756636

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

11/1/20

D.O.I.

19/5/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 151

The U/C / Chassis frame / Body Structure affected due to collision.