

22/03/2020

ASS. REC. BY:

REF: CS/SPF 2000/891/ Kqf322

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Frankie Thay

of SPF

Date/Time: 4.2.2020 1.30pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLJ 3306D

Insured: QX 311A

at Workshop m/s Opama Witez

Tel: 64811011

of 9 A Serangoon North Ave 5

Policy No:

Claim No: ACS/105/009/2020/003

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 16.1.2020

CA / REV / REP. / REV 24 HRS

map

H.O.D. Endorsement:

Date/Time: 4/2/2020 2.45p.m

Person Contacted: Sharon

Vehicle IN/OUT

Date/Time	Action/Instruction
	Sohnadi (✓)
	SLJ 3306D - X
	QX 311A - CS/SPF K1007500/GAD322
10/3/20	2.15pm checked with Sharon, the vehicle has not send in for repair.
10/3/20	Submit Preli. report. Change cost = \$1433.70 - \$1503.70; weekend.

Do Not Finalise



## Nivikha (LKK Auto)

---

**From:** Frankie THAY (SPF) <Frankie\_THAY@spf.gov.sg>  
**Sent:** Tuesday, 4 February 2020 1:35 PM  
**To:** 'assignments'; Veron Chen (LKKAuto)  
**Cc:** Cui Fen ENG (SPF); Hafizul Farhan RAHMAT (SPF); Lai Kuen LUI (SPF)  
**Subject:** RE : Pre-Repair Inspection for SLJ 3306D

Your Reference: SLJ 3306D

Our reference : ACS/105/009/2020/003

Veron,

Please conduct a Pre-Repair Inspection for vehicle SLJ3306D at the address listed below :

Location: 9A Serangoon North Avenue 5

*\*\*Please avoid 1PM - 2P*

Contact person : **Sharon Ten (Ms.)** Claims Executive, Motor Claims Department D: +65 6481 1522 | F: +65 6481 1011

Thanks.

Frankie Thay  
1 Logistics Services Executive  
Logistics Support & Services Division  
Police Logistics Department



**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	353M
Vehicle Details	
Vehicle No.:	SLJ3306D
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLC250 4MATIC
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	27492030767607
Chassis No.:	WDC2539462F143598
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$41,893.00
Original Registration Date:	06 Dec 2016
First Registration Date:	06 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$50,651.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Dec 2026
PARF Rebate Amount:	\$37,988.00
Intended COE Rebate Details	
COE Expiry Date:	05 Dec 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,903.00
COE Rebate Amount:	\$39,644.00
<b>Total Rebate Amount:</b>	<b>\$77,632.00</b>

The information contained herein is correct as at 31 Jan 2020

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	22/01/2020 16:44
Date Of Accident	16/01/2020 12:00
Exact Location Of Accident	CORONATION ROAD WEST
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ3306D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FIRST PRINTERS PTE LTD
Co Reg No	1XXXXX353M
Email Address	ALVIN@FIRSTPRINTERS.COM.SG
Mobile Phone No	(LOCAL) +65-93206966
Alternative Phone No	OFFICE-62703130

#### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	GLC 250-2.0 4MATIC (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA144918
Cover Note Number	

#### Driver

Name of Driver	YEW KOK AUN ALVIN
NRIC No	SXXXX209A
Date Of Birth	21/10/1975
Occupation	INDOOR
Date Of Driving Pass	21/10/1994
Driving Experience	25 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93206966
Fax Number	
Contact Number	
Email Address	ALVIN@FIRSTPRINTERS.COM.SG

Address 25 LIM TAI SEE WALK  
 Postcode 267793  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name BUKIT TIMAH NEIGHBOURHOOD POLICE CENTRE  
 Police Station Address ROAD: 1 DUKE ROAD , POSTCODE: 268914 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-4629999 - FAX NO: 64628933  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACH

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: REFER TO OWNER  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number QX311A  
 Vehicle Make/Model/Colour POLICE CAR  
 Details Of Properties  
 Vehicle Category GOVERNMENT  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Sketch Plan

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

*[Signature]*  
**First Printers Pte Ltd**  
 203 Henderson Road, #07-09 (Wing B)  
 Henderson Industrial Park  
 Singapore 159546  
 Tel: 6274 0225 Fax: 6274 0225

*[Signature]*  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time

21/01/2020  
 1700 hrs



Reporting Centre Personnel's Signature  
 Name: Anna  
 NRIC/FIN No:

Sketch Plan #2

SKETCH PLAN



A is SL333067

B is QX311A

*[Handwritten signature]*

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT T/20200116/2176

*[Handwritten signature]*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*  
**First Printers Pte Ltd**  
 203 Henderson Road, #07-09 (Wing B)  
 Henderson Industrial Park  
 Singapore 159546  
 Tel: 6270 3130 (3 Lines) Fax: 6274 0225

*[Signature]*  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 21/01/2020  
 1700 hrs



Reporting Centre Personnel's Signature  
 Name: Ann A  
 NRIC/FIN No.:

Police Report



SINGAPORE POLICE FORCE



T202001162173

Police Station Of Origin:  
Bukit Timah N.P.C  
1 Duke's Road SINGAPORE 268014  
Tel No. 1800 4629999

1 of 3

Report No. T202001162173

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/01/2020 21:57	Vice Report No.	Station Diary No.: 88
--	-----------------	--------------------------

Informant's Particulars			
Name of Informant: YEW KOK AUN ALVIN		Address: 25 LUY TA SEE WALK SINGAPORE 267793	
ID Type / ID No.: NRIC NO / S7531209A		Contact No. Home/Office.	Vehicle: 93208855
Nationality: SINGAPORE CITIZEN		Email.	
Sex: Male	Age: 44	Date of Birth: 21/10/1975	Type of Informant: Driver
Race: Chinese		Language	Institution / School Name
Occupation: Sales and marketing manager		Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-injury Others	Drink Driver: No	Date/Time of Accident: 16/01/2020 12:00	Type of Location: Straight Road
Location Along Road: CORONATION ROAD WEST				
Coronation Road West near to Jalan Hsu Alias				
Weather: Clear		Road Surface: Dry	Road Speed Limit	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Sweep - Opposite Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX311A	Car				Slightly Damaged	1
SLI3508D	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	No. of Pedestrians Injured: N/L	Jac of Pedestrian Crossing: NA
-----------------------------	---------------------------------	--------------------------------

Date: 01.02.2020  
 Vehicle No: SLJ3306D  
 Model: MERCEDEZ BENZ GLC 250  
 Chassis: WDC2539462F143598-2016  
 Reg.Year: 2016

Third Party Insurer: SPF  
 Third Party Veh No: QX311A  
 Date of Accident: 16.01.2020

### ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR ALLOY RIM RH	1	<i>Del/ha</i>	\$1,485.00 ✓
2	TYRE TUBE VALVE	1		<i>ha</i> \$8.00 ✓
SUB TOTAL				\$1,493.00
LESS 10%				-\$149.30
PARTS TOTAL				\$1,343.70

#### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE & REPLACE REAR ALLOY RIM RH & ETC. \$100.00 *3rd*

TO WHEEL ALIGNMENT & BALANCING. \$60.00 ✓

LABOUR TOTAL \$160.00

ONG TOTAL **\$1,503.70**

*Not withold  
 Recovery After repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display clear and part during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "no prejudice" basis
- No illegal modification, repair and
- Supplementary work is subject to final approval by LKK Auto Consultants and Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF20001891/Kqf3e2	
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1 HEMMANT ROAD SINGAPORE 438675		Date : 12-03-2020	
ATTN : FRANKIE THAY		Code : SPF	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	QX 311A	Veh. Inspected	SLJ 3306D
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2020/003	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	04/02/2020
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MERCEDES BENZ GLC250 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDC2539462F143598	Colour	METALLIC GREY
Odometer	53526	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/60 R18	MICHELIN	7 mm
L/H Front Tyre	235/60 R18	MICHELIN	7 mm
R/H Rear Tyre	235/60 R18	MICHELIN	7 mm
L/H Rear Tyre	235/60 R18	MICHELIN	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S WHEEL RIM. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	16/01/2020	Inspection Date	05/02/2020
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		
<b>5a. Remarks</b>			
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>1.500 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 3306D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR ALLOY RIM RH	DENTED / CUT	1,485.00	1,485.00
1	TYRE TUBE VALVE	NECESSARY	8.00	8.00
	LESS 10% DISCOUNT		-149.30	-149.30
			1,343.70	1,343.70
	<b>LABOUR</b>			
	LABOUR CHARGES TO REMOVE & REPLACE REAR ALLOY RIM RH & ETC.		100.00	30.00
	TO WHEEL ALIGNMENT & BALANCING.		60.00	60.00
			160.00	90.00
	<b>GRAND TOTAL</b>		<b>1,503.70</b>	<b>1,433.70</b>
	<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)</b>			<b>1,433.70</b>

Report Ref No. CS/SPF20001891/Kqf3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,433.70-\$1,503.70

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.