

ISSUE

ASS. REC. BY:

REF:

03/A19 2000/911/Gad302

Special Instruction:

Surveys: (MO) (Diana)

ASSIGNMENT (Gibco)

From (Person):

Chin Lu Ying

of

A19

Date/Time:

11/2/2020 @ 11:38am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No.:

GBJ 7712G

Insured:

GT 3333G

at Workshop n/s

Prestige Auto

Tel:

9021 0057

of

Blk 3023A Ubi Road 1 # 01-64

Policy No:

2100157700

Claim No:

347169205756

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/01/2020

CA / REV / REP. / REV 24 HRS

up)

H.O.D. Endorsement:

Date/Time:

12:20pm @ 1/2/2020

Person Contacted:

Mr Chong

Vehicle IN / OUT

Date/Time

Action/Instruction

Isbnald X

GBJ 7712G - X

GT 3333G - CCG/A19/7004219/A0302

DOB: 11/03/2017

Disassemble survey = 05/2/20

Apply paint = 07/2/20

26/2/20

Submit DRP

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, Admin-D (LKKAuto)
Cc: Lim, Kok-Chong
Sent: 2/4/2020 11:38:39 AM
Attachments:  200162.pdf

Hi LKK,

Kindly assist to survey after 12pm today.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Sally <info@catherinelimllc.com>
Sent: Friday, January 31, 2020 5:09 PM
To: ClaimsDocManagement <ClaimsDocManagement@aig.com>
Subject: [EXTERNAL] YOUR REF: GT 3333G OUR REF: CL/200162/T/PA

This message is from an external sender; be cautious with links and attachments.

Dear Sir

Please find attached, pre repair notice for your attention.

Regards
Sally Goh
Catherine Lim LLC
20 Havelock Road #03-01
Central Square
Singapore 059765
Email: info@catherinelimllc.com

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
翠 NOTARY PUBLIC - 公证官
玲 COMMISSIONER FOR OATHS- 宣誓官
律
師 CATHERINE C.L.LIM
情 DIRECTOR
LL.B (HONS) SINGAPORE-法律系-律師
M.B.A. (BUSINESS LAW)-商业系-碩士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K

Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation
with limited liability

Your Ref: GT 3333G
Our Ref: CL/200162/T/PA.sg

31 January 2020

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120
Attn: Motor Claims Department

via fax: 6415 3727 & By Hand

Hong Yong Interior Design Services Co
24 Pebble Lane
Singapore 437573

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING GBJ 7712G / GT 3333G ON 21.01.2020 ALONG TIONG BAHRU ROAD
TOWARDS GREAT WORLD CITY**

We are instructed by **UNITED ELECTRICAL SERVICES (S) PTE LTD** to notify you of a road traffic accident involving our client's vehicle No. GBJ 7712G and vehicle No. GT 3333G driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within **2 working days** of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: Prestige Auto
3023A Ubi Road 1
#01-64 S(408717)

Chong Hp: 9021 0057 Fax: 6842 3217

Yours faithfully


Etc

cc: clients

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2020 10:19
Date Of Accident	21/01/2020 14:20
Exact Location Of Accident	ALONG TIONG BAHRU ROAD TOWARDS GREAT WORLD CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ7712G
Insured/Policyholder	
Name Of Registered Owner	UNITED ELECTRICAL SERVICES (S) PTE LTD
Co Reg No	2XXXXX719N
Email Address	ADMIN@UNITEDELETRICAL.COM.SG
Mobile Phone No	(LOCAL) +65-98302204
Alternative Phone No	OFFICE-62588735

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE VAN TURBO 5DR MT
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	AVCP5B0098001900
Cover Note Number	

Driver

Name of Driver	KATHAVARAYAN VIJAYAMOORTHY
Passport No/FIN	FXXXX771U
Date Of Birth	07/03/1977
Occupation	OUTDOOR
Date Of Driving Pass	06/02/2014
Driving Experience	5 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83818151
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address C/O 1002 TOA PAYOH INDUSTRIAL PARK
#03-1475
Postcode 319074
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1
NAME: : COLLEAGUE
GENDER: : MALE
Passenger 2
NAME: : COLLEAGUE
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GJ3333G
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


22 JAN 2020
CO-196A

Driver's Signature
(If driver is not the policyholder)
Date & Time:

22 JAN 2020
CO-196A

Reporting Centre Personnel's Signature
Name: Poh Kwee Choo
NRIC/PIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

The accident happened on 21/1/2020 about 2-20pm along Tiong Bahru Road on my lane. The other vehicle (A) CGT 3333G suddenly turned and cut into my lane and braked onto my vehicle (B) CGJ 7712G and on the left hand side.

It was raining that time.


No one is injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature

Date & Time: 22 JAN 2020


 Driver's Signature
 (if driver is not the policyholder)

Date & Time: 22 JAN 2020


 Reporting Centre Personnel's Signature
 Name: Poh Kwee Choo
 NRIC/FIN No.:

VAN / LORRY (Frt)

Vehicle No: **GBJ77126**

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1004	991300	Frt Bumper	CRA	/	
2001	991477	Frt Bumper Upper clips	REL	/	
2002	991387	Frt Bumper Lower			
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side			
1006	991325	Frt Bumper Bracket	CRA	/	
1008	991433	Frt Bumper Reinforcement			
2005	991466	Frt Bumper Signal Lamp			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
2006	990247	Frt Grille Sticker			
1023	991799	Frt Grille Chrome Moulding			
2007	991891	Frt Panel			
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem			
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish			
1024	991222	Frt Apron Panel			
2012	991527	Frt Corner Panel	Buc	/	
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH			
1029	995153	Frt LH Headlamp Assy	CRA	/	
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frt Windscreen			
1115	992097	Frt Windscreen Rubber			
1117	992098	Frt Windscreen Sealant			
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)			
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round)			
2025	995015	Frt Wing Mirror Stay			
1025	992013	Frt Support Panel			
1033	990248	Bonnet	Repair	/	
1035	990287	Bonnet Lock Emblems	AC	/	
1037	990273	Bonnet Hinge	BT	/	
1039	990305	Bonnet Rubber Sticker	AC	/	
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim			
1113	995065	Frt RH Tyre			
1255	995326	Frt LH Door	Buc	/	
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge	BT	/	2
1258	995142	Frt LH Door Wing Mirror	cut	/	
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt LH Door Inner Trim Board			
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1333	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar	Repair	/	
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel	cut	/	
2042	994498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker	AC	/	2

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	719N
Vehicle No.:	GBJ7712G
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	1KD2864195
Chassis No.:	JTFHT02P600249396
Maximum Power Output:	-
Open Market Value:	\$28,138.00
Original Registration Date:	16 Aug 2019
First Registration Date:	16 Aug 2019
Transfer Count:	1
Actual ARF Paid:	\$1,407.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	15 Aug 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$12,208.00
COE Rebate Amount:	\$11,633.00
Total Rebate Amount:	\$11,633.00

The information contained herein is correct as at 04 Feb 2020

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jan 2020 Edit Reg		04 Feb 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	HONG YONG INTERIOR DESIGN SVCS CO , Co. Reg. No.: B30120300L								
Main Claimant:	UNITED ELECTRICAL SERVICES (S) PTE LTD								
Vehicle Reg. No.:	GBJ7712G	Date of Loss:	21/01/2020 21:00 - :59 [5 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3471692057SG	Policy/Cover Note No.:	2100157200 (Comprehensive)						
Vehicle Reg. No. (Insured):	GT3333G	Policy No. (Claimant):							
		Excess:							
Repairer:	Prestige Auto Ubi (HQ) BLOCK 3023A UBI ROAD 1#01-64, 408717 Ubi - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/02/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (05/02/2020): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBJ7712G (3471692057SG)
[GT3333G]

TP

UNITED ELECTRICAL SERVICES (S) PTE LTD

Jan 21 2020 9:00PM

[HONG YONG INTERIOR DESIGN SVCS CO]

Prestige Auto Ubi

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="Print"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="button" value="Print"/>
1	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
2	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
3	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
4	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
5	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
6	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
7	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
8	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
9	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
10	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
11	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
12	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
13	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
14	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
15	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
16	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
17	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
18	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
19	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
20	05/02/20 10:15	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
21	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
22	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
23	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
24	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
25	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
26	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
27	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
28	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
29	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
30	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
31	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
32	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
33	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
34	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
35	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
36	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>
37	05/02/20 10:16	General View	<input type="button" value="Load JPG"/> <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	05/02/20 10:16	General View		Load JPG <input checked="" type="checkbox"/>
39	05/02/20 10:16	General View		Load JPG <input checked="" type="checkbox"/>
40	05/02/20 10:16	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
41	05/02/20 10:16	Chassis Number		Load JPG <input checked="" type="checkbox"/>
42	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
43	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
44	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
45	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
46	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
47	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
48	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
49	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
50	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
51	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
52	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
53	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
54	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
55	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
56	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
57	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
58	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
59	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
60	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
61	05/02/20 16:52	Dismantled Parts		Load JPG <input checked="" type="checkbox"/>
62	26/03/20 10:48	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
63	26/03/20 10:48	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
64	26/03/20 10:48	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
65	26/03/20 10:48	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
66	26/03/20 10:48	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
67	26/03/20 10:48	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
68	26/03/20 10:48	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
69	26/03/20 10:48	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/02/20 13:32	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20001911/GQD3E2

Date: 26/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100157200	
Claimant Vehicle No: GBJ7712G	Insured Vehicle No: GT3333G	
Date of Loss: 21/01/2020	Nature of Claim: TP	Claim No: 3471692057SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ7712G		
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Engine No: 1KD2864195	
Reg. Date: 16/08/2019 (Man. Year: 2019)	Chassis No: JTFHT02P600249396	
Colour: Silver	Odometer: 14457 km	
Engine Capacity: 2982 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	04/02/2020	
Date Inspected:	04/02/2020	Inspected At: Prestige Auto Ubi (HQ) BLOCK 3023A UBI ROAD 1#01-64 Singapore 408717
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT BUMPER	Cracked	0.00 F	*- F	
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F	
3	1		*FRT BUMPER BRACKET	Cracked	0.00 F	*- F	
4	1		*FRT CORNER PANEL	Buckled	0.00 F	*- F	
5	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F	
6	1		*BONNET	Repair	0.00 F	*- F	
7	1		*BONNET EMBLEM	Necessary	0.00 F	*- F	
8	1		*BONNET HINGE	Bent	0.00 F	*- F	
9	1		*BONNET STICKER	Necessary	0.00 F	*- F	
10	1		*FRT LH DOOR	Buckled	0.00 F	*- F	
11	2		*FRT LH DOOR HINGE	Bent	0.00 F	*- F	
12	1		*FRT LH DOOR WING MIRROR	Cut	0.00 F	*- F	
13	1		*FRT DOOR FRT PILLAR	Repair	0.00 F	*- F	
14	1		*FRT STEP PANEL	Cut	0.00 F	*- F	
15	2		*STICKER	Necessary	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >