

INS. CASE OWNER:

HO Winnie
6568804833

CC4/ASM20001956/R1ga3

LKK:
IDAC: 158857

ASSIGNMENT

Surveyor:

RASUL

DOI: 04/02/2020

Date / Time: 04/02/2020

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SHD 365G
 Name of Insured : TRANS-CAB AUTO SERVICES PTE LTD
 Insured Tel No. : HP: _____
 Excess Sec II :S\$ _____ D.O.A: 01/02/2020 17:50
 Is driver the owner? (YES / NO) Nature of Accident : _____

Claim No. : S0M02F7V X
 Policy No. : _____
 Make / Model : _____
 Place of Accident : ALONG TAMPINES ROAD TURNING KPE

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SHC 422E



INSRS:
WSP: DING
Tel: AUTOMOTIVE
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
SHC 422E - NA/MSG14019661/n4; DOA: 11.10.2014	Non-Reporting ltr (1st):	
SHD 365G - X	Non-Reporting ltr (2nd):	
OINR. To send out first letter. File pass to Su Li	Non-Reporting ltr (Final):	
7.1.2020	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
14/2 11/4/2020	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	☒
7/12	After call ltr to OI:	☒
7/12	Authorisation To Act:	☒
7/12	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice	☒
	LTA / GIA :	☒
	Medical Bill:	☒
	PIR:	☒
	Mandate/Reject Instruction:	☒
	LOD	☒
	Payment Breakdown Form:	☒
	Post-Repair Photos:	☒
	Others:	☒

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by: RASUL
FINALIZATION	Date/Time: 10/9/04	Confirm with: 3 days	Reduction: \$775 % 43
Repair Cost:	\$5		Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 21/2/2020	Confirm with: Shunah	Email ☐ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 21	If NO or B 28, Ass. Lia :
Repair Cost:	\$5 (W/ST)		010 car-rental TP.
Loss of Rental (LOR):	\$5, +20.00	(4 days) x \$120	
Loss of Use (LOU):	\$5	(\$ x days)	
Loss of Income (LOI):	\$5	(\$50 x 4 days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐		[Tick only one]	
GIA/LTA Search	\$5		
Medical:	\$5		
Disbursement:	\$5	(e.g. Tow/ Independent)	
Legal Cost	\$5		
Total:	\$5 1967.12	Global Sum \$5:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	\$5 1967.12	Name 1: Ding Automotive Pte Ltd	
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

ASS. REC. BY:

REF:

1956

8396

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SHC 422Eat Workshop m/s DINH AUTOof 31, CORPORATION RDInsured: AXA

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 100% % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 422E

Yr Regn:

2019 / MARType: M.Car / M.Cycle / Bus / Van / Lorry Taxi / Prime Mover /

Truck / Trailer or

Make:

HYUNDAI AE 10N1Q 1.6 DCT c.c. 1585

Colour:

YELLOW

A/C:

Insured / Std / NI / NA

Sp Reading

17251

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMH C851CVKu 134.440Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: NIP / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

TRIANGLE

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

01/02/2020

D.O.I.

04/02/2020

Survey held at

DINH AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P \$1009.04 (Red - \$775 / 43%)

409.04

200

L - 600

* 3 vepaw days + 1 PRS + 1 sunday = 5 days.

Date/Time, File Pass to?



Prel. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Wheel end (\$

Survey Fee:

Transportation:

J + RS \$

Photos:

Others:

TOTAL

Report Format:

Lump Sum / U/C:

Cocita

TO :

FAX NO:

ESTIMATE REPORT 137 Quotation

04/02/2020 16:25

JOB NO: 50112407

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Pte)

CONTACT: 85533880

Page 1 of 1

ADDRESS: 353 SIN M WA DRIVE

04739522

SINGAPORE 575777-0

VEHICLE DETAILS

LICENSE NO: SHC04-25

TRANS: AUTO

CHASSIS: KMHC851GVKU134440

MAKE / MODEL: HYUNDAI / AEIONQ HEV 1.6 DI

ENGINE: 04LEJU168489

OWNER'S INSURER: MS First Capital Insurance Limited

JOB CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SURCHG	REV PRICE
LABOUR							
1. STRAIGHTEN AND PAINT TREAT ACCIDENT AREAS	1.00	400.00	0.00	400.00	Y		250
2. RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		200
3. RESPRAY REAR BUMPER CENTER GRABBAR (BLACK)	1.00	250.00	0.00	250.00	Y		150
4. RESPRAY REVERSE SENSOR SET	1.00	120.00	0.00	120.00	Y		XAN
TOT:		1,020.00	0.00	1,020.00			
MATERIALS							
1. REAR BUMPER (REPAIR)	1.00	0.00	0.00	0.00	L	Y	
2. REAR BUMPER CENTER GRABBAR (BLACK) der	1.00	388.30	77.26	309.04	L	Y	
3. REVERSE SENSOR SET	1.00	240.00	0.00	240.00	S	Y	
4. REAR BUMPER CLIPS	1.00	65.00	0.00	65.00	S	Y	
5. REAR BUMPER STICKER	1.00	150.00	0.00	150.00	S	Y	
TOT:		841.30	77.26	764.04			
TOTAL PARTS & LABOUR		1,861.30	77.26	1,784.04			

EXCESS LOADING \$5 1110

No. Of Day:

2 days

RE-SURVEY BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM \$5

DATE OF SURVEY: 04.10.2020 @ 1630

SURVEYED BY:

Rasul

CONTACT NO:

970010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

Part By Part

Labour = \$600

S/H = \$100

Parts = \$309.04

L+M+P = \$1009.04

Final Amount = \$1009.04

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

04/02/2020 16:25

JOB-NO: 50112407

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MIN-3 DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 1

VEHICLE DETAILS

LICENSE NO: SHC0422E TRANS: AUTO
 MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 Di
 OWNER'S INSURER: MS First Capital Insurance Limited
 JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: KMHC851CVKU134440
 ENGINE: G4LEJU168489

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	400.00	0.00	400.00		Y	250
2 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
3 RESPRAY REAR BUMPER CENTER GARNISH (BLACK)	1.00	250.00	0.00	250.00		Y	150
4 RESPRAY REVERSE SENSOR SET	1.00	120.00	0.00	120.00		Y	X
TOTAL		1,020.00	0.00	1,020.00			
MATERIALS							
1 REAR BUMPER (REPAIR) R	1.00	0.00	0.00	0.00	L	Y	
2 REAR BUMPER CENTER GARNISH (BLACK) de	1.00	386.30	77.26	309.04	L	Y	
3 REVERSE SENSOR SET ?	1.00	240.00	0.00	240.00 200	S	Y	
4 REAR BUMPER CLIPS X	1.00	65.00	0.00	65.00	S	Y	
5 REAR BUMPER STICKER ne	1.00	150.00	0.00	150.00 100	S	Y	
TOTAL		641.30	77.26	764.04			
TOTAL PARTS & LABOUR:		1,661.30	77.26	1,784.04			

EXCESS/LOADING: S\$ 0.00

No. Of Day:

3 days

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: 04 / 02 / 2020 @ 1630

SURVEYED BY:

Pasul

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultant hereby certify
 the Repairer of the Vehicle as

- To resurvey before the repair is completed
- To display damaged parts before resurvey
- Parts prices are subject to market change
- Third party survey is subject to the "100" basis
- No illegal modification is allowed
- Supplementary repair is subject to the "100" basis and is subject to the local insurance company

Acknowledged by Repairer

Signature:

Date:

Satisfaction Voucher

Date: 05/02/2020

MS First Capital Insurance Limited

5 FEB '20 15:36

Attention: MOTOR CLAIMS DEPT

Dear Sir/Madam

Tan Kim Huan

I/We hereby acknowledge having received from Singapore Technologies Kinetics
Ltd., 249 Jalan Boon Lay, Singapore 619523, my/our vehicle number SHC0422E
which has been repaired to my/our satisfaction and acceptance. I/We admit that
the payment of SGD _____ account for such repairs is in full discharge
of my/our claim upon the corporation under the policy number D-18088937MFSH
reference claim number 50112407 in respect of the damage caused to the
said vehicle in an accident that occurred thereto or about the 01/02/2020
at ALONG TAMPINES RD TURNING KPE

Dated this day of _____, 201 _____

Signature: Ah.

NRIC No: S125009/A

Name: CityCab PTE LTD (Fleet)

Address: 383 SIN MING DRIVE
SINGAPORE 575717 0

Company Stamp if applicable

1956/993

Service Request Details

Claim

S0M02F7V

Reference

None 

Loss Date

February 1, 2020

Report Date

Feb 4, 2020 10:03:14 AM

Request Date

February 4, 2020

Due Date

February 11, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: mohan

T: 2.28p.m 4/7/2020

V: ln

E. ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHC422E



LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu

Model

AE IONIQ HEV-1.6

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

HO Winnie

6568804833

winnie.ho@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

VISHNU BATHAM Shekhar

From: Taxis Customer Service <taxiscs@stengg.com>
Sent: Monday, February 03, 2020 8:05 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg
Subject: S0M02F7V [EXTERNAL] ACCIDENT INVOLVING SHC422E AND SHD365G ON 01/02/2020 SURVEYOR ARRANGEMENT
Attachments: SAS2744592.pdf; WhatsApp Image 2020-02-03 at 7.44.35 PM.jpeg
Categories: Shekhar

Dear Officer,

Kindly please arrange survey for vehicle **SHC422E**. Vehicle already grounded inside workshop. Survey location will be at 31 Corporation Road.

Best Regards,
VADIVELAN MOHAN
Ding Automotive Pte Ltd
Hp : 96891857 / 62657130





Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 2/3/2020

Survey Details:

Date of loss	1-Feb-2020
Date of appointment	4-Feb-2020
Date of survey	4-Feb-2020
Location of survey	Ding Automotive Pte Ltd

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SHC422E
Make and Model	HYUNDAI AE IONIQ HEV 1.6 DCT
Date of registration	12/3/2019
Parf Rebate	
Market Value	\$ -
Parf Rebate	\$ -
Nett Loss	\$ -

Repair details:

Initial Estimate	\$ 1,784.04
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 409.04
Check items (estimate)	\$ -
Labour	\$ 600.00
Total	\$ 1,009.04
Lump Sum(if applicable)	

Number of days for repair	3
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

3 RECOMMENDED REPAIR DAYS + 1PRS + 1SUNDAY = 5DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 1,079.67	W/GST
Loss of use	\$ -	
Loss of rental	\$ 600.00	5days x \$120
Loss of income	\$ 250.00	5days x \$50
LTA search fees	\$ 7.45	
Others	\$ -	
Proposed Total	\$ 1,937.12	



<MANDATE IA> - SOM02F7V {ACCIDENT INVOLVING SHD 365G (OI) & SHC 422E (TP) ON 01/02/2020}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$1937.12 (CLAIMING LOR & LOI). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL
02/03/2020

Reply

DING AUTOMOTIVE PTE LTD

Business Reg. No : 201619222G
BLK 10, #01-20 SIN MING IND EST. SEC C, SINGAPORE 575645
Tel: 6452 1208 Fax: 6452 0614

TAX INVOICE**AXA INSURANCE PTE LTD**

8 SHENTON WAY #27-01, AXA TOWER
SINGAPORE 068811

ATTN : MOTOR CLAIMS DEPT
TEL : 6749 4274 FAX :

INVOICE : I-000948
DATE : 03/03/2020
GST REG NO : 201619222G
TERMS : C.O.D.
PO NO : SHD365G
OUR REF : SHC422E
PAGE : 1 of 1

ITEM NO.	DESCRIPTION	QUANTITY	UNIT PRICE	AMOUNT
1.	Cost of repair-SHC422E	1	1,009.04	1,009.04
REMARKS : Job card: 50112407 Your ref: SHD365G Oic: Ms. Cecilia Doa: 01/02/2020		SUB TOTAL	:	1,009.04
		GST	:	70.63
		TOTAL SGD	:	1,079.67
		DEPOSIT	:	
		O/S BALANCE	:	

FOR DING AUTOMOTIVE PTE LTD

Authorised Signature

Customer Signature

I have inspected and hereby confirmed that
the job done and the amount due herein
are entire to my satisfaction

◀ <MANDATE IA> - S0M02F7V {ACCIDENT INVOLVING
SHD 365G (OI) & SHC 422E (TP) ON 01/02/2020}

Type

🔗 Question

Message

Hi Cecilia, pls proceed and offer the number of days for LOR/LOI @ 4 days as per mileage records book. Tks

Reply

**DING AUTOMOTIVE PTE LTD**

Blk 10 #01-20 Sin Ming
Industrial Est Sec C
Singapore 575645

Without Prejudice to our
driver's Injury claims

OUR REF: 50112407/TP/SHC422E/AD/01/02/2020/SHI
YOUR REF: SHD365G/--

19 February 2020
To: MOTOR CLAIMS DEPARTMENT
AXA INSURANCE
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

ACCIDENT INVOLVING : SHC422E AGAINST SHD365G 01/02/2020
LOCATION ALONG : TAMPINES ROAD TURNING KPE

We refer to the above matter:

	Rate Per Day	Repair/ Claims Day	Amount Before GST	GST 7%	Amount After GST
Cost of Repair	\$ -	5	\$ 1,009.04	\$ 70.63	\$ 1,079.67
Loss Of Rental	\$ 120.00	5	\$ 600.00	\$ -	\$ 600.00
Loss Of Income	\$ 80.00	5	\$ 400.00	\$ -	\$ 400.00
LTA/GIA Search Fee	\$ -	0	\$ 6.96	\$ 0.49	\$ 7.45
Towing Fee	\$ -	0	\$ -	\$ -	\$ -
Surveyor Fee	\$ -	0	\$ -	\$ -	\$ -
Total	\$ 200.00	5	\$ 2,016.00	\$ 71.12	\$ 2,087.12

The accident was caused solely by the negligence of your insured/driver and as a results, We had incurred the following costs of repair and losses of our insurer:

Enclosed are copies of the following documents for your perusal:

☺ Letter of Demand	☺ Rental Invoice
☺ Repair Bill	☺ Letter of Authority
☺ Repair Estimate (External Survey Only)	☺ Discharge Voucher
☺ GIA Report/Accident Police Report	☺ Certificate of Insurance
☺ LTA 3 rd Party Search Fee	
☺ Mileage Record	

Our client has authorized DING AUTOMOTIVE PTE LTD to deal with the claim in this accident case and also to receive and deal/negotiate with all payment as stated above.
Please look into our client's claim and revert soonest as possible.

Your Sincerely,
SELOSHINAH
DING AUTOMOTIVE PTE LTD
TEL: +65 93294128
FAX: +65 6452 0614





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20001956/R1ga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:WINNIE

Date : 10-03-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 365G	Veh. Inspected	SHC 422E
Policy No.	VFX/P1680520	Coverage (\$)	0.00
Claim No.	S0M02F7V	Excess (\$)	0.00
Assign From		Assign Date	04/02/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AE IONIQ 1.6 DCT	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVKU134440	Colour	YELLOW
Odometer	172151	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	TRIANGLE	6 mm
L/H Front Tyre	195/65 R15	TRIANGLE	6 mm
R/H Rear Tyre	195/65 R15	TRIANGLE	6 mm
L/H Rear Tyre	195/65 R15	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/02/2020	Inspection Date	04/02/2020
Survey held at	31 CORPORATION RD		
Repairer	DING AUTOMOTIVE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 422E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER CENTER GARNISH (BLACK) (CONSISTENT)	DEFORMED	386.30	386.30
	LESS 20% DISCOUNT		-77.26	-77.26
			309.04	309.04
SPECIAL NETT ITEMS				
1	SET REVERSE SENSOR (CONSISTENT) (SN)	NOT NECESSARY	240.00	-
1	REAR BUMPER CLIPS (CONSISTENT) (SN)	NOT NECESSARY	65.00	-
1	REAR BUMPER STICKER (CONSISTENT) (SN)	NECESSARY	150.00	100.00
			455.00	100.00
LABOUR				
	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS, INCLUSIVE OF THE REPAIR OF REAR BUMPER.		400.00	250.00
	RESPRAY REAR BUMPER .		250.00	200.00
	RESPRAY REAR BUMPER CENTER GARNISH (BLACK).		250.00	150.00
	RESPRAY REVERSE SENSOR SET.	NOT NECESSARY	120.00	-
			1,020.00	600.00
GRAND TOTAL			1,784.04	1,009.04
RECOMMENDED COST OF REPAIRS				1,009.04

Report Ref No. CC4/ASM20001956/R1ga3q2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

ClaimSOM02E7V

ReferenceCCA/ASM00001956/R1g0d2

Loss Date1 February 2020

Report Date4 Feb 2020 10:03:14 AM

Request Date4 February 2020

Due Date

Vendor NameLK& AUTO CONSULTANTS PTE LTD (TP)

Type of LossThird Party Vehicle Damage

ServicesPending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #SHC422E

MakeTPVD HYUNDAI

ModelAE IONIQ HEV-1.6

Service Address

...

Primary Contact/Insured

TRANS-CAR SERVICES PTE LTD

No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

HO Winnie

6568804833

winnie.ho@laka.com.sg

Actions

Next StepWait for Approve Invoice

Add Invoice

Additional Instructions

1

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument Subtype

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (9).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020

Claim Portal

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 RENTAL MILEAGE.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 LkkInspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 LKKAdjustmentLa (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FOIRM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	12 March 2020
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020
 MANDATE IA DO 02032020.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 PABF COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	2 March 2020
 SHD365G - QI GIA REPORT.pdf	Reports & Statement	Accident statement	HO Winnie	17 February 2020
 TP - 1A.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	16 February 2020
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	16 February 2020
 MAIL SENT TO POLICYHOLDER.mig	Letters and Correspondence	Policy Holders / Insured	VISHNU BATHAM Shekhar	4 February 2020
 WhatsApp Image 2020-02-03 at 7:44.jpg	Letters and Correspondence	Others	VISHNU BATHAM Shekhar	4 February 2020
 LIST OF SURVEYOR SENT.mig	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	4 February 2020
 GIA TP.pdf	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	4 February 2020
 EMAIL TP REG.pdf	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	4 February 2020
 EMAIL TP REG.mig	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	4 February 2020

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 SURVEYOR APPOINTED.mig	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	4 February 2020
 Service appointment in Vendor Portal claim. 508402F7V for vehicle 51HC422E.html	[[GetDocumentType_AsItem.documentType]]		VISHNU BATHAM Shekhar	4 February 2020