

(C3) TM1 2000 978 / F4f3

ASSIGNMENT

Case No. **SHA 1681C**
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: **Hyundai Ioniq**
Colour: **Blue**
Sp. No. / Reg. No. **310 658**
Eng. No. **1580**
Chassis No. **KMHCC8S1CJ0103356**
Gen. Cond. **Good** Fair / Poor / Burnt
Steering: **Order** / Jammed / Leaked / Burnt or
Brake: **Order** / Jammed / Leaked / Burnt or
Modi: **Nil** / STD A/Rim or
Tyre Size: F: **195/65 R15**
R: **-**
DS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **DAVANIL**
Front
R/Bal. **7** mm
L/Bal. **7** mm
D.O.A. **03/02/2020**
Rear
R/Bal. **7** mm
L/Bal. **7** mm
D.O.A. **01/02/2020**
Survey held at: **Comfortelgro (Loydog)**
Desc. of Damages: Frt / Rear / O/S **(N/S)** / UIC / Rooftop or
N/S
The UIC / Chassis frame / Body Structure: affected due to collision

Insured: **SSG 3422R**
Policy No. **MS006599**
Claims No. **M2000 865**
Sum Insured: **---**
(Client's Record)
Make of Veh:
(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection
Bal. or Market Value:
IDAC Accident Report: Consistent? : Yes or No
GIA / PR Secur: Consistent? : Yes or No
Est. Repair: days Res. Yes or No
Lump Sum: % J Val Yes or No
CA / REV / REP / 24 HRS
Date: Person Contacted: Vehicle: IN / OUT



Date / Time Action / Instruction

SHA 1681C - N/S / TM1 2000 1832/17 Date: 03/01/2020
SSG 3422R - X

RECEIVED 20 FEB 2020

PLP: \$4347/- with 4 repair days Cred: '868.96 : 16%'
Return on 18/02/2020 with LMT/S

[Signature]
19/2/2020

19/2 Typrst ☐ Prel. Report
☒ Final Report

Days Of Repair: **4**
Resurvey No. of Trip: **-**

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Report Format: **TP**
Lump Sum / LB: **4347**

Survey Fee
Transportation
250
11

Our Job Ref No : 305378760

Date : 07/02/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SHA1681C

Date of Accident : 03-Feb-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SJG3422R

2. The finalized amount shall be:

(a) Spare Parts after List discount

\$2,756.00

(b) Labour Charges

\$1,591.00

Total for Part-By-Part Repair Cost

\$4,347.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature 

Name : RAM

Date : 11/2/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305378760
REGN NO : SHA1681C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 03.07.2018
DATE/TIME IN : 03.02.2020 14:55
ACCIDENT DATE : 03.02.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 28-01-9999-2023-A	REAR DOOR APPS STICKER LH	1	80.00	0.00	80.00	nee
0002 04-01-0104-0596-G	REAR DOOR LH	1	1,789.90	20.00	1,431.92	no
0003 03-01-0104-2020-A	REAR WHEEL RIM LH	1	1,555.10	20.00	1,244.08	cut

SUB-TOTAL : 2,756.00

JOB NATURE

0000 PB	PANEL BEATING	640.00	/
0001 SP	SPRAYPAINT CHARGE	750.00	/
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	/
0003 L	TRANSFER OF DOOR	80.00	/
0004 L	WHEEL ALIGNMENT	60.00	/
0005 20-05	TP MERIMEN	11.00	/

SUB-TOTAL : 1,591.00


COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305378760
REGN NO : SHA1681C
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 03.07.2018
DATE/TIME IN : 03.02.2020 14:55
ACCIDENT DATE : 03.02.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 4,347.00


MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ngo Sau Wei Shawn

Date: 05 Feb 2020

Preliminary Advice

Insured Vehicle No	: SJG3422R	Accident Date	: 03/02/2020
TP Vehicle No	: SHA1681C	Assignment Date	: 04/02/2020
Make	: HYUNDAI IONIQ HYBRID	Est. Duration of Repair	: 4.00
Date of Inspection	: 04/02/2020		
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,215.96
Revised Amount	:S\$	4,347.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,347.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : survey on "wp"

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Lóyang Drive Singapore 508989

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Ubi Road Singapore 408099

24 Serangoon Loop Singapore 758156

7 Suncel Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 03.02.2020 16:46

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305378760


OMER IS COMFORT TRANSPORTATION PTE LTD OMER NO. 7010045 RESS: 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (P)	REGN NO.: SHA1681C MAKE : HYUNDAI MODEL IONIQ(G2) YR OF MANU. 03.07.2018 CHASSIS CODE KMHC851CVJU103356	MILEAGE FUEL E.....1/2.....F DATE/TIME IN 03.02.2020 14:55 TARGET DATE COMPLETION DATE/TIME:
JUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 03.02.2020

NATURE: 3P 03.02.2020/C

S/NO LABOR CODE DESCRIPTION



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Recognition Slip

Exit Pass

No.: SHA1681C

LIMITS

Vehicle No.:

SHA1681C

Service Advisor

Signature/Date

Name of Service Advisor

Date

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	03/02/2020 15:31
Date Of Accident	03/02/2020 14:25
Exact Location Of Accident	MARINA COASTAL DRIVE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHA1681C
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXXX21R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	IONIQ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	ABD HALEEM B MOHD AZAM
NRIC No	SXXXX090G
Date Of Birth	12/01/1960
Occupation	OUTDOOR
Date Of Driving Pass	09/09/1978
Driving Experience	41 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91074304
Fax Number	
Contact Number	
Email Address	AHALEEM60@YAHOO.COM

Address	BLK 507 PASIR RIS STREET 52 #03-177
Postcode	510507
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJG3422R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	FRT RIGHT
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303321K

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 3/2/20 at about 1425hrs when I Veh A was turning into the Marine South Pier, Veh B who was stationary suddenly moved forward and collided onto the left rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. T093032111

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GNRMC Sketch Plan Form 1/3

[Signature]
G.R. Moorthy
CSO
3/2/20

ComfortDelGro Engineering Pte Ltd (Co. Reg. No. 199506048W)
59 Loyang Drive
Singapore 508969
Tel: 6214 8300

IS

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

CP/P

Singapore

LKK-Ram

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	03/02/2020
Vehicle Reg. No.:	SHA1681C	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	03/07/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU045575	Chassis No:	KMHC851CVJU103356
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	3,064.96
Miscellaneous Items	11.00
Labour	2,140.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,215.96
+ GST 7.00% (S\$)	365.12
Nett Amount (S\$)	5,581.08

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

1645hrs

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Feb 2020)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA1681C/03/02/2020 16:42

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR DOOR LH <i>DD</i>	20.00	0.00	*1,789.90 FL
2	1		*REAR DOOR LWR PROTECTOR LH <i>X(R)</i>	20.00	0.00	*116.20 FL
3	1		*REAR WHEEL RIM LH <i>cut</i>	20.00	0.00	*1,555.10 FL
4	1		*REAR WHEEL TYRE LH <i>xmn</i>	0.00	0.00	*216.00 F
5	1		*REAR DOOR APPS STICKER LH <i>nee</i>	0.00	0.00	*80.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

3,757.20

- List Item Discount on L Items (S\$)

692.24

Total Parts (S\$)

3,064.96

ComfortDelGro Engineering Pte Ltd/SHA1681C/03/02/2020 16:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING - REAR FENDER LH ETC	New	800.00 \$640
2	TRANSFER OF DOOR	New	120.00 \$80
3	TUFF KOTE	New	100.00 \$50
4	WHEEL ALIGNMENT	New	120.00 \$60
5	SPRAY PAINTING - REAR BUMPER, ROCKER PANEL GARNISH LH & ETC	New	1,000.00 \$750
Gross Labour Cost (\$\$)			2,140.00

ComfortDelGro Engineering Pte Ltd/SHA1681C/03/02/2020 16:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Aminto
5/2/2020
Lam(LKK)
4/2/2020 1245hrs
Paragon@lkkauto.com
88622778
Bel paint photo
Arqquidag

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Feb 2020 Sendback Est	03 Feb 2020 16:42 S\$5,215.96	04 Feb 2020 10:38 Edit Adj Rpt	S\$4,347.00 Edit Estimates	S\$4,347.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	LEK HAN WEI, ID: S8207243H		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHA1681C	Date of Loss:	03/02/2020 14:00 - :59 [19 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2000865	Policy/Cover Note No.:	MS006599 (TP, Fire & Theft) Coverage: 27/06/2019 - 26/06/2020
Vehicle Reg. No. (Insured):	SJG3422R	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ngo Sau Wei Shawn]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 13/02/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents



SHA1681C (M2000865)
[SJG3422R]
TP
CTPL
Feb 3 2020 2:00PM
[LEK HAN WEI]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼




















Assessment Reports


































1 per page ▼ ☒

No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	03/02/20 16:42	Repairer Estimates	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/02/20 15:32	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	19/02/20 17:10	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
31	19/02/20 17:10	General View	 Load JPG	✓
32	19/02/20 17:10	General View	 Load JPG	✓
33	19/02/20 17:10	General View	 Load JPG	✓
34	19/02/20 17:10	General View	 Load JPG	✓
35	19/02/20 17:10	General View	 Load JPG	✓
36	19/02/20 17:10	General View	 Load JPG	✓
37	19/02/20 17:10	General View	 Load JPG	✓
38	19/02/20 17:10	General View	 Load JPG	✓
39	19/02/20 17:10	General View	 Load JPG	✓
40	19/02/20 17:10	General View	 Load JPG	✓
41	19/02/20 17:10	General View	 Load JPG	✓
42	19/02/20 17:10	General View	 Load JPG	✓
43	19/02/20 17:10	General View	 Load JPG	✓
44	19/02/20 17:10	General View	 Load JPG	✓
45	19/02/20 17:10	General View	 Load JPG	✓
46	19/02/20 17:10	General View	 Load JPG	✓
47	19/02/20 17:10	General View	 Load JPG	✓
48	19/02/20 17:10	General View	 Load JPG	✓
49	19/02/20 17:10	General View	 Load JPG	✓
50	19/02/20 17:10	General View	 Load JPG	✓
51	19/02/20 17:10	General View	 Load JPG	✓
52	19/02/20 17:10	General View	 Load JPG	✓
53	19/02/20 17:10	General View	 Load JPG	✓
54	19/02/20 17:10	General View	 Load JPG	✓
55	19/02/20 17:10	General View	 Load JPG	✓
56	19/02/20 17:10	Reinspection Photo	 Load JPG	✓
57	19/02/20 17:10	Reinspection Photo	 Load JPG	✓
58	19/02/20 17:10	Reinspection Photo	 Load JPG	✓
59	19/02/20 17:10	Reinspection Photo	 Load JPG	✓
60	19/02/20 17:10	Reinspection Photo	 Load JPG	✓
61	19/02/20 17:10	Reinspection Photo	 Load JPG	✓
62	19/02/20 17:10	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	03/02/20 16:44	E-filed GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI20001978/FTF3S2
Date: 20/02/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MS006599
Claimant Vehicle No: SHA1681C Insured Vehicle No: SJG3422R
Date of Loss: 03/02/2020 Nature of Claim: TP Claim No: M2000865

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA1681C
Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEJU045575
Reg. Date: 03/07/2018 (Man. Year: 2018) Chassis No: KMHC851CVJU103356
Colour: Blue Odometer: 310658 km
Engine Capacity: 1580 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Davanti 7 mm Rear Left Side: Davanti 7 mm
Front Right Side: Davanti 7 mm Rear Right Side: Davanti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,064.96	2,756.00	308.96	10.08
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,140.00	1,580.00	560.00	26.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,215.96	4,347.00	868.96	16.66
+ GST 7.00/7.00% (S\$)	365.12	304.29	60.83	16.66
Nett Amount (S\$)	5,581.08	4,651.29	929.79	16.66

INSPECTION

Date of Assignment: 04/02/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected: 04/02/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969
Estimated Period of Repair: 4.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Feb 2020)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA1681C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR DOOR LH	Dented	1,789.90 FL	-	*1,789.90 FL
2	1		*REAR DOOR LWR PROTECTOR LH	Repair	116.20 FL	-	*- FL
3	1		*REAR WHEEL RIM LH	Cut	1,555.10 FL	-	*1,555.10 FL
4	1		*REAR WHEEL TYRE LH	Not Necessary	216.00 F	-	*- F
5	1		*REAR DOOR APPS STICKER LH	Necessary	80.00 F	-	*80.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,757.20	3,425.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	692.24	669.00
Total Parts (\$\$)	3,064.96	2,756.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING - REAR FENDER LH ETC	New	800.00	640.00
2	TRANSFER OF DOOR	New	120.00	80.00
3	TUFF KOTE	New	100.00	50.00
4	WHEEL ALIGNMENT	New	120.00	60.00
5	SPRAY PAINTING - REAR BUMPER, ROCKER PANEL GARNISH LH & ETC	New	1,000.00	750.00
Gross Labour Cost (S\$)			2,140.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >