

ASS. REC. BY:

REF: CS3 / TH 2000/998 / HT301 Special Instruction:Survivor: HOCK AN ASSIGNMENT (Office)From (Person): Gabriel Wee of TH Date/Time: 4.2.2020 5.23p.m

Estimated Cost: _____ Bill to: _____

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLS 6071M Insured: SHD 3185Pat Workshop m/s Sin Seng Hong Tel: 96278521of BK 3023A Ubi Road 1 #01-63

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27.1.2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 5/2/2020 11:50am Person Contacted: Andy H.O.D. Endorsement: _____Vehicle IN / OUT

| Date/Time | Action/Instruction (X) Estimate |
|----------------|---|
| | <u>SLS 6071M - X</u> |
| | <u>SHD 3185P - CS/TH 18008579 / U95302-1 D.O.A - 21/04/2019</u> |
| <u>11/2/20</u> | <u>- sample taken.</u> |
| <u>11/2/20</u> | <u>- sample taken. 0356PM</u> |
| <u>12/2/20</u> | <u>- final post pm. 0444PM</u> |

ASS. REC. BY: H-ANNREF: TU

ASSIGNMENT

From:

Date: 11.2.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLS 6071M

at Workshop m/s

S'n seng Hong

of

BK 3023A Ubi road 1 #01-53 01-63

Insured:

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Aflor 10.30p.m

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

| | |
|-----|-----|
| X | |
| N/S | O/S |
| | |

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

my

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLS 6071M

Yr Regn:

28/07/2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

T. CHR HYBRID

c.c

1797

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

131233/km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

2YX10207.6141Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60/R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

27/1/20

D.O.I.

11/2/20 1047AM

Survey held at

S'n seng HongDes. of Damages: Frt / Rear / O/S / N/S / U/C / Roof top or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range → 2.5-3.5h
opr Days → 2 day* SLS 6071M
PR car.Submit PRS ReportMV - 71000PV - 40353NV - 30600

RECEIVED 17 FEB 2020

Mr. Andy → 96278521

Date/Time, File Pass to?

☐

Preli. Report

1) 9/2 Typist☒

Final Report

Date/Time, File Return to?

2)

Rep. Format:

TP-PRS

Lump Sum / L.B. (C)

Days Of Repair: 2Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

12011131

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 4 February 2020 5:23 PM
To: 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: ct-admin@visionlawllc.com; 'jactan@visionlawllc.com'; Manivel Priyadarshini
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLS6071M (Accident involving SLS6071M and SHD3185P on 27.01.2020)
Attachments: 4003_001.pdf; 3969_001.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SLS6071M
III INSURED VEHICLE NO. : SHD3185P
DATE OF LOSS : 27.01.20

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Priya**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

We started using audatex since 1st dec 2019. Please do adjustments throught Audatex and upload the report onto Merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Motor Claim - III
Sent: 04 February, 2020 11:47 AM

To: 'ct-admin@visionlawllc.com' <ct-admin@visionlawllc.com>; 'jactan@visionlawllc.com' <jactan@visionlawllc.com>

Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLS6071M (Accident involving SLS6071M and SHD3185P on 27.01.2020)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

We started using audatex since 1st dec 2019. Please submit your estimate/quotation through Audatex so that our surveyors can make the adjustments according.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]

Sent: 04 February, 2020 9:15 AM

To: Motor Claim - III <motorclaim@iii.com.sg>; sinsenghongspray@hotmail.com

Subject: Scan Image

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be

intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAN YINGXIAN, SELWYN
CHEONG YUNHUI, CLARISSA
SONIA LIM WEI LEI

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.Jt.Ins.S42.112800.20 (sj)
Your Ref: SHD 3185 P

05 February 2020

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
#04/#05 IOB Building
Singapore 049711

Attention: Motor Claims Department

BY FAX: 6224 4174

motorclaim@iii.com.sg

Dear Sirs,

**ACCIDENT INVOLVING SLS 6071 M & SHD 3185 P ON 27 JANUARY 2020 ALONG BUKIT MERAH LANE 4 AT ABOUT 1250 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email dated 04 February 2020 informing that your wish to conduct a pre-repair survey on our client's vehicle

Please be informed that the said vehicle can be inspected at:

Sin Seng Hong Spray Painting & Services
Block 3023A Ubi Road 1
#01-63
Singapore 408717
Mr Andy Yeo (9627-8521)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

Anjali M
(Head Office)



FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

1st Survey on _____
Appointed surveyor : _____
(Name & Signature)

2nd Survey on _____
Appointed surveyor : _____
(Name & Signature)

3rd Survey on _____
Appointed Surveyor : _____
(Name & signature)

cc: **SLS 6071 M** – By email sinsenghongspray@hotmail.com only

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|----------------------------------|
| Owner ID Type: | Company |
| Owner ID: | 630W |
| Vehicle Details | |
| Vehicle No.: | SLS6071M |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 12 Feb 2020 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | C-HR 1.8 HYBRID S AUTO 5DR |
| Primary Colour: | White |
| Manufacturing Year: | 2017 |
| Engine No.: | 2ZR8197454 |
| Chassis No.: | ZYX102076141 |
| Maximum Power Output: | 90.0 kW (120 bhp) |
| Open Market Value: | \$28,067.00 |
| Original Registration Date: | 28 Sep 2017 |
| First Registration Date: | 28 Sep 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$5,000.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 27 Sep 2027 |
| PARF Rebate Amount: | \$3,750.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 27 Sep 2027 |
| COE Category: | E - Open - all except motorcycle |
| COE Period(Years): | 10 |
| QP Paid: | \$48,005.00 |
| COE Rebate Amount: | \$36,603.00 |
| Total Rebate Amount: | \$40,353.00 |

The information contained herein is correct as at 12 Feb 2020

OK

Seize the envy of the roads, from just \$89,900*


[Register here](#)

*Terms and conditions apply.

Toyota C-HR

Price Range ▾

Depreciation ▾

Year Reg ▾

Vehicle Type ▾



Home » Used Cars » Pure Motors Pte Ltd » Toyota C-HR Hybrid 1.8A S

Toyota C-HR Hybrid 1.8A S

Overview

Financial

Accessories

Similar

Research

Photos

Map



PURE MOTORS PTE LTD



| | | | |
|-----------------|---|-----------------|---|
| Price | \$76,800 | Fuel Type | Petrol-Electric |
| Depreciation ⓘ | \$9,510 /yr View models with similar depre | Reg Date | 04-Dec-2017 (7yrs 9mths 21days COE left) |
| Mileage | 29,000 km (13.2k /yr) | Manufactured ⓘ | 2017 |
| Road Tax ⓘ | N.A. | Transmission | Auto |
| Dereg Value ⓘ | \$48,577 as of today (change) | OMV ⓘ | \$27,911 |
| COE ⓘ | \$57,390 | ARF ⓘ | \$5,000 |
| Engine Cap | 1,797 cc | No. of Owners ⓘ | 1 |
| Curb Weight ⓘ | 1,440 kg | | |
| Type of Vehicle | SUV | | |

Features

4 Cylinder 16V DOHC Hybrid Engine, CVT Transmission, FWD, ABS, Cruise Control, Electric Parking Brake, ECO Assist, Keyless System. View specs of the [Toyota C-HR Hybrid \(2016\)](#)

Accessories

Sports Rims, Leather Seats, Pioneer DVD Player, Bluetooth Interface, Reverse Camera, Reverse Sensors.

Description

Promo 1.98% Bank Loan Interest Rate. 1 Owner Only. Low Fuel Consumption And Reliable. 100% Loan Approval. Bank/In House Loan Available. Please Visit Us Now For Further Details.

Category

PARF Car, Hybrid Cars

Status

Available

Resources



Vehicle Evaluation


* Request to have this car evaluated professionally. Find out more

[Compare](#)
[- Free](#)


Location Map

Price Chart

Summary



Click on the point to view the vehicle

[Shortlist](#)
[Compare](#)
[Add nc](#)
[Report Error](#)
[More Actions](#)

Seller Information

Pure Motors Pte Ltd

7 vehicles for sale. 35 sold in past 3 mths

210 Turf Club Road Lot B49

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--------------------|
| Date Of Report | 28/01/2020 16:26 |
| Date Of Accident | 27/01/2020 12:50 |
| Exact Location Of Accident | BUKIT MERAH LANE 4 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|--------------------------------|
| Vehicle Registration Number | SLS6071M |
| Insured/Policyholder | |
| Name Of Registered Owner | THE CAR CYCLE RENTAL PTE. LTD. |
| Co Reg No | 201512630W |
| Email Address | NOEMAIL |
| Mobile Phone No | |
| Alternative Phone No | OFFICE-90073513 |

Vehicle Particulars

| | |
|--|------------------|
| Manufacturer | TOYOTA |
| Model | C-HR |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE HIRE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE HIRE |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5112884148 |
| Cover Note Number | DRIVO CLASSIC |

Driver

| | |
|----------------------|------------------------|
| Name of Driver | TENG YIT SUEN EUGENIUS |
| NRIC No | S9703685C |
| Date Of Birth | 03/02/1997 |
| Occupation | INDOOR |
| Date Of Driving Pass | 26/04/2016 |
| Driving Experience | 3 YEARS AND 9 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-83837413 |
| Fax Number | |
| Contact Number | |
| Email Address | NOEMAIL |

| | |
|---|---|
| Address | BLK 257 #11-18 SERANGOON CENTRAL DRIVE |
| Postcode | 550257 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OTHER - HIRER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |

General Information of the Accident

| | |
|--------------------|------------|
| Type Of Accident | SIDE SWIPE |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

Refer to Sketch Plan

Attachment(s)

| | |
|---|-------------------|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Remarks/ Reasons: | FILE SIZE TOO BIG |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|----------|
| Vehicle Registration Number | SHD3185P |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | TAXI |
| Name of Driver | UNKNOWN |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

Report No: MT

D.O.A: 01/01/2020

Vehicle No: SL6671M

Reporting Type:

Time: 00:01 hrs

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



28/01/20 / 16:21

Policyholder's Signature / Date & Time


28/01/20 / 16:21

Driver's Signature (If driver is not the policyholder) / Date & Time

 Alan Tang (S098825)
 Customer Care Executive
 Motor Service Centre

Witnessed by Reporting Centre Personnel

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was making a right turn. Just then, vehicle B stopped in front of me. Upon seeing this, I stopped at once behind vehicle B. Suddenly, vehicle B started to reverse. Upon seeing this, I sounded my horn. However, vehicle B continued to reverse. This resulted in the rear right area of vehicle B to hit into the front area of my vehicle A.

Declaration

I/We declare the foregoing particulars are true in every respect.



28/01/20 / 16:21

Policyholder's Signature / Date & Time

28/01/20 / 16:21

Driver's Signature (if driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel

...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|---|---------------|---|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 17 Feb 2020 Edit Reg | | 04 Feb 2020 00:00 Edit Adj Rpt | S\$0.00 Edit Estimates | S\$0.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|--|---|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | -, Co. Reg. No.: - | | | | | | | | |
| Main Claimant: | - | | | | | | | | |
| Vehicle Reg. No.: | SLS6071M | Date of Loss: | 27/01/2020 00:00 - :59 [27 Months and 30 Days From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / MCT20010652 | Policy/Cover Note No.: | MCOM0015 | | | | | | |
| Vehicle Reg. No. (Insured): | SHD3185P | Policy No. (Claimant): | | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Sin Seng Hong Spray Painting & Service (HQ) BLK 3022A UBI ROAD 1 #01-53, 408716 Ubi - Tel: | | | | | | | | |
| Handling Insurer: | India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 14/02/2020] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SLS6071M (MCT20010652)

[SHD3185P]






































TP




















-

Jan 27 2020 12:00AM

[-]

Sin Seng Hong Spray Painting & Service

| Upload Documents Upload Photos Compose New Letter | | | View View In Browser | |
|---|-----------------|-----------------------------------|--|-------------------------------------|
| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 12/02/20 09:54 | Chassis Number |  Load JPG | <input checked="" type="checkbox"/> |
| 2 | 12/02/20 09:54 | Odometer Reading |  Load JPG | <input checked="" type="checkbox"/> |
| 3 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 4 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 5 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 6 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 7 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 8 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 9 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 10 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 11 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 12 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 13 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 14 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 15 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 16 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 17 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 18 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 19 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 20 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 21 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 22 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 23 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 24 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 25 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 26 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 27 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 28 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 29 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 30 | 12/02/20 09:55 | General View |  Load JPG | <input checked="" type="checkbox"/> |
| 31 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 32 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 33 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 34 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 35 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 36 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 37 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images | | | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|--|--|-------------------------------------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 38 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 39 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 40 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 41 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 42 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 43 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 44 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 45 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 46 | 12/02/20 09:55 | Reinspection Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 47 | 17/02/20 11:00 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 48 | 17/02/20 11:00 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 49 | 17/02/20 11:00 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 50 | 17/02/20 11:00 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 51 | 17/02/20 11:00 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 52 | 17/02/20 11:00 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 53 | 17/02/20 11:00 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| 54 | 17/02/20 11:00 | After Repair Photo |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 05/02/20 13:37 | ASSIGNMENT FROM INDIA |  Load PDF | |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 06/02/20 09:12 | Singapore Accident Statement |  Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> | | | |
| Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III20001998/HTF3E2

Date: 18/02/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No : SLS6071M

Insured Vehicle No : SHD3185P

Date of Loss: 27/01/2020

Nature of Claim:

TP

Claim No: MCT20010652

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS6071M

Make & Model: TOYOTA C-HR HYBRID, 1.8 S (A)

Engine No: 2ZR8197454

Reg. Date: 28/09/2017 (Man. Year: 2017)

Chassis No: ZYX102076141

Colour: White

Odometer: 131233 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: KAPSEN 6 mm

Rear Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 04/02/2020

Date Inspected: 11/02/2020 Inspected At:

Sin Seng Hong Spray Painting & Service (HQ)

BLK 3022A UBI ROAD 1 #01-53

Singapore 408716

Estimated Period of Repair: 0.0 days

Adjuster: LEE HOCK ANN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Feb 2020)

Parts: M1-SUV TOYOTA C-HR HYBRID 1.8 S (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS6071M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >