



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

AXA INSURANCE PTE LTD

Ref : CC4/ASM20002039/Aga3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 18-05-2020



ATTn; LYNN KHONG

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBF 5541S	<b>Veh. Inspected</b>	SFL 3700J
<b>Policy No.</b>	P2053045	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S0M02FDR	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	LYNN KHONG	<b>Assign Date</b>	05/02/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	SUZUKI GRAND VITARA	<b>c.c</b>	1995
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2007
<b>Chassis No.</b>	JSAJTE54V00200334	<b>Colour</b>	GREY
<b>Odometer</b>	1163571	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	245/70 R16	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	245/70 R16	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	245/70 R16	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	245/70 R16	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	04/02/2020	<b>Inspection Date</b>	06/02/2020
<b>Survey held at</b>	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**