



Your Ref: S9M02A32

Date: 23rd April 2020

Our Ref: CS3/ASM19022020/Gtf3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Li Rui Hong

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLJ 361M
INSURED VEHICLE: PC 256Z
ACCIDENT DATE: 12/12/2019**

We thank you for your instruction on 05/02/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLJ 361M from M/s Premier Appraiser Services.
- b) Singapore Accident Statement and Police Report of Vehicles SLJ 361M.
- c) Final Repair Bill of SLJ 361M from M/s Complete VMS Pte Ltd.
- d) Colour damaged vehicle photographs of SLJ 361M.

Pre-Repair Inspection Date : 16/12/2019 at M/s Complete VMS Pte Ltd, Blk 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, Singapore 575721.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLJ 361M
Make & Model	: Nissan Qashqai 2.0 CVT ABS D/Airbag 2WD 5DR S/R
Year of Registration	: 2016
Chassis Number	: SJNFBAJ11U1770834
Engine Capacity	: 1997 cc

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.