NATIONAL Assessment Centre			4MA 120016		TV	4971
Date In \$12120 11:12	Jeb description		Date &Time Com	nleted	Done !	4
	SAS c-filing					
MAI AIN 2009 2001	Ti-mail (within)	Blus, AIC 2his)				
GBG 9310 K	1-Motor Chil	Contract to Security St. (Security St.)				
16[1]20 18:30.	16 [1   20 18:30.   I-Motor W/O (Within: OD 2his, TP 4bis)					
(11) IP ' Reparing Cirily	I-Photo Uplo					
	Assessment/Su					
IP Insuits		and the second second second second	Owner/Wksp			
ie ne no vijetanima e nezezonalitatija. Pranta e establika	V22,4 1Cebon n	y Pax / Rental	Tul	Face:	-2012/1-1220189	4 MOATT 1885
Proforred Wisp / INC Assign Wisp / QW: (		DIC/	)/Non-INC (	)		
P Particulars: Veh No: F	BK 5603 X	INC (	Tel:		)	(41)186.1
Owner / Driver: (			Cover Type: (		)	
Policy No. ( ) Perio	od: (	Dura:	Time:		)	
Confirmed by : (	T - 0	Date: N: 0-20	%; P: 21-79%.	P: 80-100%	[6]	
	The second secon		170, 1.21-12-12			Andrew Street
This of taggernance (	arranty: YES (	)/NO(			* *	
Excess: (5 ) Loading: \$1,000		With the Party of	DEPOSITE STATES	THE PARTY OF THE P	- I	
zenepálzkenjájkas Elős ésszertás kések E	KARACI MENENE	Electrocesses.	A SAME AND ENTER OF THE		-1	
) Walk-In Customer : Customer's Inform	nation strictly Co	ntidential & Str	ictly NO fater of re-			
) Total Loss Case : to e-mail Insurer			in Conf	· · · · · · · · · · · · · · · · · · ·		
Drive-In ( )/ Towed-In ( ); Invoice:	YES ( ) / P	10();1	owing Co: (	Germensung.	X79107777 ****(*)	KT-VI
confidence de la contrata de la cont			liphie standschij	10000000000000000000000000000000000000	deviloons,	by
	all and the second seco					
Apply for Transport Allowance ( )/Con	urtesy Car (	)	p.94	-		
7 (197) 101 111 11	urtesy Car (	)	, , , , ,	-		
2) QC Check/Post Repair Inspection	.( •)	)	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
) QC Check/Post Repair Inspection ) Upload Resurvey Photo [Repair Cost> \$300	.( •)	)				
) QC Check/ Post Repair Inspection ) Upload Resurvey Photo [Repair Cost> \$300 Injury:	.( ·)			(COLORD)2	green 1-10-1	
) QC Check/ Post Repair Inspection ) Upload Resurvey Photo [Repair Cost> \$300 Injury:	.( ·)				aler der Edektrer	
O QC Check/Post Repair Inspection  Upload Resurvey Photo [Repair Cost> \$300  Injury:	.( ·)				alez ive	
) QC Check/ Post Repair Inspection ) Upload Resurvey Photo [Repair Cost> \$300 Injury:	.( ·)				SOKORY.	
) QC Check/ Post Repair Inspection ) Upload Resurvey Photo [Repair Cost> \$300 Injury:	.( ·)				arz, se	
) QC Check/ Post Repair Inspection ) Upload Resurvey Photo [Repair Cost> \$300 Injury:	ooj (				SOKORY.	
) QC Check/Post Repair Inspection ) Upload Resurvey Photo [Repair Cost > \$300 Injury:  ACTIONS (ACTIONS ACTIONS)	( -)				<del>a de la va</del>	e and
OC Check/Post Repair Inspection  Upload Resurvey Photo [Repair Cost > \$300  Injury:  Inverting Cachina State Cost > \$300  Injury:	( )	)	nrayon Shediliy		And (S)	es Angle
OC Check / Post Repair Inspection  Upload Resurvey Photo [Repair Cost > \$300  Injury:  ACTIONS ACTIONS  WA 2	( -)	Tavolicita	nint(Dit Checklin		<del>a de la va</del>	Reading Co
OC Check/Post Repair Inspection  Upload Resurvey Photo [Repair Cost > \$300  Injury:  Invertigate Oxidian Section 1999 (Section 1999)  MA 2	( )	Involection  1 Alt: Acadent  2) DA: Damega	ing a (201) (She cullis Reporting (330); Assessment (3100);	INC (350) \$40/\$45	And (S)	evanue:
OC Check / Post Repair Inspection  Deployed Resurvey Photo [Repair Cost > \$300  Injury:  ACCOMM STATE OF THE OF TH	( )	Thy OILC (Lift)  All: Acadent  2) DA: Damego  3) TP: Towing P  4) FT: Follow-T	nr. at(Dir Clic Clis) Reporting (510); Assument (5100);  arough Survey	1NC (350) \$40/543 \$120	And (S)	READIQUE PARTEDIN
OC Check / Post Repair Inspection  Deposed Resurvey Photo [Repair Cost > \$300  Injury:  MA 2.0  Injury:  Injury:  Injury:  Inverting Particulary - 2.2  Injury:  Inverting Particulary - 2.2	( )	Involection  Invol	in re(10) Glicellis Reporting (330); Assessment (\$100); •• wough Survey wough Survey (Resurve) goinsting Only (wef 10	INC (550)  \$40/\$45  \$120 () \$30  Jon 2005)	And (S)	C. And bit
OC Check / Post Repair Inspection    Upload Resurvey Photo [Repair Cost > \$300   Injury :	( )	Involection  Involection  Involection  I) All: Academi  2) DA: Damage  3) TP: Towing F  4) FT: Follow-T  5) FT: Follow-T  6) TR: Re-imper	Apporting (330); Associated (3100);  rough Survey gousting Only (wef.10	1NC (350) \$40/543 \$120	Ann (65)	S. Angli) Frailbii
OC Check / Post Repuls Inspection  Upload Resurvey Photo [Repair Cost > \$300  Injury:  ACTION OF CHARLES AND	( )	Involection  Invol	Apporting (330); Assessment (3100);  rough Survey goinsUNG Only (wef.10 flon SMRT Survey	INC (550) \$40/\$45 \$120 () 530 100 2905) \$75	Ann (65)	CANU(t)
COC Check / Post Repair Inspection  Deposed Resurvey Photo [Repair Cost > \$300  Injury:  ACTIONS ACCURATE A STATE OF THE PROPERTY OF THE PROPE	( )	Involection  Involection  I) All: Accident  2) DA: Damage  3) TP: Towning P  4) FT: Follow-T  Forgialinding A  6) TR: Re-impa  7) NI: Ideo DA  3) NUC Addition	Reporting (330); Association (3100);  rough Survey goinsUNG Only (wef 10 flon SMRT Survey and Services:	INC (550)  \$40/\$45  \$120 () 530 10012905)  \$75	30.0 °	Syanges
Checked by (Engr-In-Charge):	00) (	Involection  Involection  I) All: Acadient  2) DA: Damege  3) TP: Towing P  4) FT: Follow-T  5) FT: Follow-T  Forglainding A  6) TR: Re-impa  7) NI: Ideo DA  3) NTUC Addillo  OIL  *NS: Constary  *N6: Report C	Reporting (330); Assessment (3100);  rough Survey goinsUNG Only (wef 10 flon SMRT Survey and Sarvices: Car / Tpt Allowance	INC (550)  \$40/\$45  \$120 () 530 100 2905)  \$75	30.0 °	CVANUC!
OC Check/Post Repair Inspection  Deposed Resurvey Photo [Repair Cost > \$300  Injury:  MA 2   amounts Particular (**)  Iven/Owner:  maged Portion;  Checked by (Engr-In-Charge):	00) (	Thvollectiff  1) All: Accident  2) DA: Damege  3) TP: Towing P  4) FT: Pollow-T  5) PT: Pollow-T  Porclaiming a  6) TR: Re-inspec  7) NI: Idea DA  3) NTUC Addule  OD:  NS: Countary  NS: Repair C  NS: Repair Repai	Reporting (530); Assessment (5100);  rough Survey (Resurve); flon EMRT Survey and Sarvings; Car / Tpt Allowance air Inspection but Excess Coordination	1NC (350) \$40/545 \$120 () \$30 1Joh 2999) \$75 \$5160	30.0 a	Syang(s)
Checked by (Engr-In-Charge):	00) (	Involection  Involection  I) All: Acadient  2) DA: Damege  3) TP: Towing P  4) FT: Follow-Ti  5) FT: Follow-Ti  6) TR: Re-imper  7) N1: Ideo DA  3) NTUC Addition  Oli  *N5: Countary  *N6: Repair C  *N7: Fort Rep  *N8: DV / Co  TP (BUI): TF	Cor / Tpt Allowance  cordination  cor / Expection  cor / Expectio	INC (350) \$40/\$45 \$120 () \$30 1 Joh 2999) \$5160	30.0 o	kadbil
C) QC Check/Post (cepair Inspection  1) Opload Resurvey Photo [Repair Cost > \$300  Injury:  Outerfing: (Wedgins: 1970)  Injury: (Wedgins	00) (	Thvollectiff  1) All: Accident  2) DA: Damege  3) TP: Towing P  4) FT: Pollow-T  5) PT: Pollow-T  Porclaiming a  6) TR: Re-inspec  7) NI: Idea DA  3) NTUC Addule  OD:  NS: Countary  NS: Repair C  NS: Repair Repai	Reporting (530); Assessment (5100);  rough Survey (Resurve); and Survey (Resurve); from the Survey (Re	USE (1550) 1NC (550) 540/545 5120 () 530 10H 2905) 575 5160 525	30.0 o	Kadibil

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 06/02/2020 14:05

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	ent to the archiving of this report at the confidence of a cooper of the confidence of the cooper of
Control of the Control of the Control	ACCIDENT STATEMENT
Date Of Report	05/02/2020 11:12
Date Of Accident	16/01/2020 18:30
Exact Location Of Accident	KAKI BUKIT RD 3 NEAR BLK 30
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	GBG9310K
Insured/Policyholder	
Name Of Registered Owner	GREAT-M ENGINEERING PTE LTD
Co Reg No	29
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96661118
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800139433-01
Cover Note Number	
Driver	
	THE A MAINIC CO.

HLA NAING OO Name of Driver GXXXX775R NRIC No 29/06/1978 Date Of Birth INDOOR Occupation 05/01/2018 Date Of Driving Pass **Driving Experience** 

2 YEARS AND 0 MONTHS

MALE Gender

(LOCAL) +65-87470017 Mobile Number

Fax Number Contact Number

NOEMAIL EMail Address

Address 170 JOO CHIAT TERRACE #05-03

Postcode 427317

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

NAME: : UNKNOWN

GENDER: : MALE

**Details of Police Action** 

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name

TRAFFIC POLICE DIVISION HQ

Police Station Address

ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY:

e Station Address SINGAPORE

Police Station Contact TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

I WAS TRAVELLING ALONG KAKI BUKIT RD 3 BEFORE TURNING INTO NO 30 BUILDING, I CHECK ON THE OPPOSITE ON COMING TRAFFIC, ALL VEH HAD STOP, THEN I SLOWLY TURNING INTO THE BUILDING, SUDDENLY THE MOTORCYCLE COME FROM THE OPPOSITE LANE AND HIT ONTO MY VEH RIGHT FRONT PORTION.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBK5603X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Sign Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time:

NRIC/FIN No .:

Reporting Centre Personnel's Signature Name:

	1 1 1		
			A: GBG 93101
	B dB	No 30.	B: FBK 5603
	B		
	X		
1		Kaki Bukit Rd 3	
v r		C1 12 2 4	
Ref	er to	Statement	
		r	
		1	

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No. 65470000 1 of 3 Report No. T/20200116/2164

	oate/Time Report Made 6/01/2020 20:55		Vide Report No.: G/20200116/0169	Station Diary No.
Informa	nt's Partici	ulars		
Name of HLA NA	Informant ING 00		Address	
ID Type / ID No.: FIN NO / G8176775R Nationality: MYANMAR		5R	Contact No.: Home/Office.	Mobile: 87470017
			Email:	
Sex: Male	Age:	Date of Birth: 29/06/1978	Type of Informant: Driver	
Race		Mulicaract	Language:	Institution / School Name:
Occupation AIRCON SERVICING		NG	Driving Licence Information: Class: 3	Date of Expiry:

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 16/01/2020 18:20	Type of Location	
Location: Along Road ' KAKI BUKIT	ROAD 3				
Weather: Ro		Road Surface:		Road Speed Limit:	
Traffic Flow: Tra		Traffic Control:		Traffic Volume:	
				Anyone conveyed by	

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenge
FBK5603X	Motorcycle	KAWASAKI	ZX636F	Green	Slightly Damaged	0
GBG9310K	Lorry	TOYOTA	HIACE 3.0 DX AT	Silver	Slightly Damaged	0





2 of 3

Report No. T/20200116/2164

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

## Brief Details.

On the above stated date time and place,

I was travelling along the stated location making a right turn when V2 suddenly came from the opposite direction and collided onto the front right portion of my vehicle. That is all.





T/20200116/2164

3 of 3

Report No. T/20200116/2164

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

### Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / CHUA YUEJUN GLADWYN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 16/01/2020 20:55
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt LIM ENG KUAN, CLARENCE Contact No.: 65476195	Classification Of Case
Authentication Stamp NP168	PULICE PURIE



# CERTIFICATE OF INSURANCE

# COMMERCIAL AUTOPLUS COMMERCIAL VEHICLE

Name of Policyholder

: GREAT-M ENGINEERING PTE LTD

Period of Insurance Engine No.

: 30 Nov 2019 To 29 Nov 2020

Chassis No.

: 1KD2655885 : KDH2010207641 Vehicle No.

: GBG9310K

Policy No.

1800139433-01

Endorsement No.

**Issued Date** 

: 21 Nov 2019

# ABOUT THE COVER -

Make/Model

: TOYOTA HIAGE 1.6 ton [Van]

Engine Capacity/Tonnage : 1.5 Tonnage

Sum Insured : Market Value

First Year of Registration : 2017

Driver Restriction

NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive\*;

a) Any person who is driving on the Policyholder's order or with their permission.
 b) This Policy will indevenify the Policyholder or any authorised driver only if helpho meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young antito" inexpandenced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition

: All Age Condition

Limitation as to use\*

1) Ute in connection with the Policyholder's business.
2) Use for the carriage of passenger (other than for hire or reward) in connection with the Policyholder's business,
3) Use for social, domestic or pleasure purposes. This Policy does not cover a) use for hire or reward, driving busion, driving test, racing, pace-making, reliability trial or speed-testing; and b) use whilst drawing a traiter except the towing of anyone discibled using a mechanically propelled vehicle, c) use for any purpose in connection with Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Componention) Act (Cap. 189), Section 95 of the Road Transport Act, 1997 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

#### **EXCESS**

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

# APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out, at the Sole Agent's workshop.

For other Approved Reporting CentrastAlG Augmonted Repairers, please contact our 24 hour accident emergency hottine at +65 6338 6200. Attemptively, You may refer to AlG website www.aig.sg or AlG SG Mobile App. Simply search and download "AlG SG" from Funes or Google Play.

# IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: THINKONE CREDIT PTE LTD

IAWe haveby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Read Transport Act, 1987 (Malaysia), Read Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1969 (Malaysia).

0500540020

ALLINK INSURANCE AGY-CV/FLEET

BLK 153 BUKIT BATOK ST 11 #02-290

SINGAPORE 650153

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pre-ILIE

Capyright © 2019 NG Asia Pacife Incurance Pray Ltd.