



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20002120/Apa3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 23-09-2020



ATTN: STACEY NG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMH 5644M	Veh. Inspected	SKE 548E
Policy No.	VPA/P2246599	Coverage (\$)	0.00
Claim No.	S0M02FA3	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	06/02/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 520I	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WBAXG12060DW34142	Colour	SILVER
Odometer	150660	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	PIRELLI	6 mm
L/H Front Tyre	225/55 R17	PIRELLI	6 mm
R/H Rear Tyre	225/55 R17	PIRELLI	6 mm
L/H Rear Tyre	225/55 R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/02/2020	Inspection Date	06/02/2020
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------