



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
WEE TAT LUAY  BLK 59 COMMONWEALTH DRIVE #05-125 SINGAPORE 140059  Contact No Mobile: 94743003	Cust No/Name	LCV07526/WEE TAT LUAY
	Reg No/Reg Date	SME3003S*KC17/ 30/11/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5018968
	Engine No	G4FGJH709913
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	05/02/2020/ 16:12	QUD	247 / DonBong	11174			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								825 2750.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, 55° FRONT BUMPER, REPAIR RH FRONT FENDER, REPAIR LH FRONT FENDER								
E PNT88000								? 100.00
REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK								
M SUNDRY								? 80.00
TOP UP A/CON GAS AND CHECK A/CON SYSTEM								
E PNT98000								470 1680.00
PAINT WORK FRONT BUMPER, RH FRONT FENDER, 47° LH FRONT FENDER AND AFFECTED PORTION								
M SUNDRY								80.00 ✓
SUPPLY FRONT NUMBER PLATE WITH FRAME (Acrylic car plate)								
M SUNDRY								80.00 X
APPLY BODY SEALANT								
A 54900099								30 50.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
M SUNDRY								80.00 X
PERFORM RUST PREVENTION								
A 10028901								200.00 ✓
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST (certificate)								
M SUNDRY								200 250.00
RE-APPLY PAINT PROTECTION ON AFFECTED PORTION								
M SUNDRY								20 50.00
SUNDRIES								
M CARRIER ASSY-FRONT END MODULE					1.00	675.00	00.00	675.00
M BEAM COMPLETE-FR BUMPER					1.00	497.00	00.00	497.00
M STIFFNER-FR BPR LWR					1.00	114.00	00.00	114.00
M ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	00.00	84.00
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	22.00	00.00	22.00
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	22.00	00.00	22.00
M LAMP ASSY-SIDE REPEATER,LH					1.00	143.00	00.00	143.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for WEE TAT LUAY and vehicle specifications like LCV07526/WEE TAT LUAY.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Values include CSM00081, Cash, 05/02/2020/ 16:12, QUD, 247 / DonBong, 11174.

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts like LAMP ASSY-SIDE REPEATER, AIR DUCT-FR BUMPER, etc.

Estimate

SURVEYOR NAME: Steve (LKK) WLL P/Indu
SURVEYOR SIGNATURE: [Signature]
DATE: 11/2/20, 10.30 am 3 days
REMARKS: P/P, Rj Bel sry

LKK Auto Consultants hence notify the Repairer of the following:
To resurvey before/after spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Summary table with columns: Net, 7% GST on, Total Payable. Values: 9,075.00, 635.25, 9,710.25.

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.