

22/03/2003

ASS. REC. BY:

REF:

CS/MSK20007151/Kyf3et

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Christina Wong

of

MSK

Date/Time:

07/07/20

Estimated Cost:

Bill to:

OD-TP/W/S/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMJ 2967R

Insured:

SMC 597A

at Workshop m/s

Wei Lee Motor

Tel:

of

Blk 981m Industrial Estate #01-32

Policy No:

290874115mp

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/7/20

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate ()

SMJ 2967R - X

SMC 597A - X

10/6/20

Send preli revised via merimen

13/2

C1 Lmp & 160d email & confirm Karen (Red \$1650-45, 50%)

ASS. REC. BY:

REF:

WY4

ASSIGNMENT

From:

Date:

07/1/2020

Veh No:

SMJ 2967R

Yr Regn:

04, 13

Estimated Cost:

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

SMJ 2967R

Make:

Toy A/T/A

C.C.

1598

at Workshop m/s

Wei Lee Motor

Colour

M. Green

A/C:

Insured / Std / NI / NA

of

Sp. Reading

175344

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

NR053REE104158679

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ Inorder / Jammed / Leaked / Burnt or


Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

WPI

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

5 mm

R/Bal.

3 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

5 mm

L/Bal.

3 mm

Est. Repairs:

04

days

Res.:

Yes or No

D.O.A.

5/2/20

D.O.I.

7/2/2020

Lum Sum:

20

%

3 Val.:

Yes or No

Survey held at

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

13/2/20 Typist

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

150

Transportation:

S + RS. St

Photos

Others

TOTAL

11

161

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Misc end (\$)

Report Format:

Lump Sum / E/P: 13

\$1600f

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2020		07 Feb 2020 09:55 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	SANJEEV KUMAR BHATIA, ID: S6967830J, Tel: +6596562671		
Main Claimant:	KH LEASING PTE. LTD., Co. Reg. No.: 201611813C		
Vehicle Reg. No.:	SMJ2967R	Date of Loss:	05/02/2020 12:00 - :59 [1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29087411SMP (Comprehensive) Coverage: 26/06/2019 - 25/06/2020
Vehicle Reg. No. (Insured):	SMC597A	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, 575644 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/02/2020]		
Driver/Custodian (Insured):	SANJEEV KUMAR BHATIA (50 / Male), NRIC: S6967830J, Tel: +6596562671 Email:		
Adj Asg. Remarks:	on WP. Car in 07/02/2020 survey after 10am. Liab: clear. Agree on SJE. Assign: IHS or LKK Auto Consultants Pte Ltd. Contact: Karen Seah @ 6456 9830.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Kenneth

(14)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Christina Wong	Date: 10 Feb 2020
<u>Preliminary Advice</u>	

Insured Vehicle No	: SMC597A	Accident Date	: 05/02/2020
TP Vehicle No	: SMJ2967R	Assignment Date	: 07/02/2020
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 4
Date of Inspection	: 7/2/2020		
Inspection At	: WEI LEE MOTOR WORKS		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,250.45
Revised Amount	:S\$	2,045.28
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,045.28
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


ACCIDENT STATEMENT

Date Of Report	06/02/2020 09:35
Date Of Accident	05/02/2020 12:55
Exact Location Of Accident	MACPHERSON ROAD / LORONG BAKAR BATU TOWARDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ2967R
Insured/Policyholder	
Name Of Registered Owner	KH LEASING PTE. LTD.
Co Reg No	2XXXXX813C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94770048
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107953716
Cover Note Number	
Driver	
Name of Driver	FONG BEE HOCK
NRIC No	SXXXX258G
Date Of Birth	30/04/1958
Occupation	OUTDOOR
Date Of Driving Pass	04/07/1978
Driving Experience	41 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94770048
Fax Number	
Contact Number	
EMail Address	NOEMAIL

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Macpherson Road towards the city while passing thru Jalan Bakar Bar a Car (Silver) BMW SMC 597A drove into the left side of my car. I try to sway to the right lane but he still hit me.

I feel pain in my back now.

Two Vehicle involve

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

KERINE TANG

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

514P34M SketchPlanForm_2/1

Address	BLK 21 HOUGANG AVENUE 3 #10-229 SINGAPORE
Postcode	530021
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

Passenger 1	NAME: : NA
	GENDER: : MALE
Passenger 2	NAME: : NA
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED AND POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WILL SEND TO NTUC
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC597A
Vehicle Make/Model/Colour	
Details Of Properties	REFER ATTACHED AND POLICE REPORT
Vehicle Category	PRIVATE CAR

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


KERINE TANG
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Name of Driver	MR. SANJIV
NRIC/Passport Number	
Contact Number	96562671
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	FONG BEE HOCK
Approximate Age	
Injuries Sustain	REFER ATTACHED AND POLICE REPORT
Injured person in which vehicle?	SMJ2967R
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	



**SINGAPORE
POLICE FORCE**



T/20200205/2296

1 of 3

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20200205/2296

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/02/2020 16:39		Vide Report No.:		Station Diary No.: 130
Informant's Particulars				
Name of Informant: FONG BEE HOCK		Address: APT BLK 21 HOUGANG AVENUE 3 #10-229 SINGAPORE 530021		
ID Type / ID No.: NRIC NO / S1317258G		Contact No.: Home/Office: Mobile: 94770048		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 61	Date of Birth: 30/04/1958	Type of Informant: Driver	
Race: Chinese		Language: English	Institution / School Name:	
Occupation: Grab Driver		Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 05/02/2020 12:55	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 MACPHERSON ROAD LORONG BAKAR BATU				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SMC597A	Car				Slightly Damaged	0
SMJ2967R	Car				Slightly Damaged	2

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Common Statement Pg. 1



**SINGAPORE
POLICE FORCE**



T/20200205/2296

2 of 3

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20200205/2296

CONTINUATION OF REPORT

Driver			
Name	SANJIV		ID No. NIL
Related Vehicle	SMC597A (Car)		Contact No. 96562671
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	FONG BEE HOCK		ID No. S1317258G
Related Vehicle	SMJ2967R (Car)		Contact No. 94770048
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	05/02/2020	Date Discharge	05/02/2020
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 5/2/2020 at about 1255hrs, I was at the Junction of Macpherson Rd and Lor Bakar Batu. I was travelling straight towards City area (on the second lane) when suddenly a vehicle bearing SMC597A came our Lor Bakar Batu. The said vehicle cut into my lane abruptly as such collided into the left portion of my vehicle (SMJ2967R).

After the accident, I felt pain on my body and went to see the doctor. I was given 5 days of medical leave.

I wish to state that I have an in built camera in my vehicle and I have already handed it over to the car rental workshop. I am lodging this report for insurance claim purposes.



**SINGAPORE
POLICE FORCE**



T/20200205/2296

3 of 3

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20200205/2296

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 3 LIYANA BINTE MOHD RAZALI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 05/02/2020 16:39
Officer In Charge Of Case: TP / AEIT / SSI 2 JUREMAH BINTE AHMAD Contact No.: 65476219	Classification Of Case: SN 061
Authentication Stamp NP168	

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

06, Feb 2020

MSIG Insurance (S) PL
4 Shenton Way #21-01
SGX Centre 2
S 068807

Attn: Motor claim dept-3 rd party claim
Claiming against your insured vehicle no: SMC597A
Accident involving vehicle no: SMJ2967R/SMC597A
DOA: 05/02/2020 AT Macpherson Rd/Lorong Baker Batu twds city

Dear officer incharge—

Re: Estimate cost of repair for vehicle no: SMJ2967R

To supply--

Description	Qty	Amount
Front door, Lh	1	881.90
Door protector	1	115.90
Rear door, Lh	1	780.90
Door protector	1	75.90
Parts		1,854.60
Parts less 25%		463.65
		1,390.95

To transfer door glass, power window mechanism, lock to new doors

260.00

To remove damaged parts and attachments

Repair/reshape damaged rear fender

Replace/realign all parts into position

750.00

To spray paint

850.00

3,250.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before painting
- To display damaged parts for resurvey
- Parts prices and labour charges
- Third party's assessment on "Prejudice" basis
- No illings or damages to be caused
- Support documents to be provided and is subject to LKK Auto Consultants' approval

Acknowledged by:

Signature:

Date:

3,250.95

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Feb 2020		07 Feb 2020 09:55 Edit Adj Rpt	S\$1,600.00 Edit Estimates	S\$1,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SANJEEV KUMAR BHATIA, ID: S6967830J, Tel: +6596562671								
Main Claimant:	KH LEASING PTE. LTD., Co. Reg. No.: 201611813C								
Vehicle Reg. No.:	SMJ2967R	Date of Loss:	05/02/2020 12:00 - :59 [81 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 619205	Policy/Cover Note No.:	29087411 (Comprehensive) Coverage: 26/06/2019 - 25/06/2020						
Vehicle Reg. No. (Insured):	SMC597A	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, 575644 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/03/2020]								
Driver/Custodian (Insured):	SANJEEV KUMAR BHATIA (50 / Male) , NRIC: S6967830J, Tel: +6596562671 Email:								
Adj Asg. Remarks:	on WP. Car in 07/02/2020 survey after 10am. Liab: clear. Agree on SJE. Assign: IHS or LKK Auto Consultants Pte Ltd. Contact: Karen Seah @ 6456 9830.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMJ2967R (619205)**
[SMC597A]
TP
KH LEASING PTE. LTD.
Feb 5 2020 12:00PM
[SANJEEV KUMAR BHATIA]
Wei Lee Motor Works

Upload Documents			Upload Photos			Compose New Letter			View <input type="button" value="View in Browser"/>		
Video									1 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	12/02/20 15:00	Video - Accident from OI							Load AVI		
2	13/02/20 15:33	Video - Accident by TP							Load MP4		
									1 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>
Assessment Reports									1 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	10/02/20 10:57	Adjuster Immediate Advice							Load HTM		
									3 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>
Photos/Images									3 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
2	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
3	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
4	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
5	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
6	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
7	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
8	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
9	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
10	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
11	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
12	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
13	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
14	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
15	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
16	13/02/20 16:07	General View							Load JPG	<input checked="" type="checkbox"/>	
									1 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>
Documentation									1 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	06/02/20 14:54	OI SMC597A GIA REPORT							Load PDF		
2	06/02/20 14:54	TPD SMJ2967R GIA REPORT							Load PDF		
3	06/02/20 14:54	TPD SMJ2967R - PRI							Load PDF		
4	06/02/20 16:27	Agree on SJE							Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20002151/KYF3E2

Date: 14/02/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29087411

Claimant Vehicle No : SMJ2967R

Insured Vehicle No : SMC597A

Date of Loss: 05/02/2020

Nature of Claim: TP Claim No: 619205

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMJ2967R

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 1ZRX268914

Reg. Date: 26/04/2013 (Man. Year: 2013)

Chassis No: MR053REE104158679

Colour: Metallic Green

Odometer: 175344 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Dunlop 5 mm

Rear Left Side: West Lake 3 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: West Lake 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,390.95	805.27	585.68	42.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,860.00	1,240.00	620.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,250.95	2,045.27	1,205.68	37.09
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	3,250.95	1,600.00	1,650.95	50.78
+ GST 7.00/7.00% (S\$)	227.57	112.00	115.57	50.78
Nett Amount (S\$)	3,478.52	1,712.00	1,766.52	50.78

INSPECTION

Date of Assignment: 07/02/2020

Date Inspected: 07/02/2020 Inspected At:

Wei Lee Motor Works (HQ)
BLOCK 9 SIN MING INDUSTRIAL
ESTATE #01-32
Singapore 575644

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 Feb 2020)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ2967R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR, LH	Bent / Warped	881.90 FL	*881.90 FL
2	1		*DOOR PROTECTOR	Dented	115.90 FL	*115.90 FL
3	1		*REAR DOOR, LH	Repair	780.90 FL	*- FL
4	1		*DOOR PROTECTOR	Necessary	75.90 FL	*75.90 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,854.60	1,073.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	463.65	268.43
Total Parts (\$\$)	1,390.95	805.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER DOOR GLASS, POWER WINDOW MECHANISM, LOCK TO NEW DOORS	New	260.00	60.00
2	TO REMOVE DAMAGED PARTS AND ATTACHMENTS (NPA)	New	0.00	0.00
3	REPAIR / RESHAPE DAMAGED REAR FENDER (NPA)	New	0.00	0.00
4	REPLACE / REALIGN ALL PARTS INTO POSITION	New	750.00	500.00
5	TO SPRAY PAINT	New	850.00	680.00
Gross Labour Cost (\$\$)			1,860.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >