



Your Ref: 19/19/19/VC05/022786

Date: 13th February 2020

Our Ref: CS1/LPC20002155/Eyf3s2

M/s Lonpac Insurance Bhd

300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMN 5844X
INSURED VEHICLE: YN 3998G ACCIDENT DATE: 13/12/2019**

We thank you for your instruction on 07/02/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMN 5844X from M/s Kelvin Automotive Appraising Services.
- b) Singapore Accident Statement of Vehicles SMN 5844X and YN 3998G.
- c) Colour damaged vehicle photographs of SMN 5844X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMN 5844X
Make & Model	: Honda Shuttle Hybrid 1.5(A)
Year of Registration	: 2019
Chassis Number	: GP72002487
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.