

02/01/2020

AES. REC. BY:

REF: CS3 / FWD 20002183 / Hyf3³²

Special Instruction:

Surveyor: HUCC AND

ASSIGNMENT (Office)

minim

From (Person): Venessa Chan of FWD Date/Time: 07/2/20

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 2477C Insured: SKP 5309M

at Workshop m/s: Leng Wang Tel: 67482910

of Blk 3007 Ubi Rd 1 #01-414

Policy No: Claim No: 120200007368/EB

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 26/2/2020

CA / REV / REP. / REV 24 HRS PRS' Survey on 10/2/20 H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle-IN/OUT

yo

Date/Time	Action/Instruction	Estimate	X
	SLS 2477C	CCB/MG/18006146	Ann392
	SKP 5309M	CS/MSK/17001478	Uvbn2
			date: 02/4/18
			date: 14/1/17
* 10/2/20	→ survey taken.		
* 10/2/20	→ repair taken.		
* 12/2/20	→ refer per.		

ASS. REC. BY: H-ANW

REF: FWD

ASSIGNMENT

From:

Date: 10/2/20

Veh No: SLS 2477C

Yr Regn: 15/109/2017

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SLS 2477C

Make: MAZDA 3 HB

cc: 1496

at Workshop m/s

Leng Wang Motor

Colour: Grey

A/C: Insured / Std / NI / NA

of

Blk 3007 Ubi Rd 1 # 01-414

Sp Reading: 457.72 km

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: JM 6BN 24A 8J 01 76 755

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Tyre Size: F: 215/50/R17

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent?: Yes or No

R/Bal. 7 mm

R/Bal. 7 mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal. 7 mm

L/Bal. 7 mm

Est. Repairs: 3 days

Res.: Yes or No

D.O.A. 6/2/20

D.O.A. 10/2/20

Lum Sum:

% 3 Val.: Yes or No

Survey held at: LENG WANG

CA / REV / REP. / 24 HRS

PRS

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

range → 1.8 - 2.7k
open days → 3 days

RECEIVED 24 FEB 2020

MV - 64000

PV - 38280

NV - 25700

ms. Anw → 98172032

Date/Time, File Pass to?

: Preli. Report
 : Final Report

Days Of Repair: 3

1)

Date/Time, File Return to?

Resurvey No. of Trip:

2) 24/2/20 Typist

Add Fee:

Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee:

Transportation:

3 - PRS \$

Photos:

Others:

PRR

Report Format: PRS

Lump Sum / U.C. /

Nivitha (LKK Auto)

From: Venessa Chan - SGUser <venessa.chan@fwd.com>
Sent: Friday, 7 February 2020 4:00 PM
To: 'admin-d@lkkauto.com'; 'admin-a@lkkauto.com'
Cc: Eileen Bay - SGUser; Motor Claims SG - SG Common
Subject: PRS for SLS 2477 C accident involving vehicles SKP 5309 M / SMM 4620 L / SDV 843 X And SKK 608 J on 6 February 2020 along KPE Towards MCE (Oref: LCH.lg/UB06-10079.20) FWD REF: 1202000007368/EB

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.

Kindly upload all correspondence emails/documents sent to you into Merimen.

Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Venessa Chan - SGUser
Sent: Friday, February 7, 2020 3:59 PM
To: 'Cheonghoh Law' <mail@cheonghoh.sg>
Cc: Eileen Bay - SGUser <eileen.bay@fwd.com>; Motor Claims SG - SG Common <motorclaims.sg@fwd.com>
Subject: PRS for SLS 2477 C accident involving vehicles SKP 5309 M / SMM 4620 L / SDV 843 X And SKK 608 J on 6 February 2020 along KPE Towards MCE (Oref: LCH.lg/UB06-10079.20) FWD REF: 1202000007368/EB

WITHOUT PREJUDICE

Dear Catherine,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/S LKK Auto Consultants Pte Ltd to conduct the pre-repair survey (PRS) on your client's

vehicle, SLS2477C . We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.***

Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Cheonghoh Law <mail@cheonghoh.sg>

Sent: Friday, February 7, 2020 3:45 PM

To: Venessa Chan - SGUser <venessa.chan@fwd.com>

Cc: Eileen Bay - SGUser <eileen.bay@fwd.com>; Motor Claims SG - SG Common <motorclaims.sg@fwd.com>

Subject: Re: PRS for SLS 2477 C accident involving vehicles SKP 5309 M / SMM 4620 L / SDV 843 X And SKK 608 J on 6 February 2020 along KPE Towards MCE (Oref: LCH.lg/UB06-10079.20) FWD REF: 1202000007368/EB

Dear Sirs,

We refer to the above matter and to your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your 10 appointed surveyors as stated in your aforesaid e-mail.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- (1) Kelvin Teo Hoon Tong
- (2) Chiang Fuh Keong Dave
- (3) Ho Joo Loong Danny
- (4) Lee Kok Weng
- (5) Hong Shiyuan
- (6) Lim Yong Tian Sebastian
- (7) Ong Ah Keng Kent
- (8) Ong Poh Meng
- (9) Philip Foo

(10) Thor Teck Soon David

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre-repair survey and please contact our client's workshop, Leng Wang Motor, Blk 3007 Ubi Road 1 #01-414 Singapore 408701 to contact survey of the said vehicle SLS 2477 C.

Contact Person : Ms Alice Yong
Tel: 6748 2910 / 9817 2032

Kindly proceed to do the needful.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 7 Feb 2020, at 3:35 PM, Venessa Chan - SGUser <venessa.chan@fwd.com> wrote:

WITHOUT PREJUDICE

Dear Catherine,

Refer to your email dated on 07.02.2020 of the PRI Notice of your client's vehicle SLS2477C;

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

***Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.**

Best Regards,

Venessa Chan
Administrative Assistant, Claims

<image001.png>

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg

<image002.jpg>

From: Cheonghoh Law <mail@cheonghoh.sg>

Sent: Friday, February 7, 2020 3:12 PM

To: Motor Claims SG - SG Common <motorclaims.sg@fwd.com>

Subject: Re: PRS for SLS 2477 C accident involving vehicles SKP 5309 M / SMM 4620 L / SDV 843 X And SKK 608 J on 6 February 2020 along KPE Towards MCE (Oref: LCH.lg/UB06-10079.20)

Dear Sirs,

We append below our letter of PRS and await your urgent reply.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

Begin forwarded message:

From: "Scan from HP MFP" <cheonghohscan@gmail.com>

Date: 7 February 2020 at 2:59:33 PM SGT

To: "mail@cheonghoh.sg" <mail@cheonghoh.sg>

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT

been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

LKK

MPA220016874 / Progressive Car Care Pte Ltd - HQ
 ENTRY DATE & TIME: 06/02/2020 16:30
 SUBMITTED BY: Cheong Ming Ming

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2020 16:30
Date Of Accident	06/02/2020 09:20
Exact Location Of Accident	KPE TOWARDS MCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS2477C
Insured/Policyholder	
Name Of Registered Owner	LIM DE
NRIC No	SXXXX282C
Email Address	JABEZ.LIMDE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90615600
Alternative Phone No	OTHERS-90091245
Vehicle Particulars	
Manufacturer	MAZDA
Model	3-1.5 HATCHBACK (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00524026
Cover Note Number	
Driver	
Name of Driver	LIM DE
NRIC No	SXXXX282C
Date Of Birth	24/04/1979
Occupation	OUTDOOR
Date Of Driving Pass	08/06/2007
Driving Experience	12 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90615600
Fax Number	
Contact Number	OTHERS-90091245
Email Address	JABEZ.LIMDE@GMAIL.COM

Address APT BLK 288A PUNGGOL PLACE
#14-803
Postcode 821288
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 5
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY KAREN - PROGRESSIVE CAR CARE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKP5309M
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMM4620L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SDV843X

3

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SKK608J

4

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:




 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:



 Reporting Centre Personnel's Signature
 Name:
 NRIC/PIN No.:

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along KPE towards MCE, 8.6 km, Lane 1. The front vehicle slow down, I proceed to slow down and come to a complete stop. Shortly about 2 secs later the vehicle behind me hit the back of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a fourteen (14) days clause whereby the claim against own policy must be made within the stipulated timeframe from the day of occurrence. Kindly check your policy for more details.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	282C
Vehicle Details	
Vehicle No.:	SLS2477C
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Feb 2020
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 HATCHBACK 1.5 AT DELUXE EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520466444
Chassis No.:	JM6BN24A8J0176755
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$19,627.00
Original Registration Date:	15 Sep 2017
First Registration Date:	15 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$14,627.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2027
PARF Rebate Amount:	\$10,970.00
Intended COE Rebate Details	
COE Expiry Date:	14 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$27,310.00
Total Rebate Amount:	\$38,280.00

→ 7313

The information contained herein is correct as at 13 Feb 2020

OK

DBS Bank NRO Savings Account

Get customized wealth solutions with signature lifestyle experiences. Apply Now! DBS Bank India Limited

mazda 3 Price Range Depreciation Year Reg Vehicle Type

Home » Used Cars » EU Automobile Pte Ltd » Mazda 3 HB 1.5A Deluxe

Mazda 3 HB 1.5A Deluxe

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$79,700		
Depreciation	\$8,010 /yr <small>View models with similar depre</small>	Reg Date	29-Nov-2018 <small>(8yrs 9mths 15days COE left)</small>
Mileage	18,086 km (15k /yr)	Manufactured	2018
Road Tax	\$682 /yr	Transmission	Auto
Dereg Value	\$38,669 as of today (change)	OMV	\$18,482
COE	\$28,199	ARF	\$18,482
Engine Cap	1,496 cc	Power	88.0 kW (118 bhp)
Curb Weight	1,329 kg	No. of Owners	1
Type of Vehicle	Hatchback		



Features

SkyActiv-G, 118Bhp, Transmission 6 Speed, Keyless Start/Stop/Entry, Auto Headlights And Wipers, Sport Mode, Cruise Control, USB/AUX Port, Sunroof. View specs of the Mazda 3 Hatchback (2014-2019)

Accessories

Head Up Display, Mazda Infotainment System With Navigation/Bluetooth, Front And Rear Camera/Reverse Camera, Electric Seats, Auto Fold Mirrors.

Description

1 Owner Maintained And Serviced By Agent, Low Mileage Done, Accident Free, With Agent Warranty, Very Well Maintained, Trade In Available, Flexible In House Finance Loan, Hurry Down For A No Obligation Test Drive Today Before It's Gone! (S)

Category

PARF Car

Status


Available

Resources

DOA = 6/2/20
 MV - 64000
 PV - 38286
 NV - 25700

Bonus → 7yr 7month
 upon → 7500 yr
 7500 in = 625
 = 52500 + 4375 + 7313
 = 64184

Price Chart



Click on the point to view the vehicle

Shortlist Compare Add no Report Error More Actions

Seller Information

EU Automobile Pte Ltd

32 vehicles for sale. 46 sold in past 3 mths

237 Alexandra Road #02-02



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Feb 2020 Edit Reg		07 Feb 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Woo Kah Wai, ID: S8122041G		
Main Claimant:	LIM DE, ID: S7912282C		
Vehicle Reg. No.:	SLS2477C	Date of Loss:	06/02/2020 00:00 - :59 [28 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1202000007368	Policy/Cover Note No.:	PNPV2019-00014988 (Comprehensive) Coverage: 05/10/2019 - 04/10/2020
Vehicle Reg. No. (Insured):	SKP5309M	Policy No. (Claimant):	
		Excess:	
Repairer:	Leng Wang Motor (HQ) Blk 3007 Ubi Road 1, #01-414, 408701 Ubi - Tel:		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 18/02/2020]		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS2477C (1202000007368)**
[SKP5309M]
TP
LIM DE
Feb 6 2020 12:00AM
[Woo Kah Wai]
Leng Wang Motor

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#) ▼

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/02/20 09:33	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
3	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
4	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
5	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
6	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
7	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
8	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
9	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
10	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
11	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
12	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
13	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
14	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
15	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
16	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
17	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
18	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
19	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
20	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
21	11/02/20 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
22	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
23	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
24	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
25	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
26	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
27	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
28	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
29	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
30	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
31	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
32	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
33	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
34	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/02/20 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	11/02/20 09:34	General View	Load JPG	<input checked="" type="checkbox"/>
37	11/02/20 09:34	General View	Load JPG	<input checked="" type="checkbox"/>
38	11/02/20 09:34	General View	Load JPG	<input checked="" type="checkbox"/>
39	11/02/20 09:34	General View	Load JPG	<input checked="" type="checkbox"/>
40	11/02/20 09:34	General View	Load JPG	<input checked="" type="checkbox"/>
41	11/02/20 09:34	General View	Load JPG	<input checked="" type="checkbox"/>
42	11/02/20 09:34	General View	Load JPG	<input checked="" type="checkbox"/>
43	11/02/20 09:34	General View	Load JPG	<input checked="" type="checkbox"/>
44	11/02/20 09:34	General View	Load JPG	<input checked="" type="checkbox"/>
45	11/02/20 09:34	General View	Load JPG	<input checked="" type="checkbox"/>
46	11/02/20 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	11/02/20 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	11/02/20 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	11/02/20 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	11/02/20 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	11/02/20 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	11/02/20 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	11/02/20 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	11/02/20 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	11/02/20 09:34	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	13/02/20 09:23	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
57	13/02/20 09:23	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
58	13/02/20 09:23	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
59	13/02/20 09:23	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
60	13/02/20 09:23	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/02/20 16:28	ASSIGNMENT FROM FWD	Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	10/02/20 11:55	PRI - CHEONGHOH LAW CORPORATION & TP GIA	Load PDF	
2	10/02/20 11:55	SKP5309M OI GIA	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD20002185/HYF3S2
Date: 25/02/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00014988
Claimant Vehicle No : SLS2477C **Insured Vehicle No :** SKP5309M
 Date of Loss: 06/02/2020 Nature of Claim: TP Claim No: 1202000007368

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS2477C**
 Make & Model: MAZDA 3, 1.5 HATCHBACK (A) Engine No: P520466444
 Reg. Date: 15/09/2017 (Man. Year: 2017) Chassis No: JM6BN24A8J0176755
 Colour: Grey Odometer: 45792 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/02/2020
 Date Inspected: 10/02/2020 Inspected At: Leng Wang Motor (HQ)
 Blk 3007 Ubi Road 1, #01-414
 Singapore 408701
 Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

2/25/2020

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,800.00 - \$2,700.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2020)
Parts: 144	MAZDA 3 1.5 HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLS2477C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >