

INS. CASE OWNER:

ASSIGNMENT

Surveyor:

LEE HOCK ANN

DOI: 07/02/2020

Date / Time : 7 February 2020

Registered in Merimen: _____

Pre-assign / CCU / FTE

Insured Vehicle No. : SFB 8083B

Claim No. : SOM02EK0

X

Name of Insured : LIU WEI PENG

Policy No. : GA365049

Insured Tel No. : _____ HP: _____

Make / Model : MAZDA 3-1.5 SEDAN EU6 (A)

Excess Sec II :S\$

D.O.A : 25/01/2020 14:40

Place of Accident : CLEMENTI AVE 4 OPEN CAR PARK

Is driver the owner? (☒ YES / NO)

Nature of Accident : _____

If NO, Driver Name / Age :

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : %

Final ? Yes / No

SLM 1989EINSRS:
WSP: BIFROST AUTO
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	SLM 1989E - CC4/LPC18018177/Apb3n2; DOA: 06.10.18 SFB 8083B - X		STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List: Handler	Typist
			Notification ltr (if non-pickup)	<input type="checkbox"/>
			After call ltr to OI:	<input type="checkbox"/>
			Authorisation To Act:	<input type="checkbox"/>
			Release Voucher:	<input type="checkbox"/>
			Final Repair Bill:	<input type="checkbox"/>
			Car Rental Invoice:	<input type="checkbox"/>
			Towing Invoice	<input type="checkbox"/>
			LTA / GIA :	<input type="checkbox"/>
			Medical Bill:	<input type="checkbox"/>
			PIR:	<input type="checkbox"/>
			Mandate/Reject Instruction:	<input type="checkbox"/>
			LOD	<input type="checkbox"/>
			Payment Breakdown Form:	<input type="checkbox"/>
			Post-Repair Photos:	<input type="checkbox"/>
			Others:	<input type="checkbox"/>
PRELIMINARY ADVICE	Date/Time:	Sent By:		
FINALIZATION	Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	S\$	(days) Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time:	Confirm with	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :	
Repair Cost:	S\$			
Loss of Rental (LOR):	S\$	(days)		
Loss of Use (LOU):	S\$	(\$ x days)		
Loss of Income (LOI):	S\$	(\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]			
GIA/LTA Search	S\$			
Medical:	S\$			
Disbursement:	S\$	(e.g. Tow/ Independent)	1) Claim status: Normal/Reject/Private Settle	
Legal Cost	S\$	2) Report Format:		
		3) Survey fee:		
Total:	S\$	Global Sum S\$:		
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	S\$	Name 1:		
Payee 2: (Strike if N.A.)	S\$	Name 2:		
Payee 3: (Strike if N.A.)	S\$	Name 3:		

ASS. REC. BY

H. INV

REF:

AXA

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLM 1989 E

at Workshop m/s

Bifrost

of

8 leaks burnt Arch #01-49

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLM 1989 E

Yr Regn:

23/03/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Opel Astra HB

c.c 1399

Colour

green

A/C:

Insured / Std / NI / NA

Sp. Reading

33326

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

W01BE6E2HG01P341

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40/R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

25/1/20

D.O.I.

7/2/20

Survey held at

Bifrost

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

* SLM 1989 E - do not
have Exch. on.

* pending workshop updated
parts price

MV - 64000

PV - 49005

NV - 14900

L-940

Date/Time, File Pass to?



: Preli. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + R.S. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / L&L: (\$

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

opel astra

Price Range

Depreciation

Year Reg

Vehicle Type

Home » Used Cars » Direct Owners » Opel Astra 1.4A Turbo

Opel Astra 1.4A Turbo

Overview

Financial

Accessories

Similar

Research

Photos

Map

DIRECT

Price \$62,800

Depreciation ⓘ

\$8,130 /yr

View models with similar depre

Reg Date

28-Nov-2016

(6yrs 9mths 17days COE left)

Mileage

54,000 km (16.9k /yr)

Manufactured ⓘ

2016

Road Tax ⓘ

\$626 /yr

Transmission

Auto

Dereg Value ⓘ

\$50,016 as of today (change)

OMV ⓘ

\$20,004

COE ⓘ

\$57,002

ARF ⓘ

\$15,006

Engine Cap

1,399 cc

Power

110.0 kW (147 bhp)

Curb Weight ⓘ

1,233 kg

No. of Owners ⓘ

2

Type of Vehicle

Hatchback

Features

1.4L Turbo Fully Auto, 6 Speed Gearbox, 148Bhp DOHC, 200Nm Torque, Cruise Control, Forward Collision Alert, Navigation, Bluetooth, USB, ISOFIX, TPMS. View specs of the Opel Astra

Accessories

17" Sports Rims, 6 Airbags, Keyless Entry/Start, Rain Sensors, Auto Start/Stop, Auto Headlights, Front/Rear Car Camera, Solar Film, Reverse Camera.

Description

Nice Bidded Number, 5 Years Agent Warranty And Free Servicing Until November 2021, Excellent And Original Tip Top Condition, Metallic Deep Sky Blue Colour, Leather Upholstery, Well Maintained Interior And Exterior, Accident Free, Covered Carpark, Call Now For Viewing.

Category

PARF Car, Direct Owner Sale

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Shortlist

Compare

Add no

Report Error

More Actions

Seller Information

Contact Person(s)

Miss Goh

Contact No.

93889578

Enquiry

Contact Seller

ESSENTIAL TRANSACTION FORMS

» Indemnity form

» Sales agreement

» Receipt

» Hand-over form

Ownership Transfer

GET HELP WITH
PAPERWORKSGCARMART
CONNECT

sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement and we'll help with **Car Loans, Insurance, Pay & Ownership Transfer**. FREE for all sgCarMart Advertised Vehicles.

Upload your Sales Agreement

Read our 8 Step Guide for Direct Buyers &

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	218A
Vehicle Details	
Vehicle No.:	SLM1989E
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Feb 2020
Vehicle Make:	OPEL
Vehicle Model:	ASTRA HB 1.4 AT
Primary Colour:	Green
Manufacturing Year:	2016
Engine No.:	B1162547GSGX0306
Chassis No.:	W0LBE6EC2HG018341
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$19,772.00
Original Registration Date:	23 Mar 2017
First Registration Date:	23 Mar 2017 ✓
Transfer Count:	0
Actual ARF Paid:	\$14,772.00 - 7386
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2027
PARF Rebate Amount:	\$11,079.00
Intended COE Rebate Details	
COE Expiry Date:	22 Mar 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,300.00
COE Rebate Amount:	\$37,926.00
Total Rebate Amount:	\$49,005.00

The information contained herein is correct as at 10 Feb 2020

OK