

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                               | Adj Submitted                                   | Ins Auth'ed | Status                                                          |
|------|-----------------------------------------|---------------|---------------------------------------------------|-------------------------------------------------------|-------------------------------------------------|-------------|-----------------------------------------------------------------|
| Main | 09 Feb 2020<br><a href="#">Edit Reg</a> |               | 07 Feb 2020 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$42,637.28</b><br><a href="#">Edit Estimates</a> | <b>S\$42,637.28</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | Reference | Claim Details                                                                            | Documents                             | <a href="#">Show All</a>                                   |         |             |              |            |       |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|------------------------------------------------------------------------------------------|---------------------------------------|------------------------------------------------------------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |           |                                                                                          | <a href="#">[Created by adjuster]</a> |                                                            |         |             |              |            |       |
| Insured: <b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |           |                                                                                          |                                       |                                                            |         |             |              |            |       |
| Main Claimant: <b>OH SZE HAI</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |           |                                                                                          |                                       |                                                            |         |             |              |            |       |
| Vehicle Reg. No.: <b>SLL7172K</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |           | Date of Loss: 03/02/2020 08:00 - :59<br>[9 Months and 9 Days From LTA Reg Date (Man Yr)] |                                       |                                                            |         |             |              |            |       |
| Claim Type: <b>TP / MCT20020023</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |           | Policy/Cover Note No.: MCOM0015                                                          |                                       |                                                            |         |             |              |            |       |
| Vehicle Reg. No. (Insured): <b>SHC8695G</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |           | Policy No. (Claimant): CN042646                                                          |                                       |                                                            |         |             |              |            |       |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |           | Excess:                                                                                  |                                       |                                                            |         |             |              |            |       |
| Repairer: <b>Tridente Automobili Pte Ltd (HQ)</b> 30 Leng Kee Road #01-02, 159100 Leng Kee - Tel: 64752168                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |           |                                                                                          |                                       |                                                            |         |             |              |            |       |
| Handling Insurer: <b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Priya</b> ]                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |           |                                                                                          |                                       |                                                            |         |             |              |            |       |
| Claimant's Insurer: <b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6880 4888                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |           |                                                                                          |                                       |                                                            |         |             |              |            |       |
| Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... <b>[Final Rpt due 18/02/2020]</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |           |                                                                                          |                                       |                                                            |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |           |                                                                                          |                                       | <a href="#">View All</a> <a href="#">Compose Case Mail</a> |         |             |              |            |       |
| <ul style="list-style-type: none"> <li>• III_SG (15/07/2020): <b>Alert - Adj Mandate Approved (S\$47879.35) - SLL7172K - Claim Handler: Priya</b></li> <li>• III_SG (09/07/2020): <b>Alert - Adj Mandate Maintained - SLL7172K - Claim Handler: Priya</b></li> <li>• III_SG (30/06/2020): <b>Alert - Adj Mandate Maintained - SLL7172K - Claim Handler: Priya</b></li> <li>• III_SG (29/06/2020): <b>Alert - Adj Mandate Maintained - SLL7172K - Claim Handler: Priya</b></li> <li>• III_SG (19/06/2020): <b>Alert - Adj Mandate Approved (S\$43317.14) - SLL7172K - Claim Handler: Priya</b></li> <li>• III_SG (10/06/2020): <b>Alert - Adj Mandate Approved (S\$43317.14) - SLL7172K - Claim Handler: Priya</b></li> <li>• III_SG (05/06/2020): <b>Alert - Adj Mandate Maintained - SLL7172K - Claim Handler: Priya</b></li> <li>• III_SG (03/06/2020): <b>Alert - Adj Mandate Maintained - SLL7172K - Claim Handler: Priya</b></li> <li>• III_SG (12/02/2020): <b>Alert - Adj Mandate Approved (S\$0.00) - SLL7172K - Claim Handler: Priya</b></li> </ul> |           |                                                                                          |                                       |                                                            |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |           |                                                                                          |                                       |                                                            |         |             |              |            |       |
| <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |           |                                                                                          |                                       |                                                            |         |             |              |            |       |
| Due Date                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | Priority  | Type                                                                                     | Task Group                            | Subject                                                    | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |           |                                                                                          |                                       |                                                            |         |             |              |            |       |



## Claim Documents

**\*SLL7172K (MCT20020023)**  
**[SHC8695G]**  
**TP**  
**OH SZE HAI**  
**Feb 3 2020 8:00AM**  
**[COMFORT TRANSPORTATION PTE LTD]**  
**Tridente Automobili Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View**
[View in Browser](#)

| Photos/Images |                 |                                   |  |           |       |
|---------------|-----------------|-----------------------------------|--|-----------|-------|
| 3 per page    |                 |                                   |  |           |       |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |  | Thumbnail | Print |
| 1             | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 2             | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 3             | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 4             | 10/02/20 08:15  | Chassis Number                    |  | Load JPG  |       |
| 5             | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 6             | 10/02/20 08:15  | Odometer Reading                  |  | Load JPG  |       |
| 7             | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 8             | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 9             | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 10            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 11            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 12            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 13            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 14            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 15            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 16            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 17            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 18            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 19            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 20            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 21            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 22            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 23            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 24            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 25            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 26            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 27            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 28            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 29            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 30            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 31            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 32            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 33            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 34            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 35            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 36            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 37            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 38            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 39            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |
| 40            | 10/02/20 08:15  | General View                      |  | Load JPG  |       |

| Photos/Images |                 |                                   |  |           | 3 per page                          | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-----------|-------------------------------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |  | Thumbnail | Print                               |                                     |
| 41            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 42            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 43            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 44            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 45            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 46            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 47            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 48            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 49            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 50            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 51            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 52            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 53            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 54            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 55            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 56            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 57            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 58            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 59            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 60            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 61            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 62            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 63            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 64            | 10/02/20 08:15  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 65            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 66            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 67            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 68            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 69            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 70            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 71            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 72            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 73            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 74            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 75            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 76            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 77            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 78            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 79            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 80            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 81            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 82            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 83            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 84            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 85            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 86            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 87            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 88            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 89            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 90            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 91            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 92            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 93            | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |

| Photos/Images |                 |                                   |                                                                                       | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|---------------------------------------------------------------------------------------|------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |                                                                                       | Thumbnail  | Print                               |
| 94            | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 95            | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 96            | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 97            | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 98            | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 99            | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 100           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 101           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 102           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 103           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 104           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 105           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 106           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 107           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 108           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 109           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 110           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 111           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 112           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 113           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 114           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 115           | 16/03/20 19:24  | Photographs of Damaged Parts      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 116           | 16/03/20 19:24  | Photographs of Damaged Parts      |   | Load JPG   | <input checked="" type="checkbox"/> |
| 117           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 118           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 119           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 120           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 121           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 122           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 123           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 124           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 125           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 126           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 127           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 128           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 129           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 130           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 131           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 132           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 133           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 134           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 135           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 136           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 137           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 138           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 139           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 140           | 16/03/20 19:24  | Photographs of Damaged Parts      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 141           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 142           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 143           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 144           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 145           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 146           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |

| Photos/Images |                 |                                   |                                                                                       | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|---------------------------------------------------------------------------------------|------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |                                                                                       | Thumbnail  | Print                               |
| 147           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 148           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 149           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 150           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 151           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 152           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 153           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 154           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 155           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 156           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 157           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 158           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 159           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 160           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 161           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 162           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 163           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 164           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 165           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 166           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 167           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 168           | 16/03/20 19:25  | Photographs of Damaged Items      |    | Load JPG   | <input checked="" type="checkbox"/> |
| 169           | 16/03/20 19:25  | Photographs of Damaged Items      |   | Load JPG   | <input checked="" type="checkbox"/> |
| 170           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 171           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 172           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 173           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 174           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 175           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 176           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 177           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 178           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 179           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 180           | 16/03/20 19:25  | Photographs of Damaged Items      |  | Load JPG   | <input checked="" type="checkbox"/> |
| 181           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 182           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 183           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 184           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 185           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 186           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 187           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 188           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 189           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 190           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 191           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 192           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 193           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 194           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 195           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 196           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 197           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 198           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |
| 199           | 16/03/20 19:25  | Reinspection Photo                |  | Load JPG   | <input checked="" type="checkbox"/> |

| Photos/Images |                 |                                            |  | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|--------------------------------------------|--|------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)          |  | Thumbnail  | Print                               |
| 200           | 16/03/20 19:25  | Reinspection Photo                         |  | Load JPG   | <input checked="" type="checkbox"/> |
| 201           | 16/03/20 19:25  | Reinspection Photo                         |  | Load JPG   | <input checked="" type="checkbox"/> |
| 202           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 203           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 204           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 205           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 206           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 207           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 208           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 209           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 210           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 211           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 212           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 213           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 214           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 215           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 216           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 217           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 218           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 219           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 220           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 221           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 222           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 223           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 224           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 225           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 226           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 227           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 228           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 229           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 230           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 231           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 232           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 233           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 234           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| 235           | 16/03/20 19:26  | Photographs after replacement              |  | Load JPG   | <input checked="" type="checkbox"/> |
| Documentation |                 |                                            |  | 1 per page | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)          |  | Thumbnail  | Print                               |
| 1             | 10/02/20 18:52  | TP ESTIMATE                                |  | Load PDF   |                                     |
| 2             | 10/02/20 18:52  | TP GIA REPORT                              |  | Load PDF   |                                     |
| 3             | 10/02/20 18:52  | EMAIL FROM III DD 07.02.2020               |  | Load PDF   |                                     |
| 4             | 16/02/20 22:56  | TP ESTIMATE - MARKED                       |  | Load PDF   |                                     |
| 5             | 29/05/20 15:33  | LOD AND OTHER DOCUMENTS                    |  | Load PDF   |                                     |
| 6             | 29/05/20 15:33  | LTA SEARCH INVOICE                         |  | Load PDF   |                                     |
| 7             | 05/08/20 09:22  | Authorisation to Act                       |  | Load PDF   |                                     |
| 8             | 05/08/20 09:22  | DISCHARGE VOUCHER                          |  | Load PDF   |                                     |
| 9             | 05/08/20 09:22  | LOD                                        |  | Load PDF   |                                     |
| 10            | 05/08/20 09:22  | WORKSHOP INVOICE                           |  | Load PDF   |                                     |
| No            | Finalized On    | India International Insurance Pte Ltd (HQ) |  | Thumbnail  | Print                               |
| 1             | 10/02/20 08:56  | Singapore Accident Statement               |  | Load PDF   |                                     |

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III20002219/EGA3S2**Date:** 05/08/2020REFERENCE

|                              |                                       |                             |             |
|------------------------------|---------------------------------------|-----------------------------|-------------|
| Handling Insurer:            | India International Insurance Pte Ltd | Policy No:                  | MCOM0015    |
| <b>Claimant Vehicle No :</b> | SLL7172K                              | <b>Insured Vehicle No :</b> | SHC8695G    |
| Date of Loss:                | 03/02/2020                            | Nature of Claim:            | TP          |
|                              |                                       | Claim No:                   | MCT20020023 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                     |             |                   |
|-----------------------------|-------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLL7172K</b>                     |             |                   |
| Make & Model:               | MASERATI LEVANTE DIESEL, 3.0 V6 (A) | Engine No:  | 443477            |
| Reg. Date:                  | 25/04/2019 (Man. Year: 2019)        | Chassis No: | ZN6XU61C00X329913 |
| Colour:                     | Grey                                | Odometer:   | 6349 km           |
| Engine Capacity:            | 2979 cc                             |             |                   |
| Market Value/New Car Price: | N/A                                 |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b>   |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |      |                         |     |                          |     |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes  | Engine Modification:    | No  | Pre-accident Condition:  |     |

CONDITION OF TYRES

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 235/50 R18 | Rear Tyre Size:  | 235/50 R18 |
| Front Left Side:  | Toyo 6 mm  | Rear Left Side:  | Toyo 6 mm  |
| Front Right Side: | Toyo 6 mm  | Rear Right Side: | Toyo 6 mm  |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                              | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|----------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                              | 36,705.48         | 22,557.28         | 14,148.20         | 38.55         |
| Miscellaneous Items                                | 0.00              | 0.00              | 0.00              |               |
| Labour                                             | 35,380.00         | 20,080.00         | 15,300.00         | 43.24         |
| Paintwork Labour                                   | 0.00              | 0.00              | 0.00              |               |
| Towing                                             | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (\$\$)</b>                          | <b>72,085.48</b>  | <b>42,637.28</b>  | <b>29,448.20</b>  | <b>40.85</b>  |
| <b>+ GST 7.00/7.00% (\$\$)</b>                     | 5,045.98          | 2,984.61          | 2,061.37          | 40.85         |
| <b>Nett Amount (\$\$)</b>                          | <b>77,131.46</b>  | <b>45,621.89</b>  | <b>31,509.57</b>  | <b>40.85</b>  |
| <b>+ Loss of Use (15.0 x S\$150.00/day) (\$\$)</b> |                   | 2,250.00          |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                     |                   | 7.45              |                   |               |
| <b>Nett Liability (\$\$)</b>                       |                   | <b>47,879.34</b>  |                   |               |

INSPECTION

|                             |            |               |                                                                                 |
|-----------------------------|------------|---------------|---------------------------------------------------------------------------------|
| Date of Assignment:         | 07/02/2020 |               |                                                                                 |
| Date Inspected:             | 07/02/2020 | Inspected At: | Tridente Automobili Pte Ltd (HQ)<br>30 Leng Kee Road #01-02<br>Singapore 159100 |
| Estimated Period of Repair: | 15.0 days  |               |                                                                                 |

**Adjuster:** CHEN TSUE YEE**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                      |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 05 Aug 2020)                        |
| <b>Parts:</b>        | M1-COUPÉ                                                                                                                                                                     | MASERATI LEVANTE DIESEL 3.0 V6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                    |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SLL7172K)                                                                                                                                    |                                                                      |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                      |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                      |

### Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition           | Repairer's   | Amount       |
|-----|-----|----------|----------------------------------|---------------------|--------------|--------------|
| 1   | 1   |          | *REAR BUMPER GRANSPORT / GTS     | Broken              | 3,183.00 FS  | *3,183.00 FS |
| 2   | 1   |          | *RH EXHAUST TERMINAL             | Bent                | 862.00 FS    | *862.00 FS   |
| 3   | 1   |          | *LH EXHAUST TERMINAL             | Bent                | 862.00 FS    | *862.00 FS   |
| 4   | 1   |          | *CENTRAL BRACKET                 | Deformed            | 111.00 FS    | *111.00 FS   |
| 5   | 1   |          | *RH BRACKET                      | Broken              | 83.00 FS     | *83.00 FS    |
| 6   | 1   |          | *LH BRACKET                      | Broken              | 83.00 FS     | *83.00 FS    |
| 7   | 8   |          | *SCREW                           | Necessary 4pcs Only | 31.20 FS     | *15.60 FS    |
| 8   | 4   |          | *BRACKET                         | Necessary 2pcs Only | 107.20 FS    | *53.60 FS    |
| 9   | 1   |          | *TOW HOOK PLUG                   | Cut                 | 57.40 FS     | *57.40 FS    |
| 10  | 1   |          | *DOOR                            | Missing             | 153.10 FS    | *153.10 FS   |
| 11  | 19  |          | *RIVET                           | Necessary           | 108.30 FS    | *108.30 FS   |
| 12  | 2   |          | *ENERGY ABSORBING UNIT           | Necessary           | 80.40 FS     | *80.40 FS    |
| 13  | 1   |          | *LEVANTE HFA SENSOR (LEG SENSOR) | Broken              | 648.70 FS    | *648.70 FS   |
| 14  | 1   |          | *RH SIDE LIFTGATE COVER          | Broken              | 145.50 FS    | *145.50 FS   |
| 15  | 3   |          | *SCREW                           | Necessary           | 11.70 FS     | *11.70 FS    |
| 16  | 3   |          | *BRACKET                         | Necessary           | 11.70 FS     | *11.70 FS    |
| 17  | 4   |          | *RADIAL PARKING SENSOR           | Shorted 3pcs Only   | 1,092.00 FS  | *819.00 FS   |
| 18  | 1   |          | *REAR BUMPER PARKING SENSOR B    | Cut                 | 291.00 FS    | *291.00 FS   |
| 19  | 4   |          | *SILICON RING                    | Necessary           | 61.20 FS     | *61.20 FS    |
| 20  | 14  |          | *SPECIAL NUT                     | Necessary           | 562.80 FS    | *562.80 FS   |
| 21  | 11  |          | *REAR AERODYNAMIC COVER          | Crushed             | 1,815.00 FS  | *1,815.00 FS |
| 22  | 1   |          | *STRAP UREA TANK                 | Bent                | 49.80 FS     | *49.80 FS    |
| 23  | 1   |          | *STRAP UREA TANK                 | Bent                | 49.80 FS     | *49.80 FS    |
| 24  | 16  |          | *FASTENING CLIP                  | Necessary           | 62.40 FS     | *62.40 FS    |
| 25  | 1   |          | *RH REAR WHEEL ARCH (PRIMERIZ)   | Necessary           | 1,195.00 FS  | *1,195.00 FS |
| 26  | 8   |          | *PIN                             | Necessary           | 31.20 FS     | *31.20 FS    |
| 27  | 4   |          | *WHEELHOUSE LINER ADHESIVE       | Necessary           | 23.20 FS     | *23.20 FS    |
| 28  | 10  |          | *ADHESIVE TAPE                   | Necessary           | 51.00 FS     | *51.00 FS    |
| 29  | 1   |          | *REAR RH MUFFLER RHD             | Bent                | 4,466.00 FS  | *4,466.00 FS |
| 30  | 1   |          | *RH REAR SILENCER SUPPORT        | Necessary           | 49.80 FS     | *49.80 FS    |
| 31  | 1   |          | *RH REAR BRACKET EXHAUST PIPE    | Necessary           | 61.30 FS     | *61.30 FS    |
| 32  | 1   |          | *RH BULKHEAD                     | Bent                | 99.00 FS     | *99.00 FS    |
| 33  | 1   |          | *RH BRACKET                      | Bent                | 44.80 FS     | *44.80 FS    |
| 34  | 2   |          | *SMALL BLOCK                     | Necessary           | 50.40 FS     | *50.40 FS    |
| 35  | 1   |          | *LOWER REAR GUARD ASSEMBLY       | Bent                | 950.00 FS    | *950.00 FS   |
| 36  | 1   |          | *REAR CROSS MEMBER ASSEMBLY      | Bent                | 124.30 FS    | *124.30 FS   |
| 37  | 1   |          | *LH REAR WHEEL ARCH (PRIMERIZ)   | Cracked             | 1,195.00 FS  | *1,195.00 FS |
| 38  | 1   |          | *BATTERY MULTI-FUNCTION ECU      | Shorted             | 205.68 FS    | *205.68 FS   |
| 39  | 1   |          | *TYRES PRESSURE CONTROL UNIT     | Cut                 | 238.00 FS    | *238.00 FS   |
| 40  | 2   |          | *NUT                             | Cracked             | 5.00 FS      | *5.00 FS     |
| 41  | 1   |          | *BRACKET SUPPORT ECU TPMS        | Bent                | 26.00 FS     | *26.00 FS    |
| 42  | 1   |          | *REAR WIRING HARNESS             | Repair              | 13,520.00 FS | *- FS        |
| 43  | 1   |          | *REAR NUMBER PLATE SLL7172K      | Necessary           | 50.00 FS     | *50.00 FS    |
| 44  | 1   |          | *SUNDRY ITEMS                    | Necessary           | 300.00 FS    | *150.00 FS   |
| 45  | 1   |          | *COMSUMABLES                     | Not Necessary       | 90.00 FS     | *- FS        |
| 46  | 1   |          | *R.H. FRT CUSHION FRAME          | Bent                | 2,573.20 FS  | *2,573.20 FS |

Report was unsubmitted during this print-out.

8/5/2020Adjuster Report

| No.                          | Qty | Part No. | Particulars                  | Condition     | Repairer's | Amount     |
|------------------------------|-----|----------|------------------------------|---------------|------------|------------|
| 47                           | 4   |          | *SCREW                       | Not Necessary | 46.00 FS   | *- FS      |
| 48                           | 1   |          | *REAR CRASH-BOX CROSS MEMBER | Bent          | 441.00 FS  | *441.00 FS |
| 49                           | 6   |          | *NUT                         | Necessary     | 12.00 FS   | *12.00 FS  |
| 50                           | 1   |          | *WHEEL COMPARTMENT CAP       | Necessary     | 14.60 FS   | *14.60 FS  |
| 51                           | 1   |          | *CPL BATTERY RACK            | Broken        | 228.00 FS  | *228.00 FS |
| 52                           | 1   |          | *RH REFLECTOR                | Broken        | 58.60 FS   | *58.60 FS  |
| 53                           | 4   |          | *SPECIAL SCREW               | Necessary     | 10.00 FS   | *10.00 FS  |
| 54                           | 4   |          | *RIVET                       | Necessary     | 23.20 FS   | *23.20 FS  |
| F=Franchise part. S=SpcNett. |     |          |                              |               |            |            |
| Total Parts (S\$)            |     |          |                              |               | 36,705.48  | 22,557.28  |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                | Lab.Type | Repairer's       | Amount           |
|---------------------------------|------------------------------------------------------------|----------|------------------|------------------|
| <b>Labour Items</b>             |                                                            |          |                  |                  |
| 1                               | CAT TOW-IN.                                                | New      | 150.00           | 150.00           |
| 2                               | REMOVE DAMAGED BODY PARTS AND REPLACE EFFECTED BODY PARTS. | New      | 19,800.00        | 11,880.00        |
| 3                               | TO SPRAY PAINT ON REAR 4 OUTER 2 INNER PANEL.              | New      | 7,800.00         | 5,200.00         |
| 4                               | TO ALIGN BODY SHELL AND JIG ANCHORAGE.                     | New      | 2,800.00         | 0.00             |
| 5                               | PERFORM WHEEL ALIGNMENT CHECK BEFORE REPAIR.               | New      | 495.00           | 0.00             |
| 6                               | TO CHECK AND CLEAR FAULT AFTER ACCIDENT REPAIR.            | New      | 1,200.00         | 1,200.00         |
| 7                               | TO CARRY OUT BODY CAVITY PRESERVATION.                     | New      | 990.00           | 330.00           |
| 8                               | TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER.              | New      | 660.00           | 330.00           |
| 9                               | REPLACE DRIVER SEAT CUSHION FRAME.                         | New      | 990.00           | 660.00           |
| 10                              | PERFORM WHEEL ALIGNMENT ADJUST AFTER REPAIR.               | New      | 495.00           | 330.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                            |          | <b>35,380.00</b> | <b>20,080.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >