



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/02/2020

User ID : KimBock

Section A - Accident Details

Registration Number	SMB1468M
Case Reference Number	BUS/01/20/5033
Registration Date	9/11/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Mohd Khairi Bin Mohd Nor
Type of Accident	Head To Side
Accident Date and Time	1/19/2020 4:30 PM
Accident Reported Date and Time	1/19/2020 5:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1468M-RIGHT REAR PORTION SKJ288D (TP) INSURED WITH MSIG
Prepared Date and Time	2/5/2020 1:36 PM
Chassis Number	WMAA22ZZ7E7002194
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$1,048.00	\$0.00
Total Spare Part Cost	\$3,428.96	\$0.00
Total Other Cost	\$1,440.00	\$0.00
TOTAL COST	\$8,036.96	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	05/02/2020 1:53 PM	
Signature	x	x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 05/02/2020

User ID : KimBock

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,120.00	1590.
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$1,048.00	708
Total Spray Painting & Panel Beating	\$1,048.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
ADVERTISEMENT STICKER	\$1,440.00	/
Total Other Costs	\$1,440.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010299	VE	88-25320-6008	LAMP, INDICATOR LED (MAN BUS)	1.00	\$1,274.10	0.00	\$1,274.10	Replace	/ CRA
6010298	VE	88-25225-6039	LAMP, STOP LED (MAN BUS)	1.00	\$1,141.70	0.00	\$1,141.70	Replace	/ CRU
6009988	BODY RH	A01001-CW567	PANEL, SIDE: R7, FOR MAN A22 BUS	1.00	\$885.50	0.00	\$885.50	Replace	/ DD
6009989	BODY RH	A01001-CW566	PANEL, SIDE: R8, FOR MAN A22 BUS	1.00	\$330.70	0.00	\$330.70	Replace	/ DD
6010330			WHEEL ARCH TRIM	1.00	\$124.20	0.00	\$124.20	Replace	/ BT
4006314	CONSUMABLE	SikaFlex-265	ADHESIVE: DIRECT GLAZING	10.00	\$37.00	0.00	\$370.00	Replace	/ NEC.
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	/ NEC
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	X SUR.
Total					\$3,953.20		\$4,286.20		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 3 days.

Lump Sum Repair.

After paint photo.

Sun Pin (LKK).

06/02/2020.

TP without prejudice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: