

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
GREAT AMERICAN INSURANCE COMPANY			Ref:	Ref : CS/GAI20002249/Asf3e2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date :	21-04-2020		
			Code :	GAI		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	GBJ 1427U		spected	SKM 8045U	
	Policy No.		Covera		0.00	
	Claim No.	CLMOMVC000003798	Excess	<u> </u>	0.00	
	Assign From	SHERY WONG	Assigr	n Date	10/02/2020	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ CLS 350	c.c		3498	
	Engine No.	HIDDEN	Year o	f Reg.	2011	
	Chassis No.	WDD2183592A028837	Colour	-	WHITE	
	Odometer	153700	Steerir	ng	IN ORDER	
	Brakes	IN ORDER	Modifie	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	255/35 R19	CONTIN	NENTAL	6 mm	
	L/H Front Tyre	255/35 R19	CONTIN	NENTAL	6 mm	
	R/H Rear Tyre	255/35 R19	CONTIN	NENTAL	6 mm	
	L/H Rear Tyre	255/35 R19	CONTIN	NENTAL	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	07/02/2020	Inspec	tion Date	12/02/2020	
	Survey held at	PREMIUM CARZ SERVICES PTE LTD				
		1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					