

NATIONAL Assessment Centre Services

[ver 1 Jan 03]

MMA 120018169

|                             |  |                           |               |
|-----------------------------|--|---------------------------|---------------|
| Date In: 10/2/20 14:03      | Job description                          | Date & Time Completed     | Done by       |
| Ref No: MAL/INC 20002252/hy | SAS e-filing                             |                           |               |
| Veh No: YM 9788L            | E-mail (within 2hrs, AIC 2hrs)           |                           |               |
| IP/A: 10/2/20 07:40         | I-Motor Claim Form                       | MT/1083821 <sup>001</sup> | 11/2/20 10:15 |
| ① TP Reporting Only         | I-Motor W/O (within: OD 2hrs, TP 4hrs)   |                           |               |
|                             | I-Photo Uploaded                         |                           |               |
|                             | Assessment/Survey Report                 |                           |               |
| TP Insurer:                 | Ass'l Report by Fax / Hand to Owner/Whse |                           |               |

|   |  |                       |
|---|--|-----------------------|
| Preferred Wksp / INC Assgn Wksp / QW: ( ) | Tel: ( )   | Fax: ( )              |
| TP Particulars:                           | Veh No: Unknown  | INC ( ) / Non-INC ( ) |
| Owner / Driver: ( )                       | Tel: ( )   |                       |
| Policy No: ( )                            | Period: ( )  | Cover Type: ( )       |
| Confirmed by: ( )                         | Date: ( )  | Time: ( )             |
| Insured/Driver Liability: ( ) %           | [Note-Est. Status (WO): N: 0-20%; P: 21-79%; P: 80-100%] |                       |
| Year of Registration: ( )                 | Warranty: YES ( ) / NO ( )                               |                       |
| Excess: (\$ )                             | Loading: \$1,000 ( ) / \$2,000 ( )                       |                       |

General Remarks:

( ) Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repairer.

( ) Total Loss Case: to e-mail Insurer URGENTLY.

Drive-In ( ) / Towed-In ( ); Invoice: YES ( ) / NO ( ); Towing Co: ( )

|   |         |
|---|---------|
| Comments: (INC/Non-INC/Other)                           | Done by |
| 1) Apply for Transport Allowance ( ) / Courtesy Car ( ) |         |
| 2) QC Check / Post Repair Inspection ( )                |         |
| 3) Upload Resurvey Photo [Repair Cost > \$3000] ( )     |         |

Injury: \_\_\_\_\_

| Date/Time | Action |
|-----------|--------|
|           |        |
|           |        |
|           |        |
|           |        |
|           |        |

|                                 |   |             |
|---------------------------------|---|-------------|
| MA 2001831                      |   |             |
| Claimant's Particulars:         | 1) All: Accident Reporting (\$30)               | 30.00       |
| Driver/Owner:                   | 2) DA: Damage Assessment (\$100); INC (\$50)    | 150.00      |
| Contact No:                     | 3) TP: Towing Fee \$40/\$45                     |             |
| Damaged Portion:                | 4) FT: Follow-Through Survey \$120              |             |
| QC Checked by (Bugr-In-Charge): | 5) FT: Follow-Through Survey (Resurvey) \$30    |             |
| Auditors Comments:              | For claiming against INC Only (ver 10 Jan 2003) |             |
|                                 | 6) TR: Re-inspection \$75                       |             |
|                                 | 7) NI: Idao DA + SMRT Survey \$160              |             |
|                                 | 8) NTUC Additional Services:                    |             |
|                                 | Q1:   |             |
|                                 | *NS: Courtesy Car / Tpt Allowance \$5           |             |
|                                 | *NG: Repair Co-ordination \$10                  | 10.00       |
|                                 | *NP: Post Repair Inspection \$25                |             |
|                                 | *NI: DV / Collect Excess Coordination \$5       |             |
|                                 | TP (N11): TP (Non INC) against INC \$20         |             |
|                                 | 9) N12: Idao Mobile \$0                         |             |
|                                 | Invoice dated                                   | Fee Charged |
|                                 | Invoice dated                                   | Fee Charged |

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                   |
|----------------------------|-----------------------------------|
| Date Of Report             | 10/02/2020 14:03                  |
| Date Of Accident           | 10/02/2020 07:40                  |
| Exact Location Of Accident | BEDOK INDUSTRIAL PARK E (LOT 132) |
| Country/State of Loss      | SINGAPORE                         |

### DETAILS OF OWN VEHICLE

|                             |                         |
|-----------------------------|-------------------------|
| Vehicle Registration Number | YM9788L                 |
| <b>Insured/Policyholder</b> |                         |
| Name Of Registered Owner    | CHYE HENG ORCHID GARDEN |
| Co Reg No                   | 0XXXX700W               |
| Email Address               | NOEMAIL                 |
| Mobile Phone No             |                         |
| Alternative Phone No        | OFFICE-64490585         |

### Vehicle Particulars

|  |                           |
|--|---------------------------|
| Manufacturer   | MITSUBISHI                |
| Model  | CANTER FEB21ER3SDEB (CBU) |
| Exact Purpose for which vehicle was being used at time of accident           | PARKED                    |
| Are you claiming under your own insurance policy for repair to your vehicle? | YES                       |
| If No, Please state action to be taken                                       |                           |
| Vehicle Category   | COMMERCIAL VEHICLE        |

### Insurance Company

|                           |  |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage          | COMPREHENSIVE                          |
| Fleet Policy              | NO                                     |
| Policy Number             | 5067797321-05                          |
| Cover Note Number         |  |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | TEO HAN KEONG         |
| NRIC No              | SXXXX209G             |
| Date Of Birth        | 19/11/1971            |
| Occupation           | OUTDOOR               |
| Date Of Driving Pass | 05/08/1989            |
| Driving Experience   | 30 YEARS AND 6 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-97769788  |
| Fax Number           |                       |
| Contact Number       |                       |
| EMail Address        | NOEMAIL               |

|   |                             |
|---|-----------------------------|
| Address   | BLK 29 CHAI CHEE AVE #14-84 |
| Postcode  | 460029                      |
| Was driver an employee of the Insured's Company     | NO                          |
| If No, Relationship of the Driver with the Insured  | OWNER                       |
| Vehicle Registration Number of Driver's Own Vehicle | -                           |
|   | -                           |
|   | -                           |
| Insurance Company of Driver's Own Vehicle           | -                           |
|   | -                           |
|   | -                           |

### General Information of the Accident

|                    |   |
|--------------------|---|
| Type Of Accident   | HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED |
| Weather Conditions | CLEAR   |
| Road Surface       | DRY   |

### Other Information

|   |     |
|---|-----|
| Was any foreign vehicle involved in this accident?  | NO  |
| Number of vehicles (including own vehicle) involved in the accident                         | 1   |
| Was any body injured in the Accident?   | NO  |
| Was any injured conveyed to hospital by ambulance?  |     |
| Was any other material or property damaged?   | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO  |
| Number of Passengers (Including Driver)   | 0   |

### Details of Police Action

|   |  |
|---|--|
| Was the accident reported to the police?  | YES  |
| If Yes, Please state which Police Station |  |
| Police Station Name                       | BEDOK POLICE DIVISIONAL HQ (G DIVISION)  |
| Police Station Address                    | <b>ROAD:</b> 30 BEDOK NORTH ROAD , <b>POSTCODE:</b> 469676 , <b>COUNTRY:</b> SINGAPORE |
| Police Station Contact                    | <b>TEL NO:</b> 1800-2440000 - <b>FAX NO:</b> 64443009                                  |
| Was notice of intended Prosecution given? | NO   |
| If Yes, against whom?                     |  |

### Circumstances of Accident

REFER TO POLICE REPORT G/20200210/7012

### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |                  |
|-----------------------------|------------------|
| Vehicle Registration Number | UNKNOWN          |
| Vehicle Make/Model/Colour   |                  |
| Details Of Properties       |                  |
| Vehicle Category            | MOBILE EQUIPMENT |
| Name of Driver              |                  |
| NRIC/Passport Number        |                  |
| Contact Number              |                  |
| Address                     |                  |
| Postcode                    |                  |
| Insurance Company Name      |                  |
| Nature Of Damage            |                  |

No. Of Passenger (Including Driver)

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**POLICE REPORT (NP299)**

Report No. G/20200210/7012

Police Station Of Origin  
Bedok Division HQ  
30 Bedok North Road SINGAPORE 469676  
Tel No:1800-2440000

|  |   |                     |
|--|---|---------------------|
| Date/Time Report Made<br>10/02/2020 09:47                    | Vide Report No.   | Station Diary No.   |
| Name Of Informant<br>TEO HAN KEONG                           | Address<br>APT BLK 29 CHAI CHEE AVENUE #14-84 SINGAPORE<br>460029 |                     |
| ID Type / ID No.<br>NRIC NO / S7142209G                      | Contact No.<br>Home/Office:                                       | Mobile:<br>97769788 |
| Nationality<br>SINGAPORE CITIZEN                             | Email Address<br>shaneteo@singnet.com.sg                          |                     |
| Occupation<br>Flower/Orchid farm worker                      | Sex<br>Male   | Age<br>48           |
| Institution/School Name                                      | Date of Birth<br>19/11/1971                                       | Race<br>Chinese     |
| Date/Time Of Incident<br>10/02/2020 03:00 - 10/02/2020 07:40 | Location Of Incident<br>BEDOK NORTH AVENUE 4                      |                     |

**Brief details.**

on 10/02/2020 @3am, parked lorry YM9788L at Carpark Bedok industrial Park E(Lot132) manage by G.Tech Pte Ltd...is a carpark for season parking only. Return to collect lorry on 10/02/2020 @7.40am, found out that the lorry front at driver side damage. The wind screen is cracked, side mirror broken, the light drop off and the front bumper damage. the driver side door not able to close and the accelerator is jam due to the hit. The lorry not able to move. No valuable was lost.

| <b>Subjects Involved</b>                                     |  |
|--|--|
| Signature Of Officer Recording The Report:<br>Not applicable | Signature Of Informant:<br>The identity of the person making this report has been authenticated by SingPass. No signature is required. |
| Signature Of Interpreter:<br>Not applicable                  | Date/Time:<br>10/02/2020 09:47   |
| Officer In-Charge Of Case:                                   | Classification Of Case:  |

Authentication Stamp



**POLICE REPORT (NP299)**

**CONTINUATION OF REPORT**

Report No. G/20200210/7012

| Victim                    |   |              |           |
|---------------------------|---|--------------|-----------|
| Person Name               | TEO HAN KEONG   |              |           |
| ID Type                   | NRIC NO   | ID No        | S7142209G |
| Gender                    | Male  | Age          | 48        |
| Race                      | Chinese   | Language     | English   |
| Occupation                | Flower/Orchid farm worker                                 | Address Type |           |
| Address                   | APT BLK 29 CHAI CHEE<br>AVENUE #14-84 SINGAPORE<br>460029 | Mobile No    | 97769788  |
| Is Informant A<br>Victim? | Yes   |              |           |
| Person Name               | TEO HAN KEONG (Informant)                                 |              |           |

|  |  |
|--|--|
| Signature Of Officer Recording The Report:<br>Not applicable | Signature Of Informant:<br>The identity of the person making this report has been authenticated by SingPass. No signature is required. |
| Signature Of Interpreter:<br>Not applicable                  | Date/Time:<br>10/02/2020 09:47   |
| Officer In-Charge Of Case:                                   | Classification Of Case:  |

Authentication Stamp

### Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
 MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number :** 5067797321-05

**Cover :** Comprehensive

- |  |                           |
|--|---------------------------|
| 1. Index mark and Registration Number of Vehicle   | : <b>YM9788L</b>          |
| Chassis Number   | : FEB21EA00918            |
| 2. Name of Policyholder  | : CHYE HENG ORCHID GARDEN |
| 3. Effective Date of Insurance   | : 02 Oct 2019             |
| 4. Expiry Date of Insurance  | : 01 Oct 2020             |
| 5. Persons or Classes of Persons entitled to drive#  |                           |
| (a) The Policyholder.  |                           |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission.<br>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. |                           |
| 6. Limitations as to Use#  |                           |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.  |                           |
| (b) Use for the carriage of passengers or goods in connection with the Policyholder's business.  |                           |

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

|                       |   |
|-----------------------|---|
| EXCESS (SECTION 1)    | : S\$600  |
| EXCESS (SECTION 2)    | : N/A   |
| WINDSCREEN EXCESS     | : S\$100  |
| INSURE WITH COE       | : YES   |
| HIRE PURCHASE COMPANY | : UNITED OVERSEAS BANK LIMITED                    |
| SUM INSURED           | : MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS |

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : REV AUTO PTE LTD (00000571335)

Date of Issue : 20 Sep 2019 00:46 hrs

**For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED**



Countersigned By:

\_\_\_\_\_  
 Authorised Officer



\_\_\_\_\_  
 Chief Executive

Claim Handling

Accident MT/1083821

|                     |   |                     |   |                      |           |
|---------------------|---|---------------------|---|----------------------|-----------|
| Policy No.          | 5067797321-05   | Vehicle No.         | YM9788L   | GST Registration No. |           |
| Certificate No.     |   |                     |   |                      |           |
| Policyholder Name   | CHYE HENG ORCHID GARDEN                                       | Cover Type          | Comprehensive   | Policyholder NRIC    | 07435700W |
| Product Code        | COMMERCIAL VEHICLE INSURAF                                    | Contact No.(Office) |   | Loading              | 0         |
| Contact No.(Mobile) | 64490585  | Special Remark      |   | Contact No.(Home)    |           |
| Email Address       |   | TCA                 | <input checked="" type="radio"/> No <input type="radio"/> Yes | eCode                | No        |
| KFK                 | <input checked="" type="radio"/> No <input type="radio"/> Yes | NCD Entitlement(%)  | 20  | eCode Reason         |           |
| NCD Protection      | No  |                     |   | Private Hire         | No        |

Accident Details

|                   |                                   |                               |       |                     |             |
|-------------------|-----------------------------------|-------------------------------|-------|---------------------|-------------|
| Report Date       | 11/02/2020 10:06                  | Accident Report Within 24 hrs | Yes   | Accident Type       | HIT and run |
| Date of Accident  | 16/02/2020                        | Time of Accident hh:mm        | 07:40 | Country of Accident | Singapore   |
| Reporting Centre  |                                   | Orange Force                  |       | ICM No.             |             |
| Accident Location | BEDOK INDUSTRIAL PARK E (LOT 132) |                               |       |                     |             |

Total Excess Applicable

|                            |              |                            |        |                    |         |
|----------------------------|--------------|----------------------------|--------|--------------------|---------|
| Excess Type                | Per Accident | Windscreen Excess          | 100.00 | Driver is Covered? | Covered |
| OD Standard Excess         | 600.00       | TP Standard Excess         | 0.00   |                    |         |
| YIED OD Excess             | 0.00         | YIED TP Excess             | 0.00   |                    |         |
| Additional Excess          |              |                            |        |                    |         |
| Total OD Excess Applicable | 600.00       | Total TP Excess Applicable | 0.00   |                    |         |

Benefits

GST Registered Information

|                      |   |                       |     |
|----------------------|---|-----------------------|-----|
| GST Registered       | No  | GST Registration Date |     |
| GST Registration No. |   | GST Status Verified   | Yes |
| Modification History | 11/02/2020 10:10:53 System changed GST Status Verified from No to Yes |                       |     |

Policyholder Mailing Address

|           |               |                       |                   |           |                  |
|-----------|---------------|-----------------------|-------------------|-----------|------------------|
| Address 1 | BLK 29 #14-84 | Address 2             | CHAI CHEE AVENUE  | Address 3 | SINGAPORE 460029 |
| Address 4 |               | Address Type          | Singapore address | Post Code | 460029           |
| Unit No.  |               | Related Policy Number | 5041148999-10     |           |                  |

OI Driver Info

|   |   |                     |                   |                        |                  |
|---|---|---------------------|-------------------|------------------------|------------------|
| Driver Name                             | Unnamed Driver  | Driver Type         | Unnamed Driver    | Driver DOB             | 19/11/1971       |
| Unnamed driver Name                     | TEO HAN KEONG   | Driver NRIC         | SXXXX209G         | Driving Experience     | 30               |
| Register Date of Driver License         | 05/08/1989  | Driver Age          | 48                | Contact No.(Home)      |                  |
| Contact No.(Mobile)                     | 97769788  | Contact No.(Office) |                   | Address 3              | SINGAPORE 460029 |
| Address 1                               | BLK 29 #14-84   | Address 2           | CHAI CHEE AVENUE  | Post Code              | 460029           |
| Address 4                               |   | Address Type        | Singapore address |                        |                  |
| Unit No.                                | 14-84   |                     |                   |                        |                  |
| Does he own a Singapore Registered car? | <input type="radio"/> Yes <input checked="" type="radio"/> No | Driver Vehicle No.  |                   | Driver Insurer Company |                  |

Declaration

|                                     |      |             |   |
|-------------------------------------|------|-------------|---|
| Breathalyser or Blood Test Reading? | 0 mg | Any injury? | <input checked="" type="radio"/> Yes <input type="radio"/> No |
|-------------------------------------|------|-------------|---|

Modification History

Claim 001 New

|   |                                  |                   |                           |                                 |                  |
|---|----------------------------------|-------------------|---------------------------|---------------------------------|------------------|
| Claim Type *  | OD-MD                            | Insured Name      | CHYE HENG ORCHID GARDEN   | Insured NRIC                    | 07435700W        |
| Contact No.(Mobile)                                 |                                  | Contact No.(Home) |                           | Contact No.(Office)             | 64490585         |
| Email Address                                       |                                  | OI Vehicle Number | YM9788L                   | TP Vehicle Number               | UNKN             |
| Claim Description                                   | YM9788L / UNKNOWN ON 10 Feb 2020 |                   |                           |                                 |                  |
| Preferred Workshop                                  | 0                                | Insured Liability | Not at Fault              | GIA report                      | Received         |
| Workshop Finalisation                               | Yes                              | Repair Option     | Income to assign workshop | Claim Close Date                | 11/02/2020 10:14 |
| Date Registered                                     |                                  | Report Taken By   | LIEW SHAN HUI             | Date Received                   | 11/02/2020       |
| <input checked="" type="checkbox"/> Print AK letter |                                  |                   |                           | OD Excess Collected by Workshop |                  |

Save Submit

Attachment

|                            |   |             |                  |
|----------------------------|---|-------------|------------------|
| Accident No.               | MT/1083821  | Claim No.   | 001              |
| Last Doc. Received         | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | Upload Date | 11/02/2020 10:15 |
| Path *                     |   | Category *  |                  |
| Choose File No file chosen |   | Clear       | Please Select    |
| Choose File No file chosen |   | Clear       | Please Select    |
| Choose File No file chosen |   | Clear       | Please Select    |
| Choose File No file chosen |   | Clear       | Please Select    |
| Choose File No file chosen |   | Clear       | Please Select    |
| Choose File No file chosen |   | Clear       | Please Select    |
| Message Read               |   | Clear       | Please Select    |

Attachment List

| Attachment | Uploaded By/Date   | Category              |   | Urgency | Description                     |
|------------|--|-----------------------|---|---------|---------------------------------|
|            | NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o<br>11 Feb 2020 10:15 | NRIC/ Driving License | Y | Normal  | NRIC/ Driving License 2020-2-11 |
|            | NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o<br>11 Feb 2020 10:15 | SAS                   |   | Normal  | SAS 2020-2-11                   |
|            | NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o<br>11 Feb 2020 10:15 | Photos                |   | Normal  | Photos 2020-2-11                |
|            | NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o<br>11 Feb 2020 10:15 | Photos                |   | Normal  | Photos 2020-2-11                |
|            | NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o<br>11 Feb 2020 10:14 | Photos                |   | Normal  | Photos 2020-2-11                |
|            | NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o<br>11 Feb 2020 10:14 | Photos                |   | Normal  | Photos 2020-2-11                |
|            | NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o<br>11 Feb 2020 10:14 | Photos                |   | Normal  | Photos 2020-2-11                |
|            | NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o<br>11 Feb 2020 10:14 | Photos                |   | Normal  | Photos 2020-2-11                |
|            | NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o<br>11 Feb 2020 10:14 | Photos                |   | Normal  | Photos 2020-2-11                |
|            | NAC_PAYA_UBI_800601( NATIONAL ASSESSMENT CENTRE SERVICES) o<br>11 Feb 2020 10:14 | Photos                |   | Normal  | Photos 2020-2-11                |

Video List

| Uploaded By/Date | Folder Date | File Name |  | Source |
|------------------|-------------|-----------|--|--------|
|------------------|-------------|-----------|--|--------|

ASSIGNMENT NO (40/14)

- By CSO - Nature of Accident:
- 1) Vehicle hit Vehicle:
    - a) Motorist ( )
    - b) Pedestrian ( )
    - c) Bicycle ( )
    - d) Animal ( )
  - 2) Vehicle hit Road Side Object:
    - a) Govt Property ( )
    - b) Road Work Object ( )
    - c) Private Property ( )
  - 3) Vehicle drop into drain ( )
  - 4) Damage due to Act of God:
    - a) Fallen Object ( )
    - b) Flood ( )
    - c) Other ( )
  - 5) Parked & Found Damaged:
    - a) Vandalism ( )
    - b) Hit by Moving Object ( )
  - 6) Theft Case:
    - a) Stolen ( )
    - b) Damage found when recovered ( )
  - 7) Fire:
    - a) Whilst driving ( )
    - b) Parked ( )
  - 8) Accident date more than 24hrs ( )

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss: ( )
- 2) SRS Light on ( )
- 3) ABS Light on ( )

By Assessor - 1) Vehicle Information

Vehicle: **YM 9188 L** (Year) **2 Oct 2014**

Type: M/Car / M/Cycle / Bus / Van / **Truck** / Light / Heavy Motor / etc.

Make: **Mitsubishi Canter FEB21**

Color: **White** Insurance Type: **Auto (Planned)** No: **2998**

Engine: **FEB21EA00918** Sp/Reading: **139901**

Gen Cond: **Good** (Fair / Poor / Burnt / etc)

Steering: **None** / Jammed / Leaked / Burnt / etc

Brake: **None** / Jammed / Leaked / Burnt / etc

Mod: **Nil** / S/Rim / STD / R/Rim / etc

Tyre Size: F: **195/85 R15**

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO

|       |          |    |       |            |    |
|-------|----------|----|-------|------------|----|
| Front | <b>6</b> | mm | Rear  | <b>6/6</b> | mm |
| R/Bal |          | mm | P/Bal | <b>6/6</b> | mm |
| L/Bal | <b>6</b> | mm | L/Bal | <b>6/6</b> | mm |

Parallel Import: Yes / **No**

Repair Type: **LS** / LBJ

No of Repair Days: **7**

D.O.I: **10/10/2020**

Towed-In: Yes / No

Towing Required: **Yes** / No

Vehicle in Use: **Yes** / No

Time: **4:20pm**

By Assessor - 2) Comments

- 1) Damages not due to recent accident
- 2) Damages do not seem hit onto:
  - a. Vehicle ( ) b. Motorcycle ( ) c. Bicycle ( ) d. Pedestrian ( )
  - e. Animal ( ) f. Govt Object ( ) g. Road Work Object ( )
  - h. Private Property ( ) i. Drain ( ) j. Road Kerb/Grass Veng ( )
- 3) Vehicle does not seem damaged as a result of:
  - a. Fallen Object ( ) b. Flood ( ) c. Vandalism ( ) d. Fire ( )
  - e. Moving Object ( ) f. Stolen ( ) g. Stolen & Recovered ( )

| Time Started                         | Time Completed |
|--------------------------------------|----------------|
| 1) CSO                               |                |
| 2) ASO                               |                |
| 3) Initial Inspection completed Date |                |

**VAN / LORRY (Fr)**

Vehicle No: **YM 9788L**

**Front Portion**

| NAC  | INC    | Item                          | CON  | AC | Qty |
|------|--------|-------------------------------|------|----|-----|
| 1001 | 991886 | Fr Number Plate               | BT   | ✓  | /   |
| 1002 | 991887 | Fr Number Plate Base          |      |    |     |
| 1004 | 991300 | Fr Bumper                     | BT   | ✓  | /   |
| 2001 | 991477 | Fr Bumper Upper               |      |    |     |
| 2002 | 991387 | Fr Bumper Lower               |      |    |     |
| 2003 | 991449 | Fr Bumper Side Cover          |      |    |     |
| 2004 | 991443 | Fr Bumper Side Pad RH         | DIS  | ✓  | /   |
| 1006 | 991325 | Fr Bumper Bracket             |      |    |     |
| 1008 | 991433 | Fr Bumper Reinforcement       |      |    |     |
| 2005 | 991466 | Fr Bumper Signal Lamp         |      |    |     |
| 1017 | 995100 | Fr LH Bumper Fog Lamp Cover   |      |    |     |
| 1018 | 991355 | Fr RH Bumper Fog Lamp Cover   |      |    |     |
| 1019 | 995079 | Fr LH Bumper Fog Lamp         |      |    |     |
| 1020 | 995080 | Fr RH Bumper Fog Lamp         |      |    |     |
| 1021 | 991793 | Fr Grille                     | DIS  | ✓  | /   |
| 1022 | 991328 | Fr Grille Emblem              | REC  | ✓  | /   |
| 2006 | 990247 | Fr Grille Sticker             |      |    |     |
| 1023 | 991799 | Fr Grille Chrome Moulding     |      |    |     |
| 2007 | 991891 | Fr Panel                      |      |    |     |
| 2008 | 991874 | Fr Lower Panel                |      |    |     |
| 2009 | 991328 | Fr Panel Emblem               |      |    |     |
| 2010 | 990247 | Fr Panel Sticker              |      |    |     |
| 2011 | 991893 | Fr Panel Garnish              |      |    |     |
| 1024 | 991222 | Fr Apron Panel                |      |    |     |
| 2012 | 991527 | Fr Corner Panel RH            | DD   | ✓  | /   |
| 2013 | 991532 | Fr Corner Panel Signal Lamp   |      |    |     |
| 2014 | 995245 | Fr Signal Lamp LH             |      |    |     |
| 2015 | 995246 | Fr Signal Lamp RH             | MIS  | ✓  | /   |
| 1029 | 995153 | Fr LH Headlamp Assy           |      |    |     |
| 1030 | 991821 | Fr RH Headlamp Assy           | BR   | ✓  | /   |
| 1031 | 995088 | Fr LH Side Lamp               |      |    |     |
| 1032 | 995089 | Fr RH Side Lamp               |      |    |     |
| 2016 | 992749 | Fr Wiper Panel                |      |    |     |
| 2017 | 995043 | Fr Wiper Nozzle               |      |    |     |
| 1120 | 992140 | Fr Wiper Arm                  |      |    |     |
| 1121 | 992142 | Fr Wiper Blade                |      |    |     |
| 2018 | 992145 | Fr Wiper Link                 |      |    |     |
| 2019 | 992148 | Fr Wiper Motor                |      |    |     |
| 1122 | 995045 | Wiper Panel Garnish           |      |    |     |
| 1114 | 992093 | Fr Windscreen                 | ORA  | ✓  | /   |
| 1115 | 992097 | Fr Windscreen Rubber          | CUT  | ✓  | /   |
| 1117 | 992098 | Fr Windscreen Sealant         |      |    |     |
| 2020 | 992114 | Fr Windscreen Outer Pillar RH | DD R | ✓  | /   |
| 2021 | 992113 | Fr Windscreen Inner Pillar    |      |    |     |
| 1118 | 991019 | ERP Bracket                   |      |    |     |
| 1119 | 991020 | ERP Unit                      |      |    |     |
| 2022 | 991958 | Fr Side Mirror (Big)          | ORA  | ✓  | /   |
| 2023 | 991959 | Fr Side Mirror (Small)        |      |    |     |
| 2024 | 991962 | Fr Side Mirror (Round)        |      |    |     |
| 2025 | 995015 | Fr Wing Mirror Stay           | ORA  | ✓  | /   |
| 1025 | 992013 | Fr Support Panel              |      |    |     |
| 1033 | 990248 | Bonnet                        |      |    |     |
| 1035 | 990287 | Bonnet Lock                   |      |    |     |
| 1037 | 990273 | Bonnet Hinge                  |      |    |     |
| 1039 | 990305 | Bonnet Rubber                 |      |    |     |
| 1042 | 990119 | Air Con Condenser             |      |    |     |
| 1043 | 990122 | Air Con Fan Assy              |      |    |     |
| 1048 | 990149 | Air Con Liquid Pipe           |      |    |     |
| 1049 | 995066 | Air Con Receiver Drier        |      |    |     |
| 1052 | 995074 | Radiator                      |      |    |     |
| 1053 | 992738 | Radiator Cowling              |      |    |     |
| 1054 | 992742 | Radiator Fan Assy             |      |    |     |
| 1056 | 992758 | Radiator Hose Top             |      |    |     |
| 1058 | 992741 | Radiator Expansion Tank       |      |    |     |
| 2026 | 992596 | Oil Cooler                    |      |    |     |
| 1079 | 994431 | Power Steering Cooler Pipe    |      |    |     |
| 1059 | 990151 | Air Duct                      |      |    |     |
| 1060 | 990070 | Air Cleaner Assy              |      |    |     |
| 1067 | 990219 | Battery                       |      |    |     |
| 1069 | 990223 | Battery Bracket               |      |    |     |

| NAC  | INC    | Item                             | CON | AC  | Qty |
|------|--------|----------------------------------|-----|-----|-----|
| 1085 | 991011 | Engine Under Cover               |     |     |     |
| 1086 | 990946 | Engine Mounting                  |     |     |     |
| 2027 | 991500 | Fr Cabin Assy                    |     |     |     |
| 2028 | 991501 | Fr Cabin Mounting                |     |     |     |
| 2029 | 991502 | Fr Cabin Rear Panel              |     |     |     |
| 1092 | 991520 | Fr LH Chassis Member             |     |     |     |
| 1093 | 991520 | Fr RH Chassis Member             |     |     |     |
| 1094 | 990728 | Fr Vertical Cross Member         |     |     |     |
| 1095 | 991863 | Fr Lower Cross Member            |     |     |     |
| 2030 | 990143 | Air Con Evaporator Assy          |     | ?   | /   |
| 2031 | 990106 | Air Con Blower                   |     | ?   | /   |
| 1082 | 990427 | Brake Master Pump Assy           |     |     |     |
| 1083 | 990403 | Brake Booster Pump Assy          |     |     |     |
| 2032 | 990431 | Brake Pedal                      |     |     |     |
| 2033 | 990021 | Accelerator Pedal                |     | ?   | /   |
| 2034 | 990627 | Clutch Pedal                     |     |     |     |
| 1127 | 994483 | Steering Wheel Airbag            |     |     |     |
| 1128 | 994485 | Steering Wheel Airbag Sensor     |     |     |     |
| 1131 | 990029 | Airbag Control Unit              |     |     |     |
| 1133 | 991922 | Fr RH Seat Belt Assy             |     |     |     |
| 1135 | 995182 | Fr LH Seat Belt Assy             |     |     |     |
| 1124 | 990753 | Dashboard Assy                   |     | ?   | /   |
| 1125 | 992282 | Glove Box Cover                  |     |     |     |
| 1126 | 992281 | Glove Box Compartment            |     |     |     |
| 1096 | 995070 | Fr LH Fender                     |     |     |     |
| 1097 | 995072 | Fr LH Fender Inner Panel         |     |     |     |
| 1100 | 991740 | Fr LH Fender Inner Shield        |     |     |     |
| 1101 | 995179 | Fr LH Mudflap                    |     |     |     |
| 2035 | 994966 | Fr LH Wheel Guard                |     |     |     |
| 1102 | 995170 | Fr LH Wheel Rim                  |     |     |     |
| 1104 | 995065 | Fr LH Tyre                       |     |     |     |
| 1105 | 995071 | Fr RH Fender                     |     |     |     |
| 1106 | 991739 | Fr RH Fender Inner Panel         |     |     |     |
| 1109 | 991740 | Fr RH Fender Inner Shield        |     |     |     |
| 1110 | 991884 | Fr RH Mudflap                    |     |     |     |
| 2036 | 994966 | Fr RH Wheel Guard                |     |     |     |
| 1111 | 992087 | Fr RH Wheel Rim                  |     |     |     |
| 1113 | 995065 | Fr RH Tyre                       |     |     |     |
| 1255 | 995326 | Fr LH Door                       |     |     |     |
| 1256 | 995140 | Fr LH Door Protector             |     |     |     |
| 1257 | 995104 | Fr LH Door Hinge                 |     |     |     |
| 1258 | 995142 | Fr LH Door Wing Mirror           |     |     |     |
| 1262 | 995103 | Fr LH Door Glass                 |     |     |     |
| 1263 | 991595 | Fr LH Door Glass Regulator       |     |     |     |
| 1264 | 991596 | Fr LH Door Glass Regulator Motor |     |     |     |
| 1265 | 991662 | Fr LH Door Rubber                |     |     |     |
| 1266 | 991636 | Fr LH Door Outer Handle          |     |     |     |
| 1272 | 991617 | Fr LH Door Inner Trim Board      |     |     |     |
| 1316 | 995327 | Fr RH Door                       |     | DD  | /   |
| 1317 | 991654 | Fr RH Door Entrance Garnish      |     | ORA | /   |
| 1318 | 991601 | Fr RH Door Hinge                 |     | ?   | /   |
| 1319 | 991685 | Fr RH Door Wing Mirror           |     | ?   | /   |
| 1323 | 991584 | Fr RH Door Lock                  |     | CUT | /   |
| 1324 | 991595 | Fr RH Door Edge Protector        |     | DIS | /   |
| 1325 | 991596 | Fr RH Door C...                  |     | OR  | /   |
| 1326 | 991662 | Fr RH Door Rubber                |     | ?   | /   |
| 1327 | 991636 | Fr RH Door Outer Handle          |     | ?   | /   |
| 1333 | 991617 | Fr RH Door Inner Trim Board      |     | ?   | /   |
| 2037 | 991644 | Fr Door Frt Pillar               |     | DD  | /   |
| 2038 | 991657 | Fr Door Rear Pillar              |     |     |     |
| 2039 | 992072 | Fr Wheel Arch Panel              |     |     |     |
| 2040 | 992069 | Fr Wheel Arch Panel Garnish      |     |     |     |
| 2041 | 991996 | Fr Step Panel RA                 |     | DIS | /   |
| 2042 | 994498 | Fr Step Panel Top Garnish        |     |     |     |
| 2043 | 994495 | Fr Step Panel Inner Garnish      |     |     |     |
| 1073 | 995053 | Wiper Washer Tank                |     |     |     |
| 1136 | 990247 | Sticker                          |     |     |     |
|      |        | Steering Column Coupling         |     | ?   | /   |

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                           |
|-------------------------------|---------------------------|
| Owner ID Type:                | Business                  |
| Owner ID:                     | 700W                      |
| Vehicle Details               |                           |
| Vehicle No.:                  | YM9788L                   |
| Vehicle to be Exported:       | No                        |
| Intended Deregistration Date: | 12 Feb 2020               |
| Vehicle Make:                 | MITSUBISHI                |
| Vehicle Model:                | CANTER FEB21ER3SDEB (CBU) |
| Primary Colour:               | White                     |
| Manufacturing Year:           | 2014                      |
| Engine No.:                   | 4P10B36628                |
| Chassis No.:                  | FEB21EA00918              |
| Maximum Power Output:         | -                         |
| Open Market Value:            | \$31,437.00               |
| Original Registration Date:   | 02 Oct 2014               |
| First Registration Date:      | 02 Oct 2014               |
| Transfer Count:               | 0                         |
| Actual ARF Paid:              | \$1,572.00                |
| Intended PARF Rebate Details  |                           |
| PARF Eligibility:             | No                        |
| PARF Eligibility Expiry Date: | -                         |
| PARF Rebate Amount:           | \$0.00                    |
| Intended COE Rebate Details   |                           |
| COE Expiry Date:              | 01 Oct 2024               |
| COE Category:                 | C - Goods Vehicle & Bus   |
| COE Period(Years):            | 10                        |
| QP Paid:                      | \$49,901.00               |
| COE Rebate Amount:            | \$23,134.00               |
| <b>Total Rebate Amount:</b>   | <b>\$23,134.00</b>        |

The information contained herein is correct as at 10 Feb 2020

OK

Claim Handling

Accident MT/1083821

LOS SAL SUB

|                     |   |                     |   |                      |           |
|---------------------|---|---------------------|---|----------------------|-----------|
| Policy No.          | 5067797321-05   | Vehicle No.         | YM9788L   | GST Registration No. |           |
| Certificate No.     |   |                     |   |                      |           |
| Policyholder Name   | CHYE HENG ORCHID GARDEN   |                     |   | Policyholder NRIC    | 07435700W |
| Product Code        | COMMERCIAL VEHICLE INSURAN  | Cover Type          | Comprehensive   | Loading              | 0         |
| Contact No.(Mobile) | 64490585  | Contact No.(Office) |   | Contact No.(Home)    |           |
| Email Address       |   | Special Remark      |   | eCode                | No        |
| KFK                 | <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes | TCA                 | <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes | eCode Reason         |           |
| NCD Protection      | No  | NCD Entitlement(%)  | 20  | Private Hire         | No        |

Accident Details

|                   |                                   |                               |       |                     |             |
|-------------------|-----------------------------------|-------------------------------|-------|---------------------|-------------|
| Report Date       | 11/02/2020 10:06                  | Accident Report Within 24 hrs | Yes   | Accident Type       | Hit and run |
| Date of Accident  | 10/02/2020                        | Time of Accident hh:mm        | 07:40 | Country of Accident | Singapore   |
| Reporting Centre  | NATIONAL ASSESSMENT CENTR         | Orange Force                  | No    | ICM No.             |             |
| Accident Location | BEDOK INDUSTRIAL PARK E (LOT 132) |                               |       |                     |             |

Total Excess Applicable

|                            |              |                            |        |                    |         |
|----------------------------|--------------|----------------------------|--------|--------------------|---------|
| Excess Type                | Per Accident | Windscreen Excess          | 100.00 |                    |         |
| OD Standard Excess         | 600.00       | TP Standard Excess         | 0.00   |                    |         |
| YIED OD Excess             | 0.00         | YIED TP Excess             | 0.00   | Driver is Covered? | Covered |
| Additional Excess          |              |                            |        |                    |         |
| Total OD Excess Applicable | 600.00       | Total TP Excess Applicable | 0.00   |                    |         |

Benefits

GST Registered Information

|                      |   |                       |     |
|----------------------|---|-----------------------|-----|
| GST Registered       | No  | GST Registration Date |     |
| GST Registration No. |   | GST Status Verified   | Yes |
| Modification History | 11/02/2020 10:10:53 System changed GST Status Verified from No to Yes |                       |     |

Policyholder Mailing Address

|           |               |                       |                   |           |                  |
|-----------|---------------|-----------------------|-------------------|-----------|------------------|
| Address 1 | BLK 29 #14-84 | Address 2             | CHAI CHEE AVENUE  | Address 3 | SINGAPORE 460029 |
| Address 4 |               | Address Type          | Singapore address | Post Code | 460029           |
| Unit No.  |               | Related Policy Number | 5041148999-10     |           |                  |

O1 Driver Info

|   |   |                     |                   |                        |                  |
|---|---|---------------------|-------------------|------------------------|------------------|
| Driver Name                             | Unnamed Driver  | Driver Type         | Unnamed Driver    |                        |                  |
| Unnamed driver Name                     | TED HAN KEONG   | Driver NRIC         | SXXXX205G         | Driver DOB             | 19/11/1971       |
| Register Date of Driver License         | 05/08/1989  | Driver Age          | 48                | Driving Experience     | 30               |
| Contact No.(Mobile)                     | 97760788  | Contact No.(Office) |                   | Contact No.(Home)      |                  |
| Address 1                               | BLK 29 #14-84   | Address 2           | CHAI CHEE AVENUE  | Address 3              | SINGAPORE 460029 |
| Address 4                               |   | Address Type        | Singapore address | Post Code              | 460029           |
| Unit No.                                | 14-84   |                     |                   |                        |                  |
| Does he own a Singapore Registered car? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Driver Vehicle No.  |                   | Driver Insurer Company |                  |

Declaration

|                                     |      |             |   |
|-------------------------------------|------|-------------|---|
| Breathalyser or Blood Test Reading? | 0 mg | Any injury? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
|-------------------------------------|------|-------------|---|

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Yap Chee Ling

LOS SAL SUB

|   |   |                         |                           |                                 |                  |
|---|---|-------------------------|---------------------------|---------------------------------|------------------|
| Claim Type  | OD-MD   | Insured Name            | CHYE HENG ORCHID GARDEN   | Insured NRIC                    | 07435700W        |
| Contact No.(Mobile)                                 |   | Contact No.(Home)       |                           | Contact No.(Office)             | 64490585         |
| Email Address                                       |   | O1 Vehicle Number       | YM9788L                   | TP Vehicle Number               | UNKNOWN          |
| Claim Description                                   | YM9788L / UNKNOWN ON 10 Feb 2020                                    |                         |                           | Name of Preferred Workshop      | 0                |
| Preferred Workshop Realisation                      | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Preferred Repair Option | income to assign workshop | Insured Liability report        | Not at Resolved  |
| Date Registered                                     | 11/02/2020 10:16  | Claim Close Date        |                           | Date Received                   | 11/02/2020 00:00 |
| Report Taken By                                     | LIEW SHAN HUI   | Workshop Repairer       |                           | Total Loss but Repaired         |                  |
| <input checked="" type="checkbox"/> Print AK letter |   |                         |                           | OD Excess Collected by Workshop |                  |

Modification History

Special Claim Creation Approval

|          |        |
|----------|--------|
| Approval | Reason |
| Remarks  |        |

damage assessment Attachment

Vehicle Info

|                      |            |               |              |                 |      |
|----------------------|------------|---------------|--------------|-----------------|------|
| Vehicle Make         | MITSUBISHI | Vehicle Model | FE           | Engine Capacity | 2.50 |
| Date of Registration | 02/10/2014 | Classis No.   | FEB21EA00918 |                 |      |

Towing Required \*  Yes  No

Vehicle in IDAC \*  Yes  No

Parallel Import \*  Yes  No

Type of Tender \*  Assessor Name \*  Survey Current Status

IDAC/Workshop Name NATIONAL ASSESSMENT CENTR IDAC/Workshop Location 51 UBI AVENUE 1 #01-25 PAYA

Windscreen Parts & Labour Cost Total Loss \*  Yes  No

Market Value(\$)  Scrape Value(\$)  Economical Repair Value(\$)

Remark  
REMARK:NO OF REPAIR DAYS:7DAYS.1X FRT RH BUMPER SIDE PAD - REPLACE. 1X FRT WINDSCREEN OUTER PILLAR RH - REPAIR. 1X FRT SIDE MIRROR(BIG) - REPLACE.1X FRT WING MIRROR STAY - REPLACE. 1X FRT RH DOOR ENTRANCE GARNISH - REPLACE.1X FRT RH DOOR LOCK - REPLACE.1X FRT RH DOOR EDGE PROTECTOR - REPLACE.1X FRT RH DOOR INNER TRIM BOARD - UNCONFIRM.1X FRT DOOR FRT PILLAR - REPLACE.1X STEERING COLUMN COUPLING - UNCONFIRM.

Remark for Supplementary

Damage Listing

| Find a Part                  | No. | Part No. | Description                       | Qty *                          | Repair Code * |   |
|------------------------------|-----|----------|-----------------------------------|--------------------------------|---------------|---|
| root                         |     |          |                                   |                                |               |   |
| Not Applicable               | 1   | 32200101 | NUMBER PLATE (FRONT)              | <input type="text" value="1"/> | Replace       | X |
| ABS                          | 2   | 16000101 | BUMPER (FRONT)                    | <input type="text" value="1"/> | Replace       | X |
| ABSORBER                     | 3   | 27100101 | GRILLE (FRONT)                    | <input type="text" value="1"/> | Replace       | X |
| ACCELERATOR                  | 4   | 27100801 | GRILLE EMBLEM (FRONT)             | <input type="text" value="1"/> | Replace       | X |
| ACTUATOR                     | 5   | 21300102 | CORNER PANEL (FRONT RIGHT)        | <input type="text" value="1"/> | Replace       | X |
| ADVERTISEMENT STICKER        | 6   | 38500202 | SIGNAL LAMP (FRONT RIGHT)         | <input type="text" value="1"/> | Replace       | X |
| AIR BAG                      | 7   | 27700102 | HEAD LAMP (RIGHT)                 | <input type="text" value="1"/> | Replace       | X |
| AIR BLOWER                   | 8   | 45100401 | WINDSCREEN GLASS (FRONT)          | <input type="text" value="1"/> | Replace       | X |
| AIR BOX                      | 9   | 45101901 | WINDSCREEN RUBBER (FRONT LEFT)    | <input type="text" value="1"/> | Replace       | X |
| AIR CHAMBER BOX              | 10  | 45101902 | WINDSCREEN RUBBER (FRONT RIGHT)   | <input type="text" value="1"/> | Replace       | X |
| AIR CLEANER                  | 11  | 112053   | AIR CON EVAPORATOR                | <input type="text" value="1"/> | Unconfirm     | X |
| AIR COMPRESSOR               | 12  | 112003   | AIR CON BLOWER                    | <input type="text" value="1"/> | Unconfirm     | X |
| AIR CON                      | 13  | 103002   | ACCELERATOR PEDAL                 | <input type="text" value="1"/> | Unconfirm     | X |
| AIR CON (VAN)                | 14  | 22600101 | DASHBOARD (BOTTOM)                | <input type="text" value="1"/> | Unconfirm     | X |
| AIR COOLER                   | 15  | 23300202 | DOOR (FRONT RIGHT)                | <input type="text" value="1"/> | Replace       | X |
| AIR DISTRIBUTOR              | 16  | 23300302 | DOOR HINGE (BOTTOM) (FRONT RIGHT) | <input type="text" value="1"/> | Replace       | X |
| AIR FILTER                   | 17  | 23303102 | DOOR HINGE (UPPER) (FRONT RIGHT)  | <input type="text" value="1"/> | Replace       | X |
| AIR FLOW                     | 18  | 23306102 | DOOR RUBBER (FRONT RIGHT)         | <input type="text" value="1"/> | Unconfirm     | X |
| AIR GRILLE                   | 19  | 403001   | STEP BOARD PANEL                  | <input type="text" value="1"/> | Replace       | X |
| AIR HORN                     |     |          |                                   |                                |               |   |
| AIR INTAKE                   |     |          |                                   |                                |               |   |
| AIR RESONATOR BOX            |     |          |                                   |                                |               |   |
| AIR THROTTLE BODY AND SENSOR |     |          |                                   |                                |               |   |
| ALARM                        |     |          |                                   |                                |               |   |
| ALTERNATOR                   |     |          |                                   |                                |               |   |
| ALUMINIUM PANEL - SIDE       |     |          |                                   |                                |               |   |

Save Submit



NATIONAL ASSESSMENT CENTRE SERVICES  
(LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,  
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315



Vehicle Movement Form

Vehicle Check-In

Vehicle No: YN 9788U Date In: 04-03-20 Time In: 10.4m with Keys: Yes / No

*For Office use*

Attended by: \_\_\_\_\_

Workshop Collection of Vehicle

Workshop: Auto City Auto #05-01

Collection Date: 04-03-20 Time: 10.4m with Keys: Yes / No

Tow Truck No: 86435285 Tow Man: Ken NRIC: 741671513

Signature: [Signature]

*For office use*

Attended by: \_\_\_\_\_

Approved by: \_\_\_\_\_

Workshop Return of Vehicle

Workshop: \_\_\_\_\_

Returned Date: \_\_\_\_\_ Time: \_\_\_\_\_ with Key: Yes / No

\* Tow In / Drive In  
Tow Man / Workshop Representative: \_\_\_\_\_ NRIC: \_\_\_\_\_

Signature: \_\_\_\_\_

*For office use*

Attended by: \_\_\_\_\_

Owner Collection of Vehicle

Collection Date: \_\_\_\_\_ Time: \_\_\_\_\_ with Key: Yes / No

Owner: \_\_\_\_\_ NRIC: \_\_\_\_\_

Signature: \_\_\_\_\_

*For office use*

Attended by: \_\_\_\_\_

Approved by: \_\_\_\_\_

## LKK Paya Ubi

---

**From:** Yap Chee Ling <CheeLing.Yap@income.com.sg>  
**Sent:** Wednesday, 26 February 2020 8:42 AM  
**To:** City Auto; LKK Paya Ubi  
**Subject:** YM9788L | MT/1083821 (Awarding Letter to City Auto)

**Importance:** High

Hi IDAC and City Auto,

Vehicle is currently in IDAC.

Excess of \$600 is applicable.

Please liaise with the owner – Mr Teo Han Keong at tel: 9776 9788 on the necessary.

Thank you.

### Yap Chee Ling (Ms)

Executive

Operations, Motor and Personal Lines (PL)

T +65 6430 7893

[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at [income.com.sg/careers](http://income.com.sg/careers)

**in** with you

---

Our Ref: MT/CA/OD/051/1083821-001/YCL

26 Feb 2020

CITY AUTO PTE LTD  
BLK 8 #01-58 TO 66  
SIN MING INDUSTRIAL EST SECTOR C  
SINGAPORE 575643

Dear Sir

**CLAIM NUMBER: MT/1083821-001**  
**REPAIR OF VEHICLE NUMBER: YM9788L**

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 26 Feb 2020  
Make: MITSUBISHI

Model: FE

Estimated Repair Days: 6

Location: NATIONAL ASSESSMENT CENTRE SERVICES

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits: Not applicable

Excess Applicable: 600

Please note that supplementary items will not be allowed.

If you have any queries, please contact Yap Chee Ling at 6430-7893 or email us at [motor@income.com.sg](mailto:motor@income.com.sg).

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.