

22/03/2002

ASS. REC. BY:

REF:

CS31 ASM 2000 2270 / THF3^{S2}

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Khong lyn

of

AM (AXA)

Date/Time: 10/11/2020

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SKG 22614

Insured:

SKE 1492A

at Workshop m/s

Teamwork Garage

Tel:

68442075

of BIR 53 ub AXA 1 101-24

Policy No:

Claim No:

SUMO P/V W

Sum Insured:

Excess:

Make of Veh:

D.O.A.

20. Jan. 2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

/up"

Date/Time: 10/11/2020 4.34p.m

Person Contacted:

Shuchan

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKG 22614 - CC4/AG 19018155/ T1663 ROTA - 14/10/2019
	SKE 1492A - X
28/2/20	Revised via IA in new Smart Claims
	Dismantle: 21/2/2020
	After Repair: 27/2/2020

ASS. REC. BY:

PRS

REF: ASM (A4)

ASSIGNMENT

CoE 2028 Aug

From: _____ Date: 11.2.2020

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKG 22614

at Workshop m/s Teamwork Garage

of Blk 53 ubi Ave 1 #0124

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: A65K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKG 22614 Yr Regn: 2008 / June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Estimer

C.C. 2362

Colour: Pearl white

A/C: Insured / Std / NI / NA

Sp. Reading: 139564

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. _____

D.O.I. 11/2/20 @ 12pm

Survey held at Teamwork Garage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3000-4000, 5 days
Range repair

RECEIVED 27 FEB 2020

21/2/2020

Date/Time, File Pass to?



Preli. Report

1) 21/2 Typist



Final Report

Date/Time, File Return to?

2)

Rep. Form 1

PRS

Lump Sum / F.B. / C.

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL




Service Request Details

Claim

S0M02FNW

Reference

None 

Loss Date

January 24, 2020

Report Date

Feb 7, 2020 9:21:22 AM

Request Date

February 10, 2020

Due Date

February 17, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKG2261H

MODEL

ESTIMA AERAS 2.4 A

Service Address

...

Primary Contact/Insured

PUA YOW THONG

2 PETIR ROAD, #22-15 MAYSPRINGS, 678265, Singapore

PUAYT@ONECENTUM.COM.SG

Claim Handler

KHONG Lynn

68804892

lynn.khong@axa.com.sg

Additional Instructions

WS : Teamwork Garage Pte Ltd

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

Date: 27/2/2020

To : AXA Insurance Pte Ltd

Survey details

Date of loss	24-Jan-20
Date of appointment	10-Feb-20
Date of survey	11-Feb-20
Location of survey	Teamwork Garage

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SKG 2261H
Make and Model	Toyota Estima Aeras 2.4A
Date of registration	2/6/2008
Excess	0.00
Market Value	\$65,000
Parf Rebate	\$32,135
Nett Loss	\$32,865

Repair details

Initial Estimate	\$0
------------------	-----

Proposed/Revised repair cost:

Parts	
Check item	
Labour	
Total	
Lump Sum(if applicable)	

Number of days of repair	0
--------------------------	---

Remarks:

The estimate repair cost of the damaged vehicle is in the region of \$3000 - \$4000

Summer Lee (LKK Auto)

From: TEAMWORK <claims@teamworkgarage.com>
Sent: Thursday, 6 February, 2020 7:09 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: TEAMWORK
Subject: [EXTERNAL] OUR REF : 2002-11 // YOUR REF : SKE1492A ACCIDENT INVOLVING SKE1492A AND SKG2261H
Attachments: GIA REPORT.PDF
Categories: SANTOSH

WITHOUT PREJUDICE

OUR REF : 2002-11
YOUR REF : SKE1492A

Dear Sir / Madam,
PRE-REPAIR INSPECTION FOR SKG2261H
ACCIDENT INVOLVING SKE1492A AND SKG2261H ON 24.01.2020.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention.

Thank you and have a nice day.

Regards,

Shu Shan
Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax: 6844 2474

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2020 08:45
Date Of Accident	24/01/2020 04:45
Exact Location Of Accident	ALONG 2ND LINK EXPY TWDS JB CUSTOM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG2261H
Insured/Policyholder	
Name Of Registered Owner	TOH TEONG CHOON
NRIC No	SXXXX241E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97816380
Alternative Phone No	OTHERS-97816380

Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA AERAS 2.4 A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA464246/1
Cover Note Number	

Driver

Name of Driver	ADAM YAK
NRIC No	SXXXX107Z
Date Of Birth	14/09/1996
Occupation	INDOOR
Date Of Driving Pass	25/09/2019
Driving Experience	0 YEAR AND 3 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91150440
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	509 ANG MO KIO AVENUE 8 #02-2740 SPORE 560509
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : AGNES YAK GENDER: : FEMALE
Passenger 2	NAME: : RAIN TOH GENDER: : FEMALE
Passenger 3	NAME: : RAY TOH GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKE1492A
Vehicle Make/Model/Colour	MERCEDES BENZ / E250 A
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1) Please report correctly on the details of the accident to speed up the claims process.
- 2) This form must be completed by the policy holder and/or the authorised driver.
- 3) Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5) Any false reporting may be referred to the police for investigation.
- 6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8) **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of:
 - (i) Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigations the accident and/or my claims;
 - (iii) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) Complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (i) To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposed stated, or
 - (ii) For complying with requirements under my regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Lin
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



A: SKG 2261 H
B: SKE 1492 A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was stationary along second link expy towards JB custom
as the traffic was very heavy. Vehicle B which was beside my lane
tried to squeeze into my lane resulting in vehicle B colliding onto
my front left portion of my vehicle.

*****for company vehicle only*****
I _____ is the _____ of
company _____ and im using the vehicle
_____ for work /private purpose .

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: J. L. N.
NRIC/FIN No.:


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	241E
Vehicle Details	
Vehicle No.:	SKG2261H
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	2AZF127215
Chassis No.:	ACR507056208
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$29,287.00
Original Registration Date:	02 Jun 2008
First Registration Date:	02 Jun 2008
Transfer Count:	3
Actual ARF Paid:	\$24,363.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$38,712.00
COE Rebate Amount:	\$32,135.00
Total Rebate Amount:	\$32,135.00

The information contained herein is correct as at 12 Feb 2020

OK



HELPING MILLIONS OF
ENTREPRENEURS SUCCEED ONLINE

Toyota Estima

Price Range

Depreciation

> 10 year(s) of Vehicle Type

Search

Advanced
Search

Home » Used Cars » Car Guru.Com Pte Ltd » Toyota Estima 2.4A Aeras (COE till 04/2028)

Toyota Estima 2.4A Aeras (COE till 04/2028)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Price \$62,800

Depreciation \$7,640 /yr

Reg Date 09-May-2008
(8yrs 2mths 18days COE left)

Mileage 125,284 km (10.6k /yr)

Manufactured 2008

Road Tax \$1,966 /yr

Transmission Auto

Dereg Value \$33,601 as of today (change)

OMV \$30,527

COE \$40,881

ARF \$30,527

Engine Cap 2,362 cc

Power 125.0 kW (167 bhp)

Curb Weight 1,710 kg

No. of Owners 2

Type of Vehicle MPV

Features

Powerful And Efficient 2.4L DOHC VVTi Engine, 7 Speed CVT Auto Transmission, Dual Power Sliding Doors, Keyless Entry/Start/Stop. View specs of the Toyota Estima (2006-2010)

Accessories

Leather Seats, Auto Retractable Folding Mirrors, Auto Lights, Fog Lamps, Touchscreen Audio Player, Roofmount Monitor, Reverse Sensors.

Description

Smooth Engine, Easy To Maintained Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Available! Trade In Welcome. Call For Appointment For A Test Drive Now Before The Car Is Gone.

Category

COE Car, Premium Ad Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

20 | Last Updated on: 12-Feb-2020

Compare



Location Map

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Car Guru.Com Pte Ltd

26 vehicles for sale. 30 sold in past 3 mths

210 Turf Club Road Lot A7/A8/A9

Car Mall @ The Grandstand

Tel: 67639595

Search cars nearby

Esmond Ng
Jimmy Cai90882066
90079944



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
AXA INSURANCE PTE LTD		Ref: CS3/ASM20002270/T1f3s2	
8 SHENTON WAY #24-01		Date: 28-02-2020	
AXA TOWERSINGAPORE 068811			
ATTN: LYNN KHONG		Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SKE 1492A	Veh. Inspected	SKG 2261H
Policy No.		Coverage (\$)	0.00
Claim No.	S0M02FNW	Excess (\$)	0.00
Assign From	LYNN KHONG	Assign Date	10/02/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ESTIMA	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	ACR507056208	Colour	PEARL WHITE
Odometer	139569 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R18	MICHELIN	6 mm
L/H Front Tyre	225/50 R18	MICHELIN	6 mm
R/H Rear Tyre	225/50 R18	MICHELIN	6 mm
L/H Rear Tyre	225/50 R18	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
5. General Information			
Accident Date	24/01/2020	Inspect Date / Time	11/02/2020 (12:00 PM)
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

Report Ref No. CS3/ASM20002270/T1f3s2

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.