

ASS. REC. BY: fil

REF: AIG

WAT / GAD

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 21/3/2020

Estimated Cost: \_\_\_\_\_

OD  TP  WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 8488E

at Workshop m/s Performance

of 303 Alexandra Road

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent? : **Yes or No**

GIA / PR Seen: \_\_\_\_\_ Consistent? : **Yes or No**

Est. Repairs: 5 days Res.: **Yes or No**

Lum Sum: \_\_\_\_\_ % 3 Val.: **Yes or No**

CA / REV / REP. / 24 HRS up

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: **IN / OUT**

Veh No: SLX 8488E Yr Regn: 30 Nov 2016

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or \_\_\_\_\_

Make: Bmw XI c.c. 1499

Colour: Black A/C: **Insured / Std / NI / NA**

Sp. Reading: 63099 T/Radio: **Insured / Std / NI / NA**

Eng/No: \_\_\_\_\_

C/No: WBAHS1205057 03008

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi:  Nil /  S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 225/50R18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or \_\_\_\_\_

Front 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 02-03-20

Survey held at W/S 10:40

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Rep. Format : \_\_\_\_\_

Lump Sum / L.B.I. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_ \$ + RS. \_\_\_\_\_ \$

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL \_\_\_\_\_

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	631G
Vehicle No.:	SLX8488E
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Mar 2020
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE18I AT LED NAV
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	F334H333B38A15A
Chassis No.:	WBAHS120505F03008
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$30,895.00
Original Registration Date:	30 Nov 2016
First Registration Date:	30 Nov 2016
Transfer Count:	2
Actual ARF Paid:	\$30,253.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2026
PARF Rebate Amount:	\$22,689.00
COE Expiry Date:	29 Nov 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$55,201.00
COE Rebate Amount:	\$37,214.00
<b>Total Rebate Amount:</b>	<b>\$59,903.00</b>

The information contained herein is correct as at 02 Mar 2020

OK