

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 07.02.2020

Time: 11:30:09

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305379629
 REGN NO : SHA5005D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 20.12.2017
 DATE/TIME IN : 07.02.2020 09:40
 ACCIDENT DATE : 07.02.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	CRA
0002	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	Xnn
0003	04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	103.50	20.00	82.80	Ter
0004	04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	Pxnn
0005	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	hec
0006	04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	wec
0007	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70	10.00	122.13	Xnn
0008	04-01-0103-0743-G	STAY-RR BUMPER RH	1	80.30	20.00	64.24	Pxnn
0009	04-01-0103-0742-G	STAY-RR BUMPER LH	1	80.30	20.00	64.24	Pxnn

SUB-TOTAL : 1,368.53

JOB NATURE

0000	PB	PANEL BEATING	300.00	\$280
0001	SP	SPRAYPAINT CHARGE	300.00	\$200

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305379629
 REGN NO : SHIA5005D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 20.12.2017
 DATE/TIME IN : 07.02.2020 09:40
 ACCIDENT DATE : 07.02.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0002 20-05 ADVERTISEMENT STICKER-BUMPER
 0003 20-05 ADVERTISEMENT STICKER-FENDER
 0004 L REMOVE / REFIX REVERSE SENSOR
 0005 17-01 CHECK ALL LIGHTING

50.00 *nee*
 200.00 *nee*
 80.00 \$50
 50.00 \$30

SUB-TOTAL : 980.00

TOTAL : 2,348.53

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Repairer

[Signature]
 12/2/2020

PCAN(LKK)
 47/2/2020 ~~1230~~
Papasmay@lkkauto.com
 55622778 hp
 (25) ~~2020~~ 2020/2/5
 qf repair photo