

ASS. REC. BY:

REF: (S3) AIG 20002342/HV302

Special Instruction:

SURVAYOR: Hock Ann

ASSIGNMENT (Office)

From (Person):

Chin Lee Yng

of

AIG

Date/Time:

11.2.2020 15:14

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SJZ 6488G

Insured:

SBH 777B

at Workshop m/s

Bliss Garage

Tel:

9619 9144

of

25 Kall Bukit Road 4 #03-33 synergy

Policy No.:

2100481197

Claim No.:

3301647742 SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7.2.2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11/2/2020 2:00pm

Person Contacted:

Zoon Koh

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJZ 6488G - NA / MSG 11026534 / t b.o.A - 26/12/2011
	SBH 777B - X
13/2/20	Submit DAR

ASS. REC. BY:

H-ANN

REF:

AIG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJZ 6488 G
 at Workshop m/s Bliss Garage
 of 25 Kaki Bukit Rd 4 #03-33
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJZ 6488 G Regn: 15/12/2010
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Volvo 560 c.c. 1929
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 189999 km T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: YU1F544-5BB201753
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: _____ R: 245/35/19

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

X	
N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front _____ Rear _____
 R/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 7/2/20 D.O.I. 11/2/20
 Survey held at Bliss Garage
 Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	DAN / m * SJZ 6488 G pns am -
	Repair O/S - 4 Day
	RECEIVED 14 FEB 2020
	MV - 29000
	PV - 23235
	NV - 5700

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + PS, SI _____

Photos _____

Others _____

TOTAL

Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____

Report Format: _____

Lump Sum / L.B.I: (\$) _____

150
11
191

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Feb 2020 Edit Reg		11 Feb 2020 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by adjuster]					
Insured:	TUNIAN ASHOT								
Main Claimant:	-								
Vehicle Reg. No.:	SJZ6488G	Date of Loss:	07/02/2020 00:00 - :59						
Claim Type:	TP / 3301647742SG	Policy/Cover Note No.:	2100481197						
Vehicle Reg. No. (Insured):	SBH777B	Policy No. (Claimant):							
		Excess:							
Repairer:	Bliss Garage Pte Ltd (Synergy) 25 Kaki Bukit Road 4, Synergy@Kaki Bukit, #03-33 Freesion Auto Drive, 417800 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 20/02/2020]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
<ul style="list-style-type: none"> • AIG_SG (12/02/2020): NO OI GIA REPORT • AIG_SG (12/02/2020): NO TP GIA REPORT 									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SBH777B AND SJZ6488G ON 07/02/2020

From: Chin, Lee-Ying
To: assignments, Admin-D (LKKAuto)
Cc: Lim, Kok-Chong
Sent: Tuesday, 11 February, 2020 1:51:48 PM
Attachments:  2nd PRS - AIG.docx  1st PRS.PDF

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

Your Ref : SJZ 6488G/BG/jp/hk
Our Ref : **SJZ 6488G/BG/jp/sl**
Date : 11 February 2020

Fax : 6538 3708
Tel : 3152 0985
Email : jiapei@ksegp.com

AIG Asia Pacific Insurance Pte Ltd

BY EMAIL ONLY

DATE OF ACCIDENT: 7 FEBRUARY 2020
NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your letter of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

S/n.	Name of Surveyor
1	Andrew How (Prominent Appraiser Services Pte Ltd)
2	Dave Chang (Sincere Appraisal Services Pte Ltd)
3	Nicky Seah (Absolute Appraisal Services Pte Ltd)

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Bliss Garage Pte Ltd
25 Kaki Bukit Road 4
#03-33 Synergy @ Kaki Bukit
Singapore 417800

Contact Person/Tel : Zoron Koh / 9619 9144

Yours faithfully,

f SL

Your Ref : SJZ 6488G/BG/jp/hk
Our Ref : SJZ 6488G/BG/jp/sl
Date : 11 February 2020

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of _____ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was anybody injured in the Accident? YES

Was anybody injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : KOH PEK FANG

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SBH777B

Vehicle Make/Model/Colour LAND ROVER / RANGE ROVER 3.0TDV6 TSS

Details of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN HONG SHENG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJZ6488G
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name KOH PEK FANG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJZ6488G
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6661
Vehicle Details	
Vehicle No.:	SJZ6488G
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2020
Vehicle Make:	VOLVO
Vehicle Model:	S60 2.0T AT ABS AIRBAG 2WD
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	B4204T6211267
Chassis No.:	YV1F5445BB2017533
Maximum Power Output:	149.0 kW (199 bhp)
Open Market Value:	\$38,439.00
Original Registration Date:	15 Dec 2010
First Registration Date:	15 Dec 2010
Transfer Count:	3
Actual ARF Paid:	\$38,439.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Dec 2020
PARF Rebate Amount:	\$19,219.00
Intended COE Rebate Details	
COE Expiry Date:	14 Dec 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$49,890.00
COE Rebate Amount:	\$4,016.00
Total Rebate Amount:	\$23,235.00

The information contained herein is correct as at 12 Feb 2020

OK

volvo s60 Price Range Depreciation Year Reg Vehicle Type


Home » Used Cars » Direct Owners » Volvo S60 2.0T

Volvo S60 2.0T

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map

DIRECT

Price	\$29,800	Reg Date	29-Dec-2010 (10mths 16days COE left)
Depreciation	\$12,070 /yr <small>View models with similar depre</small>	Manufactured	2010
Mileage	110,888 km (12.1k /yr)	Transmission	Auto
Road Tax	\$1,212 /yr	OMV	\$38,439
Dereg Value	\$23,593 as of today (change)	ARF	\$38,439
COE	\$49,890	Power	149.0 kW (199 bhp)
Engine Cap	1,999 cc	No. of Owners	4
Curb Weight	1,592 kg		
Type of Vehicle	Luxury Sedan		



100% PAPERWORK SUPPORT BOTH BUYER & SELLER



- Shortlist
- Compare
- Add new
- Report Error
- More Actions

Features

100% Worth Viewing. Powerful And Responsive Inline 4 Cylinder Turbo Charged Engine, 6 Speed Automatic Transmission Gear Box, ABS, SRS Airbag. View specs of the Volvo S60 (2010-2014)

Accessories

Worth Viewing! Perfect Clean Interior And Exterior. Factory Fitted Audio. Leather Seats.

Description

100% Worth To View. Genuine Low Mileage. Look Photos! Superb Perfect Clean. Beautiful Car Showroom Looks. Expensive Sport Rims. All Servicing Done. All Engine Oil Changed, Automatic Transmission Fluids Changed. Worth Time To View! Consider To Buy With Renewed COE.

Category

PARF Car, Direct Owner Sale

Don - 7/2/20

Status

Available

MV - 29000

PV - 23235

MV - 5700

Resources

Depreciation → 10 months
Buyer → 12000
12000/12 = 1000
10000 + 19217
= 29217



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Seller Information

Contact Person(s) Tirmidzi / Asyiq
Contact No. 97933151 / 9387653

ESSENTIAL TRANSACTION FORMS

- » Indemnity form
- » Sales agreement
- » Receipt
- » Hand-over form
- » Ownership Transfer



GET HELP WITH PAPERWORK



sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agree and we'll help with Car Loans, Insurance, Pay & Ownership Transfer. FREE for all sgCarMart Advertised Vehicles.

Upload your Sales Agreement

Posted on: 09-Feb-2020

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/02/2020 15:30
Date Of Accident	07/02/2020 08:50
Exact Location Of Accident	THOMSON ROAD TWDS KENG LEE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ6488G
Insured/Policyholder	
Name Of Registered Owner	AW SUET CHEE
NRIC No	SXXXX666I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91070541
Alternative Phone No	OTHERS-91070541

Vehicle Particulars

Manufacturer	VOLVO
Model	S60 2.0T AT ABS AIRBAG 2WD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA471600/1
Cover Note Number	

Driver

Name of Driver	TAN HONG SHENG
Passport No/FIN	GXXXX765L
Date Of Birth	24/06/1993
Occupation	OUTDOOR
Date Of Driving Pass	13/02/2012
Driving Experience	7 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91070541
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address 157 ANG MO KIO AVE 4 #04-554 SPORE 560157
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured RELATIVE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : KOH PEK FANG
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SBH777B
 Vehicle Make/Model/Colour LAND ROVER / RANGE ROVER 3.0TDV6 TSS
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN HONG SHENG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJZ6488G
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name KOH PEK FANG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJZ6488G
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident [all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG THOMSON ROAD TOWARD FENG LEE ROAD ON THE EXTREME RIGHT LANE OF A 4 LANE ROAD. SOMEWHERE AFTER TUA PAHAT RISE EXIT, I DRIVING STRAIGHT ALONG THE SAID ROAD. OUT OF A SUDDEN, I FELT A STRONG IMPACT FROM THE LEFT FRONT PORTION OF MY VEHICLE. DUE TO THE STRONG IMPACT, MY VEHICLE SWERVE TO THE RIGHT. AFTER THE ACCIDENT, I AWAKENED AND REALISE THAT VEHICLE (B) DROVE OUT FROM THE SLIP ROAD AND CUT INTO MY LANE AND COLLIDED INTO THE LEFT FRONT PORTION OF MY VEHICLE.

A - SLZ 6488 G
B - SBH 777 B

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Ceyna Personnel's Signature
Name: S. L. S.
NIC/PIN No.:

*GABAN/1000/1000/1000 V1

MOTOR CAR (Frt)

Front Portion

Vehicle No: **5JZ 64889**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips	CRG	✓	1
1006	991325	Frt Bumper Bracket	ARM	✓	1
1007	991462	Frt Bumper Side Retainer	ARM	✓	1
1008	991433	Frt Bumper Reinforcement	ARM	✓	1
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover	SEA	✓	1
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRG	✓	1
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	GT	✓	1
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stud			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	GT	✓	1
1097	995072	Frt LH Fender Inner Panel	ARM	✓	1
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim	SEA	✓	1
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991923	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No. of Items:

AGENCY: **H-ANN**

(07)Returned (08)Shifted (09)Bucked (10)Broken (11)Necessary
 (12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTOR CAR (UC)

(1)Replace (✓) (2)Repair (X) (3)Check (?)
 (4)Not Consistent (NC)

Vehicle No:

5JZ 64886

Undercarriage

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm			
1376	995199	Frt LH Knuckle Arm Bearing	CBM	✓	1
1377	995178	Frt LH Lower Arm			
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1404	990534	Centre Exhaust Pipe Assy			
1405	990532	Centre Exhaust Mounting			
1406	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

NAC	INC	Item	CON	AC	Qty
1428	991935	Frt RH Shock Absorber			
1429	991944	Frt RH Shock Absorber Mounting			
1430	990632	Frt RH Coil Spring			
1431	991844	Frt RH Knuckle Arm			
1432	991845	Frt RH Knuckle Arm Bearing			
1433	991851	Frt RH Lower Arm			
1434	992064	Frt RH Upper Arm			
1435	992040	Frt RH Tie Rod			
1436	991692	Frt RH Drive Shaft			
1437	990661	Frt RH Control Arm			
1438	992062	Frt RH Trailing Arm			
1439	991848	Frt RH Leaf Spring			
1440	991293	Frt RH Brake Disc Rotor			
1441	991281	Frt RH Brake Caliper			
1442	991292	Frt RH Brake Pipe			
1443	991287	Frt RH Brake Hose			
1444	991295	Frt RH Brake Sensor Wire			
1445	993720	Rear RH Shock Absorber			
1446	993723	Rear RH Shock Absorber Mounting			
1447	993173	Rear RH Coil Spring			
1448	993550	Rear RH Knuckle Arm			
1449	993551	Rear RH Knuckle Arm Bearing			
1450	993601	Rear RH Lower Arm			
1451	993885	Rear RH Upper Arm			
1452	993322	Rear RH Drive Shaft			
1453	993178	Rear RH Control Arm			
1454	995117	Rear RH Trailing Arm			
1455	995110	Rear RH Leaf Spring			
1456	992942	Rear RH Brake Disc Rotor			
1457	992938	Rear RH Brake Caliper Assy			
1458	990434	Rear RH Brake Pipe			
1459	992947	Rear RH Brake Hose			

Handwritten signature
 13/2/2020

No of Items: _____

Assessor: A-MN

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Feb 2020 Edit Reg		11 Feb 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TUNIAN ASHOT , Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	SJZ6488G	Date of Loss:	07/02/2020 00:00 - :59 [109 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3301647742SG	Policy/Cover Note No.:	2100481197						
Vehicle Reg. No. (Insured):	SBH777B	Policy No. (Claimant):							
		Excess:							
Repairer:	Bliss Garage Pte Ltd (Synergy) 25 Kaki Bukit Road 4, Synergy@Kaki Bukit, #03-33 Freesion Auto Drive, 417800 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 20/02/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (12/02/2020): NO OI GIA REPORT AIG_SG (12/02/2020): NO TP GIA REPORT 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJZ6488G (3301647742SG)
[SBH777B]
TP**

**-
Feb 7 2020 12:00AM
[TUNIAN ASHOT]
Bliss Garage Pte Ltd**

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser
Photos/Images											
										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	12/02/20 18:26	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
2	12/02/20 18:26	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
3	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
4	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
5	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
6	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
7	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
8	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
9	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
10	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
11	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
12	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
13	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
14	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
15	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
16	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
17	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
18	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
19	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
20	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
21	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
22	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
23	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
24	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
25	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
26	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
27	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
28	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
29	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
30	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
31	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
32	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
33	12/02/20 18:27	General View							Load JPG	<input checked="" type="checkbox"/>	
34	13/02/20 09:00	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
35	13/02/20 09:00	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
36	13/02/20 09:00	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
37	13/02/20 09:00	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	13/02/20 09:00	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/02/20 10:32	TP GIA REPORT	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20002342/HVF3E2**Date:** 14/02/2020**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100481197
Claimant Vehicle No : SJZ6488G **Insured Vehicle No :** SBH777B
 Date of Loss: 07/02/2020 Nature of Claim: TP Claim No: 3301647742SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ6488G**
 Make & Model: VOLVO S60, 2.0 T (A) Engine No: B4204T6211267
 Reg. Date: 15/12/2010 (Man. Year: 2010) Chassis No: YV1FS445BB2017533
 Colour: White Odometer: 189999 km
 Engine Capacity: 1999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/35 R19 Rear Tyre Size: 245/35 R19
 Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm
 Front Right Side: Goodyear 5 mm Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/02/2020
 Date Inspected: 11/02/2020 Inspected At: Bliss Garage Pte Ltd (Synergy)
 25 Kaki Bukit Road 4, Synergy@Kaki
 Bukit, #03-33 Freesion Auto Drive
 Singapore 417800
 Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cracked	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER BRACKET L/H	Crumpled	0.00 F	*- F
4	1		*FRT BUMPER SIDE RETAINER L/H	Necessary	0.00 F	*- F
5	1		*FRT LH BUMPER FOG LAMP COVER	Scratched	0.00 F	*- F
6	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
7	1		*BONNET	Bent	0.00 F	*- F
8	1		*FRT LH FENDER	Bent	0.00 F	*- F
9	1		*FRT LH FENDER INNER PANEL	Repair	0.00 F	*- F
10	1		*FRT LH WHEEL RIM	Scratched	0.00 F	*- F
11	1		*FRT BUMPER PARKING SENSOR L/H	Shorted	0.00 F	*- F
12	1		*FRT LH KNUCKLE ARM BEARING	Crumpled	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >