



Case Details

Case Reference Number : BUS/12/19/5048

Company Type : SMRT Buses Ltd

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-10189-ID

Accident Date and Time : 27/12/2019 08:08 AM

Vehicle Registration Number : SMB1418H

Assigned By : Claiming Case Owner Team

Vehicle Age(In Months) : 71

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Appro		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/
Standard	Main	Body	6010064	BUMPER:REAR,CENTRE,FOR MAN A22 BUS	1	1,868.80	1,868.80	100.00	0.00	Repair	1	0.00	Repe
									Total Spare Part Cost	0.00	Surveyor Total		0.00
									Lump Sum Discount (%)	0.00	Lump Sum Dis (%)		0
									Final Spare Part Cost	0.00	Final Sur Total		0.00

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	795.00	530	
Total:			795.00	530.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	616.00	432	
Total:			616.00	432.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	0.00	0.00
Total Labour Cost	795.00	530.00

1/22/2020

<https://vacswb.smrt.com.sg/Estimation.aspx>

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spray Painting	616.00	432.00
Other	0.00	0.00
Overall Total	1,411.00	962.00
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	962.00
Surveyor Approved Amount		962.00
No of Repair Days*	2	1
Remarks	-	Surveyor Remarks
Surveyor Name		Sun Pin (LKK)
Signature		
Survey Date	22/01/2020	Save Clear

Repair day 1 day

P/P

After paint photo.

Sun Pin (LKK)

03/02/2020

TP without prepa.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/02/2020

User ID : CatherineLee

Section A - Accident Details

Registration Number	SMB1418H
Case Reference Number	BUS/12/19/5048
Registration Date	6/1/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Hamzah Bin Mohamed
Type of Accident	Head to Rear
Accident Date and Time	27/12/2019 4:08 PM
Accident Reported Date and Time	30/12/2019 2:32 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105490
Special Instruction to ARC, if any	SMB1418H-REAR PORTION EM323R (TP) INSURED WITH AIG
Prepared Date and Time	18/1/2020 11:44 AM
Chassis Number	WMAA22ZZ4D7002006
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$616.00	\$432.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,411.00	\$962.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Kim Bock Sim	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	22/01/2020 12:16 PM	22/01/2020 1:43 PM
Signature	☒	
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

P/P
\$962
1 days



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/02/2020

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$795.00	\$530.00
Total Labour	\$795.00	\$530.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$616.00	\$432.00
Total Spray Painting & Panel Beating	\$616.00	\$432.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010064	Body	F01001-CW274	BUMPER:REAR,CENTR E, FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	Repair
Total					\$1,868.80		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Oi Sun Pin (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Tuesday, 18 February, 2020 6:54 PM
To: 'Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses)'
Subject: RE: Finalisation - SMB1418H (BUS/12/19/5048) - AIG

Hi Catherine,

Confirm the finalize amount \$962. Repair day 1 day under part by part repair.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses) [<mailto:catherineleesc@smrt.com.sg>]
Sent: Tuesday, 11 February, 2020 2:48 PM
To: Oi Sun Pin (LKK Auto); SUR; Admin A
Cc: Koo Yew Chung (Auto Svcs/ARC/ARC); AutoSvs-ARC (Bus)
Subject: Finalisation - SMB1418H (BUS/12/19/5048) - AIG

Hi Sun Pin,

Attached herewith our copy of the bus repair estimate for the case.

Our finalised amount is \$962.00 @ 1 working day under part by part repair. Attached after repair photos for your perusal.

Please confirm the COR by return email ASAP.

Thank you

Best Regards
Catherine Lee
SMRT Automotive Services Pte Ltd
(Accident Repair Centre)
DID: 6866 2669 Fax: 6368 5592
catherineleesc@smrt.com.sg

