

22032002

ASS. REC. BY:

REF:

CS / M420002453 / Kuf3

Special Instruction:

Surveyor:

Kenech

ASSIGNMENT (Office)

From (Person):

Subramaniam

of

AIG

Date/Time:

12/2/20

Estimated Cost:

Bill to:

OD / PP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 70284

Insured:

Shup 47295

at Workshop m/s

S THREE

Tel:

96620282 Joey

of

B1K 8 S/m Ind. Est. #01-64/66

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04/2/20

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12/02/20 @ 2:56pm

Person Contacted:

Yun Zheng

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate (✓)

YP 70284 - X

Shup 47295 CS/M420002087 Hvd3 borr: 04/2/20

3/3/20

@ 158pm Joey said vehicle still under repair

13/3/20

@ 430pm Joey said vehicle still under repair

ASS. REC. BY:

REF:

AIG /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YP 702801

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Iruzy NPR75L c.c.

Colour

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading

1P5422

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JAA NPR75KN 7100754

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/85R16

R:

(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

99

mm

L/Bal.

6

mm

L/Bal.

99

mm

D.O.A.

4/2/20

D.O.A.

12/2/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

PRE-REPAIR INSPECTION REQUEST – YP7028U vs SMP4729S (OI) on D.O.A.: 04/02/2020

From: Subramaniam, Divyashni
To: assignments@lkkauto.com, 'Admin A'
Cc: Lim, Kok-Chong, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Hor, Yinrul, Teo, Ericweihong, Serene Chui Yoke Har
Sent: 2/12/2020 2:00:01 PM
Attachments:  Pre-Repair Survey_AIG Asia Pacific Insurance Pte Ltd.pdf

Hi,

Please refer to the enclosed request from **Liberty Law Practice LLP**.

Claim no : 2372049462SG003
Case Owner : Lee Ming Yao

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.*

Thanks & Regards,

Divyashni Subramaniam
AIG
FNOL Adjuster I
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1012103
Divyashni.Subramaniam@aig.com | www.aig.sg

*Velu: in
T: 17/02/20 @ 2561
C: Yan Zheng
E: ✓
Kenneth*

From: Serene Chui Yoke Har <serene@libertylaw.com.sg>
Sent: Wednesday, February 12, 2020 10:06 AM
To: Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Teo, Ericweihong <Ericweihong.Teo@aig.com>
Subject: [EXTERNAL] Re: YOUR REF: 2372049462SG/003; CS/1017/20/S3. PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMP4729S AND YP7028U ON 04/02/2020

This message is from an external sender; be cautious with links and attachments.

Dear Divyashni Subramaniam,

We refer to your letter dated 11 February 2020.

Kindly arrange for **Kenneth Kong from LKK Auto Consultants Pte Ltd**, to carry out the pre-repair survey of our client's vehicle YP 7028U as a 'single joint expert'.

Please be informed that the said vehicle can be surveyed / inspected at:

Venue : **S Three Automotive Recovery Pte Ltd**
Blk 8 Sin Ming Industrial Estate
#01-64/66
Singapore 575643
Contact / Tel : **Ms. Joey / 9662 0282**

Kindly acknowledge receipt hereof.

Regards,
Serene
for and on behalf of Christine Sekhon
Liberty Law Practice LLP
10 Hoe Chiang Road
#13-03A Keppel Towers
Singapore 089315
DID: 3152 0980

Privileged and/or confidential information may be contained in this email or its attachments. If you are not the intended recipient, you must not disclose, copy or distribute the contents therein or take any action in reliance of such contents. Communication of any information in this email or its attachments to an unauthorized person is prohibited

Please consider the environment before printing this e-mail!

On Tue, Feb 11, 2020 at 3:26 PM Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com> wrote:

This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2020-02-18 01:26 CST to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2019 Proofpoint, Inc. All rights reserved.

From: Divyashni.Subramaniam@aig.com
To: serene@libertylaw.com.sg

Cc: Kok-Chorig.Lim@aig.com ,Lee-Ying.Chin@aig.com ,NoorMarlesa.AbuKassim@aig.com ,Yinrul.Hor@aig.com ,Divyashni.Subramaniam@aig.com ,Ericweihong.Teo@aig.com

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMP4729S AND YP7028U ON 04/02/2020

Date: Tue, 11 Feb 2020 07:26:19 +0000

Without Prejudice

Your Reference : CS/1017YIN/20/S3

Our Reference : 2372049462SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Divyashni Subramaniam

AIG

FNOL Adjuster I

Auto Claims | AIG Asia Pacific Insurance Pte, Ltd.

Tel: 8001206556 | Ext: 1012103

Divyashni.Subramaniam@aig.com | www.aig.sg

From: Serene Chui Yoke Har <serene@libertylaw.com.sg>

Sent: Tuesday, February 11, 2020 2:18 PM

To: Hor, Yinrul <Yinrul.Hor@aig.com>

Subject: [EXTERNAL] Your insured: SMP 4729S. Pre-Repair Survey for YP 7028U. Our ref no.: CS/1017YIN/20/S3

This message is from an external sender; be cautious with links and attachments.

Accident on 04.02.2020 involving YP 7028U and SMP 4729S along SLE towards BKE.

Dear Sirs,

We refer to the above matter.

Please find the attached copy of the Notice to Conduct Pre-Repair Survey dated 11 February 2020 together with our client's Accident Statement /Traffic Police Report and accident scene photographs for your necessary action.

Kindly acknowledge receipt hereof.

Regards,

Serene

for and on behalf of Christine Sekhon

Liberty Law Practice LLP

10 Hoe Chiang Road

#13-03A Keppel Towers

Singapore 089315

DID: 3152 0980

Privileged and/or confidential information may be contained in this email or its attachments. If you are not the intended recipient, you must not disclose, copy or distribute the contents therein or take any action in reliance of such contents. Communication of any information in this email or its attachments to an unauthorized person is prohibited

Please consider the environment before printing this e-mail!

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/02/2020 22:32
Date Of Accident	04/02/2020 07:25
Exact Location Of Accident	SLE- BKE 11.2KM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP7028U
Insured/Policyholder	
Name Of Registered Owner	CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD
Co Reg No	2XXXXX882K
Email Address	JEREMYC_QUEK@CERTISSECURITY.COM
Mobile Phone No	
Alternative Phone No	OFFICE-68428849

Vehicle Particulars

Manufacturer	ISUZU
Model	NPR75L-5.2 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D-19093619MFVS/21
Cover Note Number	

Driver

Name of Driver	MOHD HALIM BIN EHSAN
Passport No/FIN	GXXXX762L
Date Of Birth	26/12/1982
Occupation	OUTDOOR
Date Of Driving Pass	14/02/2012
Driving Experience	7 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97746026

Fax Number	
Contact Number	
Email Address	JEREMYC_QUEK@CERTISSECURITY.COM

Address	C/O: 20 JALAN AFIFI
Postcode	409179
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MUHAMMAD KHAIRUDIN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REPORT NO: F/20200204/2023

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMP4729S
Vehicle Make/Model/Colour	AUDI A4
Details Of Properties	VEH B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Insured Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or a falsifying of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by a suitable consultant is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the UK Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you/they consent to the archiving of this report at the centre and to a copy of the report being made available if needed.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) I, my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident will be collectively referred to as the "Insurers"), the Insurers' lawyer/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claim including the settlement of the claim and any necessary investigations relating to the claim;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my obligations or responding to any enquiries by me;
 - (iv) administering my claim including the mailing of correspondence, statements, invoices, reports or notices to me, which might involve disclosure of certain personal data about me to bring about delivery of the same as well as of the external cover of evidence/lost passport; and/or
 - (v) complying with applicable law in administrative, law-making, hearing and/or dealing with my claim (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes and;
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or experts including their lawyers/law firms, which may be used outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for compliance with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Policyholder's Signature
Name:
NRIC/PNR No:

QUEK KIM SENG
S8013338C

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Q10001 ID: F70700204/1023

[Handwritten description of the accident circumstances follows in the lined area]

DECLARATION

I/We declare that the information and facts in this report are true and correct.

Policyholder's
Date & Time:



Driver's Signature
(If Driver is not the policyholder)
Date & Time:

10-18-2020
04-01-2020

Reporting Officer's Signature
Name:
ID/CRN No.:

[Handwritten signature]

YOUNG UNIONS
LOCAL 5

Accident Sketch Plan Pg. 1



**SINGAPORE
POLICE FORCE**



F/20200204/2023

1 of 2

POLICE REPORT (NP289),

Report No. F/20200204/2023

Police Station Of Origin
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 8 SINGAPORE
569784
Tel No: 1800-4849999

Date/Time Report Made 04/02/2020 09:52		Vide Report No.		Station Diary No. 20	
Name Of Informant MOHD HALIM BIN EHSAN		Address 50 JLN PADI RIA 16 BANDAR BARU UDA			
ID Type / ID No. FIN NO / G2010762L		Contact No. Home/Office		Mobile 97746026	
Nationality MALAYSIAN		Email Address			
Occupation Other heavy truck and lorry drivers		Sex Male	Age 37	Date of Birth 28/12/1982	Race Malay
Institution/School Name		Language			
Date/Time Of Incident 04/02/2020 07:25 - 04/02/2020 07:30		Location Of Incident SELETAR EXPRESSWAY SINGAPORE 11.2KM point			

Brief details.

I am the driver for Emas Recovery with vehicle number YP7028U, together with my Co-driver (Muhammad Khairudin, S86365491, 90024439) and was doing our daily patrols when we spotted a vehicle at the shoulder of SLE at the 11.1km and wanted to stop however it was too late as we were on lane 2. I then wanted to take the next exit which is turf club. There was a Toyota wish that swerved in front of our recovery truck which caused me to slow down and a white audi(SMP4729S) hit the back of our Recovery truck.

Signature Of Officer Recording The Report:

F / Sgt 2 NUR FARAHIN BINTI RAHMAT
122 Khairin

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
F / Ang Mo Kio North N.P.C /
Sgt 2 KERK LI PING
Contact No.: 64849999

Authentication Stamp

Signature Of Informant:

Date/Time:
04/02/2020 08:52

Classification Of Case:

Accident Sketch Plan Pg. 1



SINGAPORE
POLICE FORCE



F/20200204/2023

2 of 2

POLICE REPORT (NP288)

CONTINUATION OF REPORT

Report No. F/20200204/2023

My recovery truck suffered scratches while the other party front bumper and hood was badly damaged.
No one was injured.

I am lodging this report for record purposes.

Signature Of Officer Recording The Report: F / Sgt 2 NUR FARHIN BINTE RAHM <i>Nur Farhin</i>	Signature Of Informant: <i>[Signature]</i>
Signature Of Interpreter: Not applicable	Date/Time: 04/02/2020 09:52
Officer In-Charge Of Case: F / Ang Mo Kio North N.P. O / Sgt 2 KERK LI PING Contact No.: 64849999	Classification Of Case:
Authentication Stamp	

[Signature]

*Not Authorised
Ung 87*

TO
ATTN: **MOTOR CLAIM DEPT.**

T/P VEH. NO.: **SMP4729S**

ESTIMATE REPORT 1st QUOTATION

JOB NO: _____

OWNER'S PARTICULAR

NAME: **CERTIS CISCO AUXILIARY POLICE FORCE PTE LTD**

CONTACT: _____

ADDRESS: _____

VEHICLE NO **YP7028U** TRANS. _____

CHASSIS NO: _____

MAKE / MODEL: **ISUZU LORRY**

ENGINE NO: _____

OWNER'S INSURER **FIRST CAPITAL**

JOB-CODE: **TP** S/A: **MICHELLE**

ACCIDENT DATE: **4-Feb-20**

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC %	DISC-PRICE	SUR-DISP	REV. PRICE
1 TAILLAMP ASSY LH	1.00	\$ 450.00	10.00	\$ 405.00	Y	X
2 TAILLAMP ASSY RH	1.00	\$ 450.00	10.00	\$ 405.00	Y	X
3 REAR MUDFLAP LH	1.00	\$ 520.00	10.00	\$ 468.00	Y	X
4 REAR MUDFLAP BRACKET INNER LH	1.00	\$ 220.00	10.00	\$ 198.00	Y	X
5 REAR MUDFLAP BRACKET OUTER LH	1.00	\$ 220.00	10.00	\$ 198.00	Y	X
6 REAR MUDFLAP LOWER RUBBER - ISUZU LH	1.00	\$ 180.00	10.00	\$ 162.00	Y	X
7 REAR NO PLATE LAMP	1.00	\$ 180.00	10.00	\$ 162.00	Y	X

TOTAL (PARTS):

\$ 2,220.00

\$ 1,998.00

SPECIAL NETT ITEM

1 REAR CABIN TAILLAMP PANEL LH	1.00	\$ 680.00	0.00	\$ 680.00	Y	X
2 REAR CABIN TAILLAMP PANEL RH	1.00	\$ 680.00	0.00	\$ 680.00	Y	X
3 REAR STICKER 60KM	1.00	\$ 30.00	0.00	\$ 30.00	Y	2012
4 REAR REFLECTOR STICKER - RED	1.00	\$ 180.00	0.00	\$ 180.00	Y	5012
5 REAR REFLECTOR STICKER SIDE RH- BLUE & ORANGE	1.00	\$ 360.00	0.00	\$ 360.00	Y	X
6 REVERSE CAMERA	1.00	\$ 380.00	0.00	\$ 380.00	Y	✓
7 REAR CRANE	1.00	\$ 9,500.00	0.00	\$ 9,500.00	Y	?
8 REAR CRANE FORK	1.00	\$ 2,800.00	0.00	\$ 2,800.00	Y	X
9 HYDRAIC OIL	1.00	\$ 450.00	0.00	\$ 450.00	Y	?
10 REVERSE SENSOR 1SET	1.00	\$ 520.00	0.00	\$ 520.00	Y	X
11 EXHAUST SILENCER	1.00	\$ 1,900.00	0.00	\$ 1,900.00	Y	X
12 REAR NUMBER PLATE	1.00	\$ 50.00	0.00	\$ 50.00	Y	X
13 REAR NUMBER PLATE BRACKET	1.00	\$ 150.00	0.00	\$ 150.00	Y	X

TOTAL (PARTS):

\$ 17,680.00

\$ 17,680.00

LABOUR

1 STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	1.00	\$ 3,800.00	0.00	\$ 3,800.00	Y	?
2 SPRAY PAINTING ON ACCIDENT AREA (2 tones)	1.00	\$ 1,800.00	0.00	\$ 1,800.00	Y	7001
3 R&R CRANE TO SERVICE TO LIFT UP & DOWN	1.00	\$ 480.00	0.00	\$ 480.00	Y	?
5 CHECK & REPAIR WIRING SYSTEM	1.00	\$ 80.00	0.00	\$ 80.00	Y	151

6	RESPRAY TUFF KOTE ON AFFECTED AREA	<i>nn</i>	1.00	\$	120.00	0.00	\$	120.00	Y	<i>X</i>
7	CONDUCT CHASSIC REPAIR REAR LH PORTION	<i>nn</i>	1.00	\$	1,200.00	0.00	\$	1,200.00	Y	<i>X</i>
8	R&R REAR AXLE, AXLE SPRING & LONG SHAFT TO ASSIT REPAIR	<i>nn</i>	1.00	\$	900.00	0.00	\$	900.00	Y	<i>X</i>
9	RESET & PROGRAMME LTA SYSTEM & INSPECTION	<i>nn</i>	1.00	\$	980.00	0.00	\$	980.00	Y	<i>X</i>
10	POST ACCIDENT REPAIR INSPECTION	<i>nn</i>	1.00	\$	180.00	0.00	\$	180.00	Y	<i>X</i>

TOTAL (LABOUR) : \$ 9,540.00 \$ 9,540.00

TOTAL PARTS & LABOUR \$ 29,440.00 \$ 29,218.00

EXCESS : \$5

NO. OF DAY : *2-4 days*

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : \$5

DATE OF SURVEY : *12/2/20*

SURVEY BY : *Mennerh*

CONTACT NO : *96910663*

FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: