

ASS. REC. BY:

REF: CS/AIG 20002459/UY f3ⁿ²

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Subramaniamof AIGDate/Time: 2.12.2020 2.04p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 3387 X

Insured:

SMH 6863 K

at Workshop m/s

Autobay bte U D

Tel:

8618 6116of 1 Kaki Bukit Ave 6 # 02-11

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 5.2.2020

CA / REV / REP. / REV 24 HRS

(imp)13/11/2020

H.O.D. Endorsement:

Date/Time:

12/12/2020 3.44p.m

Person Contacted:

LimVehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJS 3387 X - CC4/LPC 1701155/EL 63/2 R.M. - 07/06/2017SMH 6863 R - X

REF: AIG

ASSIGNMENT

SJE Manus

From:

Date:

13/11/2020

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJS 3387X

at Workshop m/s Autobay Pie WD
of 1 Paki Bukit Ave 6 #102-11

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

42k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp' LTA 24117

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJS3387X

Yr Regn:

8, 09

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A /

Make:

Toyota Corolla Altis 1598

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

117195

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR0532EE106151982

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N / S / Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

5/12/20

D.O.I.

13/2/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

LH O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Coe 30-4-2029

2/2/20

1/5 #1300 conf. with victor (Red \$319350, 71%)

RECEIVED 24 FEB 2020

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

2/2/20 Typist

Report Format:

Lump Sum / I.B.I. (\$

\$1300/

Days Of Repair:

3

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

250

11

261

PRE-REPAIR INSPECTION REQUEST – SJS3387X vs SMH6863R (OI) on D.O.A.: 05...

From: Subramaniam, Divyashni
To: assignments@lkkauto.com, 'Admin A'
Cc: Lim, Kok-Chong, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Hor, Yinrul, Teo, Ericweihong, Sally
Sent: 2/12/2020 2:02:41 PM
Attachments:  200211.pdf

Hi,

Please refer to the enclosed request from **Catherine Lim LLC**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.

Thanks & Regards,

Divyashni Subramaniam
AIG
FNOL Adjuster I
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1012103
Divyashni.Subramaniam@aig.com | www.aig.sg

veh; in
7 = 12/11/20 @ 3p
C: Mr Lim
E: ✓
Marcus
for survey.

From: Sally <info@catherinelimllc.com>
Sent: Wednesday, February 12, 2020 11:42 AM
To: Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Teo, Ericweihong <Ericweihong.Teo@aig.com>
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMH6863R AND SJS3387X ON 05/02/2020

This message is from an external sender; be cautious with links and attachments.

Dear Sir (Without Prejudice)

We refer to your email.

Our client is agreeable to Marcus Chua – LKK Auto. Please arrange.

Regards
Sally Goh
Catherine Lim LLC
20 Havelock Road #03-01
Central Square
Singapore 059765
Email: info@catherinelimllc.com

From: Subramaniam, Divyashni [<mailto:Divyashni.Subramaniam@aig.com>]

Sent: Tuesday, February 11, 2020 4:48 PM

To: Sally

Cc: Lim, Kok-Chong; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Hor, Yinrul; Subramaniam, Divyashni; Teo, Ericweihong

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMH6863R AND SJS3387X ON 05/02/2020

This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2020-02-18 03:47 EST to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2019 Proofpoint, Inc. All rights reserved.

From: Divyashni.Subramaniam@aig.com

To: info@catherinelimllc.com

Cc: Kok-Chong.Lim@aig.com , Lee-Ying.Chin@aig.com , NoorMariesa.AbuKassim@aig.com , Yinrul.Hor@aig.com , Divyashni.Subramaniam@aig.com , Ericweihong.Teo@aig.com

Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SMH6863R AND SJS3387X ON 05/02/2020

Date: Tue, 11 Feb 2020 08:47:43 +0000

Without Prejudice

Your Reference : CL/200212/T/AB

Our Reference : SMH6863R

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Divyashni Subramaniam

AIG

FNOL Adjuster I

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1012103

Divyashni.Subramaniam@aig.com | www.aig.sg

From: Sally <info@catherinelimllc.com>

Sent: Tuesday, February 11, 2020 2:42 PM

To: ClaimsDocManagement <ClaimsDocManagement@aig.com>

Subject: [EXTERNAL] YOUR REF: SMH 6863R OUR REF: CL/200212/T/AB

This message is from an external sender; be cautious with links and attachments.

Dear Sir

Please find attached, pre repair notice for your attention.

Regards

Sally Goh

Catherine Lim LLC

20 Havelock Road #03-01

Central Square

Singapore 059765

Email: info@catherinelimllc.com

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
翠 NOTARY PUBLIC - 公证官
玲 COMMISSIONER FOR OATHS - 宣誓官
律
師 CATHERINE C.L. LIM
館 DIRECTOR
LL.B (HONS) SINGAPORE - 法律系 - 律師
M.B.A. (BUSINESS LAW) - 商业系 - 碩士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K

Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation
with limited liability

Your Ref: SMH 6863R
Our Ref: CL/200212/T/AB.sg

11 February 2020

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120
Attn: Motor Claims Department

via fax: 6415 3727 & By Hand

Li Shunhua Sylvia
89 Dawson Road
#21-06
Singapore 142089

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

ACCIDENT INVOLVING SJS 3387X / SMH 6863R ON 5.2.2020 LONG ENG WATT STREET

We are instructed by VM Auto Leasing to notify you of a road traffic accident involving our client's vehicle No. SJS 3387X and vehicle No. SMH 6863R driven by you at the material time. A copy of the Singapore Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within **2 working days** of your receipt of this notice whether you/your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: Autobay Pte Ltd
1 Kaki Bukit Avenue 6
#02-11
Autobay @ Kaki Bukit
Singapore 417883

Contact 8618 6116 / 9371 6693

Yours faithfully


cc: clients

Advanced Search

Home » Used Cars » Creative Auto » Toyota Corolla Altis 1.6A Elegance (COE till 09/2029)

Toyota Corolla Altis 1.6A Elegance (COE till 09/2029)

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)
CREATIVE
AUTO

Price	\$46,888		
Depreciation	\$4,870 /yr	Reg Date	26-Nov-2009 (9yrs 7mths 17days COE left)
Mileage	107,112 km (10.5k /yr)	Manufactured	2009
Road Tax	\$816 /yr	Transmission	Auto
Dereg Value	\$28,411 as of today (change)	OMV	\$17,853
COE	\$29,485	ARF	\$17,853
Engine Cap	1,598 cc	Power	80.0 kW (107 bhp)
Curb Weight	1,195 kg	No. of Owners	2
Type of Vehicle	Mid-Sized Sedan		

Features

Responsive 1.6L DOHC 16V VVT-I Engine, 5 Speed Auto Transmission, ABS/Dual SRS Airbags, Retractable Side Mirrors With Indicators, Knockdown Rear Seat. View specs of the Toyota Corolla Altis (2008-2013)

Accessories

16" Sports Rims, Premium Leather Seats, Upgraded Pioneer Touchscreen DVD Audio System With Reverse Camera/Steering Controls, Fog Lamps, Remote Alarm.

Description

With Our Flexible Bank/In House Financing That Our Company Provide. Meticulously Well Maintained By Previous Owner With Beautiful Interior Assured! Guaranteed Accident Free With Low Mileage Done! So Hurry Don't Miss Call Us Now For A Viewing Or Test Drive Appointment Now!

Category

COE Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started


[Shortlist](#)
[Compare](#)
[Add note](#)
[Report Error](#)
[More Actions](#)

Seller Information

Creative Auto

96 vehicles for sale. 94 sold in past 3 mths

61 Ubi Avenue 2 #04-02/03/18/19/20
Automobile Megamart
[Search Cars nearby](#)

NEO 92222719
Alex Tan 97556887

Posted on: 12-Feb-2020 | Last Updated on: 12-Feb-2020

Upfront Payment

» more Financial info

Used Car List | Company Profile

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	844X
Vehicle Details	
Vehicle No.:	SJS3387X
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4920879
Chassis No.:	MR053ZEE106151982
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	12 Aug 2009
First Registration Date:	12 Aug 2009
Transfer Count:	2
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$26,175.00
COE Rebate Amount:	\$24,117.00
Total Rebate Amount:	\$24,117.00

The information contained herein is correct as at 13 Feb 2020

OK

Regn No : SJS3387X

Vehicle Make & Model : Toyota Corolla Altis

ITEM NO	DESCRIPTION OF ITEMS	QUANTITY (Piece/Set)	UNIT PRICE (S\$)	AMOUNT (S\$)
List Items:				
1	Front bumper <i>20/02</i>	1	\$ 530.00	\$ 530.00 ✓
2	Front bumper side retainer <i>11</i>	2	\$ 48.00	\$ 96.00 X
3	Front bumper reinforcement <i>11</i>	1	\$ 350.00	\$ 350.00 X
4	Front bumper clip <i>11</i>	<i>10/set</i>	\$ 5.00	\$ 50.00 ✓
5	Front fender RH <i>1</i>	1	\$ 380.00	\$ 380.00 X
6	Front fender splash shield RH <i>11</i>	1	\$ 125.00	\$ 125.00 ✓
7	Front fender splash shield clip <i>11</i>	<i>10/set</i>	\$ 5.00	\$ 75.00 ✓ <i>50</i>
8	Front headlamp RH <i>SCA</i>	1	\$ 480.00	\$ 480.00 ✓
9	Fog lamp RH <i>11</i>	1	\$ 275.00	\$ 275.00 X
10	Fog lamp cover/garnish RH <i>11</i>	1	\$ 75.00	\$ 75.00 X
11	Fog lamp cover chrome <i>11</i>	1	\$ 62.00	\$ 62.00 X
			Sub-total	\$ 2,498.00
			Less 25% List Items	\$ 624.50
			Total	\$ 1,873.50

Special Nett Items:				
1	Front number plate with holder <i>11</i>	1	\$ 60.00	\$ 60.00 X
			S/Nett Items Total	\$ 60.00

Labour Charge Items:				
1	To checking electrical wiring and check functions		\$ 60.00	20
2	To do wheel alignment		\$ 200.00	X
3	To respray undercoating/rust proofing		\$ 100.00	X
4	To respray painting & etc		\$ 1,000.00	400
5	Panel beating, cut, weld, remove and replacing above parts		\$ 1,200.00	280
			Labour Charge Total	\$ 2,560.00

Estimate Parts & Labour

Grand total \$ 4,493.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Not Authorized
Date 13/1/20
1/3 @ 1300
3 days.

1235
25%
926.45
1026.25
1301

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20002459/UYF3N2
Date: 26/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900008785
Claimant Vehicle No : SJS3387X **Insured Vehicle No :** SMH6863R
 Date of Loss: 05/02/2020 Nature of Claim: TP Claim No: 8132447545SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS3387X**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4920879
 Reg. Date: 12/08/2009 (Man. Year: 2009) Chassis No: MR053ZEE106151982
 Colour: Grey Odometer: 117195 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	1,933.50	926.25	1,007.25	52.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	700.00	1,860.00	72.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,493.50	1,626.25	2,867.25	63.81
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	4,493.50	1,300.00	3,193.50	71.07

INSPECTION

Date of Assignment: 12/02/2020
 Date Inspected: 13/02/2020 Inspected At: Autobay Pte Ltd (kaki Bukit) (HQ)
 1 KAKI BUKIT AVE 6, #02-11
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented/Deformed	530.00 FL	*530.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	96.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	350.00 FL	*- FL
4	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
5	1		*FRONT FENDER RH	Repair	380.00 FL	*- FL
6	1		*FRONT FENDER SPLASH SHIELD RH	Torn	125.00 FL	*125.00 FL
7	1		*SET FRONT FENDER SPLASH SHIELD CLIP	Necessary	75.00 FL	*50.00 FL
8	1		*FRONT HEADLAMP RH	Scratched	480.00 FL	*480.00 FL
9	1		*FOG LAMP RH	Not Necessary	275.00 FL	*- FL
10	1		*FOG LAMP COVER/GARNISH RH	Not Necessary	75.00 FL	*- FL
11	1		*FOG LAMP COVER CHROME	Not Necessary	62.00 FL	*- FL
12	1		*FRONT NUMBER PLATE WITH HOLDER	Not Necessary	60.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	2,558.00	1,235.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	624.50	308.75
Total Parts (\$\$)	1,933.50	926.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECKING ELECTRICAL WIRING AND CHECK FUNCTIONS	New	60.00	20.00
2	TO DO WHEEL ALIGNMENT	New	200.00	0.00
3	TO RESPRAY UNDERCOATING/RUST PROOFING	New	100.00	0.00
4	TO RESPRAY PAINTING & ETC	New	1,000.00	400.00
5	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	1,200.00	280.00
Gross Labour Cost (\$\$)			2,560.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >