

ASS. REC. BY:

Steve

REF:

PC1

ASSIGNMENT

From:

Date:

19.2.2020

Estimated Cost:

OD (TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SKX 73186

at Workshop m/s Cycu a carriage

of 209 Pandan Gardens

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh: 2pm owner waiting

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
XX	

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKX 73186

Yr Regn:

28/12/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Attrage

c.c

1193

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

95878

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MMIB STA 13A FH 91828

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/50R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

9/2/20

D.O.I.

19/2/20

Survey held at

C & C Pandan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-45K

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / L.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

3023

302