



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20002487/Hpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 14-07-2020



ATTN:PETER

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGG 5598P	Veh. Inspected	SJY 5766R
Policy No.	VA1/GA523544	Coverage (\$)	0.00
Claim No.	S0M02F62	Excess (\$)	0.00
Assign From		Assign Date	13/02/2020

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KNAFU411MA5228425	Colour	BLACK
Odometer	119530	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/02/2020	Inspection Date	13/02/2020
Survey held at	8 Kaki Bukit Ave 4 #08-46 Premier @ Kaki Bukit		
Repairer	SPEED AUTO WORKS		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------