

ASS. REC. BY: Steve

REF: CS/MSG20902502/F3 Esf3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: GBH 7313K Yr Regn: 13/9/18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: NISSAN NV350 c.c. 2498
 Colour: SH WHITE A/C: Insured / Std / NI / NA
 Sp. Reading: 73772 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JN1MC1E 2620909084
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: NII / S/Rim / STD AIR / Rim or

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input checked="" type="checkbox"/>	<input type="checkbox"/>

Tyre Size: F: 195R15C
 R: h
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or 2
 Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 4/2/20 D.O.I. 27/7/20
 Survey held at Efficent Motors
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-60K</u>

Date/Time, File Pass to? : Prell. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Rep. Format: _____
 Lump Sum / U.E.I. / _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	_____
Transportation:	_____
S + RS, SI	_____
Phone	_____
Others	_____
TOTAL	_____

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBH7313K

MAKE & MODEL : NISSAN NV350

CHASSIS NO : JN1MC2E26Z0009084

TO : INDIA INTERNATIONAL INSURANCE PTE LTD

*Store (LKK) with Mr
27/7/20, 10.30am
3 days
L/S
By All SM*

DATE : 27 JUL 2020

CLAIM TYPE : TP CLAIM

D.O.A : 04 FEB 2020

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	FRONT BUMPER X R		\$ 514.79	\$ 514.79
2	1	FRONT BUMPER SIDE RETAINER LH	BR	\$ 146.00	\$ 146.00
3	1	HEADLAMP ASSY LH X		\$ 468.00	\$ 468.00
4	1	FRONT CORNER PANEL LH X		\$ 477.00	\$ 477.00
5	1	FRONT DOOR LH X R		\$ 1,015.00	\$ 1,015.00
6	2	FRONT DOOR HINGE LH X		\$ 79.00	\$ 158.00
7	1	FRONT DOOR GLASS LH	BR	\$ 936.00	\$ 936.00
8	1	FRONT DOOR GLASS COVER LH	Cut	\$ 228.00	\$ 228.00
9	1	FRONT DOOR SIDE MIRROR LH	BR	\$ 912.00	\$ 912.00
10	1	FRONT DOOR RUN CHANNEL LH X		\$ 156.00	\$ 156.00
11	1	FRONT DOOR OUTER MOULDING LH	Cut	\$ 240.00	\$ 240.00
				\$ 5,171.79	\$ 5,250.79

TOTAL PRICE	\$ 5,250.79
LESS 10%	\$ 525.08
SUB TOTAL PRICE	\$ 4,725.71

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	FRONT BUMPER CLIP SET	MC	\$ 50.00	\$ 50.00
2	1	FRT DOOR CO. REG. STICKER	MC	\$ 80.00	\$ 80.00
TOTAL S/NETT				\$ 130.00	\$ 130.00

Labour Charges

1	To panel beat & align door, remove & replace damaged parts.	\$ 800.00	300
2	To apply anti rust coat and Tuff Kote repaired areas	\$ 100.00	30
3	To check and rectify lighting & wiring.	\$ 50.00	30
4	To Spray painting for Front LH Portions, & other affected areas.	\$ 800.00	500
5	To transfer front door glass & components.	\$ 150.00	X
6	To do artwork company sticker.	\$ 350.00	100
7	To do tyre balancing & wheel alignment	\$ 100.00	X

TOTAL LABOUR

\$ 2,350.00

Total Cost of Repairs

\$ 7,205.71

(Total parts + Total S/Nett + Total Labour Cost)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: