

ASS. REC. BY:

REF: es3/smo20002549/Gsd3st

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Grace Teo

of SMD

Date/Time: 13/02/2020 @ 11:13am

Estimated Cost: _____ Bill to: _____

OT / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLJ 7155 X

Insured: FBJ3222E

at Workshop m/s Apex Motoring

Tel: 9169 0825

of 25 Kaki Bukit Road 4 # 01-SS synergy

Policy No: _____ Claim No: CMPD2000670/RUC

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 05/02/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS 1wp)

H.O.D. Endorsement:

Date/Time: 11:55am @ 13/2/2020 Person Contacted: Ms. Lim

Vehicle IN / OUT

Date/Time	Action/Instruction	Signature (X)
	SLJ 7155X - X	
	FBJ 3222E - X	
14/02/20	@ 11:07 am checked with Ms. Lim, no estimate.	

ASS. FILED BY: bul
PRS

REF:

ASSIGNMENT

From _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop m/s Apex Motoring
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SLJ 7155 X yr Regn: - 2016
Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Toyota Ahtis cc 1598
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 248525 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: NR053REH 10.455 7450
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/55 R16
R: 11

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 13-02-20
Survey held at w/s
Des. of Damages Frnt / Rear / O/S / NIS / UIC / Rooftop or _____

Bal. or Market Value: _____
IDAC Accident Rport: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 7 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$ 7000 - \$ 8000</u>
	<u>14/2/2020</u>
	<u>Dismantle: 14/2/2020</u>

Date/Time, File Pass to? 14/02/20
1) Typist
Date/Time, File Return to?
2) _____

: Preli. Report
 : Final Report

Days Of Repair: 7
Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Insp (\$)
 : Wash and (\$)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Other:	
TOTAL	

Report Formed: PRS
Lump Sum / L.R. \$ _____

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 13 February 2020 11:13 AM
To: peijie@expresscar.com.sg; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; sur@lkkauto.com
Cc: Chua, Gek Tiang Ruth; Ye, Yong Kang Melvin
Subject: CMTD2000670/RUC - PRI(LKK)/ FBJ3222E(NR) & SLJ7155X ACC on 05/02/2020 @ 2320Hrs
Attachments: Untitled_11022020_171445.pdf

Our Reference : CMTD2000670/RUC
Your Reference : SLJ7155X

Without Prejudice
EMAIL ONLY

Date: 13.02.2020

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S APEX MOTORING

Dear Pei Jie,

ACCIDENT INVOLVING FBJ3222E & SLJ7155X ON 05.02.2020

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Aside to **LKK AUTO**,

Please make the arrangement to survey for **SLJ7155X** on a without prejudice and any admission of liability basis.

Please revert your report upon completion of survey to my colleague, **Ms. Ruth.**

Thank you.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

-----Original Message-----

From: peijie@expresscar.com.sg <peijie@expresscar.com.sg>

Sent: Thursday, February 13, 2020 10:32 AM

To: Teo, Grace <grace.teo@sompo.com.sg>

Cc: Chua, Gek Tiang Ruth <ruth.chua@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: Re: CMTD2000670/RUC - PRI/ FBJ3222E & SLJ7155X ACC on 05/02/2020 @ 2320Hrs

Dear Sir,

We do not agree to your list of surveyor.

Refer below for our list of surveyor :

- 1) Kelvin Teo – Kelvin Automotive Appraising Services
- 2) Chang Fuh Keong, Dave – Sincere Appraisal Services
- 3) Ho Joo Loong, Danny – HJL Auto Appraiser Services
- 4) Lee Kok Weng – Lee Automobile Appraisers Services
- 5) Terrence Hong – Kelvin Automotive Appraising Services
- 6) Ong Ah Keng, Kent – KTO Automobile Assessors
- 7) Ong Poh Meng – Aeon Auto Consultants LLP
- 8) Philip Foo – Presicion Appraisal Services
- 9) Thor Teck Soon, David – JAS Appraisal Services

Best Regards,

Peijie

82 Lorong 23 Geylang

#03-06 ATRIX

S(388409)
DID: 91690825

On 2020-02-12 14:28, Teo, Grace wrote:

> Our Reference : CMTD2000670/RUC

>

> Your Reference : SLJ7155X

>

>

> WITHOUT PREJUDICE

>

>

> EMAIL ONLY

>

> Date: 12.02.2020

>

>

>

>

> OUR EMAIL: MOTORSURVEY@SOMPO.COM.SG

>

> ATTENTION:

>

> M/S APEX MOTORING

>

> Dear Pei Jie,

>

> ACCIDENT INVOLVING FBJ3222E & SLJ7155X ON 05.02.2020

>

> We refer to your Notice of Accident dated 11.02.2020.

>

> Please be informed that MS. RUTH CHUA the handler of this case who can

> be contacted at 63295 153/ ruth.chua@sompo.com.sg .

>

> We intend to conduct a pre-repair survey of the damage to your
> client's/your customer's vehicle jointly with your client/your motor
> workshop. We propose to use one of the motor surveyors named in the
> attached list to conduct the joint pre-repair survey as a single joint
> expert.

>

> PRE-REPAIR SURVEY

>

> MOTOR SURVEYOR

>

> SURVEYOR

>

> SELECTION (INDICATE AS TICK)

>

> 1

>

> Raleigh Services

>

> Andrew Ow Yong

>

> Vincent Ng

>

> 2
>
> LKK Auto Consultants
>
> Kenneth Kong (North area)
>
> Marcus Chua (East area)
>
> Mohd Rasul (West area)
>
> Mohd Taufikh (West area)
>
> 3
>
> Priority Services
>
> Jimmy Lee
>
> Lawrence Ng
>
> Jeffery Ong
>
> Please let us know within TWO (2) WORKING DAYS whether you agree to
> the appointment of any of these motor surveyors as a single joint
> expert. You may select up to two of the listed motor surveyors. We
> will bear the cost of the pre-repair survey carried out by the single
> joint expert.
>
> Best Regards
>
> GRACE TEO
>
> Claims Division
>
> D: 6329 5170 | T: 6461 6555 | F: 6221 3147
>
> FOR MOTOR CLAIMS SURVEY REQUEST, PLEASE EMAIL TO
> MOTORSURVEY@SOMPO.COM.SG
>
> SOMPO INSURANCE SINGAPORE PTE. LTD.
> 50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
> WEBSITE: www.sompo.com.sg [1] | FACEBOOK: www.facebook.com/SompoSG [2]
>
>
> QUICK & EASY CLAIMS SUBMISSION¹ & PRODUCT PURCHASE² VIA SOMPO SG
>
> DOWNLOAD NOW @ [3] OR [4]
>
> 1 For Travel, Personal Accident & Home Insurance | 2 For Travel,
> Personal Accident, Home & Private Motor Insurance
>
> DISCLAIMER: This e-mail, including attachments, is intended for the
> person(s) or company named and may contain confidential and/or legally
> privileged information. Unauthorised disclosure, copying or use of
> this information may be unlawful and is prohibited. If you are not the
> intended recipient, please delete this message.

>
> PRIVACY POLICY NOTICE: Sompo Insurance Singapore Pte. Ltd. may
> collect, use and disclose your personal data for the purposes stated
> in our Privacy Policy. This may include disclosure to holding and
> associated companies, credit bureau, parties to whom disclosure is
> permitted/required by laws, our third party service providers and
> agents (acting on our behalf). Please click here [5] for our Privacy
> Policy
>
> -----Original Message-----
> From: peijie@expresscar.com.sg <peijie@expresscar.com.sg>
> Sent: Tuesday, February 11, 2020 5:18 PM
> To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>
> Subject: Accident between vehicle no SLJ7155X and Vehicle no FBJ3222E
> on 05/02/2020 @ 2320Hrs
>
> Dear Sir/Madam,
>
> Refer to attach for PRI.
>
> Send us your list of surveyor within two working days.
>
> ---
>
> Best Regards,
>
> Peijie
>
> 82 Lorong 23 Geylang
>
> #03-06 ATRIX
>
> S(388409)
>
> DID: 91690825
>
>
>
> Links:
> -----
> [1] <http://www.sompo.com.sg/>
> [2] <http://www.facebook.com/SompoSG>
> [3] <https://itunes.apple.com/sg/app/sompo-sg/id1387425777>
> [4]
> <https://play.google.com/store/apps/details?id=sg.com.sompo.sompoapp>
> [5] <https://www.sompo.com.sg/prc>



11/02/2020

SOMPO INSURANCE PTE LTD
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623
Email: motorsurvey@sompo.com.sg

Dear Sirs

**ACCIDENT BETWEEN VEHICLE NO. SLJ 7155 X AND VEHICLE NO. FBJ 3222 E
ON 05/02/2020 @ 2320 HRS**

We are the appointed repair workshop of vehicle no. **SLJ 7155 X**.

We understand that you are the insurer of vehicle no. **FBJ 3222 E**.

The owner of vehicle number **SLJ 7155 X** has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

The vehicle is now at our workshop awaiting for your inspection at the following address: 25 Kaki Bukit Road 4 #01-55 Synergy@KB Singapore 417800

Mobile No. 9169 0825 Miss Lim. **Kindly email 10 surveyors list to us.** Thanks.

Yours faithfully



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/02/2020 12:12
Date Of Accident	05/02/2020 23:20
Exact Location Of Accident	CROSS JUNC BET PASIR PANJANG RD CLEMENTI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ7155X
Insured/Policyholder	
Name Of Registered Owner	ASIA EXPRESS CAR RENTAL PTE LTD
Co Reg No	2XXXXX882D
Email Address	PEIJIE@EXPRESSCAR.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-96253682

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS CLASSIC 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	B 29119902 MCX
Cover Note Number	

Driver

Name of Driver	NG KIAT ENG
NRIC No	SXXXX631Z
Date Of Birth	03/11/1989
Occupation	OUTDOOR
Date Of Driving Pass	15/01/2010
Driving Experience	10 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81833834
Fax Number	
Contact Number	OTHERS-96345284
Email Address	NOEMAIL

Address BLK 468B ADMIRALTY DRIVE #10-81
 Postcode 752469
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : GRAB PASSENGER
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER ATTACHED;

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: WITH OWNER/DRIVER
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBJ322E
 Vehicle Make/Model/Colour YAMAHA / YZF-R15 MANUAL
 Details Of Properties
 Vehicle Category MOTORCYCLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my vehicle and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers) who have insured vehicles involved in this accident and to call on my records about the "insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which may include disclosure of certain personal data about me to bring about delivery of the same as well as on the essential part of correspondence and/or
 - (v) communicating with the relevant government agency/authority in connection with my claims (including the settlement).
- (b) all insurers may have indemnity liability to each other and the insurers' lawyers/law firms may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above purposes and;
- (c) my Personal Information may be disclosed by any of the insurers and/or GIA to their third party service providers, agents, including their lawyers/law firms, which may be established in Singapore, or one or more of the above purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing claims; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or


 Policyholder's Signature
 Date & Time: 11/02/2020
 4:59pm



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 11/02/2020
 4:59pm

23 Kallang Road, #02-02
 Singapore 418933
 Tel: 67416697 Fax: 67492805
 Email: vackb@viam.com.sg

Reporting Centre Personnel's Signature
 Name:
 NRIC/IN No.:
 12 FEB 2020

Accident Sketch Plan

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling straight in vehicle A along Clementine Road, along cross junction between East Parkway Road, I was in the right of way on green light while vehicle B turned right did not give way to me and hit onto my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 11/02/2020
 4:59pm


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 11/02/2020
 4:59pm

IDAC KARI BUKIT (VAC)
 23 Kaki Bukit Ave 4 #02-02
 Singapore 415933
 Tel: 67416697 Fax: 67482305
 Email: vacbh@vloom.com.sg

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

12 FEB 2020




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO20002549/Gsd3s2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date: 17-02-2020	
		Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	FBJ 3222E	Veh. Inspected	SLJ 7155X
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2000670/RUC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	13/02/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104557450	Colour	BLUE
Odometer	248525 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	DUNLOP	6 mm
L/H Front Tyre	205/55 R16	DUNLOP	6 mm
R/H Rear Tyre	205/55 R16	DUNLOP	6 mm
L/H Rear Tyre	205/55 R16	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S BODY AND ROOFTOP.			
5. General Information			
Accident Date	05/02/2020	Inspect Date / Time	13/02/2020 (04:00 PM)
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	

Report Ref No. CS3/SMO20002549/Gsd3s2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or form, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.