

ASS. REC. BY:

REF: 08/CTI 20002552 / Hs d3 | Special Instruction:

Surveyor: Huck Am

ASSIGNMENT (Office)

From (Person): Chong Boon sen of CTI Date/Time: 13/02/2020 @ 1:23pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SCX 7973J Insured: GBJ 9152J

at Workshop in/s Comfort Design Engineering Tel: _____

at 320 ubi Road 3

Policy No: _____ Claim No: SNM 200200800 / GBJ 9152J / CBS

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. _____
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{Imp)} H.O.D. Endorsement: _____

Date/Time: 2:10pm @ 13/2/2020 Person Contacted: tinie Vehicle IN (OUT)

Date/Time	Action/Instruction
	Johnnie ✓
	SCX 7973J - X
	GBJ 9152J - X

ASSIGNMENT

From: _____ Date: 17/11/20
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SCX 7973J
 at Workshop m/s Comfortdign
 of 370 Ubi Road 3
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: 3.00p.m to 4.00p.m

Veh No: SCX 7973J Yr Regn: 18/11/2003
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: T. wish c.c. 1794
 Colour: silver A/C: Insured / Std / NI / NA
 Sp. Reading: 2757581 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 2NE100084363
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65/R15
 R: / /

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
1up'
 CA / REV / REP. / 24 HRS
 Vehicle: IN / OUT
 Date: _____ Person Contacted: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front 6 Firestone Rear 6 Firestone
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 8/2/20 D.O.I. 17/2/20
 Survey held at comfortdign
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>tiniem@sparkcare * DO Dint hv Estimate cost</u>
	<u>Tink 6848 5726 Hock Ann</u>
	<u>Sheri 6848 5725 PLS check parts prices.</u>
	<u>MV - 31000</u>
	<u>PV - 27996</u>
	<u>NV - 3000</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____
 Report Format : _____
 Lump Sum / L.B.I: (\$) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____

Survey Fee: _____
 Transportation: _____
 S + RS, SI _____
 Photos _____
 Others _____
 TOTAL _____

[Signature]
 19/12

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 13 February 2020 1:23 PM
To: Tinie Ng Jing Ling
Cc: assignments
Subject: RE: OUR REF: SNM20D200800/GBJ9152J/CBS - TO ARRANGE TP SURVEY FOR SCX 7973J (GBJ9152J CHINA TAIPING)

Without Prejudice

Dear all,

Have claimant details so that I can merimen?

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen
Sent: Thursday, February 13, 2020 1:22 PM
To: Tinie Ng Jing Ling <TinieNg@sparkcarcare.com>
Cc: assignments <assignments@lkkauto.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF: SNM20D200800/GBJ9152J/CBS - TO ARRANGE TP SURVEY FOR SCX 7973J (GBJ9152J CHINA TAIPING)

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s **LKK** Auto Consultants Pte Ltd to survey your client's vehicle.

;b

Aside to **LKK**,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Tinie Ng Jing Ling [<mailto:TinieNg@sparkcarcare.com>]
Sent: Thursday, February 13, 2020 1:16 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: OUR REF: SNM20D200800/GBJ9152J/CBS - TO ARRANGE TP SURVEY FOR SCX 7973J (GBJ9152J CHINA TAIPING)

Dear Boon Sen,

Pls appoint LKK.

Best Regards,

Tinie Ng
Crash Repair
ComfortDelGro Engineering Pte Ltd
320 Ubi Road 3 Singapore 408649
Tel: 6848 5726/25 Fax: 6743 6072
email: TinieNg@sparkcarcare.com



From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: 13 February 2020 12:59
To: Tinie Ng Jing Ling <TinieNg@sparkcarcare.com>
Subject: RE: OUR REF: SNM20D200800/GBJ9152J/CBS - TO ARRANGE TP SURVEY FOR SCX 7973J (GBJ9152J CHINA TAIPING)

Without prejudice
Save as to costs

Dear Sir,
LKK
LBS
STA

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Thursday, February 13, 2020 12:17 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; TinieNg@sparkcarcare.com

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D200800/GBJ9152J/CBS - TO ARRANGE TP SURVEY FOR SCX 7973J (GBJ9152J CHINA TAIPING)

Dear Boon Sen,

Please conduct PRS for SCX7973J.

Note : officer in charge – Boon Sen 63896171.

***** Kindly quote our reference number when replying.**

Thank you,
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Tinie Ng Jing Ling <TinieNg@sparkcarcare.com>

Sent: Thursday, February 13, 2020 9:32 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Johari Bin Husin <JohariHusin@sparkcarcare.com>

Subject: TO ARRANGE TP SURVEY FOR SCX 7973J (GBJ9152J CHINA TAIPING)

Dear Survey Team,

Kindly arrange survey.

Best Regards,

Tinie Ng

Crash Repair

ComfortDelGro Engineering Pte Ltd

320 Ubi Road 3 Singapore 408649


Tel: 6848 5726/25 Fax: 6743 6072

email: TinieNg@sparkcarcare.com

COMFORTDELGRO
ENGINEERING



© ComfortDelGro Engineering



Nivitha (LKK Auto)

From: Tinie Ng Jing Ling <TinieNg@sparkcarcare.com>
Sent: Thursday, 13 February 2020 3:30 PM
To: Nivitha (LKK Auto)
Cc: ASSIGNMENTS@LKKAUTO.COM
Subject: Re: survey arrangement for SCX 7973J

Hi Nivitha,

Please arrange monday 17/02/2020 3pm to 4pm survey.

Best Regards,

Tinie Ng
Crash Repair
ComfortDelGro Engineering Pte Ltd
320 Ubi Road 3 Singapore 408649
Tel: 6848 5726/25 Fax: 6743 6072
email: TinieNg@sparkcarcare.com



 Think Before Printing

From: Nivitha (LKK Auto) <admin-d@lkkauto.com>
Sent: 13 February 2020 14:17
To: Tinie Ng Jing Ling <TinieNg@sparkcarcare.com>
Cc: ASSIGNMENTS@LKKAUTO.COM <ASSIGNMENTS@LKKAUTO.COM>
Subject: survey arrangement for SCX 7973J

Dear Tinie,

Is the vehicle SCX 7973J in the workshop?

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	234H
Vehicle Details	
Vehicle No.:	SCX7973J
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Silver
Manufacturing Year:	2003
Engine No.:	1ZZ1554370
Chassis No.:	ZNE100084363
Maximum Power Output:	-
Open Market Value:	\$24,880.00
Original Registration Date:	18 Oct 2003
First Registration Date:	18 Oct 2003
Transfer Count:	1
Actual ARF Paid:	\$32,344.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$77,410.00
COE Rebate Amount:	\$27,996.00
Total Rebate Amount:	\$27,996.00

The information contained herein is correct as at 18 Feb 2020

OK



Toyota Wish 1.8A (COE till 03/2024) Price Range Depreciation Year Reg Vehicle Type

Home » Used Cars » Car Search » Toyota Wish 1.8A (COE till 03/2024)

Toyota Wish 1.8A (COE till 03/2024)

Overview Financial Insurance Accessories Similar Research Photos Map

CONSI



Price	\$32,800	<i>-31</i>		
Depreciation	\$8,030 /yr		Reg Date	20-Mar-2009 (4yrs 1mth 1day COE left)
Mileage	150,000 km (13.7k /yr)		Manufactured	2009
Road Tax	\$1,069 /yr		Transmission	Auto
Dereg Value	\$13,488 as of today (change)		OMV	\$18,662
COE	\$16,509		ARF	\$18,662
Engine Cap	1,794 cc		Power	97.0 kW (130 bhp)
Curb Weight	1,310 kg		No. of Owners	4
Type of Vehicle	MPV			

Features

1.8L DOHC VVT-i Engine, Steptronic Automatic Transmission, SRS Airbags, ABS, Digital Auto Climatic Aircon Control, Remote Keys, Reverse Camera. View specs of the Toyota Wish

Accessories

Sports Rims, Pioneer DVD, Solar Films, Electrical Retractable Side Mirrors With Indicators, Upholstery Leather Seats.

Description

Well Maintained. Loans Available, With Lowest Interest Rates. High Trade-In Welcome. Call Now To Book An Appointment To View This Beauty. Viewing Strictly Appointment Based.

Category

COE Car, Consignment Car

Status

Available

Resources



Vehicle Evaluation



? Request to have this car evaluated professionally. Find out more

Compare

Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell a handle all documentation on the car seller's behalf

- » List of owner consignment cars
- » List of consignment agents



Shortlist Compare Add no Report Error More Actions

Seller Information

Car Search

Customer Reviews

4.8 ★★★★★ 21 reviews

Car Search recommended by 21 people



Lawrence Foo February 14

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/02/2020 16:19
Date Of Accident	08/02/2020 23:00
Exact Location Of Accident	CHERRY LOFT RESORTS CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCX7973J
Insured/Policyholder	
Name Of Registered Owner	SE ALLIANCE MANAGEMENT PTE LTD
Co Reg No	1XXXXX234H
Email Address	KSNG@SINGAPORE-E.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-91778352

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	2019-V0107434-VDP
Cover Note Number	

Driver

Name of Driver	NG KWANG SOON
NRIC No	SXXXX788H
Date Of Birth	22/11/1974
Occupation	INDOOR
Date Of Driving Pass	24/03/1997
Driving Experience	22 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91778352
Fax Number	
Contact Number	
E Mail Address	KSNG@SINGAPORE-E.COM.SG

Address 163 JALAN LOYANG BESAR
#02-02

Postcode 509413

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] T/20200209/2039

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

VIDEO WITH CDGE UBI REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: VIDEO FILE TO BIG

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBJ9152J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category GOODS VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7/2/2020 at 6:30pm, I park my vehicle SCX7973J (CAR A) in Cherry Loft Resorts car park. I lock my vehicle and left the car park.

On 9/2/2020 at 8:30am, I go to Cherry Loft Resorts car park to pick up my vehicle. I discovered a deep dent and multiple scratches on the front right bumper.

I inform the staff at Cherry Loft and a staff send me a video of the accident. The video show a van GBJ 9152 J (CAR B) moving out of the parking lot on my vehicle right and turning left, hitting the front right of my vehicle when CAR B turn left.

(Refer to police Report)

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

KSM

Driver's Signature
(If driver is not the policyholder)
Date & Time: 10/2/20

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

2223



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP

Vehicle No. : SCX7973J

Make & Model : TOYOTA WISH

Year of Manufacture : 2003

Chassis No. : ZNE100084363

Engine No. : 1ZZ1554370

Ins Company : _____

Excess : _____

Policy No. : _____

Date of Accident : 08/02/2020

Time of Accident : 23.00

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimates

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items **\$ 3,548.41**

Plus/Less 25% **\$ 887.10**

Total of Cost / List **\$ 2,661.30**

Contact No

68485725 - JOHARI

(b) Nett Price Items **\$ -**

Less _____

Total of Nett Item _____

(c) Special Nett Items **\$ -**

Total Parts Cost (Appendix A) \$ 2,661.30

Labour (Appendix B) \$ 1,650.00

Total Repair Cost \$ 4,311.30

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____
 Company : _____
 Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.
 (b) Recommended Days of Repair : _____ day(s)
 (c) Resurvey : Required / Not Required
 (d) Excess : \$ _____
 (e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
 320 UBI ROAD 3 SINGAPORE 408649
 TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : SCX7973J Case Owner : JOHARI

Make & Model : TOYOTA WISH Year Manufacture : 2003

Chassis No : ZNE100084363 Engine No : 1ZZ1554370

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	RH HEADLAMP ✓ CR19	1		\$ 930.55		
2	RH HEADLAMP LOWER BRACKET X (not use)	1				
3	FRONT BUMPER ✓ CR14	1		\$ 1,878.79		
4	FRONT BUMPER CLIP'S ✓ new	15 1set		\$ 60.00 25		
5	FRONT BUMPER SIDE RETAINER RH ?	1		\$ 79.78		
6	FRONT BUMPER REINFORCEMENT X (R)	1		\$ 395.15		
7	FRONT BUMPER SPONGE X (svc)	1		\$ 162.14		
8	FOG LAMP COVER RH ✓ m73	1		\$ 42.00		
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Labour

Vehicle No. : SCX7973J Case Owner : JOHARI
Make & Model : TOYOTA WISH Year of Manufacture : 2003

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING , WIRE SOCKET ETC , REMOVE AND REINSTALL DAMAGE PARTS , TEST AND RETIFY FOR PROPER FUNCTIONING .	\$100.00	30
2	TO KNOCK & REPAIR RH FENDER INNER PANEL , FRONT BONNET , RADIATOR SUPPORT PANEL AND AFFECTED AREA.	\$550.00	300
3	TO PUTTY & SPRAY PAINT RH FENDER , INNER PANEL , FRONT BONNET , RADIATOR SUPPORT PANEL , FRONT BUMPER AND AFFECTED AREA .	\$1,000.00	400
<div style="position: relative;"> <div style="position: absolute; top: 10px; left: 10px; font-size: small;"> <p>2/5 report with photos resurvey after paint 3 July H. ANN (1110) 85311883 17/2/20 Hank ANN @kkhAuto.com Hoccam @ 1</p> </div> <div style="position: absolute; top: 10px; right: 10px; text-align: right;"> <p><i>[Signature]</i> 17/2/2020</p> </div> <div style="border: 1px solid black; padding: 5px; margin-top: 10px; font-size: x-small;"> <p>KK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div> </div>			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.