

ASS. REC. BY:

REF: (S3) C71 20002553/QY f302

Special Instruction:

Surveyor: Sun Bin

**ASSIGNMENT (Office)**

From (Person): Tan Kah Wong

of C12

Date/Time: 13.2.2020 3.54 p.m

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

yp 6784 B

Insured:

SKJ 9493T

at Workshop m/s

Eng 500 H

Tel:

6760671

of Blk 4 Yaw Ter Ind Est 393- J mudlows Road

Policy No: DMPCSN 1938 3919000

Claim No:

SNM 2012 200803/5KJ 94931/TKL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11.2.2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 13/4/2020 4.03 PM

Person Contacted:

Eng Swon

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (X) Estimate
	YP 6784B-X
	SKJ 9493T-X

ASS. REG. BY: Sun Pm.

REF:

CTI

## ASSIGNMENT

From: \_\_\_\_\_ Date: 18-7-2020

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YP6784B

at Workshop m/s Eng Soon

of BIK 4 Year Tee Ind Est 393J

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: YP 6784 B Yr Regn: 21/06/2017.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hino XZU710R c.c. 4,009

Colour: white. A/C: Insured / Std / NI / NA

Sp. Reading: 69426 T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: JHHUCS3H401K018203

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 7-00 R 16

R: 7-00 R 16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 11/2/2020 D.O.I. 18/02/2020

Survey held at Eng Soon.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PRS

Repair day - 3 days

MV = 56,000

PV = 33,677

NV = 22,323

RECEIVED 04 MAR 2020

Repair Range  
2k-3k.

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

4/3/20 Typist

Days Of Repair: 3

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I. (\$) \_\_\_\_\_

220

220

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Feb 2020		13 Feb 2020 15:55 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	AQ WORLD PTE LTD, Co. Reg. No.: 201710811G		
Vehicle Reg. No.:	YP6784B	Date of Loss:	11/02/2020 18:00 - :59
Claim Type:	TP / SNM20D200803C02	Policy/Cover Note No.:	DMPCSN19383919000
Vehicle Reg. No. (Insured):	SKJ9493T	Policy No. (Claimant):	MOMVC000007878-01-000
		Excess:	S\$1,500.00
Repairer:	Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	Great American Insurance Company (HQ) - Tel: 6804 6047		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 24/02/2020]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Sent:** Thursday, 13 February 2020 3:52 PM  
**To:** bonnie kwok; 'assignments'  
**Subject:** RE: OUR REF : SNM20D200803/SKJ9493T/TKL - PRI: Your Vehicle: SKJ 9493 T; Our Ref: EngSoon-YP 6784 B; Accident Involving YP 6784 B & SKJ 9493 T on 11 February 2020

WITHOUT PREJUDICE  
SAVE AS TO COSTS

Dear ST,

We refer to your email of below.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 7175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** bonnie kwok [mailto:litigation@bonniekwok.com]  
**Sent:** Thursday, February 13, 2020 3:42 PM  
**To:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Subject:** Re: OUR REF : SNM20D200803/SKJ9493T/TKL - PRI: Your Vehicle: SKJ 9493 T; Our Ref: EngSoon-YP 6784 B; Accident Involving YP 6784 B & SKJ 9493 T on 11 February 2020

Sirs,

Your list of surveyors is rejected.

We have been instructed to propose the following list of surveyors for the Single Joint Expert:-

1. Fong Kok Heng
2. Danny Yap
3. Willy Goh
4. Francis Ng
5. Dennis Yap
6. Louis Ng
7. Michael Yap
8. Lim Yong Tian
9. Patrick Ng
10. Philip Foo

Kindly contact the repairers, M/s Eng Soon Painting Services at 6760 6271 for pre-repair inspection arrangements.

Regards,

ST

--

**BONNIE KWOK LLC**

Advocates & Solicitors  
101A Upper Cross Street  
#08-12 People's Park Centre  
Singapore 058358  
TEL: 6536 6026  
FAX: 6536 2279  
email : [litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)  
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Thu, 13 Feb 2020 at 15:00, Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)> wrote:

Without Prejudice

Dear ST,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

**Tan Kah Leong**

Assistant Executive

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 7175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI

**Sent:** Thursday, February 13, 2020 2:52 PM

**To:** Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)>; 'bonnie kwok' <[litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)>

**Cc:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** OUR REF : SNM20D200803/SKJ9493T/TKL - PRI: Your Vehicle: SKJ 9493 T; Our Ref: EngSoon-YP 6784 B; Accident Involving YP 6784 B & SKJ 9493 T on 11 February 2020

Dear Kah Leong,

Please conduct PRS for YP6784B.

Note : officer in charge – Kah Leong 63896193.

Thank you

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** bonnie kwok <[litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)>

**Sent:** Thursday, February 13, 2020 12:36 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** Urgent: Pre-Repair Inspection: Your Vehicle: SKJ 9493 T; Our Ref: EngSoon-YP 6784 B; Accident Involving YP 6784 B & SKJ 9493 T on 11 February 2020

**Urgent**

Dear Sirs,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. YP 6784 B at M/s Eng Soon Painting Services, Block 4 Yew Tee Industrial Estate 393-J Woodlands Road Singapore 677978.

Regards,

ST

--

**BONNIE KWOK LLC**

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : [litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	811G
<b>Vehicle Details</b>	
Vehicle No.:	YP6784B
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Feb 2020
Vehicle Make:	HINO
Vehicle Model:	HINO XZU710R-HKFMS3
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	N04CUS28916
Chassis No.:	JHHUCS3H40K018203
Maximum Power Output:	-
Open Market Value:	\$31,070.00
Original Registration Date:	21 Jun 2017
First Registration Date:	21 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$1,554.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	20 Jun 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$45,906.00
COE Rebate Amount:	\$33,677.00
<b>Total Rebate Amount:</b>	<b>\$33,677.00</b>

The information contained herein is correct as at 19 Feb 2020

OK

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report 12/02/2020 21:11  
 Date Of Accident 11/02/2020 18:05  
 Exact Location Of Accident CTE TOWARDS CITY EXIT ANG MO KIO AVE 1  
 Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number YP6784B  
 Insured/Policyholder  
 Name Of Registered Owner AQ WORLD PTE LTD  
 Co Reg No 2XXXXX811G  
 Email Address NOEMAIL  
 Mobile Phone No  
 Alternative Phone No OFFICE-62509376

## Vehicle Particulars

Manufacturer HINO  
 Model XZU710R-4.0 D 14FT WIDE CAB 5T (M)  
 Exact Purpose for which vehicle was being used at time of accident COMMERCIAL USE

Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category COMMERCIAL VEHICLE

## Insurance Company

Name of Insurance Company GREAT AMERICAN INSURANCE COMPANY  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number MOMVC000007878-01-000  
 Cover Note Number

## Driver

Name of Driver LIM BENG HUAT  
 NRIC No SXXXX711H  
 Date Of Birth 01/03/1965  
 Occupation OUTDOOR  
 Date Of Driving Pass 16/08/1988  
 Driving Experience 31 YEARS AND 5 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-90283800  
 Fax Number  
 Contact Number  
 Email Address NOEMAIL

Was driver an employee of the insured's company? YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

### General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

RAINING

Road Surface

WET

### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1

NAME: : TAN GUO SHENG

GENDER: : MALE

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

REFER TO SKETCH PLAN

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKJ9493T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver R RAJLECHUMI

NRIC Passport Number SXXXX394H

Contact Number

Address

Postcode

Insurance Company Name





A: YP 6784B.  
B: SKJ 9493T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While waiting at the give way line to merge into  
Ang Mo Kio Ave 1, suddenly SKJ 9493T hit onto  
the rear of my vehicle YP 6784B.

DECLARATION

I declare the foregoing particulars are true in every respect.



*[Signature]*  
Driver's Signature

*[Signature]*  
Witness Signature  
Date & Time

*[Signature]*  
Police Officer's Signature  
Name  
Rank/Title

## Resource Allocation Tool

Get Ahead with Project Budgeting, Resource Management and Time

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

Honda Insight Hybrid Left 4.5 Years At Only 28.8k



\$0 Drive Away At Monthly  
\$808!! Full Tank Can Go  
800+km. Low Mileage. Call  
Now!  
88 Motor Trading StarAd

**VALUE FOR MONEY  
VALUE FOR TIME  
A PEACE OF MIND**

**HOTLINE: 6741 9997** [view our cars](#)

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

1 vehicles

Hino XZU710R

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Hino XZU710R		Any	Any	<u>2017</u>	Any	Any	Any	Available



**Hino XZU710R**

**\$58,800**

**\$8,000 /yr**

**11-Jul-2017**

**4,009 cc**

**15,000 km**

**Truck**

**Available**

**Fuel Type:** Diesel

We Provide Door Steps Viewing, 1 Owner, Very Low Mileage Done, Hino XZU710R Truck, 14 Feet Wide Cab With Canopy, Very Good Condition, No Repair Needed, No Need VPC, Loan Available, Trade In Welcome And Call For Viewing.

Posted: 04-Mar-2020 Tags: 2017 Hino XZU710R, Hino XZU710R, Hino, XZU710R

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view [Expired ads](#)

20 ▼ results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Hino XZU710R, Hino XZU710R Singapore, used Hino XZU710R Singapore, used Hino XZU710R, used vehicles Singapore or even buy used Hino XZU710R Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2020 sgCarMart. All rights reserved.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Feb 2020		13 Feb 2020 15:55 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span>[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>AQ WORLD PTE LTD</b> , Co. Reg. No.: 201710811G								
Vehicle Reg. No.:	<b>YP6784B</b>	Date of Loss:	11/02/2020 18:00 - :59 [31 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM20D200803C02</b>	Policy/Cover Note No.:	DMPCSN19383919000						
Vehicle Reg. No. (Insured):	<b>SKJ9493T</b>	Policy No. (Claimant):	MOMVC000007878-01-000						
		Excess:	S\$1,500.00						
Repairer:	<b>Eng Soon Painting Services (HQ)</b> 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Tan Kah Leong</b> - 63896193]								
Claimant's Insurer:	<b>Great American Insurance Company (HQ)</b> - Tel: 6804 6047								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>OI SUN PIN</b> ] ... <b>[Final Rpt due 24/02/2020]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span><a href="#">View All</a></span> <span><a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span><a href="#">View All</a></span> <span><a href="#">Search Tasks</a></span> <span><a href="#">Create New Task</a></span> <span><a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*YP6784B (SNM20D200803C02)

[SKJ9493T]

TP















































AQ WORLD PTE LTD

Feb 11 2020 6:00PM

[-]

Eng Soon Painting Services

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View In Browser</a>		
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)		Thumbnail	Print
1	12/02/20 21:20	Accident Statement		Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)		Thumbnail	Print
1	12/02/20 21:20	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	12/02/20 21:20	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	12/02/20 21:20	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	12/02/20 21:20	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/03/20 11:15	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
2	04/03/20 11:15	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
3	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
4	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
5	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
6	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
7	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
8	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
9	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
10	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
11	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
12	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
13	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
14	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
15	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
16	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
17	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
18	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
19	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
20	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
21	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
22	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
23	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
24	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
25	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
26	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
27	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>
28	04/03/20 11:15	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
29	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
30	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
31	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
32	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
33	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
34	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
35	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
36	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
37	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
38	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
39	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
40	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
41	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
42	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
43	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
44	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
45	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
46	04/03/20 11:15	General View		<input checked="" type="checkbox"/>
47	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
48	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
49	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
50	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
51	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
52	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
53	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
54	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
55	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
56	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
57	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
58	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
59	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
60	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
61	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
62	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
63	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
64	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
65	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
66	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
67	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
68	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
69	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
70	04/03/20 11:15	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	12/02/20 21:18	Sketch Plan [Linked Accident Report Documents]		<input type="checkbox"/>
2	12/02/20 21:18	Sketch Plan #2 [Linked Accident Report Documents]		<input type="checkbox"/>
3	12/02/20 21:18	Sketch Plan #3 [Linked Accident Report Documents]		<input type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)		Thumbnail Print
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	13/02/20 15:56	Pre-Repair Survey		Load PDF

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)		Thumbnail Print
1	12/02/20 21:20	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)		Thumbnail Print
1	12/02/20 21:20	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	12/02/20 21:20	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	12/02/20 21:20	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	12/02/20 21:20	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)		Thumbnail Print
1	12/02/20 21:18	Sketch Plan		Load TIF
2	12/02/20 21:18	Sketch Plan #2		Load TIF
3	12/02/20 21:18	Sketch Plan #3		Load TIF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI20002553/QYF3E2

Date: 05/03/2020

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN19383919000

Claimant Vehicle  
No : YP6784BInsured Vehicle  
No : SKJ9493T

Date of Loss: 11/02/2020

Nature of Claim: TP

Claim  
No: SNM20D200803C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP6784B

Make &amp; Model: HINO XZU710R, 4.0 D 14FT WIDE CAB 5T (M)

Engine No: N04CUS28916

Reg. Date: 21/06/2017 (Man. Year: 2016)

Chassis No: JHHUCS3H40K018203

Colour: White

Odometer: 69426 km

Engine Capacity: 4009 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 7.00 R16

Rear Tyre Size: 7.00 R16

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 13/02/2020

Date Inspected: 18/02/2020	Inspected At:	Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD Singapore 677978
----------------------------	---------------	--

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 05 Mar 2020)	
<b>Parts:</b>	N/A	HINO XZU710R 4.0 D 14FT WIDE CAB 5T (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YP6784B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >