



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI17023429/Qvd3e2-1

C/O : COMLAW LLC*

64 CECIL ST #06-01 IOB BLDG SINGAPORE
049711

Date : 04-03-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 459K	Veh. Inspected	JRE 8188
Policy No.	DMCVSN3063121700	Coverage (\$)	0.00
Claim No.	PCS/AR/219926/19	Excess (\$)	0.00
Assign From	JEAN KOH	Assign Date	13/02/2020

2. Vehicle Particulars & Condition

Make & Model	FORD RANGER XLT	c.c	2198
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MNBLMFF80GW482850	Colour	DARK GREY
Odometer	84953	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	265/70 R16	MICHELIN	4 mm
L/H Front Tyre	265/70 R16	MICHELIN	4 mm
R/H Rear Tyre	265/70 R16	MICHELIN	4 mm
L/H Rear Tyre	265/70 R16	MICHELIN	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/11/2017	Inspection Date	12/12/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-----------------------