

ASS. REC. BY:

REF: CS/CTI 20002653/Unf312

Special Instruction:

Winnin

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Addline chng Dei Wan of CTI

Date/Time: 17.2.2020 9.38am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: CB 8014 L

Insured: PC 1096 L

at Workshop m/s Bedok Transport

Tel: 62863032

of 30-32 Defu Lane 9

Policy No: Dm B 15N 3012801900 0

Claim No: SIVM20D 200826102

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12.2.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 17/2/20 11.31am

Person Contacted: Shu Wan

Vehicle: IN/OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	CB 8014 L - X
	PC 1096 L - X

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: CB8014C

at Workshop m/s: Wholesale

of

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 95k.

IDAC Accident Rpt: Consistent? : Yes or No

GLA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS LTA 0

Date: Person Contacted: Vehicle: IN / OUT

Veh No: CB8014C Yr Regn: 12.17

Type: M.Car / M.Cycle / Bds / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: GOLDEN DRAGON c.c 6690

Colour: orange/white A/C: Insured / Std / NI / NA

Sp. Reading: T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LL3BF CDH 8GA 016890

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NH / S/Rim / STD A/Rim or

Tyre Size: F: 2 wheel/140 R: 275/70R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6/6 mm

L/Bal. 6 mm L/Bal. 8/6 mm

D.O.A. 12/2/20 D.O.I. 17/2/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

5/3/20 Date / Time Action / Instruction 20,000 confirmed under MR 1 year (Red \$26871-17, 57%)

RECEIVED 05 MAR 2020

Date/Time, File Pass to? []: Preli. Report

1) []: Final Report

Date/Time, File Return to?

2) 5/3/20 Typist

Days Of Repair: 12

Resurvey No. of Trip: 3

Survey Fee:

Transportation:

Add Fee: []: Site Insp (\$)

[]: Interview (\$)

[]: Tech. Invs (\$)

[]: Weekend (\$)

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum I.B.I. (\$ 20000)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2020		17 Feb 2020 09:38 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	SEVLAI TRANSPORT PTE LTD , Co. Reg. No.: 201003530D		
Vehicle Reg. No.:	CB8014L	Date of Loss:	12/02/2020 19:00 - :59
Claim Type:	TP / SNM20D200826C02	Policy/Cover Note No.:	DMB1SN30128019000
Vehicle Reg. No. (Insured):	PC1096L	Policy No. (Claimant):	5112276959
		Excess:	S\$1,000.00
Repairer:	Bedok Transport Pte Ltd (HQ) 30-32 DEFU LANE 9, 539270 Defu Lane - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pel Wen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/02/2020]		
Adj Asg. Remarks:	survey revert		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Monday, 17 February, 2020 9:27 AM
To: 'assignments'
Cc: shuwen@bedokmotor.com; Claims Dept of CTI; workshop@bedoktransport.com
Subject: RE: OUR REF: SNM20D200826/PC1096L/ADELINE - FW: ACC INVLG CB8014L & PC1096L ON 12-02-2020 18.55 P.M

Without Prejudice

Dear LKK

Please refer to below email and liaise with Third Party Workshop accordingly.

Thank you.

Adeline Chng

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

From: shuwen@bedokmotor.com [mailto:shuwen@bedokmotor.com]
Sent: Monday, 17 February 2020 9:25 AM
To: Adeline Chng <adeline.chng@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; workshop@bedoktransport.com
Subject: RE: OUR REF: SNM20D200826/PC1096L/ADELINE - FW: ACC INVLG CB8014L & PC1096L ON 12-02-2020 18.55 P.M

Dear Adeline,

Refer to the above.

We hereby confirm that our choice of motor surveyor is :-

LKK Auto Consultants Pte Ltd– Marcus Chua

Thank you.

Regards
SHU WEN (Ms)

From: Adeline Chng [mailto:adeline.chng@sg.cntaiping.com]

Sent: Friday, 14 February 2020 10:56 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; shuwen@bedokmotor.com;
workshop@bedoktransport.com

Subject: RE: OUR REF: SNM20D200826/PC1096L/ADELINE - FW: ACC INVLG CB8014L & PC1096L ON 12-02-2020 18.55 P.M

Without Prejudice

Dear Sirs

We refer to the above matter.

Attached PRS letter for your next action.

Thank you.

Adeline Chng

Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

From: Claims Dept of CTI

Sent: Friday, 14 February 2020 5:09 PM

To: Adeline Chng <adeline.chng@sg.cntaiping.com>; shuwen@bedokmotor.com;
workshop@bedoktransport.com

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D200826/PC1096L/ADELINE - FW: ACC INVLG CB8014L & PC1096L ON 12-02-2020 18.55 P.M

Dear Adeline,

Please conduct PRS for CB8014L.

Note : officer in charge – Adeline 63896155.

*** Kindly quote our reference number when replying.

Thank you,
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: shuwen@bedokmotor.com <shuwen@bedokmotor.com>
Sent: Friday, February 14, 2020 3:06 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: workshop@bedoktransport.com
Subject: ACC INVLG CB8014L & PC1096L ON 12-02-2020 18.55 P.M

Your insured vehicle: PC1096L

Our vehicles CB8014L

Dear sir / mdm ,

Refer to above.

Please arrange for survey for the above vehicle CB8014L at Bedok Transport Pte Ltd. Address : 30 Defu Lane 9 Singapore : 539270 . Contact No.: 62863032

Thank You

Best Regards
SHU WEN (Ms)



BEDOK MOTOR ENGINEERING PTE LTD

30 Defu Lane 9 Singapore 539270

Tel/Fax: +65 6286 3032

<http://www.bedokmotor.com>

enquire@bedokmotor.com



DISCLAIMER: This email and any files transmitted with it are confidential is intended only for the individual named. If you are not the named addressee, you should not disseminate, distribute or copy this email. Please notify the sender immediately by email if

you have received this email by mistake and delete this email from your system. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Bedok Motor Engineering Pte Ltd. Computer viruses can be transmitted via email. The recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

2016 VW Touran 1.4



7 Seater Family Unit. Well Maintained. Lowest In Market. High PARP Value. Direct Owner StarAd

AutoInn
An Inspiration For Car Buyers
click here to view our **PRISTINE USED C** at GREAT PR

Post an Ad Advertiser Login Ways of Selling

Browse by Category

Sort by Date Posted

7 vehicles

golden dragon

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	golden dragon	Any	Any	Any	Any	Any	Any
	Golden Dragon XML6770 Fuel Type: Diesel Loan Available At \$ Call Or SMS For More Information.	\$70,000	\$10,560 /yr	04-Oct-2016	3,759 cc	-	Bus
	Posted: 17-Feb-2020	Tags: 2016 Golden Dragon XML6770, 2016 golden dragon xml6770, Golden Dragon XML6770, golden dragon xml6770, Golden Dragon, XML6770, xml6770, Used Golden Dragon					
	Golden Dragon XML6957 Fuel Type: Diesel 43 Seaters Children Bus In Very Good Condition. Manual Transmission, Nice And Clean Interior. Bank / In House Loan Available, Call Now To Booking Appointment For Viewing And Test Drive.	\$58,800	\$49,450 /yr	28-Apr-2011	6,693 cc	-	Bus
	Posted: 14-Feb-2020	Tags: 2011 Golden Dragon XML6957, 2011 golden dragon xml6957, Golden Dragon XML6957, golden dragon xml6957, Golden Dragon, XML6957, xml6957, Used Golden Dragon					
	Golden Dragon XML6772 Fuel Type: Diesel Popular Golden Dragon 29 Seater Bus, Monthly Installment At \$1599 Only, Auto Gear Transmission, Spacious Seating Comfort, Comes With Luggage Compartment, Auto Sliding Door, Free 3 Servicing, 2 Years Or 150,000km Warranty Whichever Come First. Call In Now To...	\$135,988	\$14,050 /yr	23-Oct-2019	3,759 cc	-	Bus
	Posted: 13-Feb-2020	Tags: 2019 Golden Dragon XML6772, 2019 golden dragon xml6772, Golden Dragon XML6772, golden dragon xml6772, Golden Dragon, XML6772, xml6772, Used Golden Dragon					
	Golden Dragon XML6957 Fuel Type: Diesel 45 S Bus In Original And Good Condition. Loan Available Call Or SMS For More Information.	\$152,800	\$16,740 /yr	03-Apr-2019	6,690 cc	-	Bus
	Posted: 10-Feb-2020	Tags: 2019 Golden Dragon XML6957, 2019 golden dragon xml6957, Golden Dragon XML6957, golden dragon xml6957, Golden Dragon, XML6957, xml6957, Used Golden Dragon					
	Refurbished Original OZ Ultraleggera 18" Rims Original OZ ULTRALEGGERA 18" Rims & 225/40R15 Tyres, Fits all Mercedes, VW, AUDI Cars, Mpvs/SUV PCD 5/112 Find out more!						

Golden Dragon XML6957 e: Diesel Original And Good Condition. Loan Available At \$80,000 Interest Rate 4% For 5 Years Loan. Monthly Installment Estimated Month, Call Or SMS For More Information.	\$80,000	\$15,400 /yr	29-Apr-2015	6,690 cc	-	Bus
---	-----------------	---------------------	--------------------	-----------------	---	-----

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	530D
Vehicle Details	
Vehicle No.:	CB8014L
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Feb 2020
Vehicle Make:	GOLDEN DRAGON
Vehicle Model:	XML6957J14B AUTO
Primary Colour:	Multicolor
Manufacturing Year:	2016
Engine No.:	ISB67E522522171693
Chassis No.:	LL3BFCDH8GA016890
Maximum Power Output:	-
Open Market Value:	\$110,782.00
Original Registration Date:	26 Dec 2017
First Registration Date:	26 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,540.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 18 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2020 12:15
Date Of Accident	12/02/2020 19:00
Exact Location Of Accident	LORNIE ROAD TOWARDS CTE / MACRITCHIE VIADUCT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	CB8014L
Insured/Policyholder	
Name Of Registered Owner	SEVILAI TRANSPORT PTE LTD
Co Reg No	2XXXXX530D
Email Address	OPERATIONS@SEVILAITRANSPORT.COM
Mobile Phone No	
Alternative Phone No	OFFICE-67831412
Vehicle Particulars	
Manufacturer	GOLDEN DRAGON
Model	XML6957J14B-6.7 D TURBO (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5112276959
Cover Note Number	07/09/2019 TO 25/12/2020
Driver	
Name of Driver	SEVILAI SULTHAN ABDUL KADER
NRIC No	SXXXX410Z
Date Of Birth	28/11/1968
Occupation	OUTDOOR
Date Of Driving Pass	06/12/2001
Driving Experience	18 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96692137
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address APT BLK 231B SUMANG LANE #13-261 (S) 822231
 Postcode
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

refer with attach.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE SIZE TOO LARGE UNABLE TO UPLOAD
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC1096L
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category BUS
 Name of Driver MR CHUA
 NRIC/Passport Number
 Contact Number 98506216
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



A : CB8014L

B : PC1096L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12/02/2020 at around 12:30pm, I drove my bus CB8014L along Lornie road towards etc on the left lane. Vehicles in front slow down & I followed as well. Suddenly I felt an impact from my rear then realized was hit by a bus PC1096L.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Sevita
Transport
Policyholder's Signature:
Date & Time:

Abdulhadi 13/Jan/2020
12:30 PM
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



not Arthur
 name
 wrong
 17/1/20
 Zheng H. Abu Ng

Bedok Motor Engineering Pte Ltd
 30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
 +65 6286 3032

L/S \$20,000 12 days.


L/S \$20,000

Estimate To Repair CB8014L GOLDEN DRAGON XML6957J14B

Chassis No : LL3BFCDH8GA016890

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
1	1pc	Rear engine hood 3250	\$ 4,241.24
2	1pc	Rear engine hood XML6957J14B badge 182	\$ 224.14
3	1pc	Rear engine Xiamen Golden Dragon Bus Co. Ltd badge 182	\$ 292.13
4	1pc	Rear engine hood outer open handle with key lock 3 set	\$ 294.74
5	1pc	Rear engine outer handle 11	\$ 98.99
6	1set	Rear engine hood damper stay 11	\$ 393.42
7	2pcs	Rear engine hood side lock @2 \$192.21 1 set	\$ 384.42
8	2pcs	Rear engine hood side stopper @2 \$34.35 11	\$ 68.70
9	2pcs	Rear licence plate lamp @2 \$84.79 1 set	\$ 169.58
10	2pcs	Rear lamp @2 \$952.72 750 x 2 = 1500	\$ 1,905.44
11	2pcs	Rear reflector garnish @2 \$393.72 1 set	\$ 787.44
12	2pcs	Rear reflector round @2 \$131.92 11	\$ 263.84
13	2pcs	Rear lamp panel @2 \$2242.34 1 set	\$ 4,484.68
14	1pc	Crankshaft pulley assy 1250 1 set	\$ 1,919.22
15	1pc	Crankshaft pulley drive belt 157.62 S.N	\$ 303.24
16	1pc	Aircond compressor 11	\$ 3,932.14
17	2pcs	Aircond belt @2 \$192.79 192.79 S.N	\$ 385.58
18	1pc	Aircond tensioner bearing 650.00 1 set	\$ 824.72
19	1pc	Radiator assy 2815	\$ 3,212.74
20	1pc	Radiator fan blade 1 set	\$ 399.23
21	1pc	Radiator fan clutch assy w/pulley 1600 1 set	\$ 1,910.18
22	1pc	Radiator fan tensioner pulley 1 set	\$ 423.72
23	1pc	Radiator fan tensioner pulley adjuster 1 set	\$ 224.79
24	1pc	Radiator fan belt 11	\$ 201.24
25	1pc	Radiator by pass pipe 11	\$ 324.31
26	1pc	Radiator fan cowling 1 set	\$ 524.71
27	1pc	Radiator expansion tank 11	\$ 392.32
28	1pc	Radiator top hose 11	\$ 224.32
29	1pc	Radiator bottom hose 11	\$ 235.20
30	1pc	Air cleaner tank assy 1400.00 1 set	\$ 1,979.21
31	1pc	Alternator assy 11	\$ 2,678.12
32	1set	Compressor pulley 1 set	\$ 894.80
33	1pc	Engine mount L/h 11	\$ 393.21
34	1pc	Engine mount R/h 11	\$ 393.21
35	1pc	Engine mount front L/h 11	\$ 414.28
36	1pc	Engine mount front R/h 11	\$ 414.28
			\$ 36,213.52
			Less 10%
			\$ 3,621.35
			\$ 32,592.17

20632.67
 102
 18569.40



Bedok Motor Engineering Pte Ltd
 30 Defu Lane 9 Singapore 539270
 http://www.bedokmotor.com
 enquire@bedokmotor.com
 +65 6286 3032

Estimate To Repair CB8014L GOLDEN DRAGON XML6957J14B
 Chassis No : LL3BFCDH8GA016890

S/No	Quantity	Description	Amount
SPECIAL NETT ITEAMS			
37	1 pc	Rear engine hood AWC sticker <i>nee</i>	\$ 15.00 <i>10</i>
38	1 pc	Rear engine hood 60km/h sticker <i>nee</i>	\$ 15.00 <i>10</i>
39	1set	Rear engine hood wire mesh <i>11</i>	\$ 120.00 <i>X</i>
40	1pc	Rear bumper facia fibreglass <i>D.S</i>	\$ 2,980.00 <i>1800</i>
41	1set	Rear bumper stay <i>15</i>	\$ 120.00 <i>X</i>
42	1pc	Rear bumper retainer beam <i>15</i>	\$ 150.00 <i>X</i>
43	1pc	Rear licence plate <i>ene</i>	\$ 50.00 <i>40</i>
44	1pc	Radiator coolant <i>11</i>	\$ 100.00 <i>X</i>
45	1pc	Rear windscreen repair kit <i>11</i>	\$ 500.00 <i>X</i>
			\$ 4,050.00
LABOUR & MISC CHARGE			
1		Towing <i>1 hr only</i>	\$ 480.00 <i>200</i>
2		To check lighting concerned	\$ 150.00 <i>30</i>
3		To remove/refit interior filling, fixtures, to enable bodywork repairs <i>11</i>	\$ 350.00 <i>X</i>
4		To rust proof the affected portion.	\$ 150.00 <i>50</i>
5		To remove and refit rear windshield glass. <i>11</i>	\$ 450.00 <i>X</i>
6		To cut, weld off both rear lamp panels and renew the same.	\$ 3,800.00 <i>2800</i>
7		To panel beat and replace the necessary parts. To remove and renew the necessary parts.	\$ 2,200.00 <i>1200</i>
8		Putty and spray painting of the affected areas.	\$ 1,600.00 <i>X</i>
9		Labour to remove all engine necessary components, mounting pulley, alternator and many others. <i>11</i>	\$ 1,600.00 <i>X</i>
10		To remove and replace air-con compressor, belt and vaccum air-con gas. <i>11</i>	\$ 500.00 <i>X</i>
10		To restart engine and perform engine diagnosis test. <i>11</i>	\$ 550.00 <i>X</i>
			\$ 10,230.00
Total			\$ 46,872.17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

18569.40
5.2204.41
L-4280.00
2505381
20043.

CASH SALES / INVOICE



24 HOURS TOWING SERVICES
BATTERY SERVICES

裕強拖車服務
JOO KEONG TOWING SERVICE

bizSAFE₃

Blk 424 #01-235 Bukit Batok West Ave 2, Singapore 650424
DID: 6563 5620 Office: 6566 8259 Fax: 6563 3054
Email: jookeong@singnet.com.sg
Reg. No. 46409700B

No. 19624

Date, 13/02/2020

寶號 Messrs Bedok TPT

車號 Vehicle No. CB 8014 L 車型 Model No. 43 BUS

由 From: 30 DESU LANE 9 到 To: 61 DESU LANE 1-2

時間 (日/夜) Time (day / night) 11:40 - 11:55 ~~12:15~~

其他 Other _____

CASHS 140/2 CHEQUE _____

ADDITIONAL SERVICES:

- | | | | | |
|---|--|---|--|--|
| <input type="checkbox"/> Accident Case | <input type="checkbox"/> Release Brake | <input type="checkbox"/> Dismantle Shaft | <input type="checkbox"/> Sunday / P.Holiday | <input type="checkbox"/> Low bodykit Spoiler |
| <input type="checkbox"/> Multi Storey Car Park | <input type="checkbox"/> Basement Car Park | <input type="checkbox"/> Jump Start | <input type="checkbox"/> Stand by / Waiting Time | <input type="checkbox"/> Collection Car Key |
| <input type="checkbox"/> Using King Dolly | <input type="checkbox"/> Use Car Carrier | <input type="checkbox"/> Change Type & Towing | <input type="checkbox"/> Mid-Night Service | <input type="checkbox"/> Use Winch |
| <input type="checkbox"/> Loaded Cargo | <input type="checkbox"/> Unloading Cargo | <input type="checkbox"/> Door Opening Service | <input type="checkbox"/> Cancellation of Service | <input type="checkbox"/> Over Turn |
| <input type="checkbox"/> Jurong Island & PSA Port | <input type="checkbox"/> Sentosa & Cargo Complex | <input type="checkbox"/> Causeway / 2nd Link | <input type="checkbox"/> Transport Charged | <input type="checkbox"/> Crane Up |

ERP Charged \$ _____ Car Parking Charged \$ _____

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。
Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damage or other misdemeanor to your vehicle while being towed.

收貨人 Received by _____
Mobile No: _____

經手人 Issued by _____
Vehicle No: _____

CASH SALES / INVOICE



裕強拖車服務
JOO KEONG TOWING SERVICE

bizSAFE₃

Blk 424 #01-235 Bukit Batok West Ave 2, Singapore 650424
DID: 6563 5620 Office: 6566 8259 Fax: 6563 3054
Email: jookeong@singnet.com.sg
Reg. No. 46409700B

No. 19623

Date: 12/02/2020

Messrs Bedok tpe

Vehicle No CB 804 L Model No 43 BUS

From you chiu kang RD To 30 defu HANE

Time (day / night) 7:50 - 22:10 23:05

Other _____

CASHS ~~180~~ 200 CHEQUE _____

ADDITIONAL SERVICES:

- | | | | | |
|---|--|---|--|--|
| <input type="checkbox"/> Accident Case | <input type="checkbox"/> Release Brake | <input type="checkbox"/> Dismantle Shaft | <input type="checkbox"/> Sunday / PHoliday | <input type="checkbox"/> Low Bodykit Spoiler |
| <input type="checkbox"/> Multi Storey Car Park | <input type="checkbox"/> Basement Car Park | <input type="checkbox"/> Jump Start | <input type="checkbox"/> Stand by / Waiting Time | <input type="checkbox"/> Collection Car Key |
| <input type="checkbox"/> Using King Dolly | <input type="checkbox"/> Use Car Carrier | <input type="checkbox"/> Change Type & Towing | <input type="checkbox"/> Mid-Night Service | <input type="checkbox"/> Use Winch |
| <input type="checkbox"/> Loaded Cargo | <input type="checkbox"/> Unloading Cargo | <input type="checkbox"/> Door Opening Service | <input type="checkbox"/> Cancellation of Service | <input type="checkbox"/> Over Turn |
| <input type="checkbox"/> Junong Island & PSA Port | <input type="checkbox"/> Sentosa & Cargo Complex | <input type="checkbox"/> Causeway / 2nd Link | <input type="checkbox"/> Transport Charged | <input type="checkbox"/> Crane Up |

ERP Charged \$ _____ Car Parking Charged \$ _____

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damage or other misadventure to your vehicle while being towed.

Received by
Mobile No: _____

Issued by
Vehicle No: _____

CASH SALES / INVOICE



裕強拖車服務
JOO KEONG TOWING SERVICE

bizSAFE₃

Blk 424 #01-235 Bukit Batok West Ave 2, Singapore 650424
DID: 6563 5620 Office: 6566 8259 Fax: 6563 3054
Email: jookeong@singnet.com.sg
Reg. No. 46409700B

No. 19625

Date 13/02/2020

Messrs Bedok tpt

Vehicle No. CB 8014 L Model No. 43 BUS

From 61 DESU LANE 12 To 30 DESU LANE 9

Time (day / night) 12:15 - 12:40

Other _____

CASH\$ 140/- CHEQUE _____

ADDITIONAL SERVICES:

- | | | | | |
|---|--|---|--|--|
| <input type="checkbox"/> Accident Case | <input type="checkbox"/> Release Brake | <input type="checkbox"/> Dismantle Shaft | <input type="checkbox"/> Sunday / PHoliday | <input type="checkbox"/> Low Bodykit Spoiler |
| <input type="checkbox"/> Multi Storey Car Park | <input type="checkbox"/> Basement Car Park | <input type="checkbox"/> Jump Start | <input type="checkbox"/> Stand by / Waiting Time | <input type="checkbox"/> Collection Car Key |
| <input type="checkbox"/> Using King Dolly | <input type="checkbox"/> Use Car Carrier | <input type="checkbox"/> Change Type & Towing | <input type="checkbox"/> Mid-Night Service | <input type="checkbox"/> Use Winch |
| <input type="checkbox"/> Loaded Cargo | <input type="checkbox"/> Unloading Cargo | <input type="checkbox"/> Door Opening Service | <input type="checkbox"/> Cancellation of Service | <input type="checkbox"/> Over Turn |
| <input type="checkbox"/> Jurong Island & PSA Port | <input type="checkbox"/> Sentosa & Cargo Complex | <input type="checkbox"/> Causeway / 2nd Link | <input type="checkbox"/> Transport Charged | <input type="checkbox"/> Crane Up |

ERP Charged \$ _____ Car Parking Charged \$ _____

此車由本公司拖走，在拖走前，本公司已通知車主或其代理人。此車由本公司拖走，其車輛之損壞或遺失，本公司概不負責。此車由本公司拖走，其車輛之損壞或遺失，本公司概不負責。
Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damage or other misadventure to your vehicle while being towed.

Received by: [Signature]
Mobile No: _____

Issued by: [Signature]
Vehicle No: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002653/UYF3N2
Date: 09/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN30128019000
Claimant Vehicle No: CB8014L Insured Vehicle No: PC1096L
Date of Loss: 12/02/2020 Nature of Claim: TP Claim No: SNM20D200826C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **CB8014L**
Make & Model: GOLDEN DRAGON XML6957J14B, 6.7 D TURBO (M) Engine No: ISB67E522522171693
Reg. Date: 26/12/2017 (Man. Year: 2016) Chassis No: LL3BFCDH8GA016890
Colour: White/Orange Odometer: 0 km
Engine Capacity: 6690 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/70R22.5 Rear Tyre Size: 275/70R22.5(D)
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6/6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,642.17	20,773.81	15,868.36	43.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,230.00	4,280.00	5,950.00	58.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,872.17	25,053.81	21,818.36	46.55
Approved Total (Overridden) (S\$)		20,000.00		
Nett Amount (S\$)	46,872.17	20,000.00	26,872.17	57.33

INSPECTION

Date of Assignment: 17/02/2020
Date Inspected: 17/02/2020 Inspected At: Bedok Transport Pte Ltd (HQ)
30-32 DEFU LANE 9
Singapore 539270
Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Mar 2020)
Parts:	N/A GOLDEN DRAGON XML6957J14B 6.7 D TURBO (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for CB8014L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR ENGINE HOOD	Badly Dented	4,241.24 FL	*3,250.00 FL
2	1	*REAR ENGINE HOOD XML6957J14B BADGE	Necessary	224.14 FL	*182.00 FL
3	1	*REAR ENGINE XIAMEN GOLDEN GRAGON BUS CO LTD BADGE	Necessary	292.13 FL	*185.00 FL
4	1	*REAR ENGINE HOOD OUTER OPEN HANDLE WITH KEY LOCK	Bent	294.74 FL	*294.74 FL
5	1	*REAR ENGINE OUTER HANDLE	Not Necessary	98.99 FL	*- FL
6	1	*SET REAR ENGINE HOOD DAMPER STAY	Not Necessary	393.42 FL	*- FL
7	2	*REAR ENGINE HOOD SIDE LOCK	Twisted	384.42 FL	*384.42 FL
8	2	*REAR ENGINE HOOD SIDE STOPPER	Not Necessary	68.70 FL	*- FL
9	2	*REAR LICENCE PLATE LAMP	Cracked	169.58 FL	*169.58 FL
10	2	*REAR LAMP	Cracked	1,905.44 FL	*1,500.00 FL
11	2	*REAR REFLECTOR GARNISH	No such part	787.44 FL	*- FL
12	2	*REAR REFLECTOR ROUND	Not Necessary	263.84 FL	*- FL
13	2	*REAR LAMP PANEL	Cracked	4,484.68 FL	*4,484.68 FL
14	1	*CRANKSHAFT PULLEY ASSY	Cracked/Bent	1,919.21 FL	*1,250.00 FL
15	1	*AIRCOND COMPRESSOR	Not Necessary	3,932.14 FL	*- FL
16	1	*AIRCOND TENSIONER BEARING	Cracked	824.72 FL	*650.00 FL
17	1	*RADIATOR ASSY	Punctured	3,212.74 FL	*2,815.00 FL
18	1	*RADIATOR FAN BLADE	Bent	399.23 FL	*399.23 FL
19	1	*RADIATOR FAN CLUTCH ASSY W/PULLEY	Bent/Jammed	1,910.18 FL	*1,600.00 FL
20	1	*RADIATOR FAN TENSIONER PULLEY	Bent	423.72 FL	*423.72 FL
21	1	*RADIATOR FAN TENSIONER PULLEY ADJUSTER	Bent	224.79 FL	*224.79 FL
22	1	*RADIATOR FAN BELT	Not Necessary	201.24 FL	*- FL
23	1	*RADIATOR BY PASS PIPE	Not Necessary	324.31 FL	*- FL
24	1	*RADIATOR FAN COWLING	Cracked	524.71 FL	*524.71 FL
25	1	*RADIATOR EXPANSION TANK	Not Necessary	392.32 FL	*- FL
26	1	*RADIATOR TOP HOSE	Not Necessary	224.32 FL	*- FL
27	1	*RADIATOR BOTTOM HOSE	Not Necessary	235.20 FL	*- FL
28	1	*AIR CLEANER TANK ASSY	Dented	1,979.21 FL	*1,400.00 FL
29	1	*ALTERNATOR ASSY	Not Necessary	2,678.12 FL	*- FL
30	1	*ENGINE MOUNT L/H	Not Necessary	393.21 FL	*- FL
31	1	*ENGINE MOUNT R/H	Not Necessary	414.28 FL	*- FL
32	1	*ENGINE MOUNT FRONT L/H	Not Necessary	414.28 FL	*- FL
33	1	*ENGINE MOUNT FRONT R/H	Not Necessary	414.28 FL	*- FL
34	1	*SET COMPRESSOR PULLEY	Bent	894.80 FL	*894.80 FL
35	1	*CRANKSHAFT PULLEY DRIVE BELT (50%)	Torn	272.92 FS	*151.62 FS
36	1	*AIRCOND BELT (50%) (2 Pcs)	Torn	347.02 FS	*192.79 FS
37	1	*REAR ENGINE HOOD AWC STICKER	Necessary	15.00 FS	*10.00 FS
38	1	*REAR ENGINE HOOD 60KM/H STICKER	Necessary	15.00 FS	*10.00 FS
39	1	*SET REAR ENGINE HOOD WIRE MESH	Not Necessary	120.00 FS	*- FS
40	1	*REAR BUMPER FACIA FIBREGLASS	Distorted	2,980.00 FS	*1,800.00 FS
41	1	*REAR BUMPER RETAINER BEAM	No such part	150.00 FS	*- FS
42	1	*SET REAR BUMPER STAY	No such part	120.00 FS	*- FS
43	1	*REAR LICENCE PLATE	Cracked	50.00 FS	*40.00 FS
44	1	*RADIATOR COOLANT	Not Necessary	100.00 FS	*- FS
45	1	*REAR WINDSCREEN REPAIR KIT	Not Necessary	500.00 FS	*- FS

Report was unsubmitted during this print-out.

No. Qty Part No. Particulars

Condition Repairer's Amount

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	40,194.64	22,837.08
- List Item Discount on L Items 10.00/10.00% (\$)	3,552.47	2,063.27
Total Parts (\$)	36,642.17	20,773.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	480.00	200.00
2	TO CHECK LIGHTING CONCERNED	New	150.00	30.00
3	TO REMOVE/REFIT INTERIOR FILLING, FIXTURES, TO ENABLE BODYWORK REPAIRS	New	350.00	0.00
4	TO RUST PROOF THE AFFECTED PORTION	New	150.00	50.00
5	TO REMOVE AND REFIT REAR WINDSHIELD GLASS	New	450.00	0.00
6	TO CUT, WELD OFF BOTH REAR LAMP PANELS AND RENEW THE SAME. TO PANEL BEAT AND REPLACE THE NECESSARY PARTS, TO REMOVE AND RENEW THE NECESSARY PARTS	New	3,800.00	2,800.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED AREAS	New	2,200.00	1,200.00
8	LABOUR TO REMOVE ALL ENGINE NECESSARY COMPONENTS, MOUNTING PULLEY, ALTERNATOR AND MANY OTHERS	New	1,600.00	0.00
9	TO REMOVE AND REPLACE AIR-CON COMPRESSOR, BELT AND VACCUM AIR-CON GAS	New	500.00	0.00
10	TO RESTART ENGINE AND PERFORM ENGINE DIAGNOSIS TEST	New	550.00	0.00
Gross Labour Cost (S\$)			10,230.00	4,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >