

23/03/2020

ASS. REC. BY:

REF: CS/CTI 20002655 / R1v3ⁿ²

Special Instruction:

Surveyor: RusuASSIGNMENT (Office)From (Person): Adeline chng Ai Wn of CTIDate/Time: 15.3.2020 1441p

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKD 2278BInsured: CB 64624at Workshop m/s Wah Hong motors
of 38 TDh Guan Rd East #01-57Tel: 67733317Policy No: DMB 151 1745531 9032Claim No: SNM 201 200740002

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 1/2/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 17/2/2020 11.36a.mPerson Contacted: AdiVehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKD 2278B - NBR/CTI 20002655/17 R.O.A. - 02/02/2020
	CB 64624 - NBR/CTI 20002655/17 R.O.A. - 02/02/2020
27/2/20	@341pm Adi said vehicle still under repair
1/3/20	LS \$3350 confirmed by email (Recd 4/73, 5790)

Fame


ASSIGNMENT

SSSB
CGE XPRK: 2021/NOV

From: _____ Date: _____
 Estimated Cost: _____
 OD / ☒ WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SKD 2278B
 at Workshop n/s: WAH HONH
 of: 48, TOK HUAN RO GASI #0157
 Insured: CTI
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 27K
 IDAC Accident Rpt: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SKD 2278B Yr Regn: 2011 / NOV
 Type: ☒ Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: VOLKSWAGEN JETTA 1.4 TSI c.c. 1390
 Colour: BROWN A/C: Insured / Std / NI / NA
 Sp. Reading: 134437 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WVW22216ZBM107060
 Gen. Cond: Good / ☒ Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: Nil / ☒ R/Rim / STD A/Rim or
 Tyre Size: F: 225/402R18
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. 07/02/2020 D.O.I. 17/02/2020
 Survey held at WAH HONH
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S FRONT
 The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 10 MAR 2020

Date/Time, File Pass to? ☐ : Preli. Report1) ☐ : Final Report

Date/Time, File Return to?

2) 18/3 - typist

Report Forwarded:

Enquiry Date / Time: 18/3 \$3350/-Days Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Material (\$)

Survey Fee:

Transportation:

3 + RS \$

Time:

Other:

Total:

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2020		15 Feb 2020 19:41 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:				[Created by insurer]
Main Claimant:	GAYATHIRI D/O SUNDARAM, ID: S86345558			
Vehicle Reg. No.:	SKD2278B	Date of Loss:	07/02/2020 07:00 - :59	
Claim Type:	TP / SNM20D200740C02	Policy/Cover Note No.:	DMB1SN17455319033	
Vehicle Reg. No. (Insured):	CB6442Y	Policy No. (Claimant):	2019-V8007443-VDP-R004	
		Excess:	S\$2,500.00	
Repairer:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub, 608581 Jurong East - Tel: +65 6773 7377			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]			
Claimant's Insurer:	Great Eastern General Insurance Limited (HQ) - Tel: +65 248 2888			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/02/2020]			
Adj Asg. Remarks:	survey revert			

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Summer Lee (LKK Auto)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Saturday, 15 February, 2020 7:26 PM
To: 'assignments'
Cc: Wahhong motors & credit pte ltd
Subject: FW: OUR REF: SNM20D200740/CB6442Y/ADELINE - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING SKD2278B & YOUR INSURED CB6442Y ON 07/02/2020

Without Prejudice

Dear LKK

Please refer to below email and liaise with third party workshop.

Thank you.

Adeline Chng
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

-----Original Message-----

From: Wahhong motors & credit pte ltd [mailto:motor@wahhong.sg]
Sent: Saturday, 15 February 2020 10:22 AM
To: Adeline Chng <adeline.chng@sg.cntaiping.com>
Subject: Re: OUR REF: SNM20D200740/CB6442Y/ADELINE - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING SKD2278B & YOUR INSURED CB6442Y ON 07/02/2020

Dear Adeline

Thank you for your email.

We choose LKK.

On 2020-02-15 10:20, Adeline Chng wrote:

> Dear sirs
>
> LKK, LBS and STA
>
> Thank you

> Regards
 > Adeline Chng
 > -----
 >
 > FROM: Wahhong motors & credit pte ltd <motor@wahhong.sg>
 > SENT: Saturday, February 15, 2020 10:12:11 AM
 > TO: Adeline Chng <adeline.chng@sg.cntaiping.com>
 > SUBJECT: Re: OUR REF: SNM20D200740/CB6442Y/ADELINE - PRE-REPAIR
 > INSPECTION - ACCIDENT INVOLVING SKD2278B & YOUR INSURED CB6442Y ON
 > 07/02/2020
 >
 > Dear Adeline
 >
 > Sorry for the late reply.
 >
 > Kindly provide us with another list of surveyor firms that we can
 > choose from.
 >
 > On 2020-02-12 16:34, Adeline Chng wrote:
 >> Without Prejudice
 >>
 >>
 >> Dear Sirs
 >>
 >> We refer to the above matter.
 >>
 >> Attached PRS letter for your next action.
 >>
 >>
 >> Thank you.
 >>
 >> Adeline Chng
 >> Executive
 >> Claims Department
 >>
 >> China Taiping Insurance (Singapore) Pte. Ltd.
 >> 3 Anson Road #15-00 Springleaf Tower Singapore 079909
 >> DID: (65) 6389 6155 | F: (65) 6222 1033
 >>
 >> W: www.sg.cntaiping.com [1] | FB:
 > www.facebook.com/chinataipingsg/ [2]
 >> | WeChat: 太平獅城 Taiping SG
 >>
 >>
 >>
 >> -----Original Message-----
 >> From: Claims Dept of CTI
 >> Sent: Wednesday, 12 February 2020 3:51 PM
 >> To: motor@wahhong.sg; Adeline Chng <adeline.chng@sg.cntaiping.com>
 >> Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
 >> Subject: OUR REF: SNM20D200740/CB6442Y/ADELINE - PRE-REPAIR
 > INSPECTION
 >> - ACCIDENT INVOLVING SKD2278B & YOUR INSURED CB6442Y ON 07/02/2020
 >> Importance: High
 >>
 >> Dear Adeline,

>> Please conduct PRS for SKD2278B.

>> Note : officer in charge – Adeline 63896155.

>> *** Kindly quote our reference number when replying.

>> Thank you,
 >> Claims Department

>> China Taiping Insurance (Singapore) Pte. Ltd.
 >> 3 Anson Road #15-00 Springleaf Tower Singapore 079909
 >> DID: (65) 63896116 | F: (65) 62247175

>> W: www.sg.cntaiping.com [1] | FB:
 > www.facebook.com/chinataipingsg/ [2]
 >> | WeChat: 太平獅城 Taiping SG

>> Disclaimer: This e-mail and any files transmitted with it is
 > intended
 >> only for the named recipients and may contain confidential
 >> information. Any unauthorized disclosure, use or dissemination of
 > this
 >> message, either in whole or partial, is prohibited. If you are not
 > the
 >> intended recipient, please notify the sender immediately. Please
 >> delete the e-mail and any copies of it thereafter.

>> -----Original Message-----
 >> From: Wahhong motors & credit pte ltd <motor@wahhong.sg>
 >> Sent: Wednesday, February 12, 2020 11:23 AM
 >> To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
 >> Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING SKD2278B & YOUR
 >> INSURED CB6442Y ON 07/02/2020

>> Dear Sirs/Madam,

>> Please find the attached GIA and PRS Letter for your perusal.

>> Kindly arrange Pre-Repair Survey for this vehicle.

>> Take note that the Repair Estimate will be ready upon the Pre-Repair
 > Survey.

>> Workshop: WAH HONG MOTORS & CREDIT Pte
 > Ltd

>> Address: 38 TOH GUAN ROAD EAST #01-57
 >> ENTERPRISE HUB SINGAPORE
 > 608581

>> Contact Person: Victor Seng

>> HP: 87784848

>>
>> Office: 67737377

>>
>>
>> --
>>

> Thank You and Best Regards,

>

> Victor Seng

> Claims

> WAH HONG MOTORS & CREDIT PTE LTD

> ROC:199806235M

> ENTERPRISE HUB

> 38 TOH GUAN ROAD EAST

> #01-57 S(608581)

> Tel:(65)67737377

> HP :(65)87784848

> Website: www.wahhong.sg [3]

> Mail : motor@wahhong.sg

>

>

> Links:

> -----

> [1] <http://www.sg.cntaiping.com>

> [2] <http://www.facebook.com/chinataipingsg/>

> [3] <http://www.wahhong.sg>

Veron Chen (LKKAUTO)

From: Wahhong motors & credit pte ltd <motor@wahhong.sg>
Sent: Tuesday, 17 March 2020 5:21 PM
To: Rasul (LKKAUTO)
Subject: Re: SKD 2278B DOA : 07/02/2020

Hi Rasul

Finalised amount is \$ 3,350 / 6 days of lump sum repair confirmed.

LOD sent to who?

On 2020-03-17 16:54, Rasul (LKKAUTO) wrote:

> Hi Victor,
>
> Refer to attachment
>
> Finalised amount is \$ 3,350 / 6 days of lump sum repair
>
> Kindly confirm
>
> Best Regards,
>
> RASUL | Assessor
>
> LKK AUTO CONSULTANTS PTE LTD
>
> Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
>
> Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)
>
> _SAVE THE EARTH. PRINT ONLY WHEN NECESSARY._

—
Thank You and Best Regards,

Victor Seng
Claims
WAH HONG MOTORS & CREDIT PTE LTD
ROC:199806235M
ENTERPRISE HUB
38 TOH GUAN ROAD EAST
#01-57 S(608581)
Tel:(65)67737377
HP :(65)87784848
Website: www.wahhong.sg
Mail : motor@wahhong.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 555B

Vehicle Details

Vehicle No.: SKD2278B
Vehicle to be Exported: No
Intended Deregistration Date: 11 Feb 2020
Vehicle Make: VOLKSWAGEN
Vehicle Model: JETTA 1.4 TSI AT 1623Q5
Primary Colour: Brown
Manufacturing Year: 2011
Engine No.: CAV300474
Chassis No.: WVVZZZ16ZBM107060
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$24,357.00
Original Registration Date: 09 Nov 2011
First Registration Date: 09 Nov 2011
Transfer Count: 0
Actual ARF Paid: \$24,357.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 08 Nov 2021
PARF Rebate Amount: \$13,396.00

Intended COE Rebate Details

COE Expiry Date: 08 Nov 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$55,989.00
COE Rebate Amount: \$9,756.00
Total Rebate Amount: \$23,152.00

The information contained herein is correct as at 11 Feb 2020

OK

27,000
23,152

3848

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/02/2020 10:46
Date Of Accident	07/02/2020 07:20
Exact Location Of Accident	CHIJ BUKIT TIMAH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD2278B
Insured/Policyholder	
Name Of Registered Owner	GAYATHIRI D/O SUNDARAM
NRIC No	SXXXX555B
Email Address	GOLDENGLOBE9020@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91440442
Alternative Phone No	OFFICE-91440442

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA-1.4 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2019-V8007443-VDP-R004
Cover Note Number	

Driver

Name of Driver	GAYATHIRI D/O SUNDARAM
NRIC No	SXXXX555B
Date Of Birth	07/12/1986
Occupation	INDOOR
Date Of Driving Pass	05/02/2009
Driving Experience	11 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91440442
Fax Number	
Contact Number	OFFICE-91440442
EMail Address	GOLDENGLOBE9020@HOTMAIL.COM

Address	9 DAIRY FARM HEIGHTS #06-22
Postcode	677670
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LAKSHANA GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN FOR ACCIDENT DETAILS.

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB6442Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 07/02/2020 at about 0730 hrs, I was dropping my kid to school at CHIJ (BUKIT TIMAH). after dropping off my kid I moved off from the school front dropping off pouch. I was moving forward crossing the bus which was stationary at the left side of the road while I was turning right towards the exit gate. I noticed the bus tyres turning towards my direction. I stopped immediately before the hump and sound my car horn but unfortunately the driver of bus no: CB 6442 Y kept moving towards my car direction hitting the left side corner and dragging his bus against my car starting from the middle section of the bus till the end of the side of the bus. The driver had only noticed and managed to stop his bus after passing the rear tyre of his bus. after which he came down from his bus and apologised to me and mentioned that he did not notice my car from the start.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature

Date & Time: 07/02/20
10:30 AM

Driver's Signature

(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/TIN No.:

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Enterprise Hub 38 Toh Guan Road East #01-57 5(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 1

Vehicle No. SKD2278B VOLKSWAGEN JETTA-1.4 (A)

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT	
PARTS (LIST ITEMS)					
1	Bonnet <i>bt</i>	Less 10%	1020.00		
1	LH headlamp <i>bro</i>		480.00		
1	Front LH fender <i>buc</i>		440.00		
1	Front LH fendershield <i>de</i>		130.00		
1	Front bumper <i>de</i>		920.00		
1	Front reinforcement <i>xm</i>		440.00	X	
1	Front reinforcement sponge <i>xm</i>		110.00	X	
1	Front LH side retainer <i>re</i>		50.00		
1	Front LH fog lamp <i>xm</i>		180.00	X	
1	Front LH fog lamp cover <i>sc</i>		100.00		
1	Support panel <i>repar</i>		800.00	XR	
1	Front LH rim <i>sc</i> s/n - 350				
			4670.00		
			467.00		
			4203.00		
SPECIAL NETT ITEMS					
1	Front bumper clips <i>re</i>	Total Parts	35.00		
1	Front fendershield clips <i>re</i>		25.00		
1	Reverse sensor <i>xm</i>		280.00	X	
			4543.00		

3140

10%

2826

60



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 2

Vehicle No. SKD2278B VOLKSWAGEN JETTA-1.4 (A)

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1400.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1200.00	600
3	To remove and re-fix wiring and check all electrical components	180.00	30
4	To provide anti-rust treatment on affected area	150.00	80
Labour Total :		2930.00	
TOTAL (PARTS & LABOUR):		7473.00	7823

1310

2826

60

1310

4196

20%

3,356.80

415-3,350

Signature
18/2/2020 Repair

Hp 90010068

6 days

L/S

17/02/2020 @ 1500hrs

Rehug after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To return/replace spray painting
- To display damaged part(s) during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002655/R1VF3N2
Date: 20/03/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN17455319033
Claimant Vehicle No :	SKD2278B	Insured Vehicle No :	CB6442Y
Date of Loss:	07/02/2020	Nature of Claim:	TP
		Claim No:	SNM20D200740C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD2278B	Engine No:	CAV300474
Make & Model:	VOLKSWAGEN JETTA, 1.4 (A)	Chassis No:	WVWZZZ16ZBM107060
Reg. Date:	09/11/2011 (Man. Year: 2011)	Odometer:	134437 km
Colour:	Brown		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40ZR18	Rear Tyre Size:	225/40ZR18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,893.00	3,236.00	1,657.00	33.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,310.00	1,620.00	55.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,823.00	4,546.00	3,277.00	41.89
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	7,823.00	3,350.00	4,473.00	57.18
+ GST 7.00/7.00% (S\$)	547.61	234.50	313.11	57.18
Nett Amount (S\$)	8,370.61	3,584.50	4,786.11	57.18

INSPECTION

Date of Assignment:	15/02/2020	
Date Inspected:	17/02/2020	Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 20 Mar 2020)

Parts: 143 VOLKSWAGEN JETTA 1.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKD2278B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,020.00 FL	*1,020.00 FL
2	1		*LH HEADLAMP	Broken	480.00 FL	*480.00 FL
3	1		*FRONT LH FENDER	Buckled	440.00 FL	*440.00 FL
4	1		*FRONT LH FENDER SHIELD	Deformed	130.00 FL	*130.00 FL
5	1		*FRONT BUMPER	Deformed	920.00 FL	*920.00 FL
6	1		*FRONT REINFORCEMENT	Not Necessary	440.00 FL	*- FL
7	1		*FRONT REINFORCEMENT SPONGE	Not Necessary	110.00 FL	*- FL
8	1		*FRONT LH SIDE RETAINER	Necessary	50.00 FL	*50.00 FL
9	1		*FRONT LH FOG LAMP	Not Necessary	180.00 FL	*- FL
10	1		*FRONT LH FOG LAMP COVER	Scratched	100.00 FL	*100.00 FL
11	1		*SUPPORT PANEL	Repair	800.00 FL	*- FL
12	1		*FRONT LH RIM	Scratched	350.00 FS	*350.00 FS
13	1		*FRONT BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
14	1		*FRONT FENDER SHIELD CLIPS	Necessary	25.00 FS	*25.00 FS
15	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
					Sub Total (\$\$)	5,360.00 3,550.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	467.00 314.00
					Total Parts (\$\$)	4,893.00 3,236.00

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,400.00	600.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,200.00	600.00
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS	New	180.00	30.00
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREA	New	150.00	80.00
Gross Labour Cost (S\$)			2,930.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >