

A.S.S. REC. BY:

REF: CS/TMI 20002729 / Fsf322

Special Instruction:

Surveyor: Ram**ASSIGNMENT (Office)**From (Person): Shawn Ngo San Wei of TMI Date/Time: 18.2.2000 9.28 A.M

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 8755C Insured: SMR 52755at Workshop m/s Comfora delgro Tel: 6214 8300of 59 loyang DrivePolicy No: MK 000823 Claim No: M 2001261

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16/21/2000
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 18.2.2000 10.00 A.M Person Contacted: Juman H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate.
	SHA 8755C - CC3/FCJ/150K/144/tg6112 Date: 29/06/2015
	SMR 52755 - X
18/02/20	@ 16:53 pm received PA to Ngo San Wei via maimer.

ASS. REC. BY:

Ram

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHA 6735C

Yr Regn: 22/12/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai 140

c.c 1685

Colour:

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading:

370091

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH1BA10WV097735

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/60 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

16/02/2020

D.O.I.

17/02/2020

Survey held at

Comfortdelgro (Layang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

OK rear & wheel

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 06 MAR 2020

Jm1

L/S

L/S: \$1350/- with 3 x fair days

(\$ 2,503.80 Red - 65%)

consumed on 5/3/2020 with LARRY

6/3/2020

Date/Time, File Pass to?

06/03/20

1)

Typ:st

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Week end (\$

Survey Fee:

290

Transportation:

S + RS. \$

Photos

Others

11

TOTAL

261

Report Format:

Lump Sum / L/S: (\$ 1,350/- L/S)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Feb 2020 Sendback Est	17 Feb 2020 15:14 S\$3,853.80	18 Feb 2020 09:28 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	LUMENS AUTO PTE. LTD., Co. Reg. No.: 201426961K		
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHA8755C	Date of Loss:	16/02/2020 20:00 - :59 [37 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2001261	Policy/Cover Note No.:	MK000823 (Third Party Only) Coverage: 30/09/2019 - 29/09/2020
Vehicle Reg. No. (Insured):	SMR5275S	Policy No. (Claimant):	D-18088937MFSH
		Excess:	S\$3,000.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ngo Sau Wei Shawn]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/02/2020]		
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 8280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 509286

129 Upper Road Singapore 509289

24 Senoko Loop Singapore 758156

7 Sungei Kadul Way Singapore 726791

501 Yishun Industrial Park A Singapore 788733

Date/Time: 17.02.2020 14:55

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD

Sales Order:

JC NO.: 305381769

CUSTOMER

MS

CUSTOMER NO.

ADDRESS

(R)

(P)

COUNT CARD NO.

CITYCAB PTE LTD

7010070

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65551188

(O)

VARS

REGN NO.:

SHA8755C

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

16.02.2020 21:30

YR OF MANU

22.12.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMHU097755

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 16.02.2020

NATURE: 3P 16.02.2020


S/NO

LABOR CODE

DESCRIPTION

TO K10 - Right Rear

FRONT



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.:

SHA8755C

LARRY

Vehicle No.:

SHA8755C

Larry Ng

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ngo Sau Wei Shawn

Date: 18 Feb 2020

Preliminary Advice

Insured Vehicle No	: SMR5275S	Accident Date	: 16/02/2020
TP Vehicle No	: SHA8755C	Assignment Date	: 18/02/2020
Make	: HYUNDAI I40	Est. Duration of Repair	: 3 days
Date of Inspection	: 17/02/2020		
Inspection At	: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,853.80
Revised Amount	:S\$	1,676.68
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,676.68
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/02/2020 11:16
Date Of Accident	16/02/2020 20:35
Exact Location Of Accident	GAMBAS AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA8755C
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	1XXXXX839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	OOI BENG HUA
NRIC No	SXXXX197D
Date Of Birth	25/06/1957
Occupation	OUTDOOR
Date Of Driving Pass	01/01/1977
Driving Experience	43 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96609791
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 2C UPPER BOON KENG ROAD #19-672
Postcode	383002
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMR5275S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	LEFT FRT

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


CHRYSLER STEEL LTD
QUOTED NO 159902830G

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/2/20 at about 2035hrs when I Veh A was travelling along lane 2, Veh B from Lane 1 suddenly filtered left and collided onto the right rear portion of my moving vehicle

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAT PTE LTD
CO. REG. NO. 19240-2758G

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CITYCAB PTE LTD

Singapore

Claimant
Insurer: MS First Capital Insurance Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	16/02/2020
Vehicle Reg. No.:	SHA8755C	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	OOI BENG HUA		

Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	22/12/2016
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	D4FDGU700729	Chassis No:	KMHLB41UMHU097755
Odometer:	1 KM		

Paint Type:

List Item Discount: 20.00 %

Total Loss? **NO**

Est. Duration of Repair (day) 3

Description of Accident/Loss: PLS REFER TO ATTACHED

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

	Amount
Parts	2,332.80
Miscellaneous Items	11.00
Labour	1,510.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,853.80

Larry Ng

+ GST 7.00% (S\$)	269.77
Nett Amount (S\$)	<u>4,123.57</u>

This claim is handled by: NG NYUK PHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 17 Feb 2020)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA8755C/17/02/2020 15:14**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR FENDER - RH <i>x(R)</i>	20.00	0.00	*2,171.40 FL
2	1		*REAR BUMPER - RH <i>cut</i>	20.00	0.00	*553.00 FL
3	1		*REAR WHEEL COVER - RH <i>scr</i>	20.00	0.00	*107.10 FL
4	10		*REAR BUMPER CLIPS <i>rec</i>	20.00	0.00	*22.00 FL
5	1		*REAR BUMPER RUBBER MAT <i>rec</i>	0	0.00	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)**2,903.50****- List Item Discount on L Items (\$\$)****570.70****Total Parts (\$\$)****2,332.80****ComfortDelGro Engineering Pte Ltd/SHA8755C/17/02/2020 15:14. Not valid without Reference section.**Generated using **Merimen e-Claims IEAS**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	750 700.00
2	SPRAY PAINTING	New	400 500.00
3	REMOVE/REFIX REVERSE SENSOR	New	80 80.00
4	REMOVE/REFIX REAR UPHOLSTERY	New	150 150.00
5	TUFF KOTE	New	80 80.00
Gross Labour Cost (S\$)			1,510.00

ComfortDelGro Engineering Pte Ltd/SHA8755C/17/02/2020 15:14. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES

Larry No

- LKK Auto Consultants hereby notify the Repairer of the following:
- To resurvey before after spray painting
 - To display damaged car during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No final modification is allowed
 - Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

19/2/2020
Rem (LKK)
17/02/2020 1600
Pareswan@lkk.com
88622728
at repair
photo
30 repair days
HS

Our Job Ref No : 305381769

Date : 25. Feb. 2020

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SHA8755C

Date of Accident: 16. Feb. 2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO SMR5275S

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: _____

Final Lumpsum Repair cost

\$1,350.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Ram

Date : 5/3/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

3P is keen on private settlement.

...CLAIM SUBFOLDER...(Pending for Survey Report)















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Feb 2020 Sendback Est	17 Feb 2020 15:14 S\$3,853.80	18 Feb 2020 09:28 Edit Adj Rpt	S\$1,350.00 Edit Estimates	S\$1,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	LUMENS AUTO PTE. LTD., Co. Reg. No.: 201426961K								
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G								
Vehicle Reg. No.:	SHA8755C	Date of Loss:	16/02/2020 20:00 - :59 [37 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M2001261	Policy/Cover Note No.:	MK000823 (Third Party Only) Coverage: 30/09/2019 - 29/09/2020						
Vehicle Reg. No. (Insured):	SMR5275S	Policy No. (Claimant):	D-18088937MFSH						
		Excess:	S\$3,000.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ngo Sau Wei Shawn]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 27/02/2020]								
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									












Claim Documents

SHA8755C (M2001261)
[SMR5275S]
TP
CITYCAB PTE LTD
Feb 16 2020 8:00PM
[LUMENS AUTO PTE. LTD.]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print					
1	17/02/20 11:27	Accident Statement		1 Load HTM						
2	17/02/20 15:14	Repairer Estimates		1 Load HTM						
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	18/02/20 16:53	Adjuster Immediate Advice		1 Load HTM						
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print					
1	17/02/20 11:22	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
2	17/02/20 11:22	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
3	17/02/20 11:22	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
4	17/02/20 11:22	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
5	17/02/20 11:22	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
6	17/02/20 11:22	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
7	17/02/20 11:22	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
8	17/02/20 11:22	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
9	17/02/20 11:22	Accident Photo [Linked Accident Report Documents]		1 Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
2	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
3	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
4	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
5	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
6	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
7	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
8	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
9	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
10	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
11	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
12	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
13	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
14	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
15	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
16	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
17	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					
18	06/03/20 15:34	General View		1 Load JPG	<input checked="" type="checkbox"/>					

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
19	06/03/20 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
20	06/03/20 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
21	06/03/20 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
22	06/03/20 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
23	06/03/20 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
24	06/03/20 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
25	06/03/20 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
26	06/03/20 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
27	06/03/20 15:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	06/03/20 15:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	06/03/20 15:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	06/03/20 15:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	17/02/20 11:26	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail	Print
1	21/02/20 18:27	TP - SHA8755C - Singapore Accident Statement	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	17/02/20 11:27	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	17/02/20 11:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	17/02/20 11:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	17/02/20 11:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	17/02/20 11:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	17/02/20 11:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	17/02/20 11:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	17/02/20 11:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	17/02/20 11:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	17/02/20 11:22	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	17/02/20 11:26	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Repairer ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20002729/FSF3E2

Date: 06/03/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MK000823

Claimant Vehicle No : SHA8755C

Insured Vehicle No : SMR5275S

Date of Loss: 16/02/2020

Nature of Claim: TP

Claim No: M2001261

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA8755C

Make & Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDGU700729

Reg. Date: 22/12/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMHU097755

Colour: Yellow

Odometer: 370091 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes

Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes

Engine Modification: No

Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Hankook 7 mm

Rear Left Side: Hankook 7 mm

Front Right Side: Hankook 7 mm

Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,332.80	595.68	1,737.12	74.47
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,510.00	1,090.00	420.00	27.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,853.80	1,696.68	2,157.12	55.97
Approved Total (Overridden) (\$\$)		1,350.00		
(\$\$)	3,853.80	1,350.00	2,503.80	64.97
+ GST 7.00/7.00% (\$\$)	269.77	94.50	175.27	64.97
Nett Amount (\$\$)	4,123.57	1,444.50	2,679.07	64.97

INSPECTION

Date of Assignment: 18/02/2020 Present Location:

ComfortDelGro Engineering Pte Ltd
(Loyang)

Date Inspected: 17/02/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: PARASURAM SHANMUGAM**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2020)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA8755C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR FENDER - RH	Repair	2,171.40 FL	-	*- FL
2	1		*REAR BUMPER - RH	Cut	553.00 FL	-	*553.00 FL
3	1		*REAR WHEEL COVER - RH	Scratched	107.10 FL	-	*107.10 FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
5	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	-	*50.00 FS
					Sub Total (\$\$)	2,903.50	732.10
					- List Item Discount on L Items 20.00/20.00% (\$\$)	570.70	136.42
					Total Parts (\$\$)	2,332.80	595.68

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	700.00	560.00
2	SPRAY PAINTING	New	500.00	400.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	80.00
4	REMOVE/REFIX REAR UPHOLSTERY	New	150.00	0.00
5	TUFF KOTE	New	80.00	50.00
Gross Labour Cost (S\$)			1,510.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >