

ASS. REC. BY:

REF: CS/TM12 0002731/Pt f3e1 Special Instruction:

Surveyor: Row ASSIGNMENT (Office)From (Person): Jeffrey Tay of TM1 Date/Time: 18.2.2020 9.039.m

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHA 9331K Insured: SLN 372Kat Workshop m/s Comfortdugro Tel: 624 8300of 59 loyang drivePolicy No: MX 00031 Claim No: M 2001240

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15/21 2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 18/2/2020 10.000.m Person Contacted: Jumani Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 9331K - CS/FC9 17006054/ b-hn2 DOB. 23/02/2020
	SLN 372K - X
18b-	Sent preli advice.

ASS. REC. BY: Ram

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHA 9851K Yr Regn: 13/09/2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Prius (Hybrid) cc 1792Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 29/012 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STD0356003563272Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

DAWANT 1

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 15/02/2020 D.O.I. 17/02/2020Survey held at Confidential (Loyalty)Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 21 FEB 2020

D/O: \$602.07/- with 2 repair days (Red: 868.25! 59%)

confirm on 21/2/2020 with LKE

Date/Time, File Pass to?

1) 21/2 Typist

Date/Time, File Return to?

2) _____



Prel. Report



Final Report

Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Wheel and (\$

Survey Fee:

Transportation:

S + PS: \$

Photos

Others:

TOTAL

25011261Report Format: TPLump Sum / L.B.: 602.07

Our Job Ref No 305381705

Date : 19.02.20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr RAM

Vehicle Reg No. SHA9331K CCPL

15.02.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SLN372K
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$21.07
(b) Labour Charges	\$581.00
Total for Part-By-Part Repair Cost	\$602.07
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	
Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Ram

Date : 21/2/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305381705
 REGN NO : SHA9331K
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 13.09.2017
 DATE/TIME IN : 16.02.2020 08:20
 ACCIDENT DATE : 15.02.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2292-A	PRIG4 COVER FRONT BUMPER	1 L	499.90	25.00	374.92	x(R)	
0002 04-01-0302-2871-G	PRIG4 SUPPORT FRONT BUMPE	1 L	82.30	25.00	61.72	mis	7xmn
0003 04-01-0302-0633-G	PRIG4 COVER FRONT BUMPER	1 L	28.10	25.00	21.07	mis	
0004 04-01-0302-2696-G	PRIG4Q8 GRILLE SUB-ASSY	1 L	301.90	25.00	226.42	7xmn	
0005 04-01-0302-2062-G	PRIG4 GRILLE RADIATOR LOW	1 L	166.90	25.00	125.17	7xmn	
0006 04-01-0302-4891-A	PRIG4 LAMP ASSY FOG RH	1 L	920.00	25.00	690.00	Xmn	
0007 04-01-0302-2815-A	PRIG4 UNIT ASSY HEADLAMP	1 L	3455.00	25.00	2,591.25	Xmn	

SUB-TOTAL : 4,090.55

JOB NATURE

0000 L	PANEL BEATING	350.00	4320
0001 23-502	SPRAYPAINT ON AFFECTED AREA	250.00	200
0002 17-01	CHECK ALL LIGHTING	50.00	
		SUB-TOTAL : 650.00	

7567T
 Blind spot
 Bel paint
 taken

Ram (UIC)
 17/02/2020 1545hrs
 Parashram@carauto.com
 88622778
 att / Bel paint photo
 (P/P)
 Repair day 5

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305381705
REGN NO : SHA9331K
MILEAGE : 000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 13.09.2017
DATE/TIME IN : 16.02.2020 08:20
ACCIDENT DATE : 15.02.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-0633-G PRIG4 COVER FRONT BUMPER 1 L 28.10 25.00 21.07 *ms*
SUB-TOTAL : 21.07

JOB NATURE

0000 L PANEL BEATING 320.00
0001 23-502 SPRAYPAINT ON AFFECTED AREA 200.00
0002 17-01 CHECK ALL LIGHTING 50.00
0003 L MERIMEN CHARGE 11.00
SUB-TOTAL : 581.00
TOTAL : 602.07

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Feb 2020 19:52 Sendback Est	17 Feb 2020 19:58 \$51,470.32	18 Feb 2020 09:03 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	CCPL, Co. Reg. No.: 199303839G		
Main Claimant:	CCPL		
Vehicle Reg. No.:	SHA9331K	Date of Loss:	15/02/2020 18:00 - :59 [29 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2001240	Policy/Cover Note No.:	MK000031 (Comprehensive) Coverage: 09/01/2019 - 19/04/2020
Vehicle Reg. No. (Insured):	SLN372K	Policy No. (Claimant):	
		Excess:	\$50.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Jeffrey Tay - 65926413]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/02/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Team: ARC Repair TP(CFSO)1

JOB CARD

Sales Order:

JC NO: 305381705

OWNER

CITYCAB PTE LTD
7010070
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188

(R)

(P)

UNIT CARD NO.

REGN NO.

SHA9331K

MILEAGE

MAKE :

TOYOTA

FUEL

E 1/2 F

MODEL

PRIUS HYBRID(G4)16.02.2020 08:20

YR OF MANU

13.09.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU003563272


COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 15.02.2020

NATURE: 3P 15.02.2020

S/NO LABOR CODE DESCRIPTION



LED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Damage Slip

Exit Pass

SHA9331K LKE

Vehicle No.: SHA9331K

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/02/2020 07:29
Date Of Accident	15/02/2020 15:50
Exact Location Of Accident	SIN MING RD BLK 24 OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA9331K
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	1XXXXX839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

Driver

Name of Driver	CHEE AH HOE
NRIC No	SXXXX141B
Date Of Birth	15/12/1960
Occupation	OUTDOOR
Date Of Driving Pass	14/01/1981
Driving Experience	39 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97459423
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	886D 11-543 WOODLANDS DRIVE 50
Postcode	734886
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : FEMALE
Passenger 2	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN372K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN HONG BENG
NRIC/Passport Number	
Contact Number	97506543
Address	

Postcode

Insurance Company Name

Nature Of Damage

RHT FRT

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

FIRE ENGINE (CARPARK)		BLK 24
		IN Multi-storey Carpark.
		A - SHA 9331K B - SLN 372K
		DOA: 18-02-20 1550hrs
SIN MING Rd BLK 24 OPEN CARPARK.		

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18-02-2020 @ 1550hrs, I was entering Carpark Sin Ming Rd BLK 24 Open Carpark. I saw Vehicle (B) coming toward me and I stopped my taxi. Vehicle B SLN 372K without stop and sudden make right turn and hit my taxi. Front right portion Carpark damaged.

There is Video Footage on the Scene.
There is 2 Vehicle Pass and No injury.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

WILLIAMS PTE LTD
REG. NO. 1995028390

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

TOTAL GREEN PAPER LTD

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/PIN No.



50.00 —
SUB-TOTAL : 650.00
Ram (LXC)
17/02/2020 1545hrs
Razvi@LXCauto.com
8622718
148/125 print photo
(5) repair day 5

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 17.02.2020

Time: 14:17:34

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305381705
REGN NO : SHA9331K
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 13.09.2017
DATE/TIME IN : 16.02.2020 08:2
ACCIDENT DATE : 15.02.2020


JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 4,740.55

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Feb 2020 19:52 Sendback Est	17 Feb 2020 19:58 S\$1,470.32	18 Feb 2020 09:03 Edit Adj Rpt	S\$602.07 Edit Estimates	S\$602.07 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	CCPL Co. Reg. No.: 199303839G								
Main Claimant:	CCPL								
Vehicle Reg. No.:	SHA9331K	Date of Loss:	15/02/2020 18:00 - :59 [29 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M2001240	Policy/Cover Note No.:	MK000031 (Comprehensive) Coverage: 09/01/2019 - 19/04/2020						
Vehicle Reg. No. (Insured):	SLN372K	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Jeffrey Tay - 65926413]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 27/02/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHA9331K (M2001240)
[SLN372K]
TP
CCPL
Feb 15 2020 6:00PM
[CCPL]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		☒	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)								Thumbnail	Print	
1	17/02/20 19:58	Repairer Estimates								Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	18/02/20 15:51	Adjuster Immediate Advice								Load HTM		
Photos/Images									3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	21/02/20 10:03	General View								Load JPG	☒	
2	21/02/20 10:03	General View								Load JPG	☒	
3	21/02/20 10:03	General View								Load JPG	☒	
4	21/02/20 10:03	General View								Load JPG	☒	
5	21/02/20 10:03	General View								Load JPG	☒	
6	21/02/20 10:03	General View								Load JPG	☒	
7	21/02/20 10:03	General View								Load JPG	☒	
8	21/02/20 10:03	General View								Load JPG	☒	
9	21/02/20 10:03	General View								Load JPG	☒	
10	21/02/20 10:03	General View								Load JPG	☒	
11	21/02/20 10:03	General View								Load JPG	☒	
12	21/02/20 10:03	General View								Load JPG	☒	
13	21/02/20 10:03	General View								Load JPG	☒	
14	21/02/20 10:03	General View								Load JPG	☒	
15	21/02/20 10:03	General View								Load JPG	☒	
16	21/02/20 10:03	General View								Load JPG	☒	
17	21/02/20 10:03	General View								Load JPG	☒	
18	21/02/20 10:03	General View								Load JPG	☒	
19	21/02/20 10:03	General View								Load JPG	☒	
20	21/02/20 10:03	General View								Load JPG	☒	
21	21/02/20 10:03	General View								Load JPG	☒	
22	21/02/20 10:03	General View								Load JPG	☒	
23	21/02/20 10:03	General View								Load JPG	☒	
24	21/02/20 10:03	General View								Load JPG	☒	
25	21/02/20 10:03	General View								Load JPG	☒	
26	21/02/20 10:03	General View								Load JPG	☒	
27	21/02/20 10:03	General View								Load JPG	☒	
28	21/02/20 10:03	General View								Load JPG	☒	
29	21/02/20 10:03	General View								Load JPG	☒	
30	21/02/20 10:03	General View								Load JPG	☒	
31	21/02/20 10:03	General View								Load JPG	☒	
32	21/02/20 10:05	After Repair Photo								Load JPG	☒	

Assessment Reports				1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
33	21/02/20 10:05	After Repair Photo		Load JPG	☒
34	21/02/20 10:05	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	17/02/20 20:00	E-filed GIA report		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TM20002731/FTF3E2

Date: 24/02/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MK000031

Claimant Vehicle No: SHA9331K

Insured Vehicle No: SLN372K

Date of Loss: 15/02/2020

Nature of Claim: TP

Claim No: M2001240

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA9331K

Make & Model: TOYOTA PRIUS HYBRID, 1.8 (A)

Engine No: 2ZRS061215

Reg. Date: 13/09/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU003563272

Colour: Yellow

Odometer: 291012 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	809.32	21.07	788.25	97.40
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	650.00	570.00	80.00	12.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,470.32	602.07	868.25	59.05
+ GST 7.00/7.00% (S\$)	102.92	42.14	60.78	59.06
Nett Amount (S\$)	1,573.24	644.21	929.03	59.05

INSPECTION

Date of Assignment: 18/02/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 17/02/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2020)	
Parts: 144	TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SHA9331K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER COVER	Repair	499.90 FL	-	*- FL
2	1		*FRT BUMPER SUPPORT BRACKET RH	Not Necessary	82.30 FL	-	*- FL
3	1		*FRT BUMPER HOLE COVER RH	Missing	28.10 FL	-	*28.10 FL
4	1		*FRT BUMPER UPPER GRILLE ASSY	Not Necessary	301.90 FL	-	*- FL
5	1		*FRT BUMPER LOWER GRILLE ASSY	Not Necessary	166.90 FL	-	*- FL
					Sub Total (S\$)	1,079.10	28.10
					- List Item Discount on L Items 25.00/25.00% (S\$)	269.78	7.03
					Total Parts (S\$)	809.32	21.07

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	320.00
2	SPRAY PAINTING CHARGE	New	250.00	200.00
3	WIRING CHARGE	New	50.00	50.00
Gross Labour Cost (S\$)			650.00	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >