



ASS. REC. BY: Adrian King

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKN2925P Yr Regn: 2009 / August

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey C.C. 2354

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 169646 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHMRB38509C200181

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 55 R17

R: 215 / 55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 27/06/16

Survey held at Tek Soon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

AP ALG -

L/S - \$63001 Cred: \$5906.72 / 48%.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |                                                                                                                                        |                            |                                                                                     |
|-------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------------|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                |                                                                                                                                        | Ref : CC6/AIG16011893/Aug3 |                                                                                     |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDING<br>SINGAPORE 079120     |                                                                                                                                        | Date : 28-06-2016          |  |
|                                                                   |                                                                                                                                        | Code : AIG                 |                                                                                     |
| <b>Policy Particulars :- THIRD PARTY CLAIM</b>                    |                                                                                                                                        |                            |                                                                                     |
| 1.                                                                |                                                                                                                                        |                            |                                                                                     |
|                                                                   | Insured Veh. SJH 9913X                                                                                                                 | Veh. Inspected             | SKN 2925P                                                                           |
|                                                                   | Policy No.                                                                                                                             | Coverage (\$)              | 0.00                                                                                |
|                                                                   | Claim No.                                                                                                                              | Excess (\$)                | 0.00                                                                                |
|                                                                   | Assign From                                                                                                                            | Assign Date                | 28/06/2016                                                                          |
| <b>Vehicle Particulars &amp; Condition</b>                        |                                                                                                                                        |                            |                                                                                     |
| 2.                                                                |                                                                                                                                        |                            |                                                                                     |
|                                                                   | Make & Model                                                                                                                           | c.c                        | 0                                                                                   |
|                                                                   | Engine No. HIDDEN                                                                                                                      | Year of Reg.               |                                                                                     |
|                                                                   | Chassis No.                                                                                                                            | Colour                     |                                                                                     |
|                                                                   | Odometer                                                                                                                               | Steering                   |                                                                                     |
|                                                                   | Brakes                                                                                                                                 | Modification               |                                                                                     |
|                                                                   | General                                                                                                                                |                            |                                                                                     |
| <b>Conditions of Tyres</b>                                        |                                                                                                                                        |                            |                                                                                     |
| 3.                                                                |                                                                                                                                        |                            |                                                                                     |
|                                                                   | Size                                                                                                                                   | Make                       | Balance                                                                             |
|                                                                   | R/H Front Tyre                                                                                                                         |                            | mm                                                                                  |
|                                                                   | L/H Front Tyre                                                                                                                         |                            | mm                                                                                  |
|                                                                   | R/H Rear Tyre                                                                                                                          |                            | mm                                                                                  |
|                                                                   | L/H Rear Tyre                                                                                                                          |                            | mm                                                                                  |
| <b>Description of Damages</b>                                     |                                                                                                                                        |                            |                                                                                     |
| 4.                                                                |                                                                                                                                        |                            |                                                                                     |
| <b>General Information</b>                                        |                                                                                                                                        |                            |                                                                                     |
| 5.                                                                |                                                                                                                                        |                            |                                                                                     |
|                                                                   | Accident Date 24/06/2016                                                                                                               | Inspection Date            | 27/06/2016                                                                          |
|                                                                   | Survey held at TEK SOON MOTOR REPAIR & SPRAY PAINTING<br>AUTOBAY @ KAKI BUKIT<br>1 KAKI BUKIT AVE 6 BLK D #01-93<br>SINGAPORE 417883   |                            |                                                                                     |
| <b>Remarks</b>                                                    |                                                                                                                                        |                            |                                                                                     |
| 5a.                                                               |                                                                                                                                        |                            |                                                                                     |
|                                                                   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                            |                                                                                     |

67466822

SKN292SP 2009 August.

Honda Odyssey 2354cc

JHMRB38509C200181

|                                      |            |                       |
|--------------------------------------|------------|-----------------------|
| Rear Number Plate                    | 2 ASP      | 30 (SN) x             |
| Rear Number Plate Holder             | 1 New      | 30 (SN) x             |
| Rear Bumper                          | Deformed   | 796.30 -              |
| Rear Bumper Clips                    | ~          | 30 -                  |
| Rear Bumper Side Holder x02          | ~          | 299 x 2 = 598.00 -    |
| Rear Bumper Reflector x02            | Crushed    | 72.1 x 2 = 144.20 -   |
| Rear Bumper Reinforcement            | Best       | 197.20 -              |
| <del>Rear Bumper Lower Spoiler</del> |            |                       |
| Rear Bumper Tow Cover Deformed       |            | 19.20 -               |
| Reverse Sensor                       | 2nd        | 280 (SN) - 220 (SN)   |
| Rear End Panel                       | Deformed   | 496.20 -              |
| Rear End Panel Top Garnish           | Deformed   | 216.40 -              |
| Rear End Panel Sealant               | ~          | 60 (SN) -             |
| Taillamp x02                         | Crushed    | 358.4 x 2 = 716.80 -  |
| Tailgate                             | Deformed   | 991.20 -              |
| Tailgate Lock                        | 2nd        | 125.30 -              |
| Tailgate Weatherstripe               | ~          | 156.90 -              |
| Tailgate Outer Garnish               | Deformed   | 438.40 -              |
| Tailgate Outer Garnish Clips         | ~          | 20 -                  |
| Tailgate Lamp x02                    | LH crushed | 239.4 x 2 = 478.80 -  |
| Tailgate Glass Moulding              | 2 New      | 183.20 -              |
| Tailgate Glass Sealant               | ~          | 60 (SN) -             |
| 1st Tailgate Inner Trim Board        | Deformed   | 345.30 -              |
| Tailgate Inner Trim Board Clips      | ~          | 30 -                  |
| Honda Logo                           | ~          | 32.40 -               |
| Odyssey Emblem                       | ~          | 39.20 -               |
| Spore Tyre Panel Top Covers          | ~          | 391.60 -              |
| Rear Fender Inner Trim x02           | 2 New      | 569.9 x 2 = 1139.80 + |
| Rear Fender Inner Trim Clips         | ~          | 60 x                  |
| Rear LH Exhaust Pipe                 | Best       | 84.5 -                |
| Rear RH Exhaust Pipe                 | ~          | 98.5 x                |

## Thin Thin (LKKAUTO)

---

**From:** Thin Thin (LKKAUTO)  
**Sent:** Tuesday, 5 December, 2017 1:42 PM  
**To:** 'Tan, Bennie-WZ'  
**Cc:** Jas Khine (LKKAUTO); Admin A  
**Subject:** RE: Our Ref: 4392812883SG-003; accident involving SJH9913X / SKN2925P on 24/06/2016

Your Ref: 4392812883SG  
Our Ref: CC6/AIG16011893/Aub3

Dear Sir / Madam,

### ACCIDENT ON 24/06/2016 INVOLVING VEHICLES SJH 9913X AND SKN 2925P

We refer to the below matter.

Please be inform that we have inspected the vehicle **SKN 2925P** on 27/06/2016, at **TEK SOON MOTOR REPAIR & SPRAY PAINTING**.

Our surveyor had finalized with TP repairer at \$ 6,300.00 with 6 days. However, there is still no further action initiated by third-party repairer for their claim.

In view of non-development from the third-party, we will proceed to temporarily close this outstanding claim file and submit our W/P report to your good-office.

In future, if there are any new developments from the claimant, we will inform you for our further handling.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Tan, Bennie-WZ [mailto:Bennie-WZ.Tan@aig.com]  
**Sent:** Monday, 31 July, 2017 5:46 PM  
**To:** Jas Khine (LKKAUTO) <jaskhine@lkkauto.com>  
**Cc:** CS A Team <cs-a@lkkauto.com>  
**Subject:** RE: Our Ref: 4392812883SG-003; accident involving SJH9913X / SKN2925P on 24/06/2016  
**Importance:** High

Dear Jas

We will KIV case for 1 year for any TP developments.

Thereafter, close off this matter should there be no further developments.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG16011893/Aug3

19 JULY 2016

**YAU CHEOW HOO**  
33 MANDALAY ROAD  
#05-01  
SINGAPORE 308214

Dear Sir/Madam,

**ACCIDENT INVOLVING SJH 9913X & SKN 2925P ON 24/06/2016**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING

Case Handler

DID: 6841 2360

FAX: 6741 4108

Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                         | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'd | Status                                                          |
|------|-----------------------------------------|---------------|------------------------------------------------------|------------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Main | 27 Jun 2016<br><a href="#">Edit Reg</a> |               | 27 Jun 2016<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>\$56,300.00</b><br><a href="#">Edit Estimates</a> | <b>\$56,300.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|
|------|-----------|---------------|-----------|----------|

### CLAIM SUBFOLDER DETAILS

|                                    |                                                                                                                                         |                                       |                            |
|------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------|----------------------------|
| <b>Insured:</b>                    | YAU CHEOW HOO, ID: S7232823Z                                                                                                            | <a href="#">[Created by adjuster]</a> |                            |
| <b>Main Claimant:</b>              | WEE CHENG SAN, HARRY, ID: S1516693B                                                                                                     |                                       |                            |
| <b>Vehicle Reg. No.:</b>           | SKN2925P                                                                                                                                | <b>Date of Loss:</b>                  | 24/06/2016 18:00 - :59     |
| <b>Claim Type:</b>                 | TP / 4392812883SG                                                                                                                       | <b>Policy/Cover Note No.:</b>         | 2100384198 (Comprehensive) |
| <b>Vehicle Reg. No. (Insured):</b> | SJH9913X                                                                                                                                | <b>Policy No. (Claimant):</b>         | MT/00286223                |
|                                    |                                                                                                                                         | <b>Excess:</b>                        |                            |
| <b>Repairer:</b>                   | TEK SOON MOTOR REPAIR & SPRAY PAINTING (HQ) 1 KAKI BUKIT AVE 6, BLK D #01-93,,<br>AUTOBAY@KAKI BUKIT, 417883 Kaki Bukit - Tel: 67475484 |                                       |                            |
| <b>Handling Insurer:</b>           | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ -<br>6419 1718] Bennie-WZ.Tan@aig.com |                                       |                            |
| <b>Claimant's Insurer:</b>         | Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888                                                                          |                                       |                            |
| <b>Adjuster:</b>                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... <b>[Final Rpt due 19/07/2016]</b>                   |                                       |                            |

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)


### ALL ASSOCIATED TASKS

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

## Claim Documents

\*SKN2925P (4392812883SG)  
[SJH9913X]

TP

WEE CHENG SAN, HARRY

Jun 24 2016 6:20PM

[YAU CHEOW HOO]

TEK SOON MOTOR REPAIR & SPRAY PAINTING

| Upload Documents   |                 | Upload Photos                                                               | Compose New Letter | Upload Video | Upload Audio                                                                          | View      | Use Viewer                          |                                     |
|--------------------|-----------------|-----------------------------------------------------------------------------|--------------------|--------------|---------------------------------------------------------------------------------------|-----------|-------------------------------------|-------------------------------------|
| Assessment Reports |                 |                                                                             |                    |              |                                                                                       |           | 1 per page                          | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG)                                   |                    |              |                                                                                       | Thumbnail | Print                               |                                     |
| 1                  | 11/07/16 17:45  | Accident Statement<br>From: SC - Reg. No: SJH9913X, Claimant: YAU CHEOW HOO |                    |              |    | Load HTM  |                                     |                                     |
| Photos/Images      |                 |                                                                             |                    |              |                                                                                       |           | 3 per page                          | <input checked="" type="checkbox"/> |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                           |                    |              |                                                                                       | Thumbnail | Print                               |                                     |
| 1                  | 08/07/16 14:42  | Chassis Number                                                              |                    |              |    | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 2                  | 08/07/16 14:42  | General View                                                                |                    |              |    | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 3                  | 08/07/16 14:42  | General View                                                                |                    |              |    | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 4                  | 08/07/16 14:42  | General View                                                                |                    |              |    | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 5                  | 08/07/16 14:42  | General View                                                                |                    |              |    | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 6                  | 08/07/16 14:42  | General View                                                                |                    |              |    | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 7                  | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 8                  | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 9                  | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 10                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 11                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 12                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 13                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 14                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 15                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 16                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 17                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 18                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 19                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 20                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 21                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 22                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 23                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 24                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 25                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 26                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 27                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 28                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 29                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 30                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 31                 | 08/07/16 14:42  | General View                                                                |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 32                 | 08/07/16 14:44  | Reinspection Photo                                                          |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 33                 | 08/07/16 14:44  | Reinspection Photo                                                          |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 34                 | 08/07/16 14:44  | Reinspection Photo                                                          |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |
| 35                 | 08/07/16 14:44  | Reinspection Photo                                                          |                    |              |  | Load JPG  | <input checked="" type="checkbox"/> |                                     |

|    |                |                    |  |          |                                     |
|----|----------------|--------------------|--|----------|-------------------------------------|
| 36 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 37 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 38 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 39 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 40 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 41 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 42 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 43 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 44 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 45 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 46 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 47 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 48 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 49 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 50 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 51 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 52 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 53 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 54 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 55 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 56 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 57 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 58 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 59 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 60 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 61 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 62 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 63 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 64 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 65 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 66 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 67 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 68 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 69 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 70 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 71 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 72 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 73 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 74 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 75 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 76 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 77 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 78 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 79 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 80 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 81 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 82 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 83 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 84 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 85 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |
| 86 | 08/07/16 14:44 | Reinspection Photo |  | Load JPG | <input checked="" type="checkbox"/> |

|                      |                 |                                   |                                                |           |                                     |
|----------------------|-----------------|-----------------------------------|------------------------------------------------|-----------|-------------------------------------|
| 87                   | 08/07/16 14:44  | Reinspection Photo                |                                                | Load JPG  | <input checked="" type="checkbox"/> |
| 88                   | 08/07/16 14:44  | Reinspection Photo                |                                                | Load JPG  | <input checked="" type="checkbox"/> |
| <b>Documentation</b> |                 |                                   |                                                |           |                                     |
| No                   | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | 1 per page <input checked="" type="checkbox"/> |           |                                     |
| 1                    | 08/07/16 14:41  | TP GIA REPORT                     |                                                | Thumbnail | Print                               |
| 2                    | 05/12/17 13:42  | email to AIG                      |                                                | Load PDF  |                                     |
| 3                    | 22/12/17 15:27  | LETTER TO OI                      |                                                | Load PDF  |                                     |

## Documents Checklist

### DOCUMENTS CHECKLIST

There are no document checklists configured.

[Reset](#) [Save](#) [Print](#)

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG16011893/AUB3Q2

Date: 22/12/2017

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100384198  
 Claimant Vehicle No: SKN2925P Insured Vehicle No: SJH9913X  
 Date of Loss: 24/06/2016 Nature of Claim: TP Claim No: 4392812883SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKN2925P  
 Make & Model: HONDA ODYSSEY, 2.4 (A)  
 Reg. Date: 01/08/2009 (Man. Year: 2009) Engine No: HIDDEN  
 Colour: Silver Chassis No: JHMRB38509C200181  
 Engine Capacity: 2354 cc Odometer: 169646 km  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17  
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm  
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm  
*The above values represent the remaining tyre treads depth*

### COST OF CLAIMS

|                                          | Repairer's       | Adjuster's      | Difference      | Diff %       |
|------------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                                    | 10,518.40        | 5,551.20        | 4,967.20        | 47.22        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00            |              |
| Labour                                   | 3,700.00         | 2,310.00        | 1,390.00        | 37.57        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00            |              |
| Towing                                   | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>14,218.40</b> | <b>7,861.20</b> | <b>6,357.20</b> | <b>44.71</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>6,300.00</b> |                 |              |
| <b>Nett Amount (S\$)</b>                 | <b>14,218.40</b> | <b>6,300.00</b> | <b>7,918.40</b> | <b>55.69</b> |
| <b>Global Sum Settlement (S\$)</b>       |                  | <b>0.00</b>     |                 |              |

### INSPECTION

Date of Assignment: 27/06/2016  
 Date Inspected: 27/06/2016 Inspected At: TEK SOON MOTOR REPAIR & SPRAY PAINTING (HQ)  
 1 KAKI BUKIT AVE 6, BLK D #01-93,,  
 AUTOBAY@KAKI BUKIT  
 Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition     | Repairer's | Amount     |
|-----|-----|----------|----------------------------------|---------------|------------|------------|
| 1   | 1   |          | *REAR NUMBER PLATE               |               |            |            |
| 2   | 1   |          | *REAR NUMBER PLATE HOLDER        | Not Necessary | 30.00 FS   | *- FS      |
| 3   | 1   |          | *REAR BUMPER                     | Not Necessary | 30.00 FS   | *- FS      |
| 4   | 1   |          | *REAR BUMPER CLIPS               | Deformed      | 796.30 F   | *796.30 FL |
| 5   | 2   |          | *REAR BUMPER SIDE HOLDER         | Necessary     | 30.00 F    | *30.00 FL  |
| 6   | 2   |          | *REAR BUMPER REFLECTOR           | Necessary     | 59.80 F    | *59.80 FL  |
| 7   | 1   |          | *REAR BUMPER REINFORCEMENT       | Cracked       | 144.20 F   | *144.20 FL |
| 8   | 1   |          | *REAR BUMPER TOW COVER           | Bent          | 197.20 F   | *197.20 FL |
| 9   | 1   |          | *REVERSE SENSOR                  | Deformed      | 19.20 F    | *19.20 FL  |
| 10  | 1   |          | *REAR END PANEL                  | Damaged       | 280.00 FS  | *220.00 FS |
| 11  | 1   |          | *REAR END PANEL TOP GARNISH      | Dented        | 496.20 F   | *496.20 FL |
| 12  | 1   |          | *REAR END PANEL SEALANT          | Deformed      | 216.40 F   | *216.40 FL |
| 13  | 2   |          | *TAILLAMP                        | Necessary     | 60.00 FS   | *60.00 FS  |
| 14  | 1   |          | *TAILGATE                        | Cracked       | 716.80 F   | *716.80 FL |
| 15  | 1   |          | *TAILGATE LOCK                   | Dented        | 991.20 F   | *991.20 FL |
| 16  | 1   |          | *TAILGATE WEATHERSTRIPE          | Damaged       | 125.30 F   | *125.30 FL |
| 17  | 1   |          | *TAILGATE OUTER GARNISH          | Cut           | 156.90 F   | *156.90 FL |
| 18  | 1   |          | *TAILGATE OUTER GARNISH CLIPS    | Deformed      | 438.40 F   | *438.40 FL |
| 19  | 1   |          | *TAILGATE LAMP                   | Necessary     | 20.00 F    | *20.00 FL  |
| 20  | 1   |          | *TAILGATE GLASS MOULDING         | N/S Cracked   | 478.80 F   | *239.40 FL |
| 21  | 1   |          | *TAILGATE GLASS SEALANT          | Necessary     | 183.20 F   | *183.20 FL |
| 22  | 1   |          | *TAILGATE INNER TRIM BOARD       | Necessary     | 60.00 FS   | *60.00 FS  |
| 23  | 1   |          | *TAILGATE INNER TRIM BOARD CLIPS | Deformed      | 345.30 F   | *345.30 FL |
| 24  | 1   |          | *HONDA LOGO                      | Necessary     | 30.00 F    | *30.00 FL  |
| 25  | 1   |          | *ODYSSEY EMBLEM                  | Necessary     | 32.40 F    | *32.40 FL  |
| 26  | 1   |          | *SPARE TYRE PANEL TOP COVER      | Necessary     | 39.20 F    | *39.20 FL  |
| 27  | 2   |          | *REAR FENDER INNER TRIM          | Torn          | 391.60 F   | *391.60 FL |
| 28  | 1   |          | *REAR FENDER INNER TRIM CLIPS    | Not Necessary | 1,139.80 F | *- FL      |
| 29  | 1   |          | *REAR LH EXHAUST PIPE            | Not Necessary | 60.00 F    | *- FL      |
| 30  | 1   |          | *REAR RH EXHAUST PIPE            | Bent          | 845.00 F   | *845.00 FL |
| 31  | 1   |          | *CENTRE EXHAUST PIPE             | Repair        | 985.00 F   | *- FL      |
|     |     |          |                                  | Repair        | 1,120.20 F | *- FL      |

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$) 10,518.40 6,854.00  
 - List Item Discount on L Items 0.00/20.00% (S\$) 0.00 1,302.80

Total Parts (S\$) 10,518.40 5,551.20

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                  | Lab.Type | Repairer's | Amount   |
|-------------------------|----------------------------------------------|----------|------------|----------|
| <b>Labour Items</b>     |                                              |          |            |          |
| 1                       | PANEL BEATING                                | New      | 1,400.00   | 800.00   |
| 2                       | SPRAY PAINTING CHARGE                        | New      | 1,200.00   | 900.00   |
| 3                       | WIRING                                       | New      | 50.00      | 30.00    |
| 4                       | TO UNDERSEAL                                 | New      | 150.00     | 80.00    |
| 5                       | TO REMOVE REVERSE SENSOR                     | New      | 120.00     | 60.00    |
| 6                       | TO REMOVE UPHOLSTERY                         | New      | 150.00     | 80.00    |
| 7                       | TO REMOVE TAILGATE GLASS                     | New      | 180.00     | 120.00   |
| 8                       | TO TRANSFER TAILGATE FITTINGS                | New      | 150.00     | 80.00    |
| 9                       | TO REMOVE LH AND RH AND CENTRE EXHAUST PIPES | New      | 300.00     | 160.00   |
| Gross Labour Cost (S\$) |                                              |          | 3,700.00   | 2,310.00 |

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;