

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 13.02.2020

Time: 12:12:06

Page: 1

China Taiping CP/P

LKK -

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305380946
 REGN NO : SHB6630L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 23.01.2020
 DATE/TIME IN : 13.02.2020 09:25
 ACCIDENT DATE : 12.02.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	/ DEF
0002 04-01-0104-2531-G	REAR BUMPER SIDE BRKT LH	1	33.10	20.00	26.48	? / CRK
0003 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	/ NEC

SUB-TOTAL : 411.60

JOB NATURE

0000 PB	PANEL BEATING	350.00	320
0001 SP	SPRAYPAINT CHARGE	250.00	200
0002 L	R/I REVERSE SENSOR	120.00	X SVNN

SUB-TOTAL : 720.00

TOTAL : 1,131.60

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

NAZ LKK
 13/2/2020 17:15
 PIP
 20PM
 CHECK ITEM PHOTO
 BY PAINT PHOTO

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Our Job Ref No : 305380946

Date : 17/02/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHB6630L

Date of Accident : 12-Feb-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA TAIPING --- GBC7093X
2. The finalized amount shall be:

(a) Spare Parts after List discount	\$411.60
(b) Labour Charges	\$520.00
Total for Part-By-Part Repair Cost	\$931.60
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: 20%	
Final Lumpsum Repair cost	

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : *Lumps*

Signature : *NAZ*

Name : LIM T S

Name : NAZ

Tel : 62148398

Date : 5/3/2020

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Asher

Finalized

- Naz 5/3/2020