



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20002788/Kga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 28-08-2020



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 7996A	Veh. Inspected	SKQ 9799A
Policy No.	VFX/P2203857	Coverage (\$)	0.00
Claim No.	S0M02GKZ	Excess (\$)	0.00
Assign From		Assign Date	19/02/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. X3 (A)	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBAWY920100Y20959	Colour	WHITE
Odometer	18856	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/50 R18	DUNLOP	6 mm
L/H Front Tyre	245/50 R18	DUNLOP	6 mm
R/H Rear Tyre	245/50 R18	DUNLOP	7 mm
L/H Rear Tyre	245/50 R18	DUNLOP	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/02/2020	Inspection Date	19/02/2020
Survey held at	TROPICAL TECH AUTOMOBILE SERVICES BLK 5032, ANG MO KIO AVENUE 3 #01-303 IND. PARK 2 SINGAPORE 569535		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------