



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20002797/Aga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 14-05-2020



ATTN:VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 6059K	Veh. Inspected	SFG 1972E
Policy No.	GA035645	Coverage (\$)	0.00
Claim No.	S0M02GN8	Excess (\$)	0.00
Assign From		Assign Date	18/02/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN SUNNY	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JN1CFAN16Z0131204	Colour	GOLD
Odometer	107897	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/02/2020	Inspection Date	19/02/2020
Survey held at	J-MART MOTOR PTE LTD BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------