

ASS. REC. BY:

REF:

CS/INC20002803/R1e13.02

Special Instruction:

Survey: Rasul

ASSIGNMENT (Office)

From (Person): Cynthia Aug

of INC

Date/Time: 12/2/2020

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To inspect Vehicle No: GBD 275D

Insured: GBB 5975U

at Workshop m/s Woon Meng

Tel: 63161131

of 50 Bukit Batok St 23 201-06

Policy No:

Claim No: MT/1084612-002

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 15/2/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12/2

Person Contacted:

Vehicle ☒ IN/OUT

Date/Time	Action/Instruction
	GBD 275D-X
	GBB 5975U-X

ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. 9BD 275D

at Workshop in/s Woon menh

of 50, BUKA BANG ST 23 #01-06

Insured: INC

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No WBD 2750 Yr Regd 2014 / MAY
 Type: M/Car / M/Cycle / Bus / Car / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: NISSAN NU2001-SLMT c.c. 1461
 Colour WHITE A/C: Insured / Std / NI / NA
 Sp Reading 196467 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: USKYBAM2020076307
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or _____
 Brake: Order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size F: 175/70R14C
 R: 2

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

	N/S	O/S

Bail. or Market Value:			
IDAC Accident Rpt:	Consistent?	Yes or No	
GIA / PR Seen:	Consistent?	Yes or No	
Est. Repairs:	days	Res.:	Yes or No
Lum Sum:	%	3 Val.:	Yes or No
CA / REV / REP. / 24 HRS			
Date:	Person Contacted:		Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or GREEN-MAX VAN

<u>Front</u>		<u>Rear</u>
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>15/02/2020</u>		D.O.I. <u>15/02/2020</u>

Survey held at Wong Meng 4.50pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S FRt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Rasul Confirmed L/S \$ 2,450/- @ .5r days with Rasul ms. Heng. (\$ 3,335.15 Red 58 %)
	RECEIVED 13 MAR 2020
	Rasul, Pls check parts price.

Date/Time, File Path to? ☐ : Prelim Report
11 18/03/20 ☒ : Final Report
Type: 44
Code/Time, File Path to?

Days Of Repair: 5
Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp. (\$
☐ Interview (\$
☐ Tech. Insp. (\$
☐ Wash and Dry (\$

Survey Fee: _____
Transportation: _____
_____ \$ + \$ _____ \$
Flights: _____
Lodging: _____
_____ \$
_____ \$

Export Form 45
Unit Price / Meters: \$ 2.450/- 45

250

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 18 February 2020 9:53 AM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Cc: Toh Choon Hin; Thio Tse Kiat
Subject: TP CASES FARMED OUT TO LKK ON 18/02/2020

Dear LKK,

Please assist to survey the following vehicles as per Mr Toh's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OI VEH	DOA	Additional Remarks
1		MT/1084583-001	SMM1490P	SK AUTOMOBILE PTE LTD	48 Toh Guan Road East # 01-121 Enterprise Hub Singapore 608586	Winson / 62660555			
2			GBD275D	WOON MENG MOTOR PTE LTD	50 BUKIT BATOK STREET 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578	/ 63161131			
3			PC6504T	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	CHRIS / 6702 1555			
4			PC6855E	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	CHRIS / Julie / 6702 1555			6789 5155
5		MT/1082747-002	SMK1259C	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	Julie / 6789 5155			9623 4440 / 9099 6204
6			SLK6383E	XIN HUA WORKSHOP	8 KAKI BUKIT AVENUE 4 #08-40 PREMIER @ KAKI BUKIT SINGAPORE 415875	Eric / 8222 8966			

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang
Admin Assistant
Operations, Motor & Personal Lines
T +65 6430 7900
www.income.com.sg

Cc: Toh Choon Hin; Thio Tse Kiat

Subject: TP CASES FARMED OUT TO LKK ON 18/02/2020

Dear LKK,

Please assist to survey the following vehicles as per Mr Toh's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OI VEH	DOA	Additional Remarks
1	Chryllis Quah	MT/1084583-001	SMM1490P	SK AUTOMOBILE PTE LTD	48 Toh Guan Road East # 01-121 Enterprise Hub Singapore 608586	Winson / 62660555	GBJ8605B	14/02/2020	
2	Helena Tan	MT/1084612-002	GBD275D	WOON MENG MOTOR PTE LTD	50 BUKIT BATOK STREET 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578	/ 63161131	GBB5975U	15/02/2020	
3	Charlotte Chew	MT/1084714-002	PC6504T	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	CHRIS / 6702 1555	GBJ6751A	17/02/2020	
4	David Phua	MT/1084799-001	PC6855E	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	CHRIS / Julie / 6702 1555	GBB9320H	11/02/2020	6789 5155
5	Charlotte Chew	MT/1082747-002	SMK1259C	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	Julie / 6789 5155	SLQ976C	03/02/2020	9623 4440 / 9099 6204
6	Cyndie Yong	MT/1084738-001	SLK6383E	XIN HUA WORKSHOP	8 KAKI BUKIT AVENUE 4 #08-40 PREMIER @ KAKI BUKIT SINGAPORE 415875	Eric / 8222 8966	SKA2577D	15/02/2020	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang

Admin Assistant

Operations, Motor & Personal Lines

T +65 6430 7900

www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Shirley Hiew (LKK Auto)

From: Woon Meng <woonmeng@singnet.com.sg>
Sent: Tuesday, 17 March 2020 4:05 pm
To: Rasul (LKKAuto)
Cc: Shirley Hiew (LKK Auto)
Subject: GBD 275D DOA : 15/02/2020

Dear Rasul,

We refer to the matter below for your kind attention.

Kindly be informed that we confirm acceptance of amount of \$ 2,450.

Thank you & Warmest Regards,

Woon Meng Motor Pte Ltd

50, Bukit Batok Street 23
#01-06 Midview Building, Singapore (659578)
Tel : 63161131 / 63161151 || Fax : 63167050

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Tuesday, 17 March 2020 3:36 PM
To: Heng Sew Sow <woonmeng@singnet.com.sg>
Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: RE: GBD 275D DOA : 15/02/2020

Hi Ms Heng,


As spoken, kindly confirm at amount of \$ 2,450

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Rasul (LKKAuto)
Sent: Monday, 16 March, 2020 12:18 PM
To: Heng Sew Sow
Subject: GBD 275D DOA : 15/02/2020

Hi Ms Heng,

Refer to attachment

Finalised amount is \$ 2,400 / 5 days of lump sum repair

Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/02/2020 13:26
Date Of Accident	15/02/2020 11:20
Exact Location Of Accident	BLK 302 JURONG EAST ST 32 (CARPARK)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD275D
Insured/Policyholder	
Name Of Registered Owner	LITETUTORS
Co Reg No	5XXXX275D
Email Address	LITETUTORS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96553045
Alternative Phone No	OFFICE-96553045

Vehicle Particulars

Manufacturer	NISSAN
Model	NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ19-002358
Cover Note Number	

Driver

Name of Driver	WONG HIN LOONG
NRIC No	SXXXX094F
Date Of Birth	19/05/1960
Occupation	OUTDOOR
Date Of Driving Pass	31/03/1978
Driving Experience	41 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94488785
Fax Number	
Contact Number	
Email Address	LITETUTORS@GMAIL.COM

Address	BLK 302, JURONG EAST ST 32, #08-02
Postcode	600302
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) Involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WONG SIEW FOON GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB5975U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15/10/20, @ about 11:20 hrs, I was travelling along BIK 302 Juwong East
 at 32 Carpark, when suddenly vehicle B, GBB5975U exited the carpark
 and hit into my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

2. RI, SEC & IC HOME TUTORING
 Contact No: 9147 9835 / 9655 3045
 Website: www.litetutors.sg
 Policyholder's Signature: [Signature]
 Date & Time: 17-2-2020

Driver's Signature: [Signature]
 (If driver is not the policyholder)
 Date & Time: 17-2-2020

Reporting Centre Personnel's Signature: [Signature]
 Name: [Signature]
 NRIC/FIN No: 17/2/20

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : NTUC Income Insurance Cooperative Ltd
Motor Claims Dept

Date : 17 Feb 2020

Dear Sirs :

Fax : 6339 6277

RE : ESTIMATE COST FOR NISSAN NV200 - GBD275D

ACCIDENT INVOLVING GBD275D & GBB5975U ON 15/02/2020

ITEMS	DESCRIPTION	QTY	PRICE
1	Front fender n/s -net. <i>bt</i>	1pc	\$ 652.20
2	Front fender lamp n/s -net. <i>? X SU</i>	1pc	\$ 55.20 X
3	Front fender inner garnish n/s -net. <i>de</i>	1pc	\$ 381.25
4	Front headlamp n/s - net <i>? X SU</i>	1pc	\$ 748.10 X
5	Front headlamp lower garnish n/s -net <i>X SU</i>	1pc	\$ 348.60 X
6	Front bumper -net <i>scr</i>	1pc	\$ 755.20
7	Front bumper retainer n/s -net <i>Rec</i>	1pc	\$ 32.70
8	Front tyre hub n/s -net <i>scr (cap)</i>	1pc	\$ 185.30
9	Front abosber n/s -net. <i>? X SU</i>	1pc	\$ 355.40 X
10	Front lower arm n/s -net. <i>? X SU</i>	1pc	\$ 325.10 X
			\$ 3,839.05
	Less 10%		\$ (383.90)
			\$ 3,455.15
11	Tyre rim n/s. <i>bt</i>	1pc	\$ 280.00
12	Front tyre <i>? 70% X SU</i>	1pc	\$ 250.00 X
	Sum Carried Forward		\$ 3,985.15

280

Sum Carried Forward

\$ 3,985.15

Labour Charge & Misc

Towing fee

\$ 60.00

To remove, repair, replace & install rear
damaged parts.

\$ 800.00 650

To R & R undercarriage.

\$ 180.00 100 X 1.4

To wheel alignment

\$ 100.00 60

To R & R wiring & lighting.

\$ 60.00 30

To putty & spray painting.

\$ 600.00 500

Total

\$ 5,785.15

1488.78

280.00

1300.00

3068.78

20%

2455.02

4/5-2,450

5 days

20/2/2020

Resue

Hp 90010068

5 days

4/5

18/02/2020 @ 1655

Resue after repair

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Co.

Acknowledged by Repairer

Signature:

Date:

5 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20002803/R1sf3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 19-03-2020



ATTN: HELENA TAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 5975U	Veh. Inspected	GBD 275D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1084612-002	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	18/02/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200 1.5L MT	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VSKYBAM20Z0076307	Colour	WHITE
Odometer	196467 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14C	GREEN-MAX VAN	6 mm
L/H Front Tyre	175/70 R14C	GREEN-MAX VAN	6 mm
R/H Rear Tyre	175/70 R14C	GREEN-MAX VAN	6 mm
L/H Rear Tyre	175/70 R14C	GREEN-MAX VAN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/02/2020	Inspect Date / Time	18/02/2020 (04:50 PM)
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 275D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER N/S (N)	BENT	652.20	555.20
1	FRONT FENDER LAMP N/S (N)	SERVICEABLE	55.20	-
1	FRONT FENDER INNER GARNISH N/S (N)	DEFORMED	381.25	188.40
1	FRONT HEADLAMP N/S (N)	SERVICEABLE	748.10	-
1	FRONT HEADLAMP LOWER GARNISH N/S (N)	SERVICEABLE	348.60	-
1	FRONT BUMPER (N)	SCRATCHED	755.20	755.20
1	FRONT BUMPER RETAINER N/S (N)	NECESSARY	32.70	32.70
1	FRONT TYRE HUB N/S (N)	SCRATCHED	185.30	122.70
1	FRONT ABSORBER N/S (N)	SERVICEABLE	355.40	-
1	FRONT LOWER ARM N/S (N)	SERVICEABLE	325.10	-
	LESS 10% DISCOUNT		-383.90	-165.42
			3,455.15	1,488.78
SPECIAL NETT ITEMS				
1	TYRE RIM N/S (SN)	BENT	280.00	280.00
1	FRONT TYRE (SN)	SERVICEABLE	250.00	-
			530.00	280.00
LABOUR				
	TOWING FEE.		60.00	60.00
	TO REMOVE,REPAIR,REPLACE & INSTALL REAR DAMAGED PARTS.		800.00	650.00
	TO R&R UNDERCARRIAGE.	NOT NECESSARY	180.00	-
	TO WHEEL ALIGNMENT.		100.00	60.00
	TO R&R WIRING & LIGHTING.		60.00	30.00
	TO PUTTY & SPRAY PAINTING.		600.00	500.00
			1,800.00	1,300.00
GRAND TOTAL			5,785.15	3,068.78
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,450.00



Report Ref No. CS/INC20002803/R1sf3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

A handwritten signature in black ink, appearing to be 'K.K.LAU'.

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.