

ASS. REC. BY:

REF: CS/CT 20062838/ESf3 | n2
Special Agent

Special instruction:

Surveyor: Shruti ASSIGNMENT (Office)

From (Person): Adeline chng pi win of C71 Date/Time: 14.2.2024 9.32A.M

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 7843C Insured: YJ 6588H

at Workshop m/s Ding Auto Motive Tel: 96992878
of 31 Corporation Rd

Policy No: DNEVSA 0000021900 Claim No: SNM201) 20084402

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 14/2/22
(Client's Record) _____

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 19/11/2020 11:07a.m. Person Contacted: Mohan Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC FB43C - CS/FCT18018911 / Rkpd3m2 Nov - 10/16/2018
	UJ 6-5234 - X

ASS. REC. BY:

Sten

REF: C72

ASSIGNMENT

From:

Date:

20-2-2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHC 7843C

at Workshop m/s Ding Automotive

of 31 Corporation Road

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Acura 100m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

map

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SHC 7843C

Yr Regn:

30/4/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai AE 100m

c.c 1580

Colour:

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading:

116434

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHC 851CVK4 140717

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/65P15

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Valley Stone

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

14/2/20

D.O.A.

20/2/20

Survey held at

Ding Automotive

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/2/20 Final - \$1928.26, 4 days (Guang)
(\$ 1,204.08 Red - 32%)

21/2/2020

RECEIVED 27 FEB 2020

Date/Time, File Pass to?

27/02/20

1) Typ: 4

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / L.B. / P/P

☐ : Preli. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Feb 2020		19 Feb 2020 09:32 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:			
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHC7843C	Date of Loss:	14/02/2020 08:00 - :59
Claim Type:	TP / SNM20D200844C02	Policy/Cover Note No.:	DMCVSNA00000931900
Vehicle Reg. No. (Insured):	YJ6588H	Policy No. (Claimant):	D-18088937MFSH
		Excess:	S\$2,000.00
Repairer:	Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD, 649825 Boon Lay - Tel: 96992878		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 28/02/2020]		
Adj. Asp. Remarks:	survey revert		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results,									

Nivitha (LKK Auto)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Wednesday, 19 February 2020 9:22 AM
To: 'assignments'
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg;
Taxis Customer Service; Claims Dept of CTI
Subject: RE: OUR REF: SNM20D200844/YJ6588H/ADELINE - ACCIDENT INVOLVING
SHC7843C AND YJ6588H ON 14/02/2020 SURVEYOR ARRAGEMENT

Without Prejudice

Dear LKK

Please refer to below email and liaise with third party workshop.

Thank you.

Adeline Chng
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6178 | F: (65) 6225 5879

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Taxis Customer Service [mailto:taxiscs@stengg.com]
Sent: Wednesday, 19 February 2020 7:56 AM
To: Adeline Chng <adeline.chng@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg
Subject: RE: OUR REF: SNM20D200844/YJ6588H/ADELINE - ACCIDENT INVOLVING SHC7843C AND YJ6588H ON
14/02/2020 SURVEYOR ARRAGEMENT

Hi Adeline,

Please arrange surveyor Mr Simon Ho to conduct survey on requested date & time. Thank you

Best Regards,
VADIVELAN MOHAN
Ding Automotive Pte Ltd
Hp : 96891857 / 62657130

From: Adeline Chng <adeline.chng@sg.cntaiping.com>

Sent: Tuesday, February 18, 2020 11:33 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Taxis Customer Service <taxiscs@stengg.com>

Subject: RE: OUR REF: SNM20D200844/YJ6588H/ADELINE - ACCIDENT INVOLVING SHC7843C AND YJ6588H ON 14/02/2020 SURVEYOR ARRANGEMENT

WARNING! THIS EMAIL ORIGINATES FROM OUTSIDE ST ENGINEERING.

Without Prejudice

Dear Sirs

We refer to the above matter.

Attached PRS letter for your next action.

Thank you.

Adeline Chng

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

From: Claims Dept of CTI

Sent: Tuesday, 18 February 2020 8:51 PM

To: Adeline Chng <adeline.chng@sg.cntaiping.com>; Taxis Customer Service <taxiscs@stengg.com>

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D200844/YJ6588H/ADELINE - ACCIDENT INVOLVING SHC7843C AND YJ6588H ON 14/02/2020 SURVEYOR ARRANGEMENT

Dear Adeline,

Please conduct PRS for SLX6665Z.

Note : officer in charge – Adeline 63896155.

*** Kindly quote our reference number when replying.

Thank you,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Taxis Customer Service <taxiscs@stengg.com>

Sent: Tuesday, February 18, 2020 2:45 PM

To: chinkiat.ong@sg.cntaiping.com; Claims Dept of CTI <claimsdept@sg.cntaiping.com>;
elaine.cheong@sg.cntaiping.com

Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg

Subject: ACCIDENT INVOLVING SHC7843C AND YJ6588H ON 14/02/2020 SURVEYOR ARRAGEMENT

Dear Officer,

Kindly please arrange survey for vehicle **SHC7843C** on **20/02/2020@10am**. Vehicle still on road and driver will ground on 20/02/2020 before 10am. Survey location will be at 31 Corporation Road.

Best Regards,
VADIVELAN MOHAN
Ding Automotive Pte Ltd
Hp : 96891857 / 62657130

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	839G

Vehicle Details

Vehicle No.:	SHC7843C
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Feb 2020
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV 1.6 DCT
Primary Colour:	Yellow
Manufacturing Year:	2019
Engine No.:	G4LEJU188454
Chassis No.:	KMHCB51CVKU140717
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$24,872.00
Original Registration Date:	30 Apr 2019
First Registration Date:	30 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$11,821.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2027
PARF Rebate Amount:	\$8,865.00

Intended COE Rebate Details

COE Expiry Date:	29 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20,940.00
COE Rebate Amount:	\$18,824.00
Total Rebate Amount:	\$27,689.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	15/02/2020 09:20
Date Of Accident	14/02/2020 08:40
Exact Location Of Accident	ALONG BUKIT BATOK CRESCENT INFRONT UNITY CENTRE
Country/State Of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHC7B43C
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	1XXXXX839G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	AE IONIQ HEV-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	
Driver	
Name of Driver	NEO AH SAI (LIANG YASHI)
NRIC No	SXXXX808A
Date Of Birth	28/02/1974
Occupation	OUTDOOR
Date Of Driving Pass	08/02/1995
Driving Experience	25 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97559358
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 370 BUKIT BATOK STREET 31 #06-213 SINGAPORE
Postcode	650370
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE NOT SUITABLE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YJ6588H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	CHUA KOK SENG
NRIC/Passport Number	SXXXX937C
Contact Number	90683416
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 15/1/2022
09:35 hrs

Reporting Centre Personnel's Signature
Name: ✓ BQ1
NIC/FIN No.:

Accident Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 14/2/2020 ABOUT 8:40HOURS I WAS DRIVING OUT FROM UNITY CENTRE TOWARDS BURIT BATOK CRESCENT ROAD. TRAFFIC WAS SLOW AT TIME. THEREAFTER WHEN MY TAXI AT BURIT BATOK CRESCENT ROAD, OUT OF SUDDEN I LORRY VEHICLE BEARING NUMBER (VJ6588H) CAME OUT FROM STATIONARY PARK INTO MY LANE. HE DROVE HIS LORRY AND COLLIDED INTO MY VEHICLE FRONT RHS PORTION. AFTER WHICH WE EXCHANGED PARTICULARS FOR INSURANCE REPORTING PURPOSE. NO INJURY INVOLVED AT TIME.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Signature of the Policyholder

Driver's Signature
(If driver is not the policyholder)
Date & Time: 15/2/2020

04:25 PM

Reporting Centen Personnel's Signature
Name: VMOJ
NRIC/IN No.:

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

20/02/2020 8:19

JOB-NO: 50112453

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE

64739522

SINGAPORE 575717 0

VEHICLE DETAILS

LICENSE NO: SHC7843C

TRANS: AUTO

CHASSIS: KMHCB51CVKU140717

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 Di

ENGINE: G4LEJU188454

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

LABOUR

1 STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	1.00	800.00	0.00	800.00	499	Y	
2 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00	230	Y	
3 RESPRAY FRONT RHS FENDER	1.00	250.00	0.00	250.00	190	Y	
4 RUST PROOFING	1.00	80.00	0.00	80.00	30	Y	
TOTAL:		1,380.00	0.00	1,380.00			

MATERIALS

1 FRONT RHS FENDER	1.00	609.40	121.88	487.52	✓	L	Y
2 FRONT BUMPER	1.00	601.30	120.26	481.04	✓	L	Y
3 FRONT RHS BUMPER RETAINER	1.00	62.32	12.46	49.86	✓	L	Y
4 FRONT RHS INNER SHIELD	1.00	366.30	73.26	293.04	X	L	Y
5 FRONT RHS WHEEL CAP	1.00	326.30	65.26	261.04	X	L	Y
6 FRONT RHS FENDER EMBLEM (BLUE DRIVE)	1.00	62.30	12.46	49.84	✓	L	Y
7 FRONT RHS INNER SHIELD CLIPS	1.00	65.00	0.00	65.00	X	S	Y
8 FRONT BUMPER CLIPS	1.00	65.00	0.00	65.00	30	S	Y
TOTAL:		2,157.92	405.58	1,752.34			

TOTAL PARTS & LABOUR:		3,537.92	405.58	3,132.34			
----------------------------------	--	----------	--------	----------	--	--	--

EXCESS/LOADING-SS 0.00

No. Of Day: 4 dgs

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: SS

DATE OF SURVEY: 20, 1, 2, 2020

SURVEYED BY: STEPHEN CH

CONTACT NO: 8322 8817

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1098-26

L-830

1928-26

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	-----------------	----------	------------	-----	----------	--------------

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002838/ESF3N2

Date: 03/03/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00000931900
Claimant Vehicle No :	SHC7843C	Insured Vehicle No :	YJ6588H
Date of Loss:	14/02/2020	Nature of Claim:	TP
		Claim No:	SNM20D200844C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC7843C	Engine No:	G4LEJU188454
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 (A)	Chassis No:	KMHC851CVKU140717
Reg. Date:	30/04/2019 (Man. Year: 2019)	Odometer:	116434 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	VALLEY STONE 5 mm	Rear Left Side:	VALLEY STONE 5 mm
Front Right Side:	VALLEY STONE 5 mm	Rear Right Side:	VALLEY STONE 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,752.34	1,098.26	654.08	37.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	830.00	550.00	39.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,132.34	1,928.26	1,204.08	38.44
+ GST 7.00/7.00% (S\$)	219.26	134.98	84.28	38.44
Nett Amount (S\$)	3,351.60	2,063.24	1,288.36	38.44

INSPECTION

Date of Assignment:	19/02/2020		
Date Inspected:	20/02/2020	Inspected At:	Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD Singapore 649825
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Mar 2020)		
Parts:	N/A	HYUNDAI AE IONIQ HEV 1.6 (A) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SHC7843C)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RHS FENDER	Dented	609.40 FL	*609.40 FL
2	1		*FRONT BUMPER	Broken	601.30 FL	*601.30 FL
3	1		*FRONT RHS BUMPER RETAINER	Broken	62.32 FL	*62.32 FL
4	1		*FRONT RHS INNER SHIELD	Not Necessary	366.30 FL	*- FL
5	1		*FRONT RHS WHEEL CAP	Not Necessary	326.30 FL	*- FL
6	1		*FRONT RHS FENDER EMBLEM (BLUE DRIVE)	Necessary	62.30 FL	*62.30 FL
7	1		*FRONT RHS INNER SHIELD CLIPS	Not Necessary	65.00 FS	*- FS
8	1		*FRONT BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	2,157.92	1,365.32
- List Item Discount on L Items 20.00/20.00% (S\$)	405.58	267.06
Total Parts (S\$)	1,752.34	1,098.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	800.00	400.00
2	RESPRAY FRONT BUMPER	New	250.00	200.00
3	RESPRAY FRONT RHS FENDER	New	250.00	200.00
4	RUST PROOFING	New	80.00	30.00
Gross Labour Cost (\$\$)			1,380.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >