



Case Details

Case Reference Number : BUS/02/20/5017

Company Type : SMRT Buses Ltd

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Type of Repair : Accident Repair

Estimation ID : EST-10534-ID

Accident Date and Time : 10/02/2020 07:00 AM

Vehicle Registration Number : SMB5040L

Assigned By : Claiming Case Owner Team

Vehicle Age(In Months) : 60

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Re
Standard	Main	Body	6011241	MOULDING,WHEELARCH:LH & RH, FOR ADL DD	1	88.03	88.03	10.00	79.23	Replace	1	79.23	Replace / cut.
Total Spare Part Cost									79.23		Surveyor Total		79.23
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)		20
Final Spare Part Cost									63.38		Final Sur Total		63.38

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH REAR PORTION	1,060.00	795	795
Total:			1,060.00	795.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	862.00	694	694
Total:			862.00	694.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	63.38	63.38
Total Labour Cost	0.00	795.00

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spray Painting	0.00	694.00
Other	0.00	0.00
Overall Total	63.38	1,552.38
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	1,552.38
Surveyor Approved Amount		1,552.38
No of Repair Days*	3	2 <i>2 days.</i>
Remarks	-	L/S Repair Photo after paint
Surveyor Name		Sun Pin (LKK)
Signature		 Save Clear
Survey Date	18/02/2020	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: