

22/03/2002

ASS. REC. BY:

REF: CS 3 / ICS 2000 2882 / Ggd/302

General Instruction:

Survey: ANODINGASSIGNMENT (Office)From (Person): Nicholas chug of ICS Date/Time: 19/2/2002 @ 2:42pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 5836Y Insured: 8KA 3207Rat Workshop m/s Cadre Automobile Tel: 6747 7618of 1 Kaki Bukit Ave 6 #02-49 AutobayPolicy No: _____ Claim No: DMPC2000035H / EC

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17/02/2002

(Client's Record)

CA / REV / REP. / REV 24 HRS impDate/Time: 2:51pm @ 19/2/2002 Person Contacted: Vicfor H.O.D. Endorsement: _____Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Johnnie X</u>
	<u>SLK 5836Y - X</u>
	<u>8KA 3207R - CC6 / ALG 12017750 / UA-2+292</u>
	<u>ROA - 11/09 / 2012</u>
<u>7/2/20</u>	<u>Disassemble survey: 26/02/20</u>
	<u>Submit PPS.</u>

ASS. REC. BY:

REF:

ASSIGNMENT

From

Date:

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: 94C 58367 Yr Regn: 20 Jan 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: chevrolet orlando C.C. B62

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 81730 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 19-02-20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$2000 - \$3000 [Signature]
20/2/2020

RECEIVED 24 FEB 2020

Date/Time, File Pass to?

1) [Signature] ☐ : Preli. Report

Date/Time, File Return to?

2)

Report Form:

Lump Sum / F.B. / G.

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

3 + RS. SI

Photos

Others

TOTAL

120

11

131

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Wednesday, 19 February 2020 2:42 PM
To: Nancy Lam; assignments@lkkauto.com
Cc: Corene Chong; Celeste Ng; Tang Hui Ting; ECICS Claims; Elizabeth Chew Ming Lai (ECICS, Claims)
Subject: RE: Our Client's vehicle no. SLK5836Y (CA) - YOUR INSURED - SKA3207R (ECICS)- DOA 17/02/2020 TO ISSUE PRI ECICS reference DMPC2000035H/EC
Attachments: Cadre Automobile - Pre-Repair Notice (ECICS)(SLK5836Y).pdf
Importance: High

WITHOUT PREJUDICE

Hi Nancy,

Thank you for your email.

We are not agreeable with your surveyor list and we will appoint *LKK Auto Consultants Pte Ltd* for the SJE.

Aside to LKK Auto Consultants,

Please assist to arrange survey for TPV.

Best regards

Nicholas Chua

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email Nicholas_Chua@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Nancy Lam [mailto:nancy@crossbordersllc.com]
Sent: Wednesday, 19 February 2020 2:05 PM
To: ECICS Claims
Cc: Corene Chong; Celeste Ng; Tang Hui Ting; Elizabeth Chew Ming Lai (ECICS, Claims)
Subject: RE: Our Client's vehicle no. SLK5836Y (CA) - YOUR INSURED - SKA3207R (ECICS)- DOA 17/02/2020 TO ISSUE PRI

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Sirs

1. We refer to your email as below:

2. Our client objects appointing your surveyors as a single joint expert.

3. We propose one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:-

- | | | |
|----|------------------|---|
| a) | Dennis Yap | PAL'S Appraiser Pte Ltd |
| b) | Marc Ananda | United Appraisal and Management Pte Ltd |
| c) | Yap Teck Lee | LCW Appraiser Pte Ltd |
| d) | Yap Teck Chye | MC-Coy Appraiser Pte Ltd |
| e) | Dixon Yeo | Treasure Appraiser Pte Ltd |
| f) | Andrew How | Prominent Appraiser Services |
| g) | Alan Cheong K.H. | C L Appraiser Pte Ltd |
| h) | T.T. Rajan | ST Appraisal Services |
| i) | Sebastian Lim | Constanct Appraiser Services |
| j) | Aeon Auto | Consultants LLP |

4. Please let us know within two (2) working days whether you are agreeable to the appointment of any of the above motor surveyors as a single joint expert.

Thank You.

Regards

Nancy

TEL: 6438 1323 (ext 2020)

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

From: ECICS Claims <claims@ecics.com.sg>

Sent: Wednesday, 19 February 2020 1:48 pm

To: Nancy Lam <nancy@crossbordersllc.com>

Cc: Corene Chong <corene@crossbordersllc.com>; Celeste Ng <celeste@crossbordersllc.com>; Tang Hui Ting <huiting@crossbordersllc.com>; ECICS Claims <claims@ecics.com.sg>; Elizabeth Chew Ming Lai (ECICS, Claims) <Elizabeth_Chew@ecics.com.sg>

Subject: RE: Our Client's vehicle no. SLK5836Y (CA) - YOUR INSURED - SKA3207R (ECICS)- DOA 17/02/2020 TO ISSUE PRI

WITHOUT PREJUDICE

Our reference DMPC2000035H/EC

Hi Nancy,

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. Ajax Inspection Services Pte Ltd
2. Appraisals Associates Pte Ltd
3. Infiniti Appraisal Services
4. LKK Auto Consultants

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Best regards

Nicholas Chua

Senior Associate | Claims



DID (65) 6303 0167

Tel (65) 6337 4779

Email Nicholas_Chua@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600.

From: Nancy Lam [<mailto:nancy@crossbordersllc.com>]

Sent: Tuesday, 18 February 2020 3:08 PM

To: ECICS Claims

Cc: Corene Chong; Celeste Ng; Tang Hui Ting

Subject: Our Client's vehicle no. SLK5836Y (CA) - YOUR INSURED - SKA3207R (ECICS)- DOA 17/02/2020 TO ISSUE PRI

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Sirs

Please find attached our PRI notice dated 18 February 2020 for your kind attention.

Thank You.

Regards

Nancy Lam

TEL: 6438 1323 ext 2006

CrossBorders LLC

133 New Bridge Road

#23-03/04/05 Chinatown Point

Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

CrossBORDERS LLC

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.lk.CA (SLK5836Y)
Your Ref: SKA3207R

18 February 2020

ECICS Limited
10 Eunus Road 8
#09-04A Singapore Post Centre
Singapore 408600
Attn: Motor Claims Department

BY EMAIL ONLY

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION
CLAIMANT: TAY JUN XIONG MATTHEW
TRAFFIC ACCIDENT ON 17 February 2020 AT 12:45 HRS ALONG MANDARIN
GALLERY TURNING RIGHT TO MAIN ROAD INVOLVING VEHICLES NO.
SLK5836Y & SKA3207R

We are instructed by Tay Jun Xiong Matthew to notify you of a road accident on 17 February 2020 at about 12:45 hrs along Mandarin Gallery turning right to main road involving our client's vehicle registration number SLK5836Y and vehicle registration number SKA3207R driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: Cadre Automobile
Address: No. 1 Kaki Bukit Avenue 6 #02-49
Autobay @ Kaki Bukit Singapore 417883
Contact: Mr Victor @ 6747 7618

Please liaise with the above workshop directly.

Yours faithfully

CrossBorders LLC

Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com

encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

.....

CONFIDENTIALITY CAUTION

THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CrossBORDERS LLC

A LIMITED LIABILITY CORPORATION. REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284K

MAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313

BRANCH OFFICE
1 JALAN BERSEH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037

PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICE

WE DO NOT ACCEPT
SERVICE BY FAX

URGENT

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/02/2020 12:29
Date Of Accident	17/02/2020 12:45
Exact Location Of Accident	MANDARIN GALLERY TURNING RIGHT TO MAIN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK5836Y
Insured/Policyholder	
Name Of Registered Owner	TAY JUN XIONG MATTHEW
NRIC No	SXXXX751C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81687766
Alternative Phone No	OFFICE-81687766

Vehicle Particulars

Manufacturer	CHEVROLET
Model	ORLANDO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRER USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5114470160
Cover Note Number	

Driver

Name of Driver	TAY JUN XIONG MATTHEW
NRIC No	SXXXX751C
Date Of Birth	28/10/1967
Occupation	OUTDOOR
Date Of Driving Pass	27/09/1988
Driving Experience	31 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81687766
Fax Number	
Contact Number	OFFICE-81687766
Email Address	NOEMAIL

Address	APT BLK 330 TAMPINES ST 32 #06-432
Postcode	520330
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKA3207R
Vehicle Make/Model/Colour	MERCEDES BENZ
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was stationary to check on the road status before I turn right into the main road. Out of sudden, I felt an impact from my rear. After I check, discovered car A was hit onto my rear portion.

DECLARATION

I hereby declare that the information provided is true and correct.

ah

Signature of the Driver

Signature of the Witness

Signature of the Police Officer

Nivitha (LKK Auto)

From: Nancy Lam <nancy@crossbordersllc.com>
Sent: Wednesday, 19 February 2020 2:44 PM
To: ECICS Claims; assignments@lkkauto.com
Cc: Corene Chong; Celeste Ng; Tang Hui Ting; Elizabeth Chew Ming Lai (ECICS, Claims)
Subject: RE: Our Client's vehicle no. SLK5836Y (CA) - YOUR INSURED - SKA3207R (ECICS)- DOA 17/02/2020 TO ISSUE PRI ECICS reference DMPC2000035H/EC

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Sirs

1. We refer to your letter dated as below
2. Please be informed that the said vehicle can be inspected at:

Venue: Cadre Automobile
Address: No. 1 Kaki Bukit Avenue 6 #02-49
Autobay @ Kaki Bukit Singapore 417883
Contact: Mr Victor @ 6747 7618

3. Please liaise with the above workshop.

Thank You.

Regards
Nancy
TEL: 6438 1323 (ext 2020)

CrossBorders LLC
133 New Bridge Road
#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

From: ECICS Claims <claims@ecics.com.sg>
Sent: Wednesday, 19 February 2020 2:42 pm
To: Nancy Lam <nancy@crossbordersllc.com>; assignments@lkkauto.com
Cc: Corene Chong <corene@crossbordersllc.com>; Celeste Ng <celeste@crossbordersllc.com>; Tang Hui Ting <huiting@crossbordersllc.com>; ECICS Claims <claims@ecics.com.sg>; Elizabeth Chew Ming Lai (ECICS, Claims) <Elizabeth.Chew@ecics.com.sg>
Subject: RE: Our Client's vehicle no. SLK5836Y (CA) - YOUR INSURED - SKA3207R (ECICS)- DOA

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	751C
Vehicle No.:	SLK5836Y
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Feb 2020
Vehicle Make:	CHEVROLET
Vehicle Model:	ORLANDO 1.4AT TURBO
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	B14NET162660013
Chassis No.:	KL1YA7589HK608364
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$16,114.00
Original Registration Date:	20 Jan 2017
First Registration Date:	20 Jan 2017
Transfer Count:	1
Actual ARF Paid:	\$16,114.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jan 2027
PARF Rebate Amount:	\$12,085.00
COE Expiry Date:	19 Jan 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,807.00
COE Rebate Amount:	\$36,524.00
Total Rebate Amount:	\$48,609.00

The information contained herein is correct as at 19 Feb 2020

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)


































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Feb 2020 10:34 Edit Reg		19 Feb 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -, Email: EMAIL@EMAIL.COM									
Main Claimant: TAY JUN XIONG MATTHEW									
Vehicle Reg. No.: SLK5836Y		Date of Loss: 17/02/2020 12:00 - :59 [36 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): SKA3207R		Policy No. (Claimant):							
		Excess:							
Repairer: Cadre Automobile (HQ) NO. 1 KAKI BUKIT AVENUE 6, #02-49 AUTOBAY, 417883 Kaki Bukit - Tel:									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 28/02/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK5836Y
[SKA3207R]
TP
TAY JUN XIONG MATTHEW
Feb 17 2020 12:00PM
[-]
Cadre Automobile

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
2	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
3	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
4	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
5	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
6	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
7	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
8	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
9	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
10	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
11	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
12	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
13	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
14	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
15	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
16	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
17	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
18	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
19	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
20	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
21	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
22	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
23	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
24	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
25	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
26	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
27	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
28	21/02/20 15:10	General View								Load JPG	<input checked="" type="checkbox"/>			
29	21/02/20 15:10	Odometer Reading								Load JPG	<input checked="" type="checkbox"/>			
30	21/02/20 15:10	Chassis Number								Load JPG	<input checked="" type="checkbox"/>			
31	21/02/20 15:11	DISMANTLE PHOTOS								Load JPG	<input checked="" type="checkbox"/>			
32	21/02/20 15:11	DISMANTLE PHOTOS								Load JPG	<input checked="" type="checkbox"/>			
33	21/02/20 15:11	DISMANTLE PHOTOS								Load JPG	<input checked="" type="checkbox"/>			
34	21/02/20 15:11	DISMANTLE PHOTOS								Load JPG	<input checked="" type="checkbox"/>			
35	21/02/20 15:11	DISMANTLE PHOTOS								Load JPG	<input checked="" type="checkbox"/>			
36	21/02/20 15:11	DISMANTLE PHOTOS								Load JPG	<input checked="" type="checkbox"/>			
37	21/02/20 15:11	DISMANTLE PHOTOS								Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
39	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
40	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
41	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
42	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
43	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
44	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
45	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
46	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
47	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
48	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
49	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
50	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
51	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
52	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
53	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
54	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
55	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
56	21/02/20 15:11	DISMANTLE PHOTOS	 Load JPG	<input checked="" type="checkbox"/>
57	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
58	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
59	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
60	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
61	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
62	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
63	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
64	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
65	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
66	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
67	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
68	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
69	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
70	24/02/20 09:04	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS20002882/GQD3E2

Date: 26/02/2020

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SLK5836Y

Insured Vehicle No :

SKA3207R

Date of Loss: 17/02/2020

Nature of Claim:

TP

Claim No:

N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK5836Y

Make & Model: CHEVROLET ORLANDO, 1.4 (A)

Engine No: B14NET162660013

Reg. Date: 20/01/2017 (Man. Year: 2016)

Chassis No: KL1YA7589HK608364

Colour: Silver

Odometer: 81730 km

Engine Capacity: 1362 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Goodride 6 mm

Rear Left Side: Goodride 6 mm

Front Right Side: Goodride 6 mm

Rear Right Side: Goodride 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/02/2020

Date Inspected: 19/02/2020 Inspected At:

Cadre Automobile (HQ)

NO. 1 KAKI BUKIT AVENUE 6, #02-49

AUTOBAY

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2020)
Parts:	M1-MPV	CHEVROLET ORLANDO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK5836Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >