ASS, REC. BY:	
and the state of t	IGNMENT
From: Date:	Veh No: SKM 1361C 23/10/2018
Estimated Cost:	Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyota Sienta
at Workshop m/s	Golour ORMAGE A.F. Insured / Std / NI / NA
of	Sp.Reading T/F which Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: MHFZ 28H 340W 58468
Claims No.	Gen. Cond: Good / Poor / Burnt
Sum Insured: Excess:	Steering: Norde / Jammed / Leaked / Burnt or
(Client's Record)	Brake:   order / Jammed / Leaked / Burn: or
flake of Veh;	Modi: Nil /S/Rim / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	P·
emark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
al. or Market Value:	Front Prag
PAC Accident Rport: Consistent? : Yes or No	O.Col
A / PR Seen: Consistent?: Yes or No	L /Dol
	1131
	-20/40 M
m Sum: % 3 Val.: Yes or No	Survey held at
A / REV / REP. / 24 HRS	Des. of Damages (Frt) Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT ete: Person Contacted:	
	The U/C / Chassis frame / Body Structure affected due to collisi
late / Time   Action / Instruction	
submit \$2503.49,2days (red 0%)	
(10d 070)	
fair and reasonable	
2	
no tyre size, no cc,no GIA report	
no tyre size, no co,no dia report	
Time, File Pass to? : Preli. Report	Days Of Repair: 2
26/5/2020 : Final Report	Resurvey No. of Trip: Survey Fee:
Time, File Return to?	And the state of t
Add Fe	e: Site Insp (\$ S+85 or
THE CONTRACT OF	0,10
	: Interview (\$
Former 1	: Tech. Invs (\$