


ASSIGNMENT

Surveyor: ABT DOI: 18/2/2020 Date / Time: 18/2/2020
Registered in Merimen: 19/2/2020


Pre-assign / CCU / FTE




Insured Vehicle No. : SMH 7204L Claim No. : _____
Name of Insured : _____ Policy No. : _____
Insured Tel No. : _____ HP: _____ Make / Model : _____
Excess Sec II :S\$ _____ D.O.A : 13/2/2020 Place of Accident : _____
Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : _____ OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Driver Tel No. : _____ (V/L: YES / NO) Insured Liability : % Final ? Yes / No

SHC1663U → → → →



INSRS: _____
WSP: Bifrost
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
	LOD	<input type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
PRELIMINARY ADVICE Date/Time: _____ Sent By: _____	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>
FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____		
Repair Cost: S\$ _____ (_____ days) Reduction: _____ % Email <input type="checkbox"/> Call <input type="checkbox"/>		
FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email <input type="checkbox"/> Call <input type="checkbox"/>		
Final Liability: % _____ (Agreed / Assessed) BOLA S/N No. : _____ If NO or B 28, Ass. Lia :		
Repair Cost: S\$ _____		
Loss of Rental (LOR): S\$ _____ (_____ days)		
Loss of Use (LOU): S\$ _____ (\$ _____ x _____ days)		
Loss of Income (LOI): S\$ _____ (\$ _____ x _____ days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search S\$ _____		
Medical: S\$ _____		
Disbursement: S\$ _____ (e.g. Tow/ Independent)	1) Claim status: Normal/Reject/Private Settle	
Legal Cost S\$ _____	2) Report Format:	
Total: S\$ _____ Global Sum S\$: _____	3) Survey fee:	
FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email <input type="checkbox"/> Call <input type="checkbox"/>		
Payee 1: S\$ _____ Name 1: _____		
Payee 2: (Strike if N.A.) S\$ _____ Name 2: _____		
Payee 3: (Strike if N.A.) S\$ _____ Name 3: _____		


ASSIGNMENT

COB Oct 2025

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 1663U Yr Regn: 2017 Oct
 Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /
 Truck / Trailer or
 Make: Toyota Prius c.c 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 484044 T/Radio: Insured / Std / NI / NA
 Eng/No: 2ZR3066540
 C/No: JTDKB3FU303565131
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65 R15
 R: — 11 —
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Deventi
 Front S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 12/02/2020 13/02/2020 D.O.I. 18/02/2020
 Survey held at Bijrost Sun Ming
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>ALG SMH 7204L</u>

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____ Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.H. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$) _____)
 : Interview (\$) _____)
 : Tech. Invs (\$) _____)
 : Weekend (\$) _____)

Survey Fee: _____
 Transportation: _____ S + RS. _____ SI
 Photos _____
 Others _____
 TOTAL _____