



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI20002894/Kpa3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 11-05-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 2221C	Veh. Inspected	GBJ 8605B
Policy No.	DMPPHQ20-000795	Coverage (\$)	0.00
Claim No.	DM20HO00348-SG	Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	19/02/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	VM20138328	Colour	WHITE
Odometer	8747	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	165/80 R14	YOKOHAMA	9 mm
L/H Front Tyre	165/80 R14	YOKOHAMA	9 mm
R/H Rear Tyre	165/80 R14	YOKOHAMA	9 mm
L/H Rear Tyre	165/80 R14	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION AND FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/02/2020	Inspection Date	21/02/2020
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------