



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM20002896/R1pa3q2 Date: 02/03/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKU 5729H	Veh. Inspected	XD 8406E
	Policy No.	VA1/GA054532	Coverage (\$)	0.00
	Claim No.	S0M02FHE	Excess (\$)	0.00
	Assign From		Assign Date	19/02/2020
2. Vehicle Particulars & Condition				
	Make & Model	IVECO TRAKKER 13L AUTO	c.c	12882
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WJM3J3SS40C229857	Colour	MULTI
	Odometer	232705 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	315/80 R22.5	AUFINE	8 mm
	L/H Front Tyre	315/80 R22.5	AUFINE	8 mm
	R/H Rear Tyre	315/80 R22.5 (D)	AUFINE	8/8 mm
	L/H Rear Tyre	315/80 R22.5 (D)	AUFINE	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/02/2020	Inspection Date	25/02/2020
	Survey held at	WTS ENGINEERING PTE LTD 8 Gul Circle Singapore6 29564		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			1 Working Days