

ASS. REC. BY:

REF: CS/CT1 20002905/Qsf3

Special Instruction:

Surveyor: Sun Pin

ASSIGNMENT (Office)

From (Person): Addeline Chmy Pei Wan of C71 Date/Time: 20.2.2020 1.05 p.m.

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLX 6665Z Insured: GBD 73795

at Workshop m/s Hua Hong Phu Ltd Tel: 67608815

of 25 b Sungai Radut street 1

Policy No: DMCVSA 17044219022 Claim No: SNM 201200 862102

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 14.2.2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 20.2.2020 9:04 AM Person Contacted: Jellison Vehicle: IN/OUT /

H.O.D. Endorsement:

Vehicle ~~IN~~/OUT /

Date/Time	Action/Instruction (✓) Estimate liability
	SLX 66652 - CC4 ITI 19017041/GP6342 DCA - 131001/2012
	GBD 43495 - X